

Accessibility Survey



City of Downey Meldar Avenue - Charloma Drive to Cul-De-Sac

Charloma Drive to Cul-De-Sac
Downey, CA 90242

Date of Inspection
7/10/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Meldar Avenue - Charloma Drive to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

East Side

Sidewalk North of Charloma Drive @ 33.954355846869, -118.120263218880

Sidewalks : Width

Finding

Sidewalk does not have enough width.

On-Site Finding 47.00 inches for 21.00 feet

Recommendation

Widen the sidewalk to the recommended value.

Recommendation At least 48.00 inches

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-403.5.1

Progress

Record Number	467311	Resolution	None
Progress	Not_Started	Priority	Three
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Meldar Avenue - Charloma Drive to Cul-De-Sac

Sidewalks - Exterior : Sidewalks , Surface

East Side

Sidewalk North of Charloma Drive @ 33.954355846869, -118.120263218880

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 3.30 percent for 37.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302, CA 11B-403.3

Progress

Record Number	467312	Resolution	None
Progress	Not_Started	Priority	Three
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Meldar Avenue - Charloma Drive to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

East Side

Sidewalk North of Charloma Drive @ 33.954491562379, -118.120133131742

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 85.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	467310	Resolution	None
Progress	Not_Started	Priority	Three
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Meldar Avenue - Charloma Drive to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

West Side @ 33.954450402780, -118.120369166136

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	467313	Resolution	None
Progress	Not_Started	Priority	Three
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Meldar Avenue - Charloma Drive to Cul-De-Sac



Meldar Avenue - Charloma Drive to Cul-De-Sac

Charloma Drive to Cul-De-Sac
Downey, CA 90242

Date of Inspection
7/10/2017

*Estimated Facility Total: \$3,612

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Meldar Avenue - Manzanar Avenue to End

Manzanar Avenue to End
Downey, CA 90242

Date of Inspection
6/20/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Meldar Avenue - Manzanar Avenue to End

Sidewalks - Exterior : Sidewalks

East Side @ 33.960806543900, -118.111524581909

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	453615	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Meldar Avenue - Manzanar Avenue to End

Sidewalks - Exterior : Sidewalks

West Side @ 33.961221445247, -118.111208081245

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	453616	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Meldar Avenue - Manzanar Avenue to End



Meldar Avenue - Manzanar Avenue to End

**Manzanar Avenue to End
Downey, CA 90242**

Date of Inspection
6/20/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Meldar Avenue - Vista Del Rio Avenue to Gallatin Road

Vista Del Rio Avenue to Gallatin Road
Downey, CA 90242

Date of Inspection
7/12/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Meldar Avenue - Vista Del Rio Avenue to Gallatin Road

Sidewalks - Exterior : Sidewalks

East Side @ 33.959083513708, -118.114322125912

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	468172	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Meldar Avenue - Vista Del Rio Avenue to Gallatin Road

Sidewalks - Exterior : Sidewalks

West Side @ 33.959210322801, -118.114440143108

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	468173	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Meldar Avenue - Vista Del Rio Avenue to Gallatin Road



Meldar Avenue - Vista Del Rio Avenue to Gallatin Road

Vista Del Rio Avenue to Gallatin Road
Downey, CA 90242

Date of Inspection
7/12/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

