

## Accessibility Survey

---



## City of Downey Benfield Avenue - Studebaker Road to Cecilia Street

Benfield Avenue - Studebaker Road to Cecilia Street  
Downey, CA 90424

Date of Inspection  
2/12/2017

Prepared By

**Disability Access Consultants**

(800) 743-7067

**Benfield Avenue - Studebaker Road to Cecilia Street**

**Sidewalks - Exterior : Sidewalks , Change in Level**

---

**East Side**

**Change In Level South of Studebaker Road @ 33.932481685685, - 118.098246306181**

Sidewalks , Change in Level : Change in Level Non Beveled

**Finding**

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.62 inches

**Recommendation**

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

**Costing Info (Estimated)**

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

**Progress**

---

<b>Record Number</b>	359262	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Two
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2021
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Benfield Avenue - Studebaker Road to Cecilia Street**

**Sidewalks - Exterior : Sidewalks**

---

**East Side**

**Sidewalk South of Studebaker Road @ 33.932378203686, -118.098240941763**

Sidewalks : Missing Sidewalk

**Finding**

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 119.00 feet

**Recommendation**

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

**Costing Info (Estimated)**

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

**Progress**

---

<b>Record Number</b>	359261	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2037
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Benfield Avenue - Studebaker Road to Cecilia Street**

**Sidewalks - Exterior : Sidewalks , Surface**

---

**East Side**

**Sidewalk South of Studebaker Road @ 33.934258663403, -118.098246306181**

Sidewalks , Surface : Cross Slope

**Finding**

Sidewalk cross slope is not compliant.

**On-Site Finding** 3.00 percent for 25.00 feet

**Recommendation**

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

**Costing Info (Estimated)**

Repave surface \$1,092



**Code Reference** ADA 206, 302,CA 11B-403.3

**Progress**

---

<b>Record Number</b>	359260	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2032
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

**Benfield Avenue - Studebaker Road to Cecilia Street**

**Sidewalks - Exterior : Sidewalks**

---

**West Side**

**Sidewalk North of Cecilia Street @ 33.932075545935, -118.098412603140**

Sidewalks : Missing Sidewalk

**Finding**

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 799.00 feet

**Recommendation**

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

**Costing Info (Estimated)**

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

**Progress**

---

<b>Record Number</b>	359259	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2037
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

**Benfield Avenue - Studebaker Road to Cecilia Street**



**Benfield Avenue - Studebaker Road to Cecilia Street**

**Benfield Avenue - Studebaker Road to Cecilia Street  
Downey, CA 90424**

Date of Inspection  
2/12/2017

**\*Estimated Facility Total: \$3,810**

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

**Disability Access Consultants**

(800) 743-7067

Prepared Using

