

Accessibility Survey



City of Downey Kipway Drive - Priscilla Street To Birdvale Drive

Priscilla Street To Birdvale Drive
Downey, CA 90242

Date of Inspection
12/2/2016

Prepared By
Disability Access Consultants
(800) 743-7067

Kipway Drive - Priscilla Street To Birdvale Drive

Sidewalks - Exterior : Sidewalks

East Side

Sidewalk South Of Priscilla Street @ 33.911161739063, -118.138970285654

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 475.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	313058	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Kipway Drive - Priscilla Street To Birdvale Drive

Sidewalks - Exterior : Sidewalks

West Side

Sidewalk North Of Birdvale Drive @ 33.910320316375, -118.139213025570

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 310.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	313060	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Kipway Drive - Priscilla Street To Birdvale Drive

Sidewalks - Exterior : Sidewalks

West Side

Sidewalk North Of West Side @ 33.909827256628, -118.139261305332

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 83.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	313059	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Kipway Drive - Priscilla Street To Birdvale Drive

Sidewalks - Exterior : Sidewalks , Hazards & Gratings

West Side

Tree North Of Birdvale Drive @ 33.910269118430, -118.139207661152

Sidewalks , Hazards & Gratings : Overhead Obstruction Height

Finding

Overhead obstruction height is not compliant.

On-Site Finding 76.00 inches

Recommendation

Provide a compliant vertical clearance height.

Recommendation At least 80.00 inches

Costing Info (Estimated)

Unassigned



Code Reference ADA 206, 307.4, CA 11B-307.4

Progress

Record Number	313061	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Kipway Drive - Priscilla Street To Birdvale Drive



Kipway Drive - Priscilla Street To Birdvale Drive

Priscilla Street To Birdvale Drive
Downey, CA 90242

Date of Inspection
12/2/2016

*Estimated Facility Total: \$3,780

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

