

## Accessibility Survey

---



## City of Downey Meadow Road - Birchdale Avenue To Lakewood Boulevard

Birchdale Avenue To Lakewood Boulevard  
Downey, CA 90638

Date of Inspection  
3/17/2017

Prepared By

**Disability Access Consultants**

(800) 743-7067

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.919085841502, - 118.139258623123

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385551      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | One        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2018 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.918175497535, -118.137253671885

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.25 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385540      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2020 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.918260077580, -118.137418627739

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385539      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.918482656244, -118.137838393450

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.87 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385537      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |



**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Sidewalks - Exterior : Sidewalks , Change in Level**

---

**North Side**

**Change In Level East Of Birchdale Avenue @ 33.918513817211, -118.137890696526**

Sidewalks , Change in Level : Change in Level Non Beveled

**Finding**

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.62 inches

**Recommendation**

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

**Costing Info (Estimated)**

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

**Progress**

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385538      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.919098083225, -118.138942122459

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385544      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.919279483096, -118.139272034168

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385545      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |



**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Sidewalks - Exterior : Sidewalks , Change in Level**

---

**North Side**

**Change In Level East Of Birchdale Avenue @ 33.919459769702, -118.139597922564**

Sidewalks , Change in Level : Change in Level Non Beveled

**Finding**

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.62 inches

**Recommendation**

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

**Costing Info (Estimated)**

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

**Progress**

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385541      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Sidewalks - Exterior : Sidewalks , Change in Level**

---

**North Side**

**Change In Level East Of Birchdale Avenue @ 33.919537671204, -118.139737397432**

Sidewalks , Change in Level : Change in Level Non Beveled

**Finding**

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

**Recommendation**

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

**Costing Info (Estimated)**

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

**Progress**

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385542      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.919547687106, -118.139766901731

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.75 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385546      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918083127127, - 118.137430697680

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385556      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918114288239, -118.137483755

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.00 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385554      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |



## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918124304309, - 118.137519210577

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.00 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385559      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918420334277, - 118.138036876917

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.12 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385558      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918431463203, - 118.138059675694

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.75 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385560      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918438140558, - 118.138070404530

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.12 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385555      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.919099196108, - 118.139293491840

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 1.25 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385553      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2020 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |



## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.919140372800, - 118.139367252588

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.75 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385557      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.919325111224, - 118.139682412148

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.75 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385561      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Two        |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2021 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.918503801187, -118.137873262167

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.37 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385536      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Three      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 12/31/2022 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### North Side

#### Change In Level East Of Birchdale Avenue @ 33.919305079366, -118.139325678349

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.37 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385543      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Three      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 12/31/2022 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### South Side

#### Change In Level West Of Lakewood Boulevard @ 33.918165481471, - 118.137574195862

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.37 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385552      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Three      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 12/31/2022 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |



## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### North Side

#### Sidewalk East Of Birchdale Avenue @ 33.918482656244, -118.137838393450

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 4.40 percent for 105.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385532      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### North Side

#### Sidewalk East Of Birchdale Avenue @ 33.919016842666, -118.138791918755

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 3.70 percent for 141.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385531      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### North Side

#### Sidewalk East Of Birchdale Avenue @ 33.919365174925, -118.139432966709

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 3.50 percent for 167.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

Notes : Surface is rough and uneven for 3 feet.

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385534      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### North Side

#### Sidewalk East Of Birchdale Avenue @ 33.919365174925, -118.139432966709

Sidewalks , Surface : Running Slope

#### Finding

Sidewalk running slope is not compliant.

**On-Site Finding** 9.90 percent for 3.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended running slope.

Recommendation Up to 5.00 percent

#### Costing Info (Estimated)

Repave surface \$1,184



**Code Reference** ADA 206, 302

Notes : Surface is rough and uneven for 3 feet.

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385535      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### North Side

#### Sidewalk East Of Birchdale Avenue @ 33.919896017194, -118.140395879745

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 4.20 percent for 274.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385533      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |



## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks

#### North Side @ 33.919957225210, -118.140488415957

Sidewalks : 60X60 Turn Area

#### Finding

There is no 60X60 turn area at every 200 feet.

**On-Site Finding** Not Found

#### Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$2,400



**Code Reference** ADA 206, 302

### Progress

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385530      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### South Side

#### Sidewalk West Of Lakewood Boulevard @ 33.918374705664, -118.137964457273

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 3.70 percent for 159.00 feet

#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385549      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

## Meadow Road - Birchdale Avenue To Lakewood Boulevard

### Sidewalks - Exterior : Sidewalks , Surface

---

#### South Side

#### Sidewalk West Of Lakewood Boulevard @ 33.918946730889, -118.138990402222

Sidewalks , Surface : Cross Slope

#### Finding

Sidewalk cross slope is not compliant.

**On-Site Finding** 3.70 percent for 92.00 feet


#### Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

#### Progress

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385550      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |

**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Sidewalks - Exterior : Sidewalks**

---

**South Side**

**Sidewalk West Of Lakewood Boulevard @ 33.919012391127, -118.139127194881**

Sidewalks : Opening

**Finding**

Ground surface has an opening that is not compliant.

**On-Site Finding** Not Compliant

**Recommendation**

Make sure that the surface opening does not allow passage of a sphere more than 1/2 inch in diameter.

Recommendation See Recommendation

**Costing Info (Estimated)**

Unassigned



**Code Reference** ADA 302

Notes : Surface is rough and uneven.

**Progress**

---

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385548      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments | <b>New Value</b>      | 0          |
| <b>Assignment</b>       | None        |                       |            |
| <b>Designated Staff</b> |             |                       |            |

**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Sidewalks - Exterior : Sidewalks**

**South Side @ 33.917991869517, -118.137261718512**

Sidewalks : 60X60 Turn Area

**Finding**

There is no 60X60 turn area at every 200 feet.

**On-Site Finding** Not Found

**Recommendation**

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

**Costing Info (Estimated)**

\$2,400



**Code Reference** ADA 206, 302

**Progress**

|                         |             |                       |            |
|-------------------------|-------------|-----------------------|------------|
| <b>Record Number</b>    | 385547      | <b>Resolution</b>     | None       |
| <b>Progress</b>         | Not_Started | <b>Priority</b>       | Seven      |
| <b>Actual Date</b>      |             | <b>Projected Date</b> | 06/30/2032 |
| <b>Actual Cost</b>      | \$0.00      | <b>Contractor</b>     |            |
| <b>Comments</b>         | No Comments |                       |            |
| <b>Assignment</b>       | None        | <b>New Value</b>      | 0          |
| <b>Designated Staff</b> |             |                       |            |



**Meadow Road - Birchdale Avenue To Lakewood Boulevard**



**Meadow Road - Birchdale Avenue To Lakewood Boulevard**

**Birchdale Avenue To Lakewood Boulevard  
Downey, CA 90638**

Date of Inspection  
3/17/2017

**\*Estimated Facility Total: \$16,892**

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

**Disability Access Consultants**

(800) 743-7067

Prepared Using

