

Accessibility Survey



City of Downey Manzanar Avenue - Charloma Drive to Lubec Street

Charloma Drive to Lubec Street
Downey, CA 90242

Date of Inspection
7/12/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Manzanar Avenue - Charloma Drive to Lubec Street

Sidewalks - Exterior : Sidewalks , Surface

East Side

Sidewalk South of Charloma Drive @ 33.953583821734, -118.119981586933

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 3.50 percent for 90.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302, CA 11B-403.3

Progress

Record Number	468101	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Charloma Drive to Lubec Street

Sidewalks - Exterior : Sidewalks , Surface

East Side

Sidewalk South of Charloma Drive @ 33.953845243133, -118.119720071554

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 4.20 percent for 86.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302, CA 11B-403.3

Progress

Record Number	468100	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Charloma Drive to Lubec Street

Sidewalks - Exterior : Sidewalks

East Side @ 33.953859704719, -118.119698613882

Sidewalks : 60X60 Turn Area

Finding

There is no 60X60 turn area at every 200 feet.

On-Site Finding Not Found

Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

Costing Info (Estimated)

\$2,400



Code Reference ADA 206, 302

Progress

Record Number	468099	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Charloma Drive to Lubec Street

Sidewalks - Exterior : Sidewalks

West Side @ 33.953490377294, -118.120269924402

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	468098	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Charloma Drive to Lubec Street



Manzanar Avenue - Charloma Drive to Lubec Street

**Charloma Drive to Lubec Street
Downey, CA 90242**

Date of Inspection
7/12/2017

***Estimated Facility Total: \$4,584**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Manzanar Avenue - Charloma Drive to Suva Street

Charloma Drive to Suva Street
Downey, CA 90242

Date of Inspection
7/10/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Manzanar Avenue - Charloma Drive to Suva Street

Sidewalks - Exterior : Sidewalks

East Side @ 33.953988746454, -118.119567185640

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	467308	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Charloma Drive to Suva Street

Sidewalks - Exterior : Sidewalks

West Side @ 33.954052154820, -118.119690567255

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	467309	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Manzanar Avenue - Charloma Drive to Suva Street



Manzanar Avenue - Charloma Drive to Suva Street

**Charloma Drive to Suva Street
Downey, CA 90242**

Date of Inspection
7/10/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Manzanar Avenue - Cherokee Drive to End

Cherokee Drive to End
Downey, CA 90242

Date of Inspection
7/28/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Manzanar Avenue - Cherokee Drive to End

Sidewalks - Exterior : Sidewalks

West Side @ 33.946269259136, -118.125608861446

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	475397	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Cherokee Drive to End



Manzanar Avenue - Cherokee Drive to End

**Cherokee Drive to End
Downey, CA 90242**

Date of Inspection
7/28/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Manzanar Avenue - Telegraph Road to End

Telegraph Road to End
Downey, CA 90242

Date of Inspection
6/20/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Manzanar Avenue - Telegraph Road to End

Curb Ramps - Exterior : Curb Ramp

Southwest Corner of Telegraph Road @ 33.961544021303, - 118.111049830914

Curb Ramp : Not Wholly Contained Within The Marked Crossing

Finding

The curb ramp is not wholly contained within the marked crossing.

On-Site Finding Not Found

Recommendation

Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.

Recommendation See Recommendation

Costing Info (Estimated)

Install crosswalk \$800



Code Reference ADA 406, 406.5

Progress

Record Number	453611	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Manzanar Avenue - Telegraph Road to End

Curb Ramps - Exterior : Curb Ramp , Landings and Transitions

Southwest Corner of Telegraph Road @ 33.961544021303, - 118.111049830914

Bottom Landing

Curb Ramp , Landings and Transitions : Bottom Landing Slope

Finding

The slope at the bottom landing is greater than allowed.

On-Site Finding 7.40 percent

Recommendation

Provide a compliant bottom landing that does not exceed the maximum slope requirements.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Provide compliant landing \$240



Code Reference ADA 402, 406.4, 406.2, 403.3, 406.1, CA 11B-406.5.3

Progress

Record Number	453612	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Telegraph Road to End

Sidewalks - Exterior : Sidewalks

East Side @ 33.961399418395, -118.110921084881

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	453613	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Telegraph Road to End

Sidewalks - Exterior : Sidewalks

West Side @ 33.961544021303, -118.111049830914

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	453614	Resolution	None
Progress	Not_Started	Priority	Four
Actual Date		Projected Date	06/30/2023
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Telegraph Road to End



Manzanar Avenue - Telegraph Road to End

Telegraph Road to End
Downey, CA 90242

Date of Inspection
6/20/2017

***Estimated Facility Total: \$1,040**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Manzanar Avenue - Vista Del Rio Avenue to Gallatin Road

Vista Del Rio Avenue to Gallatin Road
Downey, CA 90242

Date of Inspection
7/12/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Manzanar Avenue - Vista Del Rio Avenue to Gallatin Road

Sidewalks - Exterior : Sidewalks

East Side @ 33.958473937536, -118.113780319691

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	468175	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Vista Del Rio Avenue to Gallatin Road

Sidewalks - Exterior : Sidewalks

West Side @ 33.958574050711, -118.113892972469

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	468174	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2019
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Manzanar Avenue - Vista Del Rio Avenue to Gallatin Road



Manzanar Avenue - Vista Del Rio Avenue to Gallatin Road

**Vista Del Rio Avenue to Gallatin Road
Downey, CA 90242**

Date of Inspection
7/12/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

