

Accessibility Survey



City of Downey Bigby Street - Vultee Avenue to Clancey Avenue

Vultee Avenue to Clancey Avenue
Downey, CA 90242

Date of Inspection
6/12/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Bigby Street - Vultee Avenue to Clancey Avenue

Sidewalks - Exterior : Sidewalks

North Side @ 33.943918453298, -118.118053078651

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	446286	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigby Street - Vultee Avenue to Clancey Avenue

Sidewalks - Exterior : Sidewalks

South Side @ 33.943802747028, -118.118141591549

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	446285	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigby Street - Vultee Avenue to Clancey Avenue



Bigby Street - Vultee Avenue to Clancey Avenue

Vultee Avenue to Clancey Avenue
Downey, CA 90242

Date of Inspection
6/12/2017

*Estimated Facility Total: \$0

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Biggy Street - Birchdale Avenue to Bellder Drive

Birchdale Avenue to Bellder Drive
Downey, CA 90242

Date of Inspection
7/28/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Bigpy Street - Birchdale Avenue to Bellder Drive

Sidewalks - Exterior : Sidewalks

North Side @ 33.946107942306, -118.121898025274

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	475392	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigpy Street - Birchdale Avenue to Bellder Drive

Sidewalks - Exterior : Sidewalks

South Side @ 33.946026738, -118.121970444918

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	475391	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigpy Street - Birchdale Avenue to Bellder Drive



Bigpy Street - Birchdale Avenue to Bellder Drive

Birchdale Avenue to Bellder Drive
Downey, CA 90242

Date of Inspection
7/28/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Biggy Street - End to End

End to End
Downey, CA 90242

Date of Inspection
7/28/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Bigpy Street - End to End

Sidewalks - Exterior : Sidewalks

North Side @ 33.948368575111, -118.125759065151

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	475398	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Biggy Street - End to End

Sidewalks - Exterior : Sidewalks

South Side

Dolan Avenue South Crossing @ 33.948034824046, -118.125348687172

Sidewalks : Vehicular Traffic Slope

Finding

Slope at vehicular traffic is not compliant.

On-Site Finding 9.70 percent

Recommendation

Repave the surface to provide a compliant slope.

Recommendation Up to 5.00 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference

Progress

Record Number	475401	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Biggy Street - End to End

Sidewalks - Exterior : Sidewalks , Vehicular Traffic

South Side

Driveway East of End @ 33.948279574955, -118.125827461481

Sidewalks , Vehicular Traffic : Cross Walks and Detectable Warnings

Finding

There are no detectable warnings where the pedestrian route crosses vehicular traffic.

On-Site Finding Not Found

Recommendation

Provide detectable warnings.

Recommendation See Recommendation

Costing Info (Estimated)

Install compliant detectable warnings \$190



Code Reference ADA 705,CA 11B-705.1.2.5,CA 11B-247.1.2.5

Progress

Record Number	475402	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Biggy Street - End to End

Sidewalks - Exterior : Sidewalks

South Side

Sidewalk East of Dolan Avenue @ 33.948001448867, -118.125257492065

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 156.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	475400	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Biggy Street - End to End

Sidewalks - Exterior : Sidewalks , Surface

South Side

Sidewalk East of End @ 33.948221724804, -118.125714808702

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 3.90 percent for 98.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302, CA 11B-403.3

Progress

Record Number	475399	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigpy Street - End to End



Bigpy Street - End to End

End to End
Downey, CA 90242

Date of Inspection
7/28/2017

*Estimated Facility Total: \$3,634

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Biggy Street - Woodruff Avenue to Hasty Avenue

Woodruff Avenue to Hasty Avenue
Downey, CA 90242

Date of Inspection
6/13/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Biggy Street - Woodruff Avenue to Hasty Avenue

Sidewalks - Exterior : Sidewalks , Surface

North Side

Sidewalk East of Woodruff Avenue @ 33.941145909785, -118.112398982048

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 4.40 percent for 45.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302, CA 11B-403.3

Progress

Record Number	446587	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Biggy Street - Woodruff Avenue to Hasty Avenue

Sidewalks - Exterior : Sidewalks

North Side

Sidewalk East of Woodruff Avenue to Hasty Avenue @ 33.941043550912, - 118.112203180790

Sidewalks : Missing Sidewalk

Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

On-Site Finding 865.00 feet

Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

Costing Info (Estimated)

\$1,260



Code Reference ADA 206, 302,CA 11B-302,CA 11B-206

Progress

Record Number	446586	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Biggy Street - Woodruff Avenue to Hasty Avenue

Sidewalks - Exterior : Sidewalks

South Side @ 33.941036875330, -118.112476766109

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	446588	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Bigpy Street - Woodruff Avenue to Hasty Avenue



Bigpy Street - Woodruff Avenue to Hasty Avenue

**Woodruff Avenue to Hasty Avenue
Downey, CA 90242**

Date of Inspection
6/13/2017

***Estimated Facility Total: \$2,352**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

