

Accessibility Survey



City of Downey Blandwood Road - Elmont Avenue to Elston Avenue

Elmont Avenue to Elston Avenue
Downey, CA 90242

Date of Inspection
6/21/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Blandwood Road - Elmont Avenue to Elston Avenue

Sidewalks - Exterior : Sidewalks

North Side @ 33.963448307441, -118.117661476135

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	454974	Resolution	None
Progress	Not_Started	Priority	Six
Actual Date		Projected Date	06/30/2027
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blandwood Road - Elmont Avenue to Elston Avenue

Sidewalks - Exterior : Sidewalks

South Side @ 33.963354873835, -118.117774128914

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	454975	Resolution	None
Progress	Not_Started	Priority	Six
Actual Date		Projected Date	06/30/2027
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blandwood Road - Elmont Avenue to Elston Avenue



Blandwood Road - Elmont Avenue to Elston Avenue

Elmont Avenue to Elston Avenue
Downey, CA 90242

Date of Inspection
6/21/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Blandwood Road - Samoline Avenue to Cul-De-Sac

Samoline Avenue to Cul-De-Sac
Downey, CA 90242

Date of Inspection
6/22/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Blandwood Road - Samoline Avenue to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

North Side @ 33.966257941494, -118.120045959949

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found


Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	455958	Resolution	None
Progress	Not_Started	Priority	Six
Actual Date		Projected Date	06/30/2027
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blandwood Road - Samoline Avenue to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

South Side @ 33.966205664906, -118.120165318251

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	455957	Resolution	None
Progress	Not_Started	Priority	Six
Actual Date		Projected Date	06/30/2027
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blandwood Road - Samoline Avenue to Cul-De-Sac



Blandwood Road - Samoline Avenue to Cul-De-Sac

Samoline Avenue to Cul-De-Sac
Downey, CA 90242

Date of Inspection
6/22/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Blandwood Road - Tweedy Lane to Cul-De-Sac

Tweedy Lane to Cul-De-Sac
Downey, CA 90242

Date of Inspection
6/22/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Blandwood Road - Tweedy Lane to Cul-De-Sac

Sidewalks - Exterior : Sidewalks

North Side @ 33.968421274224, -118.120732605457

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	456018	Resolution	None
Progress	Not_Started	Priority	Six
Actual Date		Projected Date	06/30/2027
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blandwood Road - Tweedy Lane to Cul-De-Sac



Blandwood Road - Tweedy Lane to Cul-De-Sac

Tweedy Lane to Cul-De-Sac
Downey, CA 90242

Date of Inspection
6/22/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Blanwood Road - True Avenue to Pico Vista Road

True Avenue to Pico Vista Road
Downey, CA 90242

Date of Inspection
6/17/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks , Change in Level

North Side

Change in Level East of True Avenue @ 33.947911335820, -118.099042922258

Sidewalks , Change in Level : Change in Level Non Beveled

Finding

There is a change in elevation greater than recommended value.

On-Site Finding 0.50 inches

Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

Costing Info (Estimated)

Remove tripping hazards \$198



Code Reference ADA 206, 302

Progress

Record Number	451810	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks , Change in Level

South Side

Change in Level West of Pico Vista Road @ 33.947664358831, -118.098918199539

Sidewalks , Change in Level : Change in Level Non Beveled

Finding

There is a change in elevation greater than recommended value.

On-Site Finding 1.00 inches

Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

Costing Info (Estimated)

Remove tripping hazards \$198



Code Reference ADA 206, 302

Progress

Record Number	451806	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks , Change in Level

South Side

Change in Level West of Pico Vista Road @ 33.947734446968, -118.099041581154

Sidewalks , Change in Level : Change in Level Non Beveled

Finding

There is a change in elevation greater than recommended value.

On-Site Finding 0.62 inches


Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

Costing Info (Estimated)

Remove tripping hazards \$198



Code Reference ADA 206, 302

Progress

Record Number	451807	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks , Hazards & Gratings

North Side

Curb Northeast Corner of True Avenue @ 33.948072649232, -118.099337965250

Sidewalks , Hazards & Gratings : Curb is on Path of Travel

Finding

There is a curb on the designated path of travel.

On-Site Finding Not Compliant

Recommendation

Provide a compliant curb ramp.

Recommendation See Recommendation

Costing Info (Estimated)

Install curb ramp \$2,500



Code Reference ADA 402, 303, 406, 403.4, 303.4

Progress

Record Number	451811	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks

North Side @ 33.948072649232, -118.099337965250

Sidewalks : 60X60 Turn Area

Finding

There is no 60X60 turn area at every 200 feet.

On-Site Finding Not Found

Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

Costing Info (Estimated)

\$2,400



Code Reference ADA 206, 302

Progress

Record Number	451809	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks , Hazards & Gratings

South Side

Curb Southeast Corner of True Avenue @ 33.947941373513, -118.099441230297

Sidewalks , Hazards & Gratings : Curb is on Path of Travel

Finding

There is a curb on the designated path of travel.

On-Site Finding Not Compliant

Recommendation

Provide a compliant curb ramp.

Recommendation See Recommendation

Costing Info (Estimated)

Install curb ramp \$2,500



Code Reference ADA 402, 303, 406, 403.4, 303.4

Progress

Record Number	451808	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road

Sidewalks - Exterior : Sidewalks

South Side @ 33.947360642902, -118.098424673080

Sidewalks : 60X60 Turn Area

Finding

There is no 60X60 turn area at every 200 feet.

On-Site Finding Not Found

Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

Costing Info (Estimated)

\$2,400



Code Reference ADA 206, 302

Progress

Record Number	451805	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2032
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Blanwood Road - True Avenue to Pico Vista Road



Blanwood Road - True Avenue to Pico Vista Road

True Avenue to Pico Vista Road
Downey, CA 90242

Date of Inspection
6/17/2017

***Estimated Facility Total: \$10,394**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

