

Accessibility Survey



City of Downey Salford Avenue - Benares Street To Cul-de-sac

Benares Street To Cul-de-sac
Downey, CA 90242

Date of Inspection
4/20/2017

Prepared By
Disability Access Consultants
(800) 743-7067

Salford Avenue - Benares Street To Cul-de-sac

Sidewalks - Exterior : Sidewalks

East Side @ 33.944636051174, -118.154882490635

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	408616	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Benares Street To Cul-de-sac

Sidewalks - Exterior : Sidewalks

West Side @ 33.944705029256, -118.155017942190

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	408615	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Benares Street To Cul-de-sac



Salford Avenue - Benares Street To Cul-de-sac

**Benares Street To Cul-de-sac
Downey, CA 90242**

Date of Inspection
4/20/2017

***Estimated Facility Total: \$0**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Salford Avenue - Stewart & Gray Road To De Palma Street

Stewart & Gray Road To De Palma Street
Downey, CA 90242

Date of Inspection
4/20/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks , Change in Level

West Side

Change In Level North Of Fontana Street @ 33.942182842729, -118.156340271235

Sidewalks , Change in Level : Change in Level Non Beveled

Finding

There is a change in elevation greater than recommended value.

On-Site Finding 0.75 inches

Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

Costing Info (Estimated)

Remove tripping hazards \$198



Code Reference ADA 206, 302

Progress

Record Number	408648	Resolution	None
Progress	Not_Started	Priority	Two
Actual Date		Projected Date	06/30/2021
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Curb Ramps - Exterior : Curb Ramp

Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675

Curb Ramp : Curb Ramp Slope

Finding

The running slope is greater than allowed.

On-Site Finding 13.00 percent

Recommendation

Provide a compliant curb ramp.

Recommendation Up to 8.33 percent

Costing Info (Estimated)

Install curb ramp \$1,300



Code Reference ADA 406, 406.1, 405.2, CA 11B-406

Progress

Record Number	408654	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Curb Ramps - Exterior : Curb Ramp , Ramp Run

Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675

Curb Ramp , Ramp Run : Grade Break

Finding

Curb ramp run surface has a grade break.

On-Site Finding Not Compliant

Recommendation

Provide a compliant curb ramp.

Recommendation See Recommendation

Costing Info (Estimated)

Install curb ramp \$1,440



Code Reference CA 11B-406.5.6

Progress

Record Number	408655	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Curb Ramps - Exterior : Curb Ramp

Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675

Bottom Landing

Curb Ramp : Bottom Landing Slope

Finding

The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.

On-Site Finding 6.80 percent

Recommendation

Ensure the bottom landing slope is compliant and provides a smooth transition.

Recommendation Up to 5.00 percent

Costing Info (Estimated)

Repave landing \$1,260



Code Reference ADA 406, 406.2, CA 11B-406.5.8

Progress

Record Number	408656	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks , Surface

East Side

Sidewalk South Of De Palma Street @ 33.941912484820, -118.156338099

Sidewalks , Surface : Cross Slope

Finding

Sidewalk cross slope is not compliant.

On-Site Finding 3.40 percent for 120.00 feet

Recommendation

Repave the sidewalk surface with the recommended cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302,CA 11B-403.3

Progress

Record Number	408653	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks

East Side @ 33.942618973842, -118.155818581581

Sidewalks : 60X60 Turn Area

Finding

There is no 60X60 turn area at every 200 feet.

On-Site Finding Not Found

Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

Costing Info (Estimated)

\$2,400



Code Reference ADA 206, 302

Progress

Record Number	408652	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks , Hazards & Gratings

West Side

Curb Northwest Corner Of Fontana Street @ 33.942081597687, -118.156400620937

Sidewalks , Hazards & Gratings : Curb is on Path of Travel

Finding

There is a curb on the designated path of travel.

On-Site Finding Not Compliant

Recommendation

Provide a compliant curb ramp.

Recommendation See Recommendation

Costing Info (Estimated)

Install curb ramp \$2,500



Code Reference ADA 402, 303, 406, 403.4, 303.4

Progress

Record Number	408650	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks , Hazards & Gratings

West Side

Curb Southwest Corner Of Fontana Street @ 33.941949200142, -118.156491816044

Sidewalks , Hazards & Gratings : Curb is on Path of Travel

Finding

There is a curb on the designated path of travel.

On-Site Finding Not Compliant

Recommendation

Provide a compliant curb ramp.

Recommendation See Recommendation

Costing Info (Estimated)

Install curb ramp \$2,500



Code Reference ADA 402, 303, 406, 403.4, 303.4

Progress

Record Number	408649	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments	New Value	0
Assignment	None		
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street

Sidewalks - Exterior : Sidewalks

West Side

Fontana Street West Crossing @ 33.942008167141, -118.156448900700

Sidewalks : Vehicular Traffic Cross Slope

Finding

Cross slope at vehicular traffic is not compliant.

On-Site Finding 5.00 percent

Recommendation

Repave the surface to provide a compliant cross slope.

Recommendation Up to 2.08 percent

Costing Info (Estimated)

Repave surface \$1,092



Code Reference ADA 206, 302,CA 11B-403.3

Progress

Record Number	408651	Resolution	None
Progress	Not_Started	Priority	Five
Actual Date		Projected Date	06/30/2025
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			

Salford Avenue - Stewart & Gray Road To De Palma Street



Salford Avenue - Stewart & Gray Road To De Palma Street

**Stewart & Gray Road To De Palma Street
Downey, CA 90242**

Date of Inspection
4/20/2017

***Estimated Facility Total: \$13,782**

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

