

## Accessibility Survey

---



## City of Downey Brunache Street - Rives Avenue To Julius Avenue

Rives Avenue To Julius Avenue  
Downey, CA 90242

Date of Inspection  
4/17/2017

Prepared By  
**Disability Access Consultants**  
(800) 743-7067

## Brunache Street - Rives Avenue To Julius Avenue

### Sidewalks - Exterior : Sidewalks

---

#### North Side

#### Sidewalk East Of Horley Avenue @ 33.935586087183, -118.150270432234

Sidewalks : Missing Sidewalk

#### Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 83.00 feet

#### Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

### Progress

---

<b>Record Number</b>	407234	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

## Brunache Street - Rives Avenue To Julius Avenue

### Sidewalks - Exterior : Sidewalks

---

#### North Side

#### Sidewalk East Of Horton Avenue @ 33.936494019779, -118.152067512274

Sidewalks : Missing Sidewalk

#### Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 273.00 feet

#### Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

### Progress

---

<b>Record Number</b>	407236	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

**Brunache Street - Rives Avenue To Julius Avenue**

**Sidewalks - Exterior : Sidewalks**

---

**North Side**

**Sidewalk East Of Julius Avenue @ 33.936901251107, -118.152873516083**

Sidewalks : Missing Sidewalk

**Finding**

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 240.00 feet

**Recommendation**

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

**Costing Info (Estimated)**

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

**Progress**

---

<b>Record Number</b>	407235	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

## Brunache Street - Rives Avenue To Julius Avenue

### Sidewalks - Exterior : Sidewalks

---

#### North Side

#### Sidewalk East Of Richeon Avenue @ 33.936042280016, -118.151148855686

Sidewalks : Missing Sidewalk

#### Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 266.00 feet

#### Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

### Progress

---

<b>Record Number</b>	407237	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

## Brunache Street - Rives Avenue To Julius Avenue

### Sidewalks - Exterior : Sidewalks

---

#### South Side

#### Sidewalk West Of Rives Avenue @ 33.935383581289, -118.150210082531

Sidewalks : Missing Sidewalk

#### Finding

Section of sidewalk is missing and consists of dirt, grass or gravel.

**On-Site Finding** 988.00 feet

#### Recommendation

Provide a compliant sidewalk for the missing section.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$1,260



**Code Reference** ADA 206, 302,CA 11B-302,CA 11B-206

### Progress

---

<b>Record Number</b>	407233	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

## Brunache Street - Rives Avenue To Julius Avenue

### Sidewalks - Exterior : Sidewalks

#### South Side @ 33.935079821544, -118.149688392878

Sidewalks : 60X60 Turn Area

#### Finding

There is no 60X60 turn area at every 200 feet.

**On-Site Finding** Not Found

#### Recommendation

Provide a 60X60 turn every 200 feet on the sidewalk.

Recommendation See Recommendation

#### Costing Info (Estimated)

\$2,400



**Code Reference** ADA 206, 302

### Progress

<b>Record Number</b>	407232	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Six
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2027
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Brunache Street - Rives Avenue To Julius Avenue**



**Brunache Street - Rives Avenue To Julius Avenue**

**Rives Avenue To Julius Avenue  
Downey, CA 90242**

Date of Inspection  
4/17/2017

**\*Estimated Facility Total: \$8,700**

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

**Disability Access Consultants**

(800) 743-7067

Prepared Using

