
Accessibility Survey



City of Downey Yankey Street - Pomering Road To Cul-de-sac

Pomering Road To Cul-de-sac Downey, CA 90242

Date of Inspection 4/17/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Yankey Street - Pomering Road To Cul-de-sac

Sidewalks - Exterior : Sidewalks

North Side @ 33.936133518290, -118.155310302973

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	407202	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	

Comments No Comments

Assignment None **New Value** 0

Sidewalks - Exterior : Sidewalks

South Side @ 33.936027815403, -118.155260682106

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	407201	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	
Comments	No Comments		
Assignment	None	New Value	0
Designated Staff			



Yankey Street - Pomering Road To Cul-de-sac

Pomering Road To Cul-de-sac Downey, CA 90242

Date of Inspection 4/17/2017

*Estimated Facility Total: \$0

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Yankey Street - Sarabeth Street To Cul-de-sac

Sarabeth Street To Cul-de-sac Downey, CA 90242

Date of Inspection 4/17/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Sidewalks - Exterior : Sidewalks

North Side @ 33.934892891932, -118.152007162571

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	407228	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
	± 0. 00		

Actual Cost \$0.00 Contractor

Comments No Comments

Assignment None New Value 0

Sidewalks - Exterior : Sidewalks

South Side @ 33.934628074279, -118.152021914721

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number 407227 Resolution None **Progress** Not_Started **Priority** Seven **Actual Date Projected Date** 06/30/2037 Contractor **Actual Cost** \$0.00 Comments No Comments **Assignment** None **New Value** 0 **Designated Staff**



Yankey Street - Sarabeth Street To Cul-de-sac

Sarabeth Street To Cul-de-sac Downey, CA 90242

Date of Inspection 4/17/2017

*Estimated Facility Total: \$0

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By


Disability Access Consultants

(800) 743-7067

Prepared Using



Accessibility Survey



City of Downey Yankey Street - Sarabeth Street To Rives Avenue

Sarabeth Street To Rives Avenue Downey, CA 90242

Date of Inspection 4/17/2017

Prepared By

Disability Access Consultants

(800) 743-7067

Curb Ramps - Exterior : Curb Ramp

Southwest Corner Of Rives Avenue @ 33.933661149048, - 118.150762617588

Curb Ramp : Side Flare Slope

Finding

The slope of the curb ramp side flare is greater than allowed.

On-Site Finding 12.20 percent

Recommendation

Provide curb ramp side flares with a compliant slope.

Recommendation Up to 10.00 percent

Costing Info (Estimated)

Install flared sides \$1,300



Code Reference ADA 406, 406.3,CA 11B-406.2.2

Progress

Record Number407230ResolutionNoneProgressNot_StartedPrioritySevenActual DateProjected Date06/30/2032Actual Cost\$0.00Contractor

Comments No Comments

Assignment None **New Value** 0

Yankey Street - Sarabeth Street To Rives Avenue

Sidewalks - Exterior : Sidewalks

North Side @ 33.933811362548, -118.150706291199

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Designated Staff

Record Number 407231 Resolution None **Progress** Not_Started **Priority** Seven **Actual Date Projected Date** 06/30/2037 Contractor **Actual Cost** \$0.00 Comments No Comments Assignment None **New Value** 0

Yankey Street - Sarabeth Street To Rives Avenue

Sidewalks - Exterior : Sidewalks

South Side @ 33.933691191769, -118.150785416365

Sidewalks : No Sidewalk

Finding

No sidewalk exists at the location.

On-Site Finding Not Found

Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

Costing Info (Estimated)

Unassigned



Code Reference ADA 206

Progress

Record Number	407229	Resolution	None
Progress	Not_Started	Priority	Seven
Actual Date		Projected Date	06/30/2037
Actual Cost	\$0.00	Contractor	

Comments No Comments

Assignment None **New Value** 0



Yankey Street - Sarabeth Street To Rives Avenue

Sarabeth Street To Rives Avenue Downey, CA 90242

Date of Inspection 4/17/2017

*Estimated Facility Total: \$1,300

*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

Disability Access Consultants

(800) 743-7067

Prepared Using

