

## Right of Way Curb Ramp Schedule

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470146	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.949284158814, - 118.122176975012		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/18
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470147	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.949284158814, - 118.122176975012	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/18
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470148	Curb Ramps	Northwest Corner of Birchdale Avenue @ 33.948100461859, - 118.119874298573		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/18
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470149	Curb Ramps	Northwest Corner of Birchdale Avenue @ 33.948100461859, - 118.119874298573		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/18
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470150	Curb Ramps	Northwest Corner of Birchdale Avenue @ 33.948100461859, - 118.119874298573	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/18
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470160	Curb Ramps	Southwest Corner of Birchdale Avenue @ 33.947986986286, - 118.119970858097	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
11th Street - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	470161	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.949148434999, - 118.122264146805	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477629	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477630	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477631	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477634	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477635	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477632	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477633	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.939173254629, - 118.129105120897	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477636	Curb Ramps	South Side West of Brookshire Avenue - 2nd @ 33.939404679597, - 118.129518181086		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477637	Curb Ramps	South Side West of Brookshire Avenue - 2nd @ 33.939404679597, - 118.129518181086		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477638	Curb Ramps	South Side West of Brookshire Avenue - 2nd @ 33.939404679597, - 118.129518181086		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477639	Curb Ramps	South Side West of Brookshire Avenue - 2nd @ 33.939404679597, - 118.129518181086		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477640	Curb Ramps	South Side West of Brookshire Avenue - 2nd @ 33.939404679597, - 118.129518181086	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477641	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477642	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477643	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477646	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477644	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477645	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.939253363343, - 118.129031360149	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477654	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477655	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477656	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477657	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477660	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477658	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477659	Curb Ramps	North Side East of End @ 33.939483675475, - 118.129455149174	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477661	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477662	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477663	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477664	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477665	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477666	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Brookshire Avenue to End - Brookshire Avenue to End Downey, CA 90242	477667	Curb Ramps	South Side West of Brookshire Avenue - 1st @ 33.939404679597, - 118.129518181086	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard Downey, CA 90242	474040	Curb Ramps	South Side West of Downey Avenue - 2nd @ 33.941101405942, - 118.132764995098		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard Downey, CA 90242	474041	Curb Ramps	South Side West of Downey Avenue - 2nd @ 33.941101405942, - 118.132764995098		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard Downey, CA 90242	473826	Curb Ramps	South Side West of Downey Avenue - 2nd @ 33.941101405942, - 118.132764995098	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard Downey, CA 90242	473827	Curb Ramps	South Side West of Downey Avenue - 6th @ 33.941264957449, - 118.133139163256	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard Downey, CA 90242	473828	Curb Ramps	South Side West of Downey Avenue - 5th @ 33.941264957449, - 118.133139163256		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473829	Curb Ramps	South Side West of Downey Avenue - 5th @ 33.941264957449, - 118.133139163256	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473880	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473881	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473882	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473883	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473884	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473885	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.943594697857, - 118.137134313583	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473921	Curb Ramps	South Side West of Downey Avenue - 7th @ 33.941483025636, - 118.133465051651		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473922	Curb Ramps	South Side West of Downey Avenue - 7th @ 33.941483025636, - 118.133465051651	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474046	Curb Ramps	South Side West of Downey Avenue - 4th @ 33.941264957449, - 118.133139163256		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474047	Curb Ramps	South Side West of Downey Avenue - 4th @ 33.941264957449, - 118.133139163256		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473925	Curb Ramps	South Side West of Downey Avenue - 4th @ 33.941264957449, - 118.133139163256	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473926	Curb Ramps	South Side West of Downey Avenue - 4th @ 33.941264957449, - 118.133139163256	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473927	Curb Ramps	South Side West of Downey Avenue - 4th @ 33.941264957449, - 118.133139163256	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474048	Curb Ramps	South Side West of Downey Avenue - 3rd @ 33.941205989935, - 118.132999688387		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474049	Curb Ramps	South Side West of Downey Avenue - 3rd @ 33.941205989935, - 118.132999688387		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474050	Curb Ramps	South Side West of Downey Avenue - 3rd @ 33.941205989935, - 118.132999688387		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473931	Curb Ramps	South Side West of Downey Avenue - 3rd @ 33.941205989935, - 118.132999688387	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474051	Curb Ramps	South Side West of Downey Avenue - 1st @ 33.941060239867, - 118.132660388947		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	474052	Curb Ramps	South Side West of Downey Avenue - 1st @ 33.941060239867, - 118.132660388947		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473934	Curb Ramps	South Side West of Downey Avenue - 1st @ 33.941060239867, - 118.132660388947	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473935	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473936	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473937	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473938	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473939	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473941	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473942	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
2nd Street - Downey Avenue to Paramount Boulevard - Downey Avenue to Paramount Boulevard	473940	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.943460077535, - 118.137216120958	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue	483366	Curb Ramps	South Side West of End @ 33.940323697540, - 118.131316602230		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue	483367	Curb Ramps	South Side West of End @ 33.940323697540, - 118.131316602230		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483368	Curb Ramps	South Side West of End @ 33.940323697540, - 118.131316602230		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483370	Curb Ramps	North Side East of Downey Avenue @ 33.940419381646, - 118.131265640259		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483371	Curb Ramps	North Side East of Downey Avenue @ 33.940419381646, - 118.131265640259		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483372	Curb Ramps	North Side East of Downey Avenue @ 33.940419381646, - 118.131265640259		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483356	Curb Ramps	North Side East of Downey Avenue @ 33.940419381646, - 118.131265640259	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
2nd Street - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483357	Curb Ramps	North Side East of Downey Avenue @ 33.940419381646, - 118.131265640259	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	463195	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	463196	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463197	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463198	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463011	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463012	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463010	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.943609161185, - 118.137517869473	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463199	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, - 118.137405216694		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463200	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, - 118.137405216694		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463201	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463202	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463203	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463050	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463051	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463052	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	463053	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.943738218462, -118.137405216694	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463204	Curb Ramps	North Side East of Smallwood Avenue @ 33.943910665381, - 118.137761950493		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463205	Curb Ramps	North Side East of Smallwood Avenue @ 33.943910665381, - 118.137761950493		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463206	Curb Ramps	North Side East of Smallwood Avenue @ 33.943910665381, - 118.137761950493		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463058	Curb Ramps	North Side East of Smallwood Avenue @ 33.943910665381, - 118.137761950493	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
2nd Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 463057	Curb Ramps	North Side East of Smallwood Avenue @ 33.943910665381, - 118.137761950493	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
2nd Street - Rives Avenue to Pomeroy Road - Rives Avenue to Pomeroy Road	Downey, CA 90242 465732	Curb Ramps	Northwest Corner of Rives Avenue @ 33.945836484329, - 118.141533136368		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	
2nd Street - Rives Avenue to Pomeroy Road - Rives Avenue to Pomeroy Road	Downey, CA 90242 464597	Curb Ramps	Northwest Corner of Rives Avenue @ 33.945836484329, - 118.141533136368	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
2nd Street - Rives Avenue to Pomeroy Road - Rives Avenue to Pomeroy Road	Downey, CA 90242 464598	Curb Ramps	Northwest Corner of Rives Avenue @ 33.945836484329, - 118.141533136368	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Downey Avenue to End - Downey Avenue to End	473943	Curb Ramps	Southeast Corner of Civic Center Drive @ 33.940616312551, - 118.129885643721		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473944	Curb Ramps	Southeast Corner of Civic Center Drive @ 33.940616312551, - 118.129885643721		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473945	Curb Ramps	Southeast Corner of Civic Center Drive @ 33.940616312551, - 118.129885643721	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473946	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473947	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473948	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473951	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473952	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473949	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473950	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.940847733596, - 118.129676431417	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Downey Avenue to End - Downey Avenue to End	473953	Curb Ramps	Southwest Corner of Civic Center Drive - West Crossing @ 33.940802116997, - 118.130038529634		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473954	Curb Ramps	Southwest Corner of Civic Center Drive - West Crossing @ 33.940802116997, - 118.130038529634		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473955	Curb Ramps	Southwest Corner of Civic Center Drive - West Crossing @ 33.940802116997, - 118.130038529634		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473956	Curb Ramps	Southwest Corner of Civic Center Drive - West Crossing @ 33.940802116997, - 118.130038529634	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473972	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473973	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473974	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473977	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473978	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473975	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Downey Avenue to End - Downey Avenue to End	473976	Curb Ramps	North Side East of Civic Center Drive - 2nd @ 33.940676393075, - 118.129366636276	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473979	Curb Ramps	Southwest Corner of Civic Center Drive - South Crossing @ 33.940732023152, - 118.130015730858		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473980	Curb Ramps	Southwest Corner of Civic Center Drive - South Crossing @ 33.940732023152, - 118.130015730858		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473981	Curb Ramps	Southwest Corner of Civic Center Drive - South Crossing @ 33.940732023152, - 118.130015730858		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473982	Curb Ramps	Southwest Corner of Civic Center Drive - South Crossing @ 33.940732023152, - 118.130015730858	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473983	Curb Ramps	Southwest Corner of Civic Center Drive - South Crossing @ 33.940732023152, - 118.130015730858	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473991	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473992	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473993	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473994	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Downey Avenue to End - Downey Avenue to End	473995	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473996	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473997	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473998	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	473999	Curb Ramps	North Side East of Civic Center Drive - 1st @ 33.940717559335, - 118.129457831383	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	474000	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.940914489550, - 118.129941970110		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	474001	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.940914489550, - 118.129941970110		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	474002	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.940914489550, - 118.129941970110		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	474004	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.940914489550, - 118.129941970110	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Downey Avenue to End - Downey Avenue to End	474003	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.940914489550, - 118.129941970110	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463213	Curb Ramps	Southeast Corner of Old River School Road @ 33.949680204120, -118.147121518850		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463214	Curb Ramps	Northeast Corner of Old River School Road @ 33.949814814604, -118.147022277117		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463215	Curb Ramps	Northeast Corner of Old River School Road @ 33.949814814604, -118.147022277117		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463106	Curb Ramps	Northeast Corner of Old River School Road @ 33.949814814604, -118.147022277117	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453597	Curb Ramps	Northeast Corner of Rives Avenue @ 33.946461726403, -118.140780776739		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453598	Curb Ramps	Northeast Corner of Rives Avenue @ 33.946461726403, -118.140780776739		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453599	Curb Ramps	Northeast Corner of Rives Avenue @ 33.946461726403, -118.140780776739		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453600	Curb Ramps	Northeast Corner of Rives Avenue @ 33.946461726403, - 118.140780776739	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453601	Curb Ramps	Northeast Corner of Rives Avenue @ 33.946461726403, - 118.140780776739	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	454116	Curb Ramps	Southeast Corner of Rives Avenue @ 33.946332673254, - 118.140882700682		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	454117	Curb Ramps	Southeast Corner of Rives Avenue @ 33.946332673254, - 118.140882700682		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	454118	Curb Ramps	Southeast Corner of Rives Avenue @ 33.946332673254, - 118.140882700682		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453606	Curb Ramps	Southeast Corner of Rives Avenue @ 33.946332673254, - 118.140882700682	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
3rd Street - Rives Avenue to Smallwood Avenue - Rives Avenue to Smallwood Avenue Downey, CA 90242	453605	Curb Ramps	Southeast Corner of Rives Avenue @ 33.946332673254, - 118.140882700682	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
4th Place - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463208	Curb Ramps	Northeast Corner of Old River School Road @ 33.950543487500, - 118.146485835314		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Place - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463209	Curb Ramps	Northeast Corner of Old River School Road @ 33.950543487500, - 118.146485835314		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/19
4th Place - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	463210	Curb Ramps	Southeast Corner of Old River School Road @ 33.950396640945, - 118.146595805883		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	349781	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, - 118.136352449656		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	349782	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, - 118.136352449656		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	349783	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, - 118.136352449656		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	349784	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, - 118.136352449656		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349785	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, -118.136352449656		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349786	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, -118.136352449656	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349787	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, -118.136352449656	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349788	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945230150885, -118.136352449656	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349822	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 349823	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	349824	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832	Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	349825	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	349826	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832	Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	349828	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832	Top Landing	Top Landing Clear Length - Landings Provide a level top landing with enough clear length.	6/30/19	
4th Place - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	349827	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945374781273, -118.136226385832	Bottom Landing	Bottom Landing Change in Level Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	Downey, CA 90242	473267	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473268	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473269	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473270	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473271	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473272	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473273	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, -118.135692626238	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/19	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473274	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.945563912948, - 118.135692626238	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473814	Curb Ramps	Northwest Corner of La Reina Avenue @ 33.943719304908, - 118.132936656475		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473815	Curb Ramps	Northwest Corner of La Reina Avenue @ 33.943719304908, - 118.132936656475		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473816	Curb Ramps	Northwest Corner of La Reina Avenue @ 33.943719304908, - 118.132936656475		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473308	Curb Ramps	Northwest Corner of La Reina Avenue @ 33.943719304908, - 118.132936656475	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue - Downey, CA 90242	473817	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.943585797347, - 118.133019804955		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473818	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.943585797347, - 118.133019804955		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473819	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.943585797347, - 118.133019804955		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473312	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.943585797347, - 118.133019804955	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473821	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473822	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	473823	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	473358	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	473359	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
4th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	473360	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.945757494345, - 118.135565221310	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348781	Curb Ramps	Northeast Corner Of Rives Avenue - 1st		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348782	Curb Ramps	Northeast Corner Of Rives Avenue - 1st @ 33.947963623649, - 118.139762878418	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348783	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd @ 33.947963623649, - 118.139762878418		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348784	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd @ 33.947963623649, - 118.139762878418		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348785	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd @ 33.947963623649, - 118.139762878418		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348786	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348787	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd @ 33.947963623649, - 118.139762878418	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	348788	Curb Ramps	Northeast Corner Of Rives Avenue - 2nd @ 33.947963623649, - 118.139762878418	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90241	350419	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350420	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350421	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Curb Ramp Width		Provide a compliant curb ramp.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350422	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Curb Ramp Slope		Provide a compliant curb ramp.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350423	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350425	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350426	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350424	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.945809783497, - 118.135905861855	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350427	Curb Ramps	Southeast Corner Of Rives Avenue - 1st @ 33.947813435117, - 118.139867484570		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350428	Curb Ramps	Southeast Corner Of Rives Avenue - 1st @ 33.947813435117, - 118.139867484570		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350429	Curb Ramps	Southeast Corner Of Rives Avenue - 1st @ 33.947813435117, - 118.139867484570	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350430	Curb Ramps	Southeast Corner Of Rives Avenue - 1st @ 33.947813435117, - 118.139867484570	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350431	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350432	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350433	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748	Curb Ramp Width		Provide a compliant curb ramp.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350434	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350435	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350436	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.945933274772, - 118.135814666748	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350456	Curb Ramps	Southeast Corner Of Rives Avenue - 2nd @ 33.947813435117, - 118.139867484570		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350457	Curb Ramps	Southeast Corner Of Rives Avenue - 2nd @ 33.947813435117, - 118.139867484570	Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350458	Curb Ramps	Southeast Corner Of Rives Avenue - 2nd @ 33.947813435117, - 118.139867484570	Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.	6/30/19	
4th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	350459	Curb Ramps	Southeast Corner Of Rives Avenue - 2nd @ 33.947813435117, - 118.139867484570	Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/19	
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue	Downey, CA 90242	407624	Curb Ramps	Southwest Corner @ 33.942155028169, - 118.126794397831	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue	Downey, CA 90242	407625	Curb Ramps	Northwest Corner @ 33.942300776362, - 118.126697838306	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue	Downey, CA 90242	407626	Curb Ramps	Northwest Corner @ 33.942300776362, - 118.126697838306	Grade Break	Provide a compliant curb ramp.	6/30/19	
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue	Downey, CA 90242	407628	Curb Ramps	Northwest Corner @ 33.942300776362, - 118.126697838306	Top Landing	Top Landing Clear Length - Landings Provide a level top landing with enough clear length.	6/30/19	
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue	Downey, CA 90242	407627	Curb Ramps	Northwest Corner @ 33.942300776362, - 118.126697838306	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407629	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407630	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407631	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407632	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407633	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407634	Curb Ramps	Southeast Corner @ 33.942044882422, -118.126582503319	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407635	Curb Ramps	Northeast Corner @ 33.942195081132, -118.126471191645		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407636	Curb Ramps	Northeast Corner @ 33.942195081132, -118.126471191645		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407637	Curb Ramps	Northeast Corner @ 33.942195081132, -118.126471191645		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407639	Curb Ramps	Northeast Corner @ 33.942195081132, -118.126471191645	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407640	Curb Ramps	Northeast Corner @ 33.942195081132, - 118.126471191645	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
5th Street & Brookshire Avenue - 5th Street & Brookshire Avenue Downey, CA 90242	407638	Curb Ramps	Northeast Corner @ 33.942195081132, - 118.126471191645	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
5th Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	471933	Curb Ramps	Northwest Corner of Parrot Avenue @ 33.945906573971, - 118.134342133999	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	461753	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.946826634245, - 118.135534375906		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	461754	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.946826634245, - 118.135534375906		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	461690	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.946826634245, - 118.135534375906	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	461757	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.946861122405, - 118.135598748922		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue			North Side East of Smallwood Avenue - 1st @ 33.946861122405, - 118.135598748922					
Downey, CA 90242	461735	Curb Ramps		Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
5th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue			North Side East of Smallwood Avenue - 1st @ 33.946861122405, - 118.135598748922					
Downey, CA 90242	461736	Curb Ramps		Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Dolan Avenue @ 33.943870613225, - 118.127902150154					
Downey, CA 90242	471775	Curb Ramps			No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Dolan Avenue @ 33.943870613225, - 118.127902150154					
Downey, CA 90242	471639	Curb Ramps		Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Dolan Avenue @ 33.943870613225, - 118.127902150154					
Downey, CA 90242	471638	Curb Ramps		Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325					
Downey, CA 90242	471641	Curb Ramps			No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325					
Downey, CA 90242	471642	Curb Ramps			Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue			Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325					
Downey, CA 90242	471643	Curb Ramps			Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471644	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471645	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471646	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.942982785586, - 118.126197606325	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471667	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.943812760077, - 118.127794861794		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471668	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.943812760077, - 118.127794861794		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471669	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.943812760077, - 118.127794861794		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471670	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.943812760077, - 118.127794861794	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471671	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.943812760077, - 118.127794861794	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471672	Curb Ramps	South Side West of Dolan Avenue - 2nd @ 33.944815171561, - 118.129795789719		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471673	Curb Ramps	South Side West of Dolan Avenue - 2nd @ 33.944815171561, - 118.129795789719		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471674	Curb Ramps	South Side West of Dolan Avenue - 2nd @ 33.944815171561, - 118.129795789719		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471675	Curb Ramps	South Side West of Dolan Avenue - 2nd @ 33.944815171561, - 118.129795789719	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471676	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471677	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471678	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471679	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471680	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471681	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.943116294093, - 118.126109093428	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471682	Curb Ramps	South Side West of Dolan Avenue - 1st @ 33.944780682572, - 118.129723370075		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471683	Curb Ramps	South Side West of Dolan Avenue - 1st @ 33.944780682572, - 118.129723370075		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	471684	Curb Ramps	South Side West of Dolan Avenue - 1st @ 33.944780682572, - 118.129723370075	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard Downey, CA 90242	471701	Curb Ramps	Northwest Corner of Lakewood Boulevard @ 33.940581821860, - 118.121085315943	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard Downey, CA 90242	471714	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.940428282488, - 118.121187239885	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471715	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.940428282488, - 118.121187239885	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471732	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471733	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471734	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471735	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	Downey, CA 90242 471736	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471737	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.942878203776, - 118.125960230827	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471738	Curb Ramps	Northeast Corner of Tristan Drive @ 33.941469674539, - 118.122899830341		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471739	Curb Ramps	Northeast Corner of Tristan Drive @ 33.941469674539, - 118.122899830341		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471740	Curb Ramps	Northeast Corner of Tristan Drive @ 33.941469674539, - 118.122899830341		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471741	Curb Ramps	Northeast Corner of Tristan Drive @ 33.941469674539, - 118.122899830341	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471742	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.942998361589, - 118.125875741243		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471743	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.942998361589, -118.125875741243		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471744	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.942998361589, -118.125875741243		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
6th Street - Brookshire Avenue to Lakewood Boulevard - Brookshire Avenue to Lakewood Boulevard	471745	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.942998361589, -118.125875741243	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	348737	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	348738	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	348739	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348740	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348741	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348743	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348744	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348742	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.947444081452, -118.134709596634	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241 348764	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, -118.134600967169		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348765	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348766	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169	Curb Ramp Width		Provide a compliant curb ramp.	6/30/19
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348767	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169	Curb Ramp Slope		Provide a compliant curb ramp.	6/30/19
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348768	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/19
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348770	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19
6th Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	Downey, CA 90241	348769	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.947570907891, - 118.134600967169	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Western Avenue to New Street - Western Avenue to New Street	471517	Curb Ramps	Southwest Corner of New Street @ 33.945200112235, - 118.130376487970		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471518	Curb Ramps	Southwest Corner of New Street @ 33.945200112235, - 118.130376487970		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471519	Curb Ramps	Southwest Corner of New Street @ 33.945200112235, - 118.130376487970		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471520	Curb Ramps	Southwest Corner of New Street @ 33.945200112235, - 118.130376487970		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471521	Curb Ramps	Southwest Corner of New Street @ 33.945200112235, - 118.130376487970	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471522	Curb Ramps	North Side East of Western Avenue @ 33.946053428273, - 118.131767213345		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471524	Curb Ramps	North Side East of Western Avenue @ 33.946053428273, - 118.131767213345	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471523	Curb Ramps	North Side East of Western Avenue @ 33.946053428273, - 118.131767213345	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
6th Street - Western Avenue to New Street - Western Avenue to New Street	471525	Curb Ramps	Northwest Corner of New Street @ 33.945295790860, - 118.130301386118		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471526	Curb Ramps	Northwest Corner of New Street @ 33.945295790860, - 118.130301386118		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471527	Curb Ramps	Northwest Corner of New Street @ 33.945295790860, - 118.130301386118		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
6th Street - Western Avenue to New Street - Western Avenue to New Street	471528	Curb Ramps	Northwest Corner of New Street @ 33.945295790860, - 118.130301386118	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
7th Street - Birchdale Avenue to Lakewood Boulevard - Birchdale Avenue to Lakewood Boulevard	475363	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.941726682797, - 118.120412081480		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
7th Street - Birchdale Avenue to Lakewood Boulevard - Birchdale Avenue to Lakewood Boulevard	475365	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.941726682797, - 118.120412081480	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
7th Street - Birchdale Avenue to Lakewood Boulevard - Birchdale Avenue to Lakewood Boulevard	475364	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.941726682797, - 118.120412081480	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347211	Curb Ramps	Southwest Corner Of Stamps Road @ 33.945897673702, - 118.128792643547	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347260	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.946287059595, - 118.129625469446	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347261	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.944470281039, - 118.125480115414		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347262	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.944470281039, - 118.125480115414		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347263	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.944470281039, - 118.125480115414		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347264	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.944470281039, - 118.125480115414	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347265	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.944470281039, - 118.125480115414	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347266	Curb Ramps	Southeast Corner Of Nedra Avenue @ 33.945473797320, - 118.127924948931	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347267	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347268	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347269	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347272	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347270	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347271	Curb Ramps	Northwest Corner Of Stamps Road @ 33.945885435831, - 118.128461390734	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347273	Curb Ramps	Southeast Corner Of Stamps Road @ 33.945840934466, - 118.128682672977	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347319	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.946443925980, - 118.129536956549		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/19
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347320	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.946443925980, - 118.129536956549	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	Downey, CA 90241	347321	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.944314523571, - 118.125512301922		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347322	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.944314523571, - 118.125512301922		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347323	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.944314523571, - 118.125512301922		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347324	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.944314523571, - 118.125512301922	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347325	Curb Ramps	Southwest Corner Of Nedra Avenue @ 33.945516073799, - 118.128022849560		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347326	Curb Ramps	Southwest Corner Of Nedra Avenue @ 33.945516073799, - 118.128022849560	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
7th Street - Brookshire Avenue To Paramount Boulevard - Brookshire Avenue To Paramount Boulevard	347327	Curb Ramps	Southwest Corner Of Nedra Avenue @ 33.945516073799, - 118.128022849560	Top Landing	Top Landing Right Side Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461741	Curb Ramps	South Side West of Paramount Boulevard @ 33.948426425163, - 118.134344816208		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461742	Curb Ramps	South Side West of Paramount Boulevard @ 33.948426425163, - 118.134344816208	Curb Ramp - Cross Slope		Provide a compliant curb ramp.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461616	Curb Ramps	South Side West of Paramount Boulevard @ 33.948426425163, - 118.134344816208	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461615	Curb Ramps	South Side West of Paramount Boulevard @ 33.948426425163, - 118.134344816208	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461743	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.948581062608, - 118.134331405163		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461618	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.948581062608, - 118.134331405163	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242	461744	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.948565487626, - 118.134244233370		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461745	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.948565487626, - 118.134244233370		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461621	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.948565487626, - 118.134244233370	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461747	Curb Ramps	Northeast Corner of Rives Avenue @ 33.950374391445, - 118.138014078140		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461748	Curb Ramps	Northeast Corner of Rives Avenue @ 33.950374391445, - 118.138014078140		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461642	Curb Ramps	Northeast Corner of Rives Avenue @ 33.950374391445, - 118.138014078140	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461643	Curb Ramps	Northeast Corner of Rives Avenue @ 33.950374391445, - 118.138014078140	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 461750	Curb Ramps	Southeast Corner of Rives Avenue @ 33.950248681660, - 118.138118684292		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	461751	Curb Ramps	Southeast Corner of Rives Avenue @ 33.950248681660, - 118.138118684292		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
7th Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	461667	Curb Ramps	Southeast Corner of Rives Avenue @ 33.950248681660, - 118.138118684292	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477535	Curb Ramps	Northeast Corner of Elm Vista Drive @ 33.926259189702, - 118.124139010906		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477536	Curb Ramps	Northeast Corner of Elm Vista Drive @ 33.926259189702, - 118.124139010906		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477425	Curb Ramps	Northeast Corner of Elm Vista Drive @ 33.926259189702, - 118.124139010906	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477538	Curb Ramps	Northwest Corner of Elm Vista Drive @ 33.926263640863, - 118.124321401119		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477539	Curb Ramps	Northwest Corner of Elm Vista Drive @ 33.926263640863, - 118.124321401119		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adenmoor Avenue - Elm Vista Drive to Cul-De-Sac - Elm Vista Drive to Cul-De-Sac	477433	Curb Ramps	Northwest Corner of Elm Vista Drive @ 33.926263640863, - 118.124321401119	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	317497	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.927951726913, -118.124173879623		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	317498	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.927951726913, -118.124173879623		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	317499	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.927951726913, -118.124173879623	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	330546	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.927938373693, -118.123932480812		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	330547	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.927938373693, -118.123932480812		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	330548	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.927938373693, -118.123932480812		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	330549	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.927938373693, -118.123932480812		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adenmoor Avenue - Hall Road To Stewart and Gray Road - Hall Road To Stewart and Gray Road Downey, CA 90241	317505	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.927938373693, -118.123932480812	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	326338	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	326339	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	326340	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	318991	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	318992	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street Downey, CA 90424	318993	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, -118.123551607132	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adenmoor Avenue - Priscilla Street to Angell Street - Adenmoor Avenue - Priscilla Street to Angell Street	Downey, CA 90424	318994	Curb Ramps	Southeast Corner Of Angell Street @ 33.912631982842, - 118.123551607132	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317513	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317514	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714	Curb Ramp Slope		Provide a compliant curb ramp.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317515	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317518	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317516	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	Downey, CA 90424	317517	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914058796233, - 118.123546242714	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	326320	Curb Ramps	Southwest Corner Of Imperial Highway @ 33.916892318923, - 118.123763501644		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	326321	Curb Ramps	Southwest Corner Of Imperial Highway @ 33.916892318923, - 118.123763501644		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	326322	Curb Ramps	Southwest Corner Of Imperial Highway @ 33.916892318923, - 118.123763501644		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	317523	Curb Ramps	Southwest Corner Of Imperial Highway @ 33.916892318923, - 118.123763501644	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	317522	Curb Ramps	Southwest Corner Of Imperial Highway @ 33.916892318923, - 118.123763501644	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	317547	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street Downey, CA 90424	317548	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317549	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317550	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317551	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317552	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317553	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.123731315136	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317555	Curb Ramps	Southeast Corner Of Imperial Highway @ 33.916939061241, - 118.123522102833	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adenmoor Avenue - Imperial Highway to Adoree Street - Adenmoor Avenue - Imperial Highway to Adoree Street	317556	Curb Ramps	Southeast Corner Of Imperial Highway @ 33.916939061241, - 118.123522102833	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402158	Curb Ramps	Northeast Corner @ 33.913828415344, -118.133985400200	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402159	Curb Ramps	Northeast Corner @ 33.913828415344, -118.133985400200	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402160	Curb Ramps	Northwest Corner @ 33.913818398770, -118.134273737669	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402189	Curb Ramps	Southeast Corner @ 33.913639213183, -118.134152349	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402190	Curb Ramps	Southeast Corner @ 33.913639213183, -118.134152349	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street & Columbia Way - Adoree Street & Columbia Way Downey, CA 90242	402191	Curb Ramps	Southwest Corner @ 33.913665924102, -118.134268373251	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street - Ardis Avenue to End - Adoree Street - Ardis Avenue to End Downey, CA 90424	319631	Curb Ramps	Southeast Corner Of Ardis Avenue @ 33.913816172864, -118.129688501358		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Ardis Avenue to End - Adoree Street - Ardis Avenue to End Downey, CA 90424	319632	Curb Ramps	Southeast Corner Of Ardis Avenue @ 33.913816172864, -118.129688501358		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Ardis Avenue to End - Adoree Street - Ardis Avenue to End Downey, CA 90424	319633	Curb Ramps	Southeast Corner Of Ardis Avenue @ 33.913816172864, -118.129688501358		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adoree Street - Ardis Avenue to End - Adoree Street - Ardis Avenue to End Downey, CA 90424	319634	Curb Ramps	Southeast Corner Of Ardis Avenue @ 33.913816172864, -118.129688501358	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Ardis Avenue to End - Adoree Street - Ardis Avenue to End	Downey, CA 90424	319635	Curb Ramps	Southeast Corner Of Ardis Avenue @ 33.913816172864, - 118.129688501358	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401017	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.915314194186, - 118.142964094877	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401018	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.915314194186, - 118.142964094877	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401019	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.915314194186, - 118.142964094877	Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401020	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.915314194186, - 118.142964094877	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401021	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401022	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	Downey, CA 90242	401023	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	401024	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	401025	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	401027	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	401028	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street - Blodgett Avenue To Barlin Avenue - Blodgett Avenue To Barlin Avenue	401026	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.915432165029, - 118.142866194248	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard	401064	Curb Ramps	Northwest Corner Of Whitewood Avenue @ 33.913819511723, - 118.136057406664		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard	401065	Curb Ramps	Northwest Corner Of Whitewood Avenue @ 33.913819511723, - 118.136057406664		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401066	Curb Ramps	Northwest Corner Of Whitewood Avenue @ 33.913819511723, - 118.136057406664	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401067	Curb Ramps	Northwest Corner Of Whitewood Avenue @ 33.913819511723, - 118.136057406664	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401068	Curb Ramps	Northwest Corner Of Whitewood Avenue @ 33.913819511723, - 118.136057406664	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401069	Curb Ramps	Northeast Corner Of Glenshire Road @ 33.913817285817, - 118.136717230082		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401070	Curb Ramps	Northeast Corner Of Glenshire Road @ 33.913817285817, - 118.136717230082		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401071	Curb Ramps	Northeast Corner Of Glenshire Road @ 33.913817285817, - 118.136717230082		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401072	Curb Ramps	Northeast Corner Of Glenshire Road @ 33.913817285817, - 118.136717230082	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401073	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401074	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401075	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401078	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401079	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401076	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401077	Curb Ramps	Northwest Corner Of Vultee Avenue @ 33.913816172864, - 118.138525038958	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401081	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401082	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401083	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401086	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401087	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401084	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adoree Street - Columbia Way To Lakewood Boulevard - Columbia Way To Lakewood Boulevard Downey, CA 90242	401085	Curb Ramps	Northeast Corner Of Vultee Avenue @ 33.913811721053, - 118.138364106417	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328153	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.921194730563, - 118.153892755508		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328154	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.921194730563, - 118.153892755508		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328155	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.921194730563, - 118.153892755508		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328041	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.921194730563, - 118.153892755508	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328042	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.918746411209, - 118.149011135101		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328044	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.918746411209, - 118.149011135101	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328043	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.918746411209, - 118.149011135101	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328156	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.918884409261, - 118.148909211159	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328157	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328158	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328159	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328160	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328162	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adoree Street - Downey Avenue To Paramount Boulevard - Downey Avenue To Paramount Boulevard Downey, CA 90424	328161	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.921337176069, - 118.153812289238	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313363	Curb Ramps	Southeast Corner Of Angell Street @ 33.912378225697, - 118.129660338163		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313364	Curb Ramps	Southeast Corner Of Angell Street @ 33.912378225697, - 118.129660338163		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313365	Curb Ramps	Southeast Corner Of Angell Street @ 33.912378225697, - 118.129660338163		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313366	Curb Ramps	Southeast Corner Of Angell Street @ 33.912378225697, - 118.129660338163	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313367	Curb Ramps	Southeast Corner Of Angell Street @ 33.912378225697, - 118.129660338163	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313368	Curb Ramps	Northeast Corner Of Foster Road		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313369	Curb Ramps	Northeast Corner Of Foster Road @ 33.909857307755, - 118.129646927118	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313370	Curb Ramps	Northwest Corner Of Foster Road @ 33.909980851167, - 118.129845410585		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313371	Curb Ramps	Northwest Corner Of Foster Road @ 33.909980851167, - 118.129845410585		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313372	Curb Ramps	Northwest Corner Of Foster Road @ 33.909980851167, - 118.129845410585		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313373	Curb Ramps	Northwest Corner Of Foster Road @ 33.909980851167, - 118.129845410585	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	351043	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	351044	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	351045	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313386	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313387	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adris Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313388	Curb Ramps	Southwest Corner Of Angell Street @ 33.912390468383, - 118.129856139421	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480203	Curb Ramps	Northwest Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480204	Curb Ramps	Northwest Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480205	Curb Ramps	Northwest Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480206	Curb Ramps	Northwest Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480207	Curb Ramps	Northwest Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480405	Curb Ramps	Northeast Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480406	Curb Ramps	Northeast Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480407	Curb Ramps	Northeast Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480212	Curb Ramps	Northeast Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480213	Curb Ramps	Northeast Corner of Ratliffe Street @ 33.912542945333, - 118.129848092794	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480214	Curb Ramps	West Side North of Ratliffe Street - 2nd @ 33.915037073356, - 118.129860162735		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480215	Curb Ramps	West Side North of Ratliffe Street - 2nd @ 33.915037073356, - 118.129860162735		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480216	Curb Ramps	West Side North of Ratliffe Street - 2nd @ 33.915037073356, - 118.129860162735		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480217	Curb Ramps	West Side North of Ratliffe Street - 2nd @ 33.915037073356, - 118.129860162735	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480218	Curb Ramps	West Side North of Ratliffe Street - 2nd @ 33.915037073356, - 118.129860162735	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480242	Curb Ramps	West Side North of Ratliffe Street - 1st @ 33.914867906784, - 118.129857480526		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480243	Curb Ramps	West Side North of Ratliffe Street - 1st @ 33.914867906784, - 118.129857480526		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480244	Curb Ramps	West Side North of Ratliffe Street - 1st @ 33.914867906784, - 118.129857480526		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adris Avenue - Ratliffe Street to Imperial Highway - Ratliffe Street to Imperial Highway Downey, CA 90242	480245	Curb Ramps	West Side North of Ratliffe Street - 1st @ 33.914867906784, - 118.129857480526	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404157	Curb Ramps	Northeast Corner @ 33.944080886835, - 118.151118010283		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404158	Curb Ramps	Northeast Corner @ 33.944080886835, - 118.151118010283		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404159	Curb Ramps	Northeast Corner @ 33.944080886835, - 118.151118010283		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404160	Curb Ramps	Northeast Corner @ 33.944080886835, - 118.151118010283	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404161	Curb Ramps	Northeast Corner @ 33.944080886835, - 118.151118010283	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404237	Curb Ramps	Northwest Corner - North @ 33.944183242056, - 118.151332587004		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404238	Curb Ramps	Northwest Corner - North @ 33.944183242056, - 118.151332587004		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404239	Curb Ramps	Northwest Corner - North @ 33.944183242056, - 118.151332587004	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404240	Curb Ramps	Northwest Corner - North @ 33.944183242056, - 118.151332587004	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404241	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404242	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404243	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404246	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404247	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404244	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404245	Curb Ramps	Northwest Corner - South @ 33.944073098933, - 118.151433169842	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404248	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404249	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404250	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404254	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404255	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404251	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404252	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404253	Curb Ramps	Southwest Corner @ 33.943948492400, -118.151527047157	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404256	Curb Ramps	Southeast Corner @ 33.943952942637, -118.151205182076		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404257	Curb Ramps	Southeast Corner @ 33.943952942637, -118.151205182076		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404258	Curb Ramps	Southeast Corner @ 33.943952942637, - 118.151205182076		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404260	Curb Ramps	Southeast Corner @ 33.943952942637, - 118.151205182076	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street & Old River School Road - Adwen Street & Old River School Road Downey, CA 90242	404259	Curb Ramps	Southeast Corner @ 33.943952942637, - 118.151205182076	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	403410	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.942574470769, - 118.148288279772		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	403411	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.942574470769, - 118.148288279772		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	403412	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.942574470769, - 118.148288279772		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	403413	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.942574470769, - 118.148288279772		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	403414	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.942574470769, - 118.148288279772	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403415	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403416	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403417	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403418	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403419	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403420	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.940814355600, - 118.145328462124	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403421	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.942676827801, - 118.148851543665		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403422	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.942676827801, - 118.148851543665		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403423	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.942676827801, - 118.148851543665		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403424	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.942676827801, - 118.148851543665	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403425	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.942676827801, - 118.148851543665	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403467	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403468	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403469	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403470	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403472	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403471	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.942601172615, - 118.148710727692	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403473	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403474	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403475	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403476	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403477	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403478	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.940933403727, - 118.145250678062	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403479	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403480	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403481	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403484	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403485	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403482	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Adwen Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	403483	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.942650125978, - 118.148453235626	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue	385562	Curb Ramps	Southwest Corner @ 33.925382306442, - 118.136636763811		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue	385563	Curb Ramps	Southwest Corner @ 33.925382306442, - 118.136636763811		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385564	Curb Ramps	Southwest Corner @ 33.925382306442, -118.136636763811		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385565	Curb Ramps	Southwest Corner @ 33.925382306442, -118.136636763811	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385566	Curb Ramps	Southwest Corner @ 33.925382306442, -118.136636763811	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385567	Curb Ramps	Southwest Corner @ 33.925382306442, -118.136636763811	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385568	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385569	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385570	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385571	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385572	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385573	Curb Ramps	Northeast Corner @ 33.925457976927, -118.136438280344	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385574	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385575	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385576	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385577	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385579	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385578	Curb Ramps	Northwest Corner @ 33.925524744946, - 118.136552274227	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385580	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385581	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385582	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385583	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385584	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793		Grade Break	Provide a compliant curb ramp.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385587	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385588	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385585	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Alameda Street & Birchdale Avenue - Alameda Street & Birchdale Avenue Downey, CA 90242	385586	Curb Ramps	Southeast Corner @ 33.925301071876, - 118.136482536793	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Brookshire Avenue - Alameda Street & Brookshire Avenue Downey, CA 90242	402243	Curb Ramps	Northwest Corner @ 33.926419431352, - 118.138645738363	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Brookshire Avenue - Alameda Street & Brookshire Avenue Downey, CA 90242	402244	Curb Ramps	Southwest Corner @ 33.926280332715, - 118.138742297888	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street & Brookshire Avenue - Alameda Street & Brookshire Avenue Downey, CA 90242	402245	Curb Ramps	Southeast Corner @ 33.926189083885, - 118.138506263494		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408137	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408138	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408139	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408141	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408142	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408140	Curb Ramps	Southwest Corner @ 33.927734736842, - 118.142133951187	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408199	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408200	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408201	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408202	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408203	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408204	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408205	Curb Ramps	Northwest Corner @ 33.927876058643, - 118.142038732767	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408206	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408207	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408208	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408209	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408210	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408211	Curb Ramps	Southeast Corner @ 33.927642376798, - 118.141918033361	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408212	Curb Ramps	Northeast Corner @ 33.927780360441, - 118.141812086105		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408213	Curb Ramps	Northeast Corner @ 33.927780360441, - 118.141812086105		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408214	Curb Ramps	Northeast Corner @ 33.927780360441, - 118.141812086105	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408215	Curb Ramps	Northeast Corner @ 33.927780360441, - 118.141812086105	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Alameda Street & Downey Avenue - Alameda Street & Downey Avenue Downey, CA 90242	408216	Curb Ramps	Northeast Corner @ 33.927780360441, - 118.141812086105	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319079	Curb Ramps	Northwest Corner Of Anderberg Avenue @ 33.928886447051, - 118.144065141678		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319080	Curb Ramps	Northwest Corner Of Anderberg Avenue @ 33.928886447051, - 118.144065141678		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319081	Curb Ramps	Northwest Corner Of Anderberg Avenue @ 33.928886447051, - 118.144065141678	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330780	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.928218790856, - 118.142675757408		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330781	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.928218790856, - 118.142675757408		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330782	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.928218790856, - 118.142675757408		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319085	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.928218790856, - 118.142675757408	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330783	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.928646091424, - 118.143893480301		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330784	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.928646091424, - 118.143893480301		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	330785	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.928646091424, - 118.143893480301		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319090	Curb Ramps	Southeast Corner Of Caladre Avenue @ 33.928147573886, - 118.142992258072		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319091	Curb Ramps	Southeast Corner Of Caladre Avenue @ 33.928147573886, - 118.142992258072		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319092	Curb Ramps	Southeast Corner Of Caladre Avenue @ 33.928147573886, - 118.142992258072		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319093	Curb Ramps	Southeast Corner Of Caladre Avenue @ 33.928147573886, - 118.142992258072	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319094	Curb Ramps	Southeast Corner Of Caladre Avenue @ 33.928147573886, - 118.142992258072	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319095	Curb Ramps	Southeast Corner Of Marbel Avenue @ 33.923945667278, - 118.133717179298		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319096	Curb Ramps	Southeast Corner Of Marbel Avenue @ 33.923945667278, - 118.133717179298		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319097	Curb Ramps	Southeast Corner Of Marbel Avenue @ 33.923945667278, - 118.133717179298		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319098	Curb Ramps	Southeast Corner Of Marbel Avenue @ 33.923945667278, - 118.133717179298	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319099	Curb Ramps	Northeast Corner Of Marbel Avenue @ 33.924105913281, - 118.133690357208		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319100	Curb Ramps	Northeast Corner Of Marbel Avenue @ 33.924105913281, - 118.133690357208		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319101	Curb Ramps	Northeast Corner Of Marbel Avenue @ 33.924105913281, - 118.133690357208	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319102	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.924591100729, - 118.135095834732		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319103	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.924591100729, - 118.135095834732		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319104	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.924591100729, - 118.135095834732		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319105	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.924591100729, - 118.135095834732	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319106	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.924591100729, - 118.135095834732	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319107	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.928276654600, - 118.142825961113		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319108	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.928276654600, - 118.142825961113		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319109	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.928276654600, - 118.142825961113		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319110	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.928276654600, - 118.142825961113	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319111	Curb Ramps	Northwest Corner Of Marbel Avenue @ 33.924177133630, - 118.133883476257		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319112	Curb Ramps	Northwest Corner Of Marbel Avenue @ 33.924177133630, - 118.133883476257	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319113	Curb Ramps	Northwest Corner Of Marbel Avenue @ 33.924177133630, - 118.133883476257	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319114	Curb Ramps	Southwest Corner Of Dolan Avenue @ 33.926936876291, - 118.140251040459		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319115	Curb Ramps	Southwest Corner Of Dolan Avenue @ 33.926936876291, - 118.140251040459		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319116	Curb Ramps	Southwest Corner Of Dolan Avenue @ 33.926936876291, - 118.140251040459		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319118	Curb Ramps	Southwest Corner Of Dolan Avenue @ 33.926936876291, - 118.140251040459	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319117	Curb Ramps	Southwest Corner Of Dolan Avenue @ 33.926936876291, - 118.140251040459	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319119	Curb Ramps	Southwest Corner Of Marbel Avenue @ 33.923990180087, - 118.133829832077		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319120	Curb Ramps	Southwest Corner Of Marbel Avenue @ 33.923990180087, - 118.133829832077		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319121	Curb Ramps	Southwest Corner Of Marbel Avenue @ 33.923990180087, - 118.133829832077		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319122	Curb Ramps	Southwest Corner Of Marbel Avenue @ 33.923990180087, - 118.133829832077	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319123	Curb Ramps	Southwest Corner Of Caladre Avenue @ 33.928249948261, - 118.143169283867		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319124	Curb Ramps	Southwest Corner Of Caladre Avenue @ 33.928249948261, - 118.143169283867		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319125	Curb Ramps	Southwest Corner Of Caladre Avenue @ 33.928249948261, - 118.143169283867		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319126	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.926838951468, - 118.140111565590		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319127	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.926838951468, - 118.140111565590		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319129	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.926838951468, - 118.140111565590	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319128	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.926838951468, - 118.140111565590	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319161	Curb Ramps	Northeast Corner Of Anderberg Avenue @ 33.928828583721, - 118.143893480301		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319162	Curb Ramps	Northeast Corner Of Anderberg Avenue @ 33.928828583721, - 118.143893480301	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319163	Curb Ramps	Southeast Corner Of Blodgett Avenue @ 33.924502075716, - 118.134934902191		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319164	Curb Ramps	Southeast Corner Of Blodgett Avenue @ 33.924502075716, - 118.134934902191		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319166	Curb Ramps	Southeast Corner Of Blodgett Avenue @ 33.924502075716, - 118.134934902191	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319165	Curb Ramps	Southeast Corner Of Blodgett Avenue @ 33.924502075716, - 118.134934902191	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319168	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.928525913356, - 118.143721818924		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319169	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.928525913356, - 118.143721818924		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319170	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.928525913356, - 118.143721818924		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319171	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.928525913356, - 118.143721818924	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Alameda Street - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90242	319172	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.928525913356, - 118.143721818924	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Alderdale Street - Guatemala Avenue to Botany Street - Guatemala Avenue to Botany Street Downey, CA 90240	346670	Curb Ramps	Northeast Corner Of Botany Street @ 33.967579304993, - 118.123119771481		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Alderdale Street - Guatemala Avenue to Botany Street - Guatemala Avenue to Botany Street Downey, CA 90240	346671	Curb Ramps	Northeast Corner Of Botany Street @ 33.967579304993, - 118.123119771481		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Alderdale Street - Guatemala Avenue to Botany Street - Guatemala Avenue to Botany Street Downey, CA 90240	346672	Curb Ramps	Northeast Corner Of Botany Street @ 33.967579304993, - 118.123119771481		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Alderdale Street - Guatemala Avenue to Botany Street - Guatemala Avenue to Botany Street Downey, CA 90240	346673	Curb Ramps	Northeast Corner Of Botany Street @ 33.967579304993, - 118.123119771481	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Aliwin Street - True Avenue to Dalewood Avenue - True Avenue to Dalewood Avenue Downey, CA 90242	452631	Curb Ramps	Southeast Corner of True Avenue @ 33.950195282757, - 118.098090738058	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Aliwin Street - True Avenue to Dalewood Avenue - True Avenue to Dalewood Avenue	452632	Curb Ramps	Southeast Corner of True Avenue @ 33.950195282757, - 118.098090738058	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352404	Curb Ramps	Northwest Corner Of Danvers Street @ 33.963973313412, - 118.121531903744		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352405	Curb Ramps	Northwest Corner Of Danvers Street @ 33.963973313412, - 118.121531903744		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352406	Curb Ramps	Northwest Corner Of Danvers Street @ 33.963973313412, - 118.121531903744		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352407	Curb Ramps	Northwest Corner Of Danvers Street @ 33.963973313412, - 118.121531903744	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352441	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352442	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Allengrove Street - Tweedy Lane to Danvers Street - Tweedy Lane to Danvers Street	352443	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Allengrove Street - Tweedy Lane to Danvers Street - Downey, CA 90240	352446	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Allengrove Street - Tweedy Lane to Danvers Street - Downey, CA 90240	352444	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Allengrove Street - Tweedy Lane to Danvers Street - Downey, CA 90240	352445	Curb Ramps	Southwest Corner Of Danvers Street @ 33.963842062223, - 118.121641874313	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Allengrove Street - Tweedy Lane to Guatemala Avenue - Downey, CA 90240	352333	Curb Ramps	Northeast Corner Of Guatemala Avenue @ 33.967461406390, - 118.128087222576		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Allengrove Street - Tweedy Lane to Guatemala Avenue - Downey, CA 90240	352334	Curb Ramps	Northeast Corner Of Guatemala Avenue @ 33.967461406390, - 118.128087222576		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Allengrove Street - Tweedy Lane to Guatemala Avenue - Downey, CA 90240	352335	Curb Ramps	Northeast Corner Of Guatemala Avenue @ 33.967461406390, - 118.128087222576		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Allengrove Street - Tweedy Lane to Guatemala Avenue - Downey, CA 90240	352336	Curb Ramps	Northeast Corner Of Guatemala Avenue @ 33.967461406390, - 118.128087222576	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Allengrove Street - Tweedy Lane to Guatemala Avenue - Downey, CA 90240	352337	Curb Ramps	Northeast Corner Of Guatemala Avenue @ 33.967461406390, - 118.128087222576	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464827	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464828	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464829	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464830	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464833	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464834	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464831	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464832	Curb Ramps	Southwest Corner of Erickson Avenue @ 33.926042195319, -118.160228133202	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464875	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.926144572225, -118.159793615341		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464876	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.926144572225, -118.159793615341		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464877	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.926144572225, -118.159793615341	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464878	Curb Ramps	North Side East of Old River School Road - 2nd @ 33.926536274033, -118.161327838898		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464879	Curb Ramps	North Side East of Old River School Road - 2nd @ 33.926536274033, -118.161327838898		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464880	Curb Ramps	North Side East of Old River School Road - 2nd @ 33.926536274033, -118.161327838898		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464881	Curb Ramps	North Side East of Old River School Road - 2nd @ 33.926536274033, - 118.161327838898		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464882	Curb Ramps	North Side East of Old River School Road - 2nd @ 33.926536274033, - 118.161327838898	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464936	Curb Ramps	North Side East of Old River School Road - 1st @ 33.926514018296, - 118.161445856094		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464937	Curb Ramps	North Side East of Old River School Road - 1st @ 33.926514018296, - 118.161445856094		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464938	Curb Ramps	North Side East of Old River School Road - 1st @ 33.926514018296, - 118.161445856094		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464939	Curb Ramps	North Side East of Old River School Road - 1st @ 33.926514018296, - 118.161445856094	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464940	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464941	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464942	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464943	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464944	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464945	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464946	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464947	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.925895306501, - 118.159976005554	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464948	Curb Ramps	Northwest Corner of Erickson Avenue @ 33.926224693196, -118.160099387169		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464949	Curb Ramps	Northwest Corner of Erickson Avenue @ 33.926224693196, -118.160099387169		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464950	Curb Ramps	Northwest Corner of Erickson Avenue @ 33.926224693196, -118.160099387169	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Amigos Avenue - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	464951	Curb Ramps	Northwest Corner of Erickson Avenue @ 33.926224693196, -118.160099387169	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue Downey, CA 90424	326350	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, -118.115703463554		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue Downey, CA 90424	326351	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, -118.115703463554		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue Downey, CA 90424	326352	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, -118.115703463554		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue	Downey, CA 90424 319024	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, - 118.115703463554	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue	Downey, CA 90424 319025	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, - 118.115703463554	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Angell Street - Carfax Avenue to Adenmoor Avenue - Angell Street - Carfax Avenue to Adenmoor Avenue	Downey, CA 90424 319026	Curb Ramps	Southeast Corner Of Faust Avenue @ 33.913250790959, - 118.115703463554	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Apollo Way & Lakewood Boulevard - Apollo Way & Lakewood Boulevard	Downey, CA 90242 434210	Curb Ramps	Southeast Corner @ 33.922411073974, - 118.133502602577	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Apollo Way & Lakewood Boulevard - Apollo Way & Lakewood Boulevard	Downey, CA 90242 434211	Curb Ramps	Northwest Corner to Lakewood Boulevard - Frontage Road @ 33.922754941011, - 118.133620619774		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Apollo Way & Lakewood Boulevard - Apollo Way & Lakewood Boulevard	Downey, CA 90242 434213	Curb Ramps	Northwest Corner to Lakewood Boulevard - Frontage Road @ 33.922754941011, - 118.133620619774	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Apollo Way & Lakewood Boulevard - Apollo Way & Lakewood Boulevard	Downey, CA 90242 434212	Curb Ramps	Northwest Corner to Lakewood Boulevard - Frontage Road @ 33.922754941011, - 118.133620619774	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Ardine Street - Pangborn Avenue to Newville Avenue - Downey, CA 90241	418394	Curb Ramps	Southeast Corner Of Pangborn Avenue @ 33.932104476502, - 118.112707436085		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Ardine Street - Pangborn Avenue to Newville Avenue - Downey, CA 90241	418395	Curb Ramps	Southeast Corner Of Pangborn Avenue @ 33.932104476502, - 118.112707436085	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Ardine Street - Pangborn Avenue to Newville Avenue - Downey, CA 90241	418396	Curb Ramps	Southeast Corner Of Pangborn Avenue @ 33.932104476502, - 118.112707436085	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Ardine Street - Pangborn Avenue to Newville Avenue - Downey, CA 90241	418397	Curb Ramps	Southeast Corner Of Pangborn Avenue @ 33.932104476502, - 118.112707436085	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/19
Ardine Street - Pangborn Avenue to Newville Avenue - Downey, CA 90241	418398	Curb Ramps	Southeast Corner Of Pangborn Avenue @ 33.932104476502, - 118.112707436085	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey, CA 90242	446727	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey, CA 90242	446728	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey, CA 90242	446729	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446730	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446731	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446732	Curb Ramps	Northwest Corner of Downey Avenue @ 33.937393041536, - 118.134988546371	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446739	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446740	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446741	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446742	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446743	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Downey Avenue to Mcgovern Avenue - Downey Avenue to Mcgovern Avenue Downey, CA 90242	446744	Curb Ramps	Southwest Corner of Downey Avenue @ 33.937261749346, - 118.135071694851	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420507	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420508	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420509	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420510	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420511	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420512	Curb Ramps	Southwest Corner Of Old River School Road @ 33.945694079798, - 118.150279819965	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420524	Curb Ramps	Northwest Corner Of Old River School Road @ 33.945836484329, - 118.150171190500		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420525	Curb Ramps	Northwest Corner Of Old River School Road @ 33.945836484329, - 118.150171190500		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420526	Curb Ramps	Northwest Corner Of Old River School Road @ 33.945836484329, - 118.150171190500		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420528	Curb Ramps	Northwest Corner Of Old River School Road @ 33.945836484329, - 118.150171190500	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Arnett Street - Firestone Boulevard To Old River School Road - Firestone Boulevard To Old River School Road Downey, CA 90242	420527	Curb Ramps	Northwest Corner Of Old River School Road @ 33.945836484329, - 118.150171190500	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361666	Curb Ramps	Southwest Corner Of Norlain Avenue @ 33.945237938681, - 118.149456381798	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361667	Curb Ramps	Southeast Corner Of Norlain Avenue @ 33.945140034903, - 118.149316906929	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361684	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945593951469, -118.149858713150		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361685	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945593951469, -118.149858713150		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361686	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945593951469, -118.149858713150		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361687	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945593951469, -118.149858713150		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361688	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945593951469, -118.149858713150	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361689	Curb Ramps	Southeast Corner Of Old River School Road @ 33.945527199185, -118.149971365929		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361690	Curb Ramps	Southeast Corner Of Old River School Road @ 33.945527199185, -118.149971365929		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Old River School Road To Julius Avenue - Old River School Road To Julius Avenue Downey, CA 90421	361691	Curb Ramps	Southeast Corner Of Old River School Road @ 33.945527199185, - 118.149971365929		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411696	Curb Ramps	Southwest Corner Of Julius Avenue @ 33.944117601222, - 118.147365599871	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411697	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.944252220504, - 118.147269040346	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411698	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.944043059875, - 118.147231489420		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411699	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.944043059875, - 118.147231489420	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411700	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945697417407, - 118.149935156107		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411701	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945697417407, - 118.149935156107		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411702	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945697417407, -118.149935156107		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411703	Curb Ramps	Northeast Corner Of Old School River Road @ 33.945697417407, -118.149935156107	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411704	Curb Ramps	Southwest Corner Of Old School River Road @ 33.945568363100, -118.150034397841		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411705	Curb Ramps	Southwest Corner Of Old School River Road @ 33.945568363100, -118.150034397841		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411706	Curb Ramps	Southwest Corner Of Old School River Road @ 33.945568363100, -118.150034397841		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411707	Curb Ramps	Southwest Corner Of Old School River Road @ 33.945568363100, -118.150034397841		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Arnett Street - Old School River Road To Julius Avenue - Old School River Road To Julius Avenue Downey, CA 90242	411708	Curb Ramps	Southwest Corner Of Old School River Road @ 33.945568363100, -118.150034397841	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Arnett Street - Pruess Avenue To Rives Avenue - Pruess Avenue To Rives Avenue	411939	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.941802338759, - 118.144378960133		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Arnett Street - Pruess Avenue To Rives Avenue - Pruess Avenue To Rives Avenue	411940	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.941802338759, - 118.144378960133		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Arnett Street - Pruess Avenue To Rives Avenue - Pruess Avenue To Rives Avenue	411941	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.941802338759, - 118.144378960133		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Arnett Street - Pruess Avenue To Rives Avenue - Pruess Avenue To Rives Avenue	411942	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.941802338759, - 118.144378960133	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Arnett Street - Pruess Avenue To Rives Avenue - Pruess Avenue To Rives Avenue	411943	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.941802338759, - 118.144378960133	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Arnett Street - Rives Avenue To Horton Avenue - Rives Avenue To Horton Avenue	412872	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.942446524306, - 118.144124150276	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Arnett Street - Rives Avenue To Horton Avenue - Rives Avenue To Horton Avenue	412873	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.942321915393, - 118.144222050905	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End	459191	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End	459192	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831		Curb Ramp Width	Provide a compliant curb ramp.	6/30/19	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459193	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459194	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459195	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459196	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.969720359671, - 118.122777789831	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459197	Curb Ramps	Southwest Corner of Guatemala Avenue @ 33.969879407296, - 118.122836798429		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459198	Curb Ramps	Southwest Corner of Guatemala Avenue @ 33.969879407296, - 118.122836798429		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459199	Curb Ramps	Southwest Corner of Guatemala Avenue @ 33.969879407296, - 118.122836798429		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459200	Curb Ramps	Southwest Corner of Guatemala Avenue @ 33.969879407296, - 118.122836798429	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Bangle Road - Tweedy Lane to End - Tweedy Lane to End Downey, CA 90242	459201	Curb Ramps	Southwest Corner of Guatemala Avenue @ 33.969879407296, - 118.122836798429	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402093	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402094	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402095	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402096	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402097	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402098	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Barlin Avenue - Cheyenne Street To Gardendale Street - Cheyenne Street To Gardendale Street Downey, CA 90242	402099	Curb Ramps	Southeast Corner Of Cheyenne Street @ 33.913561306289, - 118.144138902426	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Barlin Avenue - Cheyenne Street To Imperial Highway - Cheyenne Street To Imperial Highway Downey, CA 90242	402054	Curb Ramps	East Side South Of Dalen Street - 2nd @ 33.916606299894, - 118.142011910677		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310767	Curb Ramps	Northwest Corner Of Prichard Street @ 33.907094785786, - 118.148317784071	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310768	Curb Ramps	Southeast Corner Of Golden Street @ 33.908472718895, - 118.147163093090		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310769	Curb Ramps	Southeast Corner Of Golden Street @ 33.908472718895, - 118.147163093090		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310771	Curb Ramps	Southeast Corner Of Golden Street @ 33.908472718895, - 118.147163093090	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310770	Curb Ramps	Southeast Corner Of Golden Street @ 33.908472718895, - 118.147163093090	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310772	Curb Ramps	Southwest Corner Of Golden Street @ 33.908567325763, - 118.147306591272		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310773	Curb Ramps	Southwest Corner Of Golden Street @ 33.908567325763, - 118.147306591272		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310774	Curb Ramps	Southwest Corner Of Golden Street @ 33.908567325763, - 118.147306591272		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310775	Curb Ramps	Southwest Corner Of Golden Street @ 33.908567325763, - 118.147306591272	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310776	Curb Ramps	Southwest Corner Of Golden Street @ 33.908567325763, - 118.147306591272	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard	310777	Curb Ramps	Southwest Corner Of Prichard Street @ 33.906957881684, - 118.148399591446	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard	310778	Curb Ramps	Southeast Corner Of Prichard Street @ 33.906877742596, - 118.148233294487	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard	310779	Curb Ramps	Northeast Corner Of Parkcliff Street @ 33.905782500835, - 118.148978948593	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Barlin Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard	310784	Curb Ramps	Northwest Corner Of Century Boulevard @ 33.905497557582, - 118.149386644363	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Baysinger Street - Birchdale Avenue to Tristan Drive - Birchdale Avenue to Tristan Drive	470184	Curb Ramps	Southeast Corner of Birchdale Avenue @ 33.947729996929, - 118.120990097523		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Baysinger Street - Birchdale Avenue to Tristan Drive - Birchdale Avenue to Tristan Drive	470185	Curb Ramps	Southeast Corner of Birchdale Avenue @ 33.947729996929, - 118.120990097523	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Baysinger Street - Paramount Boulevard to End - Paramount Boulevard to End	460690	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, - 118.130827099085		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Baysinger Street - Paramount Boulevard to End - Paramount Boulevard to End	460691	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, - 118.130827099085		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Baysinger Street - Paramount Boulevard to End - Paramount	460692	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, -118.130827099085		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460693	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, -118.130827099085		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460286	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, -118.130827099085	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460287	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, -118.130827099085	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460288	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952727243862, -118.130827099085	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460694	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, -118.130892813206		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460695	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, -118.130892813206		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount	460696	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, -118.130892813206		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Baysinger Street - Paramount Boulevard to End - Paramount Boulevard to End Downey, CA 90242	460697	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, - 118.130892813206		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount Boulevard to End Downey, CA 90242	460293	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, - 118.130892813206	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Baysinger Street - Paramount Boulevard to End - Paramount Boulevard to End Downey, CA 90242	460294	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.952646035383, - 118.130892813206	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446289	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446290	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446291	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446293	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446294	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Baysinger Street - Vultee Avenue to Haledon Avenue - Vultee Avenue to Haledon Avenue Downey, CA 90242	446292	Curb Ramps	Southeast Corner of Vultee Avenue @ 33.945936612372, - 118.116705268621	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Belder Drive - Everest Street To Imperial Highway - Everest Street To Imperial Highway Downey, CA 90242	351426	Curb Ramps	Southeast Corner Of Everest Street @ 33.921455138573, - 118.141270279884		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/19	
Belder Drive - Everest Street To Imperial Highway - Everest Street To Imperial Highway Downey, CA 90242	351447	Curb Ramps	Southwest Corner Of Everest Street @ 33.921536376806, - 118.141396343708	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322322	Curb Ramps	Southeast Corner Of Hall Road		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322323	Curb Ramps	Northeast Corner Of Hall Road @ 33.931666066090, - 118.125313818455		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322324	Curb Ramps	Northeast Corner Of Hall Road @ 33.931666066090, - 118.125313818455		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312028	Curb Ramps	Northeast Corner Of Hall Road @ 33.931666066090, - 118.125313818455	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312029	Curb Ramps	Northeast Corner Of Hall Road @ 33.931666066090, - 118.125313818455	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322325	Curb Ramps	Southeast Corner Of Iowa Street @ 33.932505052571, - 118.125316500664		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322326	Curb Ramps	Southeast Corner Of Iowa Street @ 33.932505052571, - 118.125316500664		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	322327	Curb Ramps	Southeast Corner Of Iowa Street @ 33.932505052571, - 118.125316500664		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312471	Curb Ramps	Northwest Corner Of Hall Road @ 33.931503608866, - 118.125573992729		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312472	Curb Ramps	Northwest Corner Of Hall Road @ 33.931503608866, - 118.125573992729		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312473	Curb Ramps	Northwest Corner Of Hall Road @ 33.931503608866, - 118.125573992729	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312475	Curb Ramps	Southwest Corner Of Hall Road @ 33.931519186969, - 118.125571310520	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312474	Curb Ramps	Southwest Corner Of Hall Road @ 33.931519186969, - 118.125571310520	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312476	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312477	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312478	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312479	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312480	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312481	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312482	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312483	Curb Ramps	Southwest Corner Of Buckles Street @ 33.929596382397, - 118.125555217266	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312485	Curb Ramps	Northeast Corner Of Elm Vista Drive @ 33.926249174589, - 118.125286996365	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312486	Curb Ramps	Southeast Corner Of Elm Vista Drive @ 33.926113414049, - 118.125273585320		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312487	Curb Ramps	Southeast Corner Of Elm Vista Drive @ 33.926113414049, - 118.125273585320		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312488	Curb Ramps	Southeast Corner Of Elm Vista Drive @ 33.926113414049, - 118.125273585320	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312522	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848		No Detectable Warnings	Provide compliant detectable warnings to surface.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312523	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312524	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312525	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312526	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312527	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/19	
Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way - Bellflower Boulevard - Lakewood Boulevard to Congressman Steve Horn Way Downey, CA 90242	312528	Curb Ramps	Northwest Corner Of Buckles Street @ 33.929603058877, - 118.125549852848	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336854	Curb Ramps	Northeast Corner @ 33.920892033073, - 118.125262856483		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336608	Curb Ramps	Northeast Corner @ 33.920892033073, -118.125262856483	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/19	
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336855	Curb Ramps	Southwest Corner @ 33.920691717965, -118.125568628311		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/19	
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336611	Curb Ramps	Southwest Corner @ 33.920691717965, -118.125568628311	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/19	
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336856	Curb Ramps	Southwest Corner @ 33.920691717965, -118.125568628311	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/19	
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336857	Curb Ramps	Southeast Corner @ 33.920713975223, -118.125268220901		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/19	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336858	Curb Ramps	Northwest Corner @ 33.920945450355, -118.125616908073		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336859	Curb Ramps	Northwest Corner @ 33.920945450355, -118.125616908073		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Bellflower Boulevard & Congressman Steve Horn Way - Bellflower Boulevard & Congressman Steve Horn Way Downey, CA 90240	336692	Curb Ramps	Northwest Corner @ 33.920945450355, -118.125616908073	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Bellflower Boulevard & Foster Road - Bellflower Boulevard & Foster Road Downey, CA 90640	336434	Curb Ramps	Northeast Corner @ 33.909877341834, -118.125241398811	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/19
Bellflower Boulevard & Foster Road - Bellflower Boulevard & Foster Road Downey, CA 90640	336435	Curb Ramps	Northeast Corner @ 33.909877341834, -118.125241398811	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Bellflower Boulevard & Foster Road - Bellflower Boulevard & Foster Road Downey, CA 90640	336436	Curb Ramps	Northwest Corner @ 33.909878454838, -118.125513643026		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & Foster Road - Bellflower Boulevard & Foster Road Downey, CA 90640	336437	Curb Ramps	Northwest Corner @ 33.909878454838, - 118.125513643026		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/19
Bellflower Boulevard & Foster Road - Bellflower Boulevard & Foster Road Downey, CA 90640	336438	Curb Ramps	Northwest Corner @ 33.909878454838, - 118.125513643026	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/19
Bellflower Boulevard & Imperial Highway - Bellflower Boulevard & Imperial Highway Downey, CA 90240	436700	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917186127353, - 118.125244081020	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Bellflower Boulevard & Imperial Highway - Bellflower Boulevard & Imperial Highway Downey, CA 90240	436701	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917186127353, - 118.125244081020	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Bellflower Boulevard & Imperial Highway - Bellflower Boulevard & Imperial Highway Downey, CA 90240	436702	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916925706296, - 118.125547170639	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336290	Curb Ramps	Southwest Corner @ 33.913554628552, - 118.125528395176		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336291	Curb Ramps	Southwest Corner @ 33.913554628552, - 118.125528395176		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336292	Curb Ramps	Southwest Corner @ 33.913554628552, - 118.125528395176		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336293	Curb Ramps	Southwest Corner @ 33.913554628552, - 118.125528395176	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336294	Curb Ramps	Southwest Corner @ 33.913554628552, - 118.125528395176	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336295	Curb Ramps	Southeast Corner @ 33.913582452453, - 118.125260174274		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336296	Curb Ramps	Southeast Corner @ 33.913582452453, - 118.125260174274		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336297	Curb Ramps	Southeast Corner @ 33.913582452453, - 118.125260174274		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336298	Curb Ramps	Southeast Corner @ 33.913582452453, - 118.125260174274	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336299	Curb Ramps	Southeast Corner @ 33.913582452453, - 118.125260174274	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336354	Curb Ramps	Northeast Corner @ 33.913781671320, - 118.125264197588		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336355	Curb Ramps	Northeast Corner @ 33.913781671320, - 118.125264197588		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336356	Curb Ramps	Northeast Corner @ 33.913781671320, - 118.125264197588		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336358	Curb Ramps	Northeast Corner @ 33.913781671320, - 118.125264197588	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336357	Curb Ramps	Northeast Corner @ 33.913781671320, - 118.125264197588	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336359	Curb Ramps	Northwest Corner @ 33.913703764556, - 118.125549852848		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336360	Curb Ramps	Northwest Corner @ 33.913703764556, - 118.125549852848		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336361	Curb Ramps	Northwest Corner @ 33.913703764556, - 118.125549852848	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336362	Curb Ramps	Northwest Corner @ 33.913703764556, - 118.125549852848	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/19
Bellflower Boulevard & N\O I 105 Ramp - Bellflower Boulevard & N\O I 105 Ramp Downey, CA 90240	336363	Curb Ramps	Northwest Corner @ 33.913703764556, - 118.125549852848	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/19
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336364	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/19
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336365	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535		Curb Ramp Width	Provide a compliant curb ramp.		6/30/19
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336366	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336367	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336370	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336368	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336369	Curb Ramps	Southwest Corner @ 33.912517347032, - 118.125545829535	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336421	Curb Ramps	Northeast Corner @ 33.912698760913, - 118.125253468752		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336424	Curb Ramps	Northeast Corner @ 33.912698760913, - 118.125253468752	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336422	Curb Ramps	Northeast Corner @ 33.912698760913, - 118.125253468752	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336423	Curb Ramps	Northeast Corner @ 33.912698760913, - 118.125253468752	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336425	Curb Ramps	Southeast Corner @ 33.912564091750, - 118.125244081020		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336426	Curb Ramps	Southeast Corner @ 33.912564091750, - 118.125244081020		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336427	Curb Ramps	Southeast Corner @ 33.912564091750, - 118.125244081020	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336428	Curb Ramps	Southeast Corner @ 33.912564091750, - 118.125244081020	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336429	Curb Ramps	Northwest Corner @ 33.912686518270, - 118.125520348549		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336430	Curb Ramps	Northwest Corner @ 33.912686518270, - 118.125520348549		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336433	Curb Ramps	Northwest Corner @ 33.912686518270, - 118.125520348549	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336431	Curb Ramps	Northwest Corner @ 33.912686518270, - 118.125520348549	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Bellflower Boulevard & S\O I 105 Ramp - Bellflower Boulevard & S\O I 105 Ramp Downey, CA 90240	336432	Curb Ramps	Northwest Corner @ 33.912686518270, - 118.125520348549	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336491	Curb Ramps	Southeast Corner @ 33.927702466476, - 118.125309795141	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336490	Curb Ramps	Southeast Corner @ 33.927702466476, - 118.125309795141	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336492	Curb Ramps	Northeast Corner @ 33.927945050303, - 118.125296384096	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336849	Curb Ramps	Northwest Corner @ 33.927950614144, - 118.125571310520		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336850	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520		Curb Ramp Width	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336851	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336852	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336600	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336601	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336602	Curb Ramps	Northwest Corner @ 33.927950614144, -118.125571310520	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336853	Curb Ramps	Southwest Corner @ 33.927684662132, -118.125622272491		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336606	Curb Ramps	Southwest Corner @ 33.927684662132, - 118.125622272491	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336604	Curb Ramps	Southwest Corner @ 33.927684662132, - 118.125622272491	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Bellflower Boulevard & Stewart and Gray Road - Bellflower Boulevard & Stewart and Gray Road Downey, CA 90240	336605	Curb Ramps	Southwest Corner @ 33.927684662132, - 118.125622272491	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312529	Curb Ramps	Southwest Corner Of Borson Street @ 33.914457231275, - 118.125512301922		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312530	Curb Ramps	Southwest Corner Of Borson Street @ 33.914457231275, - 118.125512301922		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312531	Curb Ramps	Southwest Corner Of Borson Street @ 33.914457231275, - 118.125512301922	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312532	Curb Ramps	Southwest Corner Of Borson Street @ 33.914457231275, - 118.125512301922	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312533	Curb Ramps	Southwest Corner Of Borson Street @ 33.914457231275, - 118.125512301922	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312534	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312535	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312536	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312539	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312537	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312538	Curb Ramps	Northwest Corner Of Borson Street @ 33.914630850431, - 118.125512301922	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312540	Curb Ramps	Southwest Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312541	Curb Ramps	Southwest Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312542	Curb Ramps	Southwest Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312543	Curb Ramps	Southwest Corner Of Dalen Street @ 33.914893504379, - 118.125525712967	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312544	Curb Ramps	Southwest Corner Of Dalen Street @ 33.914893504379, - 118.125525712967	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312545	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312546	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312547	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312548	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312549	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	312550	Curb Ramps	Northeast Corner Of Dalen Street @ 33.914893504379, - 118.125525712967	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313169	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313170	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313171	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313172	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313173	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313174	Curb Ramps	Northeast Corner Of Priscilla Street @ 33.911645887242, - 118.125286996365	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313175	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313176	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313177	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313180	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313181	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313178	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bellflower Boulevard - Foster Road to Imperial Highway - Bellflower Boulevard - Foster Road to Imperial Highway Downey, CA 90242	313179	Curb Ramps	Southeast Corner Of Priscilla Street @ 33.911581334310, - 118.125278949738	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415936	Curb Ramps	Southeast Corner @ 33.933115927448, - 118.125607520342	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415937	Curb Ramps	Northeast Corner @ 33.933386313290, - 118.125364780426	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415938	Curb Ramps	Northeast Corner @ 33.933386313290, - 118.125364780426	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415939	Curb Ramps	Northwest Corner @ 33.933721234480, - 118.125583380461		Curb Ramp Width	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415940	Curb Ramps	Northwest Corner @ 33.933721234480, - 118.125583380461		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415941	Curb Ramps	Northwest Corner @ 33.933721234480, - 118.125583380461	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415942	Curb Ramps	Southwest Corner @ 33.933473103625, - 118.125803321600		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415943	Curb Ramps	Southwest Corner @ 33.933473103625, - 118.125803321600		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415945	Curb Ramps	Southwest Corner @ 33.933473103625, - 118.125803321600	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bellflower Boulevard / Coca Cola & Lakewood Boulevard - Bellflower Boulevard / Coca Cola & Lakewood Boulevard Downey, CA 90242	415944	Curb Ramps	Southwest Corner @ 33.933473103625, - 118.125803321600	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/20	
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408568	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408569	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083		Curb Ramp Width	Provide a compliant curb ramp.	6/30/20	
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408570	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408571	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408572	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408573	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408574	Curb Ramps	Northwest Corner Of Old River School Road @ 33.943027288445, - 118.152219057083	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408595	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408596	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408597	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408598	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408599	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408600	Curb Ramps	Southeast Corner Of Mitla Avenue @ 33.946393862271, - 118.158550411463	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408601	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.946540715733, - 118.158441781998		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408602	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.946540715733, - 118.158441781998		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408603	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.946540715733, - 118.158441781998	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408604	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.946540715733, - 118.158441781998	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408605	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942868190617, - 118.152322322130		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408606	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942868190617, - 118.152322322130		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408607	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942868190617, - 118.152322322130		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Benares Street - Old River School Road To Mitla Avenue - Old River School Road To Mitla Avenue Downey, CA 90242	408608	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942868190617, - 118.152322322130	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Benares Street - Rives Avenue To Cul-de-sac - Rives Avenue To Cul-de-sac Downey, CA 90242	408107	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.939422481491, - 118.146142512560		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Benares Street - Rives Avenue To Cul-de-sac - Rives Avenue To Cul-de-sac Downey, CA 90242	408108	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.939422481491, - 118.146142512560		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Benares Street - Rives Avenue To Cul-de-sac - Rives Avenue To Cul-de-sac Downey, CA 90242	408109	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.939422481491, - 118.146142512560	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Benares Street - Rives Avenue To Cul-de-sac - Rives Avenue To Cul-de-sac Downey, CA 90242	408113	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.939540418949, - 118.146049976349		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Benares Street - Rives Avenue To Cul-de-sac - Rives Avenue To Cul-de-sac	408114	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.939540418949, - 118.146049976349	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Birchbark Avenue - Telegraph Road to Birchcrest Road - Telegraph Road to Birchcrest Road	452769	Curb Ramps	Northeast Corner of Birchcrest Road @ 33.964040051227, - 118.114755302668		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchbark Avenue - Telegraph Road to Birchcrest Road - Telegraph Road to Birchcrest Road	452770	Curb Ramps	Northeast Corner of Birchcrest Road @ 33.964040051227, - 118.114755302668		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Birchbark Avenue - Telegraph Road to Birchcrest Road - Telegraph Road to Birchcrest Road	452771	Curb Ramps	Northeast Corner of Birchcrest Road @ 33.964040051227, - 118.114755302668		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Birchbark Avenue - Telegraph Road to Birchcrest Road - Telegraph Road to Birchcrest Road	452728	Curb Ramps	Northeast Corner of Birchcrest Road @ 33.964040051227, - 118.114755302668	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Birchbark Avenue - Telegraph Road to Birchcrest Road - Telegraph Road to Birchcrest Road	452729	Curb Ramps	Northeast Corner of Birchcrest Road @ 33.964040051227, - 118.114755302668	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount Boulevard to Cul-De-Sac	456407	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.966461486199, - 118.117055296898		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount Boulevard to Cul-De-Sac	456408	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.966461486199, - 118.117055296898		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456035	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.966461486199, -118.117055296898	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456036	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.966461486199, -118.117055296898	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456037	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.966461486199, -118.117055296898	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456409	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.966554916392, -118.116893023252		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456410	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.966554916392, -118.116893023252		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456040	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.966554916392, -118.116893023252	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Birchcrest Road - Paramount Boulevard to Cul-De-Sac - Paramount	456041	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.966554916392, -118.116893023252	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407741	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407742	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407743	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407744	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407747	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407748	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407745	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407746	Curb Ramps	Southeast Corner Of 5th Street @ 33.941141459402, - 118.124796152115	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407749	Curb Ramps	Southwest Corner Of 5th Street @ 33.941213778100, - 118.124931603670		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407750	Curb Ramps	Southwest Corner Of 5th Street @ 33.941213778100, - 118.124931603670		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407751	Curb Ramps	Southwest Corner Of 5th Street @ 33.941213778100, - 118.124931603670		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Birchdale Avenue - 5th Street To End - 5th Street To End Downey, CA 90242	407752	Curb Ramps	Southwest Corner Of 5th Street @ 33.941213778100, - 118.124931603670	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchdale Avenue - 5th Street To End - 5th Street To End	407753	Curb Ramps	Southwest Corner Of 5th Street @ 33.941213778100, - 118.124931603670	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471749	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471750	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471751	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471752	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471755	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471753	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471754	Curb Ramps	Northeast Corner of 5th Street @ 33.941289434518, - 118.124696910381	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471776	Curb Ramps	Northwest Corner of 5th Street @ 33.941361753091, - 118.124839067459		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471777	Curb Ramps	Northwest Corner of 5th Street @ 33.941361753091, - 118.124839067459		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street Downey, CA 90242	471778	Curb Ramps	Northwest Corner of 5th Street @ 33.941361753091, - 118.124839067459		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Birchdale Avenue - 6th Street to 5th Street - 6th Street to 5th Street Downey, CA 90242	471761	Curb Ramps	Northwest Corner of 5th Street @ 33.941361753091, - 118.124839067459	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382881	Curb Ramps	Southeast Corner Of Springer Street @ 33.922858434702, - 118.138319849968		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357504	Curb Ramps	Southeast Corner Of Springer Street @ 33.922858434702, - 118.138319849968	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357505	Curb Ramps	Southeast Corner Of Springer Street @ 33.922858434702, - 118.138319849968	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382882	Curb Ramps	Northeast Corner Of Springer Street @ 33.922978620767, - 118.138232678175		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382883	Curb Ramps	Northeast Corner Of Springer Street @ 33.922978620767, - 118.138232678175		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357508	Curb Ramps	Northeast Corner Of Springer Street @ 33.922978620767, - 118.138232678175	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382884	Curb Ramps	Northeast Corner Of Boyson Street @ 33.924212743782, - 118.137303292751		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357510	Curb Ramps	Northeast Corner Of Boyson Street @ 33.924212743782, - 118.137303292751	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357511	Curb Ramps	Northeast Corner Of Boyson Street @ 33.924212743782, - 118.137303292751	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357512	Curb Ramps	Northeast Corner Of Boyson Street @ 33.924212743782, - 118.137303292751	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357513	Curb Ramps	Northeast Corner Of Boyson Street @ 33.924212743782, - 118.137303292751	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382891	Curb Ramps	Southeast Corner Of Boyson Street @ 33.924091446640, - 118.137387782335		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382892	Curb Ramps	Southeast Corner Of Boyson Street @ 33.924091446640, - 118.137387782335		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357535	Curb Ramps	Southeast Corner Of Boyson Street @ 33.924091446640, - 118.137387782335	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357536	Curb Ramps	Southeast Corner Of Boyson Street @ 33.924091446640, - 118.137387782335	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382893	Curb Ramps	Southeast Corner Of Mory Street @ 33.923466040288, - 118.137862533331		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382894	Curb Ramps	Southeast Corner Of Mory Street @ 33.923466040288, - 118.137862533331		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382895	Curb Ramps	Southeast Corner Of Mory Street @ 33.923466040288, - 118.137862533331		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357540	Curb Ramps	Southeast Corner Of Mory Street @ 33.923466040288, - 118.137862533331	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357541	Curb Ramps	Southeast Corner Of Mory Street @ 33.923466040288, - 118.137862533331	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382896	Curb Ramps	Northeast Corner Of Mory Street @ 33.923600692222, - 118.137765973806		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382897	Curb Ramps	Northeast Corner Of Mory Street @ 33.923600692222, - 118.137765973806		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357544	Curb Ramps	Northeast Corner Of Mory Street @ 33.923600692222, - 118.137765973806	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	357545	Curb Ramps	Northeast Corner Of Mory Street @ 33.923600692222, - 118.137765973806	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Birchdale Avenue - Alameda Street To End - Alameda Street To End Downey, CA 90242	382898	Curb Ramps	Southeast Corner Of Everest Street @ 33.920731781025, - 118.139939904213	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bixler Avenue - Century Boulevard To Downey Avenue - Century Boulevard To Downey Avenue Downey, CA 90242	314235	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.907935127287, - 118.151751011610	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Bixler Avenue - Century Boulevard To Downey Avenue - Century Boulevard To Downey Avenue Downey, CA 90242	314238	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.908164411079, - 118.151796609163		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bixler Avenue - Century Boulevard To Downey Avenue - Century Boulevard To Downey Avenue Downey, CA 90242	314239	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.908164411079, - 118.151796609163	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bixler Avenue - Century Boulevard To Downey Avenue - Century Boulevard To Downey Avenue Downey, CA 90242	314240	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.908164411079, - 118.151796609163	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Blodgett Avenue - Gardendale Street To Priscilla Street - Gardendale Street To Priscilla Street Downey, CA 90242	313012	Curb Ramps	Northwest Corner Of Gardendale Street @ 33.911279715654, - 118.143877387047	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Blodgett Avenue - Gardendale Street To Priscilla Street - Gardendale Street To Priscilla Street Downey, CA 90242	313013	Curb Ramps	Northwest Corner Of Gardendale Street @ 33.911279715654, - 118.143877387047	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue Downey, CA 90242	311190	Curb Ramps	Southwest Corner Of Golden Street @ 33.911249665029, - 118.144370913506	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue Downey, CA 90242	311191	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.908280165768, - 118.146375864744		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue Downey, CA 90242	311192	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.908280165768, - 118.146375864744		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue Downey, CA 90242	311193	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.908280165768, - 118.146375864744		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311194	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.908280165768, - 118.146375864744	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311196	Curb Ramps	Northeast Corner Of Golden Street @ 33.908195575818, - 118.146208226681		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311197	Curb Ramps	Northeast Corner Of Golden Street @ 33.908195575818, - 118.146208226681		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311198	Curb Ramps	Northeast Corner Of Golden Street @ 33.908195575818, - 118.146208226681		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311199	Curb Ramps	Northeast Corner Of Golden Street @ 33.908195575818, - 118.146208226681	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Blodgett Avenue - Golden Street To Gardendale Avenue - Golden Street To Gardendale Avenue	311200	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.911176207899, - 118.144195228815	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Blodgett Avenue - Parkcliff Street To Prichard Street - Parkcliff Street To Prichard Street	310793	Curb Ramps	Southeast Corner Of Prichard Street @ 33.906127548030, - 118.146688342094	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End	357898	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357899	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357900	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357901	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357902	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357903	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357904	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/20	
Bluff Road - Suva Street to End - North - Suva Street to End Downey, CA 90240	357905	Curb Ramps	East Side North Of Suva Street @ 33.965517168128, - 118.135624229908	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356582	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.924561054797, - 118.137249648571		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356583	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.924561054797, - 118.137249648571		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356584	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.924561054797, - 118.137249648571		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356585	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.924561054797, - 118.137249648571	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356586	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.924561054797, - 118.137249648571	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356587	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.924433081267, - 118.137373030186		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356588	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.924433081267, - 118.137373030186		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Boyson Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	356589	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.924433081267, - 118.137373030186	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brock Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	360161	Curb Ramps	East Side South Of Priscilla Avenue @ 33.916801060038, - 118.154966980219		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brock Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	360162	Curb Ramps	East Side South Of Priscilla Avenue @ 33.916801060038, - 118.154966980219	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408124	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408125	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323		Curb Ramp Width	Provide a compliant curb ramp.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408126	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408127	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408128	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408129	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408130	Curb Ramps	Northeast Corner Of Old River School Road @ 33.943433375958, -118.151606172323	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408131	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, -118.151685297489		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408132	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, -118.151685297489		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408133	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, -118.151685297489		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408134	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, - 118.151685297489	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408135	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, - 118.151685297489	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Brookmill Road - Old River School Road To End - Old River School Road To End Downey, CA 90242	408136	Curb Ramps	Southeast Corner Of Old River School Road @ 33.943294305110, - 118.151685297489	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90242	413273	Curb Ramps	Southeast Corner Of Morning Avenue @ 33.939070893384, - 118.143609166145		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90242	413274	Curb Ramps	Southeast Corner Of Morning Avenue @ 33.939070893384, - 118.143609166145	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90242	413275	Curb Ramps	Southeast Corner Of Morning Avenue @ 33.939070893384, - 118.143609166145	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90242	413281	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90242	413282	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413283	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413285	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413286	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413284	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.939215534237, - 118.143733888865	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413287	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.940162369442, - 118.145588636398	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookmill Road - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	413288	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.940295882372, - 118.145490735769	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450849	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450850	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450851	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450852	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450855	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450856	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450853	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450854	Curb Ramps	Northeast Corner of True Avenue @ 33.947500819619, - 118.099772483110	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450857	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450858	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450859	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450860	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450865	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450866	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450861	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450862	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450863	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450864	Curb Ramps	Northwest Corner of Pico Vista Road @ 33.946901173154, - 118.098784089088	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450869	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450870	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090		Curb Ramp Width	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450871	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450872	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450876	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450877	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450873	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450874	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450875	Curb Ramps	Southeast Corner of Pico Vista Road @ 33.946762107972, - 118.098873943090	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450878	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450879	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450880	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450881	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450882	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450883	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450884	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - Pico Vista Road to True Avenue - Pico Vista Road to True Avenue	450885	Curb Ramps	Southeast Corner of True Avenue @ 33.947369543018, - 118.099863678217	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451838	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451839	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451840	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451841	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451842	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451843	Curb Ramps	Northwest Corner of Songfest Drive @ 33.949612342555, - 118.101316094399	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451847	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451848	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039		Curb Ramp Width	Provide a compliant curb ramp.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451849	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451850	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451852	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451853	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451851	Curb Ramps	Southwest Corner of True Avenue @ 33.947600945704, - 118.099899888039	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451854	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.948632237528, - 118.100657612085		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451855	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.948632237528, - 118.100657612085		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451856	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.948632237528, - 118.100657612085		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451857	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.948632237528, - 118.100657612085	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451858	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.948632237528, - 118.100657612085	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451859	Curb Ramps	Northeast Corner of Klinedale Avenue @ 33.948514312666, - 118.100581169128		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451860	Curb Ramps	Northeast Corner of Klinedale Avenue @ 33.948514312666, - 118.100581169128		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451861	Curb Ramps	Northeast Corner of Klinedale Avenue @ 33.948514312666, - 118.100581169128		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451862	Curb Ramps	Northeast Corner of Klinedale Avenue @ 33.948514312666, - 118.100581169128	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451863	Curb Ramps	Northeast Corner of Klinedale Avenue @ 33.948514312666, - 118.100581169128	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451864	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451865	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451866	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451869	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451867	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451868	Curb Ramps	Northeast Corner of Songfest Drive @ 33.949495531538, - 118.101235628128	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookpark Road - True Avenue to Cord Avenue - True Avenue to Cord Avenue	451870	Curb Ramps	Northwest Corner of True Avenue @ 33.947736671987, - 118.099801987410		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookpark Road - True Avenue to Cord Avenue - True Avenue	451871	Curb Ramps	Northwest Corner of True Avenue @ 33.947736671987, - 118.099801987410		Curb Ramp Width	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue	451872	Curb Ramps	Northwest Corner of True Avenue @ 33.947736671987, - 118.099801987410		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue	451873	Curb Ramps	Northwest Corner of True Avenue @ 33.947736671987, - 118.099801987410		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookpark Road - True Avenue to Cord Avenue - True Avenue	451874	Curb Ramps	Northwest Corner of True Avenue @ 33.947736671987, - 118.099801987410	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive	436387	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive	436388	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive	436389	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive	436390	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive	436391	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive Downey, CA 90240	436392	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive Downey, CA 90240	436431	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.939946523095, - 118.128165006638	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive Downey, CA 90240	436432	Curb Ramps	Northeast Corner of Civic Center Drive @ 33.939946523095, - 118.128165006638	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue & Civic Center Drive - Brookshire Avenue & Civic Center Drive Downey, CA 90240	436433	Curb Ramps	Southeast Corner of Civic Center Drive @ 33.939915369969, - 118.128492236137	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Firestone Boulevard to 6th Street - Firestone Boulevard to 6th Street Downey, CA 90242	478960	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.941058014674, - 118.127632588148		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/20
Brookshire Avenue - Firestone Boulevard to 6th Street - Firestone Boulevard to 6th Street Downey, CA 90242	478961	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.941058014674, - 118.127632588148		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Firestone Boulevard to 6th Street - Firestone Boulevard to 6th Street Downey, CA 90242	478962	Curb Ramps	Southwest Corner of Civic Center Drive @ 33.941058014674, - 118.127632588148	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Firestone Boulevard to 6th Street - Firestone Boulevard to 6th Street Downey, CA 90242	478992	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.941161486124, - 118.127532005310		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/20
Brookshire Avenue - Firestone Boulevard to 6th Street - Firestone Boulevard to 6th Street Downey, CA 90242	478993	Curb Ramps	Northwest Corner of Civic Center Drive @ 33.941161486124, - 118.127532005310		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478924	Curb Ramps	Northwest Corner of Muller Street @ 33.943831673610, - 118.125673234463		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478925	Curb Ramps	Northwest Corner of Muller Street @ 33.943831673610, - 118.125673234463		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478926	Curb Ramps	Northwest Corner of Muller Street @ 33.943831673610, - 118.125673234463		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478927	Curb Ramps	Northwest Corner of Muller Street @ 33.943831673610, - 118.125673234463		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478928	Curb Ramps	Northwest Corner of Muller Street @ 33.943831673610, - 118.125673234463	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	479048	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	479049	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	479050	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	479051	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478933	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Florence Avenue to 6th Street - Florence Avenue to 6th Street Downey, CA 90242	478934	Curb Ramps	Southwest Corner of Muller Street @ 33.943684815475, - 118.125736266375	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351787	Curb Ramps	Northwest Corner Of Borson Street @ 33.918016353275, - 118.145360648632		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351788	Curb Ramps	Northwest Corner Of Borson Street @ 33.918016353275, - 118.145360648632		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351789	Curb Ramps	Northwest Corner Of Borson Street @ 33.918016353275, - 118.145360648632	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351790	Curb Ramps	Northwest Corner Of Borson Street @ 33.918016353275, - 118.145360648632	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351791	Curb Ramps	Northwest Corner Of Comolette Street @ 33.916816640830, - 118.146259188652		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351792	Curb Ramps	Northwest Corner Of Comolette Street @ 33.916816640830, - 118.146259188652		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	351793	Curb Ramps	Southwest Corner Of Dalen Street @ 33.918477091784, - 118.145007938147		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351794	Curb Ramps	Southwest Corner Of Dalen Street @ 33.918477091784, - 118.145007938147		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351795	Curb Ramps	Southwest Corner Of Dalen Street @ 33.918477091784, - 118.145007938147	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351796	Curb Ramps	Southwest Corner Of Puritan Street @ 33.914934683103, - 118.147707581520		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351797	Curb Ramps	Southwest Corner Of Puritan Street @ 33.914934683103, - 118.147707581520		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351798	Curb Ramps	Southwest Corner Of Puritan Street @ 33.914934683103, - 118.147707581520	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351799	Curb Ramps	Southwest Corner Of Puritan Street @ 33.914934683103, - 118.147707581520	Bottom Landing	Bottom Landing Change in Level due to Overlayment - Beveled	Ensure the change in elevation is within the recommended height.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351800	Curb Ramps	Southwest Corner Of Lyndora Street @ 33.919055793629, - 118.144557327032		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351801	Curb Ramps	Southwest Corner Of Lyndora Street @ 33.919055793629, - 118.144557327032		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351802	Curb Ramps	Southwest Corner Of Lyndora Street @ 33.919055793629, - 118.144557327032	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351803	Curb Ramps	Southwest Corner Of Lyndora Street @ 33.919055793629, - 118.144557327032	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351804	Curb Ramps	Southwest Corner Of Adoree Street @ 33.917282950364, - 118.145897090435		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351805	Curb Ramps	Southwest Corner Of Adoree Street @ 33.917282950364, - 118.145897090435		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351806	Curb Ramps	Southwest Corner Of Devenir Street @ 33.916067646666, - 118.146837204695		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351807	Curb Ramps	Southwest Corner Of Devenir Street @ 33.916067646666, - 118.146837204695		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351808	Curb Ramps	Southwest Corner Of Devenir Street @ 33.916067646666, - 118.146837204695	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351809	Curb Ramps	Southwest Corner Of Borson Street @ 33.917873902217, - 118.145462572575		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351810	Curb Ramps	Southwest Corner Of Borson Street @ 33.917873902217, - 118.145462572575		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351811	Curb Ramps	Southwest Corner Of Borson Street @ 33.917873902217, - 118.145462572575	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351812	Curb Ramps	Southwest Corner Of Borson Street @ 33.917873902217, - 118.145462572575	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351863	Curb Ramps	Northwest Corner Of Adoree Street @ 33.917417612070, - 118.145795166492		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351864	Curb Ramps	Northwest Corner Of Adoree Street @ 33.917417612070, - 118.145795166492		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351865	Curb Ramps	Northwest Corner Of Dalen Street @ 33.918607342, - 118.144903331995		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351866	Curb Ramps	Northwest Corner Of Dalen Street @ 33.918607342, - 118.144903331995		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	351867	Curb Ramps	Northwest Corner Of Dalen Street @ 33.918607342, - 118.144903331995		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351868	Curb Ramps	Northwest Corner Of Devenir Street @ 33.916204536136, - 118.146736621857		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351869	Curb Ramps	Northwest Corner Of Devenir Street @ 33.916204536136, - 118.146736621857		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351870	Curb Ramps	Northwest Corner Of Devenir Street @ 33.916204536136, - 118.146736621857	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351871	Curb Ramps	Northwest Corner Of Devenir Street @ 33.916204536136, - 118.146736621857	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351872	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.919214935947, - 118.144454061985		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351873	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.919214935947, - 118.144454061985		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351874	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.919214935947, - 118.144454061985	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351875	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.919214935947, - 118.144454061985	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351876	Curb Ramps	Southwest Corner Of Comolette Street @ 33.916675300682, - 118.146390616894		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351877	Curb Ramps	Southwest Corner Of Comolette Street @ 33.916675300682, - 118.146390616894		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351878	Curb Ramps	Southwest Corner Of Comolette Street @ 33.916675300682, - 118.146390616894		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351880	Curb Ramps	Southwest Corner Of Comolette Street @ 33.916675300682, - 118.146390616894	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351879	Curb Ramps	Southwest Corner Of Comolette Street @ 33.916675300682, - 118.146390616894	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351881	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351882	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351883	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351884	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351885	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	351886	Curb Ramps	Northwest Corner Of Puritan Street @ 33.915076026138, - 118.147580176592	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352595	Curb Ramps	Southeast Corner Of Puritan Street @ 33.914629737489, - 118.147633820772		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352596	Curb Ramps	Southeast Corner Of Puritan Street @ 33.914629737489, - 118.147633820772		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352597	Curb Ramps	Southeast Corner Of Puritan Street @ 33.914629737489, - 118.147633820772	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352598	Curb Ramps	Northeast Corner Of Puritan Street @ 33.914786662193, - 118.147517144680		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352599	Curb Ramps	Northeast Corner Of Puritan Street @ 33.914786662193, - 118.147517144680		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352600	Curb Ramps	Northeast Corner Of Puritan Street @ 33.914786662193, - 118.147517144680		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352602	Curb Ramps	Northeast Corner Of Puritan Street @ 33.914786662193, - 118.147517144680	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352601	Curb Ramps	Northeast Corner Of Puritan Street @ 33.914786662193, - 118.147517144680	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352603	Curb Ramps	Southeast Corner Of Adoree Street @ 33.917170546629, - 118.145709335804		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352604	Curb Ramps	Southeast Corner Of Adoree Street @ 33.917170546629, - 118.145709335804		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352605	Curb Ramps	Southeast Corner Of Adoree Street @ 33.917170546629, - 118.145709335804	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352606	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352607	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352611	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352608	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352609	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352610	Curb Ramps	Northeast Corner Of Adoree Street @ 33.917307434326, - 118.145606070757	Bottom Landing	Bottom Landing Change in Level due to Overlayment - Beveled	Ensure the change in elevation is within the recommended height.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352612	Curb Ramps	Northeast Corner Of Comolette Street @ 33.916710913970, - 118.146063387394		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352613	Curb Ramps	Northeast Corner Of Comolette Street @ 33.916710913970, - 118.146063387394		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352614	Curb Ramps	Northeast Corner Of Comolette Street @ 33.916710913970, - 118.146063387394	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway - Downey, CA 90242	352615	Curb Ramps	Northeast Corner Of Comolette Street @ 33.916710913970, - 118.146063387394	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352616	Curb Ramps	Northeast Corner Of Comolette Street @ 33.916710913970, - 118.146063387394	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352618	Curb Ramps	Southeast Corner Of Devenir Street @ 33.915953015478, - 118.146613240242	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352617	Curb Ramps	Southeast Corner Of Devenir Street @ 33.915953015478, - 118.146613240242	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352619	Curb Ramps	Northeast Corner Of Devenir Street @ 33.916076550053, - 118.146515339613		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352620	Curb Ramps	Northeast Corner Of Devenir Street @ 33.916076550053, - 118.146515339613	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352621	Curb Ramps	Northeast Corner Of Devenir Street @ 33.916076550053, - 118.146515339613	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352675	Curb Ramps	Southeast Corner Of Comolette Street @ 33.916566234896, - 118.146126419306		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352676	Curb Ramps	Southeast Corner Of Comolette Street @ 33.916566234896, - 118.146126419306		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	352678	Curb Ramps	Southeast Corner Of Comolette Street @ 33.916566234896, - 118.146126419306	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	352679	Curb Ramps	Southeast Corner Of Comolette Street @ 33.916566234896, - 118.146126419306	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	352677	Curb Ramps	Southeast Corner Of Comolette Street @ 33.916566234896, - 118.146126419306	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476569	Curb Ramps	Southwest Corner of Luxor Street @ 33.932554011739, - 118.134146332741		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476570	Curb Ramps	Southwest Corner of Luxor Street @ 33.932554011739, - 118.134146332741	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476612	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476613	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476614	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476615	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476616	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476617	Curb Ramps	East Side South of Iowa Street - 1st @ 33.935230032542, - 118.131828904152	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476618	Curb Ramps	Northwest Corner of Davis Street @ 33.935212229771, - 118.132149428129	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	476658	Curb Ramps	East Side South of Iowa Street - 2nd @ 33.935098737018, - 118.131929486990	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321876	Curb Ramps	Northwest Corner Of Eucalyptus Street @ 33.922855096198, - 118.141323924065		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321877	Curb Ramps	Northwest Corner Of Eucalyptus Street @ 33.922855096198, - 118.141323924065	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321879	Curb Ramps	Southeast Corner Of Boyne Street @ 33.927533325051, - 118.137622475624	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330819	Curb Ramps	Southwest Corner Of Everest Street @ 33.921964823742, - 118.142176866531		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330820	Curb Ramps	Southwest Corner Of Everest Street @ 33.921964823742, - 118.142176866531		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321886	Curb Ramps	Northeast Corner Of Boyne Street @ 33.927631249075, - 118.137542009354		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321887	Curb Ramps	Northeast Corner Of Boyne Street @ 33.927631249075, - 118.137542009354		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321888	Curb Ramps	Northeast Corner Of Boyne Street @ 33.927631249075, - 118.137542009354	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321891	Curb Ramps	Northeast Corner Of Boyson Street @ 33.925387870451, - 118.139070868492		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321892	Curb Ramps	Northeast Corner Of Boyson Street @ 33.925387870451, - 118.139070868492		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321894	Curb Ramps	Northeast Corner Of Boyson Street @ 33.925387870451, - 118.139070868492	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321893	Curb Ramps	Northeast Corner Of Boyson Street @ 33.925387870451, - 118.139070868492	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321895	Curb Ramps	Southeast Corner Of Cavel Street @ 33.928129769635, - 118.137150406837	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321896	Curb Ramps	Southeast Corner Of Alameda Street @ 33.926180181555, - 118.138502240181	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321897	Curb Ramps	Northeast Corner Of Cavel Street @ 33.928263301432, - 118.137027025223		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330821	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.919886001333, - 118.143652081490		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321900	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.919886001333, - 118.143652081490	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321924	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.930533309955, - 118.135299682617	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321925	Curb Ramps	Northeast Corner Of Eucalyptus Street @ 33.922721555923, - 118.141152262688		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322858	Curb Ramps	Northeast Corner Of Albia Street @ 33.926990289783, - 118.138003349304		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330822	Curb Ramps	Southwest Corner Of Eucalyptus Street @ 33.922757166683, - 118.141436576843		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321929	Curb Ramps	Southeast Corner Of Orange Street @ 33.924328476674, - 118.139929175377	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321930	Curb Ramps	Northeast Corner Of Everest Street @ 33.921947018198, - 118.141838908195		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321932	Curb Ramps	Northeast Corner Of Donovan Street @ 33.923602917872, - 118.140476346016	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321933	Curb Ramps	Southeast Corner Of Eucalyptus Street @ 33.922596918144, - 118.141248822212	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321934	Curb Ramps	Northeast Corner Of Orange Street @ 33.924346281720, - 118.139848709106		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321935	Curb Ramps	Northeast Corner Of Orange Street @ 33.924346281720, - 118.139848709106	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321937	Curb Ramps	Southeast Corner Of Boyson Street @ 33.925236529289, - 118.139210343361	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322860	Curb Ramps	Northeast Corner Of Alameda Street @ 33.926318167567, - 118.138411045074		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322861	Curb Ramps	Northeast Corner Of Alameda Street @ 33.926318167567, - 118.138411045074		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321940	Curb Ramps	Northeast Corner Of Alameda Street @ 33.926318167567, - 118.138411045074	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321941	Curb Ramps	Northeast Corner Of Alameda Street @ 33.926318167567, - 118.138411045074	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322862	Curb Ramps	Northwest Corner Of Cavel Street @ 33.928379028820, - 118.137295246124		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322863	Curb Ramps	Northwest Corner Of Cavel Street @ 33.928379028820, - 118.137295246124	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322864	Curb Ramps	Southwest Corner Of Albia Street @ 33.926954680792, - 118.138330578804		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322865	Curb Ramps	Southwest Corner Of Albia Street @ 33.926954680792, - 118.138330578804		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322866	Curb Ramps	Southwest Corner Of Albia Street @ 33.926954680792, - 118.138330578804		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330823	Curb Ramps	Southwest Corner Of Alameda Street @ 33.926304814091, - 118.138732910156		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322869	Curb Ramps	Southwest Corner Of Alameda Street @ 33.926304814091, - 118.138732910156	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322870	Curb Ramps	Northwest Corner Of Alameda Street @ 33.926438348750, - 118.138641715050		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322871	Curb Ramps	Northwest Corner Of Alameda Street @ 33.926438348750, - 118.138641715050		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322872	Curb Ramps	Northwest Corner Of Alameda Street @ 33.926438348750, - 118.138641715050		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330824	Curb Ramps	Northwest Corner Of Byers Street @ 33.928926506256, - 118.136790990829		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330825	Curb Ramps	Northwest Corner Of Byers Street @ 33.928926506256, - 118.136790990829		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330826	Curb Ramps	Southwest Corner Of Cavel Street @ 33.928245497204, - 118.137381076813		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330827	Curb Ramps	Southwest Corner Of Cavel Street @ 33.928245497204, - 118.137381076813		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330828	Curb Ramps	Southwest Corner Of Cavel Street @ 33.928245497204, - 118.137381076813		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322880	Curb Ramps	Southwest Corner Of Cavel Street @ 33.928245497204, - 118.137381076813	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322881	Curb Ramps	Southwest Corner Of Donovan Street @ 33.923536148346, - 118.140835762024	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322882	Curb Ramps	Northwest Corner Of Boyne Street @ 33.927715819733, - 118.137767314911		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322883	Curb Ramps	Northwest Corner Of Boyne Street @ 33.927715819733, - 118.137767314911		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322884	Curb Ramps	Northwest Corner Of Boyne Street @ 33.927715819733, - 118.137767314911	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322885	Curb Ramps	Northwest Corner Of Boyne Street @ 33.927715819733, - 118.137767314911	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322886	Curb Ramps	Northwest Corner Of Orange Street @ 33.924559941985, - 118.140068650246		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322887	Curb Ramps	Northwest Corner Of Orange Street @ 33.924559941985, - 118.140068650246	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322888	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.930657936122, - 118.135535717010		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322889	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.930657936122, - 118.135535717010		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322891	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.930657936122, - 118.135535717010	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322890	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.930657936122, - 118.135535717010	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330829	Curb Ramps	Southwest Corner Of Byers Street @ 33.928824132694, - 118.136914372444		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330830	Curb Ramps	Southwest Corner Of Byers Street @ 33.928824132694, - 118.136914372444		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330831	Curb Ramps	Southwest Corner Of Byers Street @ 33.928824132694, - 118.136914372444	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330832	Curb Ramps	Southwest Corner Of Boyne Street @ 33.927595640352, - 118.137869238853		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330833	Curb Ramps	Northwest Corner Of Albia Street @ 33.927074861077, - 118.138212561607		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330834	Curb Ramps	Northwest Corner Of Albia Street @ 33.927074861077, - 118.138212561607		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322900	Curb Ramps	Northwest Corner Of Albia Street @ 33.927074861077, - 118.138212561607	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Brookshire Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	322901	Curb Ramps	Northwest Corner Of Donovan Street @ 33.923705297709, - 118.140717744827		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Buckles Street - Lakewood Boulevard to Bellman Avenue - Lakewood Boulevard to Bellman Avenue Downey, CA 90242	477440	Curb Ramps	Southwest Corner of Lakewood Boulevard @ 33.929954686077, - 118.128325939178	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Buckles Street - Bellflower Boulevard To Lakewood Boulevard - Bellflower Boulevard To Lakewood Boulevard Downey, CA 90241	317657	Curb Ramps	Southeast Corner Of Lakewood Boulevard @ 33.929905725415, - 118.128014802933	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Buckles Street - Bellflower Boulevard To Lakewood Boulevard - Bellflower Boulevard To Lakewood Boulevard Downey, CA 90241	317658	Curb Ramps	Northeast Corner Of Lakewood Boulevard @ 33.930034803464, - 118.127848505974	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Buell Street - Pangborn Avenue To Lesterford Avenue - Buell Street To Lesterford Avenue	419711	Curb Ramps	Northwest Corner Of Lesterford Avenue @ 33.933455300487, - 118.108155727386		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Buell Street - Pangborn Avenue To Lesterford Avenue - Buell Street To Lesterford Avenue	419712	Curb Ramps	Northwest Corner Of Lesterford Avenue @ 33.933455300487, - 118.108155727386		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Buell Street - Pangborn Avenue To Lesterford Avenue - Buell Street To Lesterford Avenue	419713	Curb Ramps	Northwest Corner Of Lesterford Avenue @ 33.933455300487, - 118.108155727386	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Buhman Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	448395	Curb Ramps	Southwest Corner of Cedartree Road @ 33.954736294720, - 118.103160113096	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Buhman Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	448394	Curb Ramps	Southwest Corner of Cedartree Road @ 33.954736294720, - 118.103160113096	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419210	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419211	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419212	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419213	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419214	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419215	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419216	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.943780495804, - 118.142860829830	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419217	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, - 118.138936758041		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419218	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, -118.138936758041		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419219	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, -118.138936758041		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419220	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, -118.138936758041		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419221	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, -118.138936758041	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419222	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.941665490425, -118.138936758041	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419223	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419224	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419225	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419226	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419227	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419228	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/20
Burns Avenue - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	419229	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.941745596794, -118.138877749443	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Calmcrest Drive - Tweedy Lane to Cul-de-sac - Tweedy Lane to Cul-de-sac Downey, CA 90240	356714	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.961077954125, - 118.126911073923	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Calmcrest Drive - Tweedy Lane to Cul-de-sac - Tweedy Lane to Cul-de-sac Downey, CA 90240	356731	Curb Ramps	Northwest Corner Of Tweedy Lane @ 33.961203647912, - 118.126813173294	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Calmcrest Drive - Tweedy Lane to Cul-de-sac - Tweedy Lane to Cul-de-sac Downey, CA 90240	356730	Curb Ramps	Northwest Corner Of Tweedy Lane @ 33.961203647912, - 118.126813173294	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312376	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904014946850, - 118.146969974041		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312377	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904014946850, - 118.146969974041	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312378	Curb Ramps	Southeast Corner Of Reydon Street @ 33.907246159172, - 118.145398199558		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312379	Curb Ramps	Southeast Corner Of Reydon Street @ 33.907246159172, - 118.145398199558		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312380	Curb Ramps	Southeast Corner Of Reydon Street @ 33.907246159172, - 118.145398199558		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312382	Curb Ramps	Southeast Corner Of Reydon Street @ 33.907246159172, - 118.145398199558	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312381	Curb Ramps	Southeast Corner Of Reydon Street @ 33.907246159172, - 118.145398199558	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312388	Curb Ramps	Southeast Corner Of Deming Avenue @ 33.908472718895, - 118.144197911024		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Castana Avenue - Rosecrans Avenue To Deming Avenue - Rosecrans Avenue To Deming Avenue Downey, CA 90242	312389	Curb Ramps	Southeast Corner Of Deming Avenue @ 33.908472718895, - 118.144197911024	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cecilia Street - Woodruff Avenue to Lakewood Boulevard · Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444093	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cecilia Street - Woodruff Avenue to Lakewood Boulevard · Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444094	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/20	
Cecilia Street - Woodruff Avenue to Lakewood Boulevard · Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444095	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cecilia Street - Woodruff Avenue to Lakewood Boulevard - Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444096	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cecilia Street - Woodruff Avenue to Lakewood Boulevard - Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444097	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Cecilia Street - Woodruff Avenue to Lakewood Boulevard - Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444098	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cecilia Street - Woodruff Avenue to Lakewood Boulevard - Woodruff Avenue to Lakewood Boulevard Downey, CA 90242	444099	Curb Ramps	Southwest Corner of Woodruff Avenue @ 33.936156884173, - 118.115176409483	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cedartree Road - Stamps Road to Stoakes Avenue - Stamps Road to Stoakes Avenue Downey, CA 90242	452732	Curb Ramps	Northeast Corner of Stamps Road @ 33.962720857371, - 118.112959563732	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cedartree Road - True Avenue to Klinedale Avenue - True Avenue to Klinedale Avenue Downey, CA 90242	450824	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.951152008022, - 118.097393363714		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cedartree Road - True Avenue to Klinedale Avenue - True Avenue to Klinedale Avenue Downey, CA 90242	450825	Curb Ramps	Northwest Corner of Klinedale Avenue @ 33.951152008022, - 118.097393363714	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Century Boulevard - End To Downey Avenue - End To Downey Avenue Downey, CA 90242	311201	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.906155374356, - 118.151370137930	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Century Boulevard - Klondike Avenue To Downey Avenue - Klondike Avenue To Downey Avenue Downey, CA 90242	314247	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.906577220343, - 118.151651769876	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Century Boulevard - Klondike Avenue To Downey Avenue - Klondike Avenue To Downey Avenue Downey, CA 90242	314248	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.906577220343, - 118.151651769876	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448897	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448898	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448899	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448361	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448362	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448363	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Chaney Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448364	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956171302005, - 118.105218708515	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Charloma Drive - Brookshire Avenue to Stamps Avenue - Brookshire Avenue to Stamps Avenue Downey, CA 90242	467388	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.953610520126, - 118.118926137686		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/20	
Charloma Drive - Brookshire Avenue to Stamps Avenue - Brookshire Avenue to Stamps Avenue Downey, CA 90242	467307	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.953489264860, - 118.119100481272	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Charloma Drive - Brookshire Avenue to Stamps Avenue - Brookshire Avenue to Stamps Avenue Downey, CA 90242	467306	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.953489264860, - 118.119100481272	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349484	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349485	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349486	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349487	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349488	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349491	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349489	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349490	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.945657366091, - 118.124804198742	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349492	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.945915474239, - 118.124910145998		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349493	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.945915474239, - 118.124910145998	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349494	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.945915474239, - 118.124910145998	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349495	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.945915474239, - 118.124910145998	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349528	Curb Ramps	Northwest Corner Of Stamps Road @ 33.947214903372, - 118.127419352531	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349529	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.946636392852, - 118.126280754805		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349530	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.946636392852, - 118.126280754805	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349531	Curb Ramps	Northwest Corner Of Tristan Drive @ 33.943986319403, - 118.121053129435		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349532	Curb Ramps	Northwest Corner Of Tristan Drive @ 33.943986319403, - 118.121053129435		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349533	Curb Ramps	Northwest Corner Of Tristan Drive @ 33.943986319403, - 118.121053129435	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349534	Curb Ramps	Northwest Corner Of Tristan Drive @ 33.943986319403, - 118.121053129435	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349535	Curb Ramps	Northwest Corner Of Tristan Drive @ 33.943986319403, - 118.121053129435	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349536	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349537	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349538	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349541	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349542	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349539	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349540	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.944273359050, - 118.122046887875	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349543	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349544	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349545	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349546	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349547	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349548	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.945773069840, - 118.125025480986	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349549	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349550	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349551	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349552	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349555	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349553	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	349554	Curb Ramps	Southeast Corner Of Dolan Avenue @ 33.946589666830, - 118.126599937677	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	353533	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.943326569567, - 118.119577914476		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cherokee Drive - Downey Avenue To Lakewood Boulevard - Downey Avenue To Lakewood Boulevard Downey, CA 90241	353534	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.943326569567, - 118.119577914476	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400986	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400987	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400988	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400991	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400989	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400990	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.913808382194, - 118.142760246992	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	400999	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401000	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401001	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401002	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401003	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401004	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.913732701362, - 118.143941760063	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401005	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401006	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401007	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401010	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401011	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401008	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	401009	Curb Ramps	Northwest Corner Of Airpoint Avenue @ 33.913748282716, - 118.143033832312	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400953	Curb Ramps	Northeast Corner Of Sandy Lane @ 33.913611389300, - 118.145305663347		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400954	Curb Ramps	Northeast Corner Of Sandy Lane @ 33.913611389300, - 118.145305663347		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400955	Curb Ramps	Northeast Corner Of Sandy Lane @ 33.913611389300, - 118.145305663347		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400956	Curb Ramps	Northeast Corner Of Sandy Lane @ 33.913611389300, - 118.145305663347	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400957	Curb Ramps	Northeast Corner Of Sandy Lane @ 33.913611389300, - 118.145305663347	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400959	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400960	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400961	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400964	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400962	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400963	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.913543498989, - 118.144369572401	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400965	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400966	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400967	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400970	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400968	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400969	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.913685957286, - 118.144234120846	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400971	Curb Ramps	Northwest Corner Of Sandy Lane @ 33.913563532201, - 118.145627528429		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400972	Curb Ramps	Northwest Corner Of Sandy Lane @ 33.913563532201, - 118.145627528429		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400973	Curb Ramps	Northwest Corner Of Sandy Lane @ 33.913563532201, - 118.145627528429		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400974	Curb Ramps	Northwest Corner Of Sandy Lane @ 33.913563532201, - 118.145627528429	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Laureldale Avenue To Barlin Avenue - Laureldale Avenue To Barlin Avenue Downey, CA 90242	400975	Curb Ramps	Northwest Corner Of Sandy Lane @ 33.913563532201, - 118.145627528429	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328366	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.918568348875, - 118.155979514122		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328367	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.918568348875, - 118.155979514122		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328368	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.918568348875, - 118.155979514122		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328369	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.918568348875, - 118.155979514122	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328370	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.918568348875, - 118.155979514122	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328371	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.916974674418, - 118.152471184731		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328372	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.916974674418, - 118.152471184731		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328373	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.916974674418, - 118.152471184731		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328374	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.916974674418, - 118.152471184731	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328375	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.916974674418, - 118.152471184731	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328376	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.917802676599, - 118.154472112656		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328377	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.917802676599, - 118.154472112656		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328378	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.917802676599, - 118.154472112656		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328380	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.917802676599, - 118.154472112656	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328379	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.917802676599, - 118.154472112656	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328381	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.917900611809, - 118.154354095459		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328382	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.917900611809, - 118.154354095459		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328383	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.917900611809, - 118.154354095459	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328384	Curb Ramps	Northwest Corner Of Downey Ave @ 33.916186729388, - 118.150920867920		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328385	Curb Ramps	Northwest Corner Of Downey Ave @ 33.916186729388, - 118.150920867920		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328386	Curb Ramps	Northwest Corner Of Downey Ave @ 33.916186729388, - 118.150920867920	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328387	Curb Ramps	Northwest Corner Of Downey Ave @ 33.916186729388, - 118.150920867920	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328388	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.917063707297, - 118.152685761452		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328389	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.917063707297, - 118.152685761452		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328390	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.917063707297, - 118.152685761452		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328391	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.917063707297, - 118.152685761452	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328392	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.917833837814, - 118.154182434082		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328393	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.917833837814, - 118.154182434082		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328394	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.917833837814, - 118.154182434082		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328395	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.917833837814, - 118.154182434082		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328404	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918661831646, - 118.155818581581		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328405	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918661831646, - 118.155818581581		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328406	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918661831646, - 118.155818581581		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328407	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918661831646, - 118.155818581581	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328408	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.916827769965, - 118.152567744255		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328409	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.916827769965, - 118.152567744255		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328410	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.916827769965, - 118.152567744255		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328411	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.916827769965, - 118.152567744255	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328412	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917575644544, - 118.154059052467		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328413	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917575644544, - 118.154059052467		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328414	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917575644544, - 118.154059052467		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328415	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917575644544, - 118.154059052467	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave	328416	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917575644544, - 118.154059052467	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328417	Curb Ramps	Southwest Corner Of Downey Ave @ 33.916070985436, - 118.151012063026		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328418	Curb Ramps	Southwest Corner Of Downey Ave @ 33.916070985436, - 118.151012063026		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/20
Cheyenne Street - Paramount Boulevard To Downey Ave - Paramount Boulevard To Downey Ave Downey, CA 90424	328419	Curb Ramps	Southwest Corner Of Downey Ave @ 33.916070985436, - 118.151012063026	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435756	Curb Ramps	Northeast Corner of Imperial Highway @ 33.922641431657, - 118.148844838142		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435757	Curb Ramps	Northeast Corner of Imperial Highway @ 33.922641431657, - 118.148844838142		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435758	Curb Ramps	Southwest Corner of Imperial Highway @ 33.922641431657, - 118.148844838142		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435759	Curb Ramps	Southwest Corner of Imperial Highway @ 33.922641431657, -118.148844838142		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435760	Curb Ramps	Southwest Corner of Imperial Highway @ 33.922641431657, -118.148844838142	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435761	Curb Ramps	Northwest Corner of Imperial Highway @ 33.922641431657, -118.148844838142		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/20
Citizenship Court Road & Imperial Highway - Citizenship Court Road & Imperial Highway Downey, CA 90240	435762	Curb Ramps	Northwest Corner of Imperial Highway @ 33.922641431657, -118.148844838142	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/20
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479603	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, -118.128870427608		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/20
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479604	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, -118.128870427608		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/20
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479605	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, -118.128870427608		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/20

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479406	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, - 118.128870427608	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479407	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, - 118.128870427608	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479404	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, - 118.128870427608	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479405	Curb Ramps	East Side North of 3rd Street - 3rd @ 33.941541992958, - 118.128870427608	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479606	Curb Ramps	East Side North of 3rd Street - 1st @ 33.941422945681, - 118.129245936871		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479607	Curb Ramps	East Side North of 3rd Street - 1st @ 33.941422945681, - 118.129245936871		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479608	Curb Ramps	East Side North of 3rd Street - 1st @ 33.941422945681, - 118.129245936871		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479412	Curb Ramps	East Side North of 3rd Street - 1st @ 33.941422945681, - 118.129245936871	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479411	Curb Ramps	East Side North of 3rd Street - 1st @ 33.941422945681, - 118.129245936871	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479609	Curb Ramps	West Side South of Brookshire Avenue - 1st @ 33.941191526199, - 118.127607107162		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479414	Curb Ramps	West Side South of Brookshire Avenue - 1st @ 33.941191526199, - 118.127607107162	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479610	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479611	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479612	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479613	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479419	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/20	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479420	Curb Ramps	East Side North of 3rd Street - 2nd @ 33.941479687862, - 118.129148036242	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479614	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479615	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/20	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479616	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479427	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479428	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479424	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479425	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479426	Curb Ramps	East Side North of 3rd Street - 4th @ 33.941529754461, - 118.128764480352	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479617	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479618	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479619	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479432	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479433	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479434	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479435	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479436	Curb Ramps	East Side North of 3rd Street - 5th @ 33.941086942189, - 118.127883374691	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479620	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479621	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570		Curb Ramp Width	Provide a compliant curb ramp.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479622	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479623	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479624	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479444	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479445	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479442	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479443	Curb Ramps	East Side North of 3rd Street - 6th @ 33.941045776107, - 118.127817660570	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479626	Curb Ramps	West Side South of Brookshire Avenue - 2nd @ 33.941233804806, - 118.127688914537		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/21	
Civic Center Drive - 3rd Street to Brookshire Avenue - 3rd Street to Brookshire Avenue Downey, CA 90242	479459	Curb Ramps	West Side South of Brookshire Avenue - 2nd @ 33.941233804806, - 118.127688914537	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Clancey Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street Downey, CA 90242	446200	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938140735568, - 118.119925260544		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/21	
Clancey Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street Downey, CA 90242	446201	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938140735568, - 118.119925260544		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Clancey Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street Downey, CA 90242	446203	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938140735568, - 118.119925260544	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Clancey Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street Downey, CA 90242	446202	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938140735568, - 118.119925260544	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Clancey Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street Downey, CA 90242	446205	Curb Ramps	Northeast Corner of Cecilia Street @ 33.938066188988, - 118.119775056839		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318370	Curb Ramps	Southeast Corner Of Patton Road @ 33.932527306742, - 118.131136894226		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318377	Curb Ramps	Southwest Corner Of Patton Road @ 33.932589618389, - 118.131276369095		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318378	Curb Ramps	Southwest Corner Of Patton Road @ 33.932589618389, - 118.131276369095	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318404	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934912920124, - 118.136458396912		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318405	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934912920124, - 118.136458396912		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318406	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934912920124, - 118.136458396912		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318407	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934912920124, - 118.136458396912	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318408	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934912920124, - 118.136458396912	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318409	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.934717088708, - 118.136576414108		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318410	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.934717088708, - 118.136576414108		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318411	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.934717088708, - 118.136576414108	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318412	Curb Ramps	Northwest Corner Of Patton Road @ 33.932776553057, - 118.131233453751		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318413	Curb Ramps	Northwest Corner Of Patton Road @ 33.932776553057, - 118.131233453751	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318414	Curb Ramps	Northeast Corner Of Patton Road @ 33.932607421708, - 118.131029605865		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318415	Curb Ramps	Northeast Corner Of Patton Road @ 33.932607421708, - 118.131029605865		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318416	Curb Ramps	Northeast Corner Of Patton Road @ 33.932607421708, - 118.131029605865		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318417	Curb Ramps	Northeast Corner Of Patton Road @ 33.932607421708, - 118.131029605865	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318418	Curb Ramps	Northeast Corner Of Patton Road @ 33.932607421708, - 118.131029605865	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cleta Street - Lakewood Boulevard To Downey Avenue - Lakewood Boulevard To Downey Avenue Downey, CA 90241	318419	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.933417468805, - 118.133583068848	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/21	
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413298	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413299	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945		Curb Ramp Width	Provide a compliant curb ramp.	6/30/21	
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413300	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413301	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413304	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413305	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413302	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413303	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.937489841580, - 118.142002522945	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413312	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413313	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142		Curb Ramp Width	Provide a compliant curb ramp.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413314	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413315	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413317	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cleta Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	413316	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.937355211604, - 118.142120540142	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	326344	Curb Ramps	Southwest Corner Of Angell Street @ 33.912660920013, - 118.122881054878		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	326345	Curb Ramps	Southwest Corner Of Angell Street @ 33.912660920013, - 118.122881054878		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	326346	Curb Ramps	Southwest Corner Of Angell Street @ 33.912660920013, - 118.122881054878		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	319011	Curb Ramps	Southwest Corner Of Angell Street @ 33.912660920013, - 118.122881054878	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	319012	Curb Ramps	Southwest Corner Of Angell Street @ 33.912660920013, - 118.122881054878	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street Coldbrook Avenue - Cul-de-sac to Angell Street Downey, CA 90424	326347	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street								
Coldbrook Avenue - Cul-de-sac to Angell Street	326348	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street								
Coldbrook Avenue - Cul-de-sac to Angell Street	326349	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street								
Coldbrook Avenue - Cul-de-sac to Angell Street	319017	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street								
Coldbrook Avenue - Cul-de-sac to Angell Street	319018	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Coldbrook Avenue - Cul-de-sac to Angell Street - Angell Street								
Coldbrook Avenue - Cul-de-sac to Angell Street	319019	Curb Ramps	Southeast Corner Of Angell Street @ 33.912683179368, - 118.122666478157	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street								
Downey, CA 90424	316879	Curb Ramps	Southeast Corner Of Imperial Highway Service Road @ 33.916807737520, - 118.122671842575		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316880	Curb Ramps	Southeast Corner Of Imperial Highway Service Road @ 33.916807737520, -	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316881	Curb Ramps	Southeast Corner Of Imperial Highway Service Road @ 33.916807737520, -	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316887	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316888	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316889	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316892	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Downey, CA 90424 Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316893	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Downey, CA 90424 Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316890	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/21	
Downey, CA 90424 Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316891	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914072151627, -	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Downey, CA 90424 Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316897	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914072151627, -		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316898	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914072151627, - 118.122685253620		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316899	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914072151627, - 118.122685253620		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Coldbrook Avenue - Imperial Highway Service Road to Adoree Street - Coldbrook Avenue - Imperial Highway Service Road to Adoree Street	316900	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914072151627, - 118.122685253620	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Cole Street - Milta Avenue To Cul-de-sac - Milta Avenue To Cul-de-sac	419055	Curb Ramps	Southeast Corner Of Pernell Avenue @ 33.942225120843, - 118.159824460745	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cole Street - Milta Avenue To Cul-de-sac - Milta Avenue To Cul-de-sac	419056	Curb Ramps	Southeast Corner Of Pernell Avenue @ 33.942225120843, - 118.159824460745	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Cole Street - Milta Avenue To Cul-de-sac - Milta Avenue To Cul-de-sac	419057	Curb Ramps	Southwest Corner Of Pernell Avenue @ 33.942143902342, - 118.159680962563	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	319644	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.931067420815, - 118.139317631721		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319645	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.931067420815, - 118.139317631721		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319646	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.931067420815, - 118.139317631721		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319647	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.931067420815, - 118.139317631721	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319648	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.931058518995, - 118.139585852623		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319649	Curb Ramps	Southwest Corner Of Patton Road @ 33.928770720352, - 118.134173154831		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319650	Curb Ramps	Southwest Corner Of Patton Road @ 33.928770720352, - 118.134173154831	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road	Downey, CA 90241 319651	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.933341805391, - 118.144708871841		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319652	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.933341805391, - 118.144708871841		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319653	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.933341805391, - 118.144708871841		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319654	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.933341805391, - 118.144708871841	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319674	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.933177125965, - 118.144735693932		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319675	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.933177125965, - 118.144735693932		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319676	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.933177125965, - 118.144735693932		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319677	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.933177125965, - 118.144735693932	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319678	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.930942795248, - 118.139414191246		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319679	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.930942795248, - 118.139414191246	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319681	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.929545196034, - 118.136088252068	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319683	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.931160889871, - 118.139537572861		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319684	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.931160889871, - 118.139537572861	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319685	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.929723235425, - 118.136195540428		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Patton Road - Paramount Boulevard To Patton Road Downey, CA 90241	319686	Curb Ramps	Northwest Corner Of Brookshire Avenue @ 33.929723235425, - 118.136195540428		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330787	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.935602777208, - 118.149005770683		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330788	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330789	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330790	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330791	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	320306	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	320307	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.935086497594, - 118.147602975369	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	320324	Curb Ramps	Northwest Corner Of Smallwood Avenue @ 33.935122103185, - 118.147739768028		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	320325	Curb Ramps	Northwest Corner Of Smallwood Avenue @ 33.935122103185, - 118.147739768028		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	320326	Curb Ramps	Northwest Corner Of Smallwood Avenue @ 33.935122103185, - 118.147739768028		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	320327	Curb Ramps	Northwest Corner Of Smallwood Avenue @ 33.935122103185, - 118.147739768028	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	330792	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.933539865361, - 118.144944906235		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	330793	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.933539865361, - 118.144944906235		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue	330794	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.933539865361, - 118.144944906235		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330795	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.933539865361, - 118.144944906235	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330796	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.933671163289, - 118.144842982292		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330797	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.933671163289, - 118.144842982292		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330798	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.933671163289, - 118.144842982292		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	330799	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.933671163289, - 118.144842982292	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	320335	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.933671163289, - 118.144842982292	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	320336	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.935729621289, - 118.148914575577		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cole Street - Paramount Boulevard To Rives Avenue - Paramount Boulevard To Rives Avenue Downey, CA 90241	320337	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.935729621289, - 118.148914575577	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Colombia Way - Foster Road to Lakewood Boulevard · Colombia Way - Foster Road to Lakewood Boulevard Downey, CA 90706	311924	Curb Ramps	Southwest Corner Of Angell Street @ 33.912177890574, - 118.134269714355	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Colombia Way - Foster Road to Lakewood Boulevard · Colombia Way - Foster Road to Lakewood Boulevard Downey, CA 90706	311925	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911345381799, - 118.134253621101	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Colombia Way - Foster Road to Lakewood Boulevard · Colombia Way - Foster Road to Lakewood Boulevard Downey, CA 90706	322321	Curb Ramps	Northwest Corner Of Priscilla Street @ 33.911507877466, - 118.134240210056		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Colombia Way - Foster Road to Lakewood Boulevard · Colombia Way - Foster Road to Lakewood Boulevard Downey, CA 90706	311958	Curb Ramps	Northwest Corner Of Angell Street @ 33.912351514374, - 118.134250938892	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436814	Curb Ramps	Northwest Corner of Foster Road @ 33.909867324795, - 118.134267032146		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436815	Curb Ramps	Northwest Corner of Foster Road @ 33.909867324795, - 118.134267032146	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436816	Curb Ramps	Northwest Corner of Foster Road @ 33.909867324795, - 118.134267032146	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436818	Curb Ramps	Northeast Corner of Foster Road @ 33.909856194751, - 118.133982717991	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436819	Curb Ramps	Southeast Corner of Foster Road @ 33.909629141525, - 118.133982717991		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/21	
Columbia Way & Foster Road - Columbia Way & Foster Road Downey, CA 90240	436820	Curb Ramps	Southwest Corner of Foster Road @ 33.909646949643, - 118.134272396564		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/21	
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327215	Curb Ramps	Northeast Corner Of Congressman Steve Horn Way @ 33.915376518426, - 118.133980035782		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/21	
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327216	Curb Ramps	East Side South Of Congressman Steve Horn Way - 1st @ 33.919520978031, - 118.133974671364	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327217	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917174998265, - 118.133996129036		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327218	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917174998265, - 118.133996129036		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327219	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917174998265, - 118.133996129036	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327220	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917174998265, - 118.133996129036	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327221	Curb Ramps	Northwest Corner Of Adoree Street @ 33.913818398770, - 118.134280443192		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327222	Curb Ramps	Northwest Corner Of Adoree Street @ 33.913818398770, - 118.134280443192	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327243	Curb Ramps	Southeast Corner Of Congressman Steve Horn Way @ 33.920193153876, - 118.133990764618		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327244	Curb Ramps	Southeast Corner Of Congressman Steve Horn Way @ 33.920193153876, - 118.133990764618		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/21	
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327269	Curb Ramps	Southwest Corner Of James Street @ 33.918733056546, - 118.134242892265		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Columbia Way - Lakewood Boulevard To Adoree Street - Lakewood Boulevard To Adoree Street Downey, CA 90242	327270	Curb Ramps	Southwest Corner Of James Street @ 33.918733056546, - 118.134242892265		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Comolette Street - Barlin Avenue To Cul- de-sac - Barlin Avenue To Cul-de- sac Downey, CA 90242	401047	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Comolette Street - Barlin Avenue To Cul- de-sac - Barlin Avenue To Cul-de- sac Downey, CA 90242	401048	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Barlin Avenue To Cul- de-sac - Barlin Avenue To Cul-de- sac Downey, CA 90242	401049	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Barlin Avenue To Cul- de-sac - Barlin Avenue To Cul-de- sac Downey, CA 90242	401050	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401052	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401053	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401051	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.915209578397, - 118.143252432346	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401054	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401055	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401056	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401057	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401058	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Comolette Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	401059	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.915094946054, - 118.143339604139	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328013	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.919903807308, - 118.152841329575		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328014	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.919903807308, - 118.152841329575		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328015	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.919903807308, - 118.152841329575	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328016	Curb Ramps	Southeast Corner Of Paramout Boulevard @ 33.920571528675, - 118.154493570328		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328017	Curb Ramps	Southeast Corner Of Paramout Boulevard @ 33.920571528675, - 118.154493570328		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328018	Curb Ramps	Southeast Corner Of Paramout Boulevard @ 33.920571528675, - 118.154493570328		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue	328019	Curb Ramps	Southeast Corner Of Paramout Boulevard @ 33.920571528675, - 118.154493570328	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue Downey, CA 90242	328020	Curb Ramps	Southeast Corner Of Paramout Boulevard @ 33.920571528675, - 118.154493570328	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue Downey, CA 90242	328021	Curb Ramps	Northeast Corner Of Paramout Boulevard @ 33.920642751979, - 118.154332637787		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue Downey, CA 90242	328036	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.918154352510, - 118.149392008781	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/21
Comolette Street - Paramout Boulevard To Downey Avenue - Paramout Boulevard To Downey Avenue Downey, CA 90242	328037	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.918154352510, - 118.149392008781	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Conrad Street - Paramout Boulevard To End - Paramout Boulevard To End Downey, CA 90242	345821	Curb Ramps	Northwest Corner Of Montgomery Street @ 33.927552242201, - 118.147749155760		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Conrad Street - Paramout Boulevard To End - Paramout Boulevard To End Downey, CA 90242	345822	Curb Ramps	Northwest Corner Of Montgomery Street @ 33.927552242201, - 118.147749155760		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/21
Conrad Street - Paramout Boulevard To End - Paramout Boulevard To End Downey, CA 90242	345823	Curb Ramps	Northwest Corner Of Montgomery Street @ 33.927552242201, - 118.147749155760		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Conrad Street - Paramout Boulevard To End - Paramout Boulevard To End Downey, CA 90242	345824	Curb Ramps	Northwest Corner Of Montgomery Street @ 33.927552242201, - 118.147749155760	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Conrad Street - Paramount Boulevard To End - Paramount Boulevard To End Downey, CA 90242	345825	Curb Ramps	Northwest Corner Of Montgomery Street @ 33.927552242201, - 118.147749155760	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318750	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318751	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318752	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318753	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318754	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318755	Curb Ramps	Southeast Corner Of Angell Street @ 33.913008165290, - 118.118774592876	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318756	Curb Ramps	Northwest Corner Of Foster Road @ 33.909874002821, - 118.118522465229		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318757	Curb Ramps	Northwest Corner Of Foster Road @ 33.909874002821, - 118.118522465229	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318758	Curb Ramps	Northwest Corner Of Foster Road @ 33.909874002821, - 118.118522465229	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318762	Curb Ramps	Northeast Corner Of Foster Road @ 33.909891810888, - 118.118533194065	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318763	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318764	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318765	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318766	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318767	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Cornuta Avenue - Foster Road to Angell Street - Cornuta Avenue - Foster Road to Angell Street Downey, CA 90424	318768	Curb Ramps	Southwest Corner Of Angell Street @ 33.913014843070, - 118.118922114372	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street Downey, CA 90424	316949	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914283611765, - 118.118771910667		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street Downey, CA 90424	316950	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914283611765, - 118.118771910667		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street Downey, CA 90424	316951	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914283611765, - 118.118771910667		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316952	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914283611765, - 118.118771910667	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316953	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914283611765, - 118.118771910667	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316954	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914270256403, - 118.118959665298		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316955	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914270256403, - 118.118959665298		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316956	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914270256403, - 118.118959665298		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Cornuta Avenue - Imperial Highway Service Road to Adoree Street - Cornuta Avenue - Imperial Highway Service Road to Adoree Street	316957	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914270256403, - 118.118959665298	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Cornuta Avenue - Washburn Road To Spry Street - Washburn Road To Spry Street	316969	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.119217157364	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314411	Curb Ramps	Northeast Corner Of Foster Road @ 33.909876228830, - 118.126661628485		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314412	Curb Ramps	Northeast Corner Of Foster Road @ 33.909876228830, - 118.126661628485	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314413	Curb Ramps	Northeast Corner Of Foster Road @ 33.909876228830, - 118.126661628485	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314414	Curb Ramps	Northwest Corner Of Foster Road @ 33.909870663808, - 118.126861453056		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314415	Curb Ramps	Northwest Corner Of Foster Road @ 33.909870663808, - 118.126861453056	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Corrigan Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314416	Curb Ramps	Northwest Corner Of Foster Road @ 33.909870663808, - 118.126861453056	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	465735	Curb Ramps	Northwest Corner of Old River School Road @ 33.952295614343, - 118.145496100187		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	465736	Curb Ramps	Northwest Corner of Old River School Road @ 33.952295614343, - 118.145496100187		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	465737	Curb Ramps	Northwest Corner of Old River School Road @ 33.952295614343, - 118.145496100187		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	464704	Curb Ramps	Northwest Corner of Old River School Road @ 33.952295614343, - 118.145496100187	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	464705	Curb Ramps	Northwest Corner of Old River School Road @ 33.952295614343, - 118.145496100187	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	465738	Curb Ramps	Southwest Corner of Old River School Road @ 33.952204393391, - 118.145569860935		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	465739	Curb Ramps	Southwest Corner of Old River School Road @ 33.952204393391, - 118.145569860935		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Country Club Drive - Old River School Road to End - Old River School Road to End	464710	Curb Ramps	Southwest Corner of Old River School Road @ 33.952204393391, - 118.145569860935	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Country Club Drive - Old River School Road to End - Old River School Road to End	464709	Curb Ramps	Southwest Corner of Old River School Road @ 33.952204393391, - 118.145569860935	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	456390	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	456391	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	456392	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	455963	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	455964	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac	455965	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	455962	Curb Ramps	Northwest Corner of Brookpark Road @ 33.967527029217, - 118.121274411678	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	456394	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	456395	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484		Curb Ramp Width	Provide a compliant curb ramp.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	456396	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	456397	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	455978	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Crider Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	455979	Curb Ramps	Northeast Corner of Brookpark Road @ 33.967402457027, - 118.121246248484	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street - Downey, CA 90242	356440	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street Downey, CA 90242	356441	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/21
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street Downey, CA 90242	356442	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street Downey, CA 90242	356443	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street Downey, CA 90242	356444	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Crossdale Avenue - Dollison Drive to Cecilia Street - Crossdale Avenue - Dollison Drive to Cecilia Street Downey, CA 90242	356445	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932133407059, - 118.097410798073	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dacosta Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive Downey, CA 90242	468726	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.951632591539, - 118.120382577181	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Dacosta Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive Downey, CA 90242	468727	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.951632591539, - 118.120382577181	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dacosta Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive Downey, CA 90242	468728	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.951471284874, - 118.120505958796	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Dacosta Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive Downey, CA 90242	468729	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.951471284874, - 118.120505958796	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dacosta Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	468734	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.951806134920, - 118.120558261871		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dacosta Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	468735	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.951806134920, - 118.120558261871	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dacosta Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	468736	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.951806134920, - 118.120558261871	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dacosta Street - Downey Avenue to Dolan Avenue - Downey Avenue to Dolan Avenue Downey, CA 90242	468118	Curb Ramps	Northeast Corner of Downey Avenue @ 33.951628141704, - 118.120381236076	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464711	Curb Ramps	Southwest Corner of Golondrinas Street @ 33.923821031290, - 118.159101605415		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464712	Curb Ramps	Southwest Corner of Golondrinas Street @ 33.923821031290, - 118.159101605415	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464729	Curb Ramps	West Side North of Consuelo Street - 3rd @ 33.922779423401, - 118.159847259521		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464730	Curb Ramps	West Side North of Consuelo Street - 3rd @ 33.922779423401, - 118.159847259521		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464731	Curb Ramps	West Side North of Consuelo Street - 3rd @ 33.922779423401, - 118.159847259521		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464733	Curb Ramps	West Side North of Consuelo Street - 3rd @ 33.922779423401, - 118.159847259521	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464732	Curb Ramps	West Side North of Consuelo Street - 3rd @ 33.922779423401, - 118.159847259521	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464734	Curb Ramps	West Side North of Consuelo Street - 2nd @ 33.922717104577, - 118.159890174866		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464735	Curb Ramps	West Side North of Consuelo Street - 2nd @ 33.922717104577, - 118.159890174866		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464737	Curb Ramps	West Side North of Consuelo Street - 2nd @ 33.922717104577, - 118.159890174866	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464736	Curb Ramps	West Side North of Consuelo Street - 2nd @ 33.922717104577, - 118.159890174866	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464738	Curb Ramps	West Side North of Consuelo Street - 1st @ 33.922263066051, - 118.160222768784		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464739	Curb Ramps	West Side North of Consuelo Street - 1st @ 33.922263066051, - 118.160222768784		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464740	Curb Ramps	West Side North of Consuelo Street - 1st @ 33.922263066051, - 118.160222768784	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464741	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464742	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464743	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street Downey, CA 90242	464745	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464746	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dahlia Street - Consuelo Street to Golondrinas Street - Consuelo Street to Golondrinas Street	464744	Curb Ramps	West Side North of Consuelo Street - 4th @ 33.923447122231, - 118.159316182137	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard	399042	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.916978013153, - 118.141728937626		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard	399043	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.916978013153, - 118.141728937626		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard	399044	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.916978013153, - 118.141728937626	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard	399045	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.916978013153, - 118.141728937626	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard Downey, CA 90242	399046	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.916887867272, - 118.141777217388		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard Downey, CA 90242	399047	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.916887867272, - 118.141777217388		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard Downey, CA 90242	399048	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.916887867272, - 118.141777217388		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard Downey, CA 90242	399049	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.916887867272, - 118.141777217388	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Dalen Street - Barlin Avenue To Lakewood Boulevard - Barlin Avenue To Lakewood Boulevard Downey, CA 90242	399050	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.916887867272, - 118.141777217388	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac Downey, CA 90242	451818	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451819	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451820	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451821	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451824	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451825	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451822	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451823	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947165952634, - 118.099532425404	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451826	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451827	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451828	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451831	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451829	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Dalewood Avenue - Brookpark Road to Cul-De-Sac - Brookpark Road to Cul-De-Sac - Downey, CA 90242	451830	Curb Ramps	Southeast Corner of Brookpark Road @ 33.947089188920, - 118.099405020475	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road - Downey, CA 90242	451875	Curb Ramps	Northwest Corner of Alwin Street @ 33.949881563526, - 118.097378611565		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road - Downey, CA 90242	451876	Curb Ramps	Northwest Corner of Alwin Street @ 33.949881563526, - 118.097378611565		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road - Downey, CA 90242	451877	Curb Ramps	Northwest Corner of Alwin Street @ 33.949881563526, - 118.097378611565	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road Downey, CA 90242	451878	Curb Ramps	Northwest Corner of Alwin Street @ 33.949881563526, - 118.097378611565	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road Downey, CA 90242	451884	Curb Ramps	Southwest Corner of Alwin Street @ 33.949750290597, - 118.097453713417		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road Downey, CA 90242	451885	Curb Ramps	Southwest Corner of Alwin Street @ 33.949750290597, - 118.097453713417		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dalewood Avenue - Cedartree Road to Pico Vista Road - Cedartree Road to Pico Vista Road Downey, CA 90242	451886	Curb Ramps	Southwest Corner of Alwin Street @ 33.949750290597, - 118.097453713417	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	356480	Curb Ramps	Northwest Corner of Cecilia @ 33.932130068918, - 118.096716105938		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	356481	Curb Ramps	Northwest Corner of Cecilia @ 33.932130068918, - 118.096716105938		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	356482	Curb Ramps	Northwest Corner of Cecilia @ 33.932130068918, - 118.096716105938		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	356483	Curb Ramps	Northwest Corner of Cecilia @ 33.932130068918, - 118.096716105938	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	357571	Curb Ramps	Northeast Corner of Cecilia @ 33.932128956205, - 118.096539080143		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	357572	Curb Ramps	Northeast Corner of Cecilia @ 33.932128956205, - 118.096539080143		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	357573	Curb Ramps	Northeast Corner of Cecilia @ 33.932128956205, - 118.096539080143	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	357574	Curb Ramps	Northeast Corner of Cecilia @ 33.932128956205, - 118.096539080143	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
Dalwood Avenue - Cecilia Street to End - Dalwood Avenue - Cecilia Street to End Downey, CA 90424	357575	Curb Ramps	Northeast Corner of Cecilia @ 33.932128956205, - 118.096539080143	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476659	Curb Ramps	Northwest Corner of Dolan Avenue @ 33.936263699559, - 118.133769482374		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476660	Curb Ramps	Northwest Corner of Dolan Avenue @ 33.936263699559, - 118.133769482374		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476661	Curb Ramps	Northwest Corner of Dolan Avenue @ 33.936263699559, - 118.133769482374		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476662	Curb Ramps	Northwest Corner of Dolan Avenue @ 33.936263699559, - 118.133769482374	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476663	Curb Ramps	Northwest Corner of Dolan Avenue @ 33.936263699559, - 118.133769482374	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476664	Curb Ramps	Southwest Corner of Dolan Avenue @ 33.936124616999, - 118.133886158466		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476665	Curb Ramps	Southwest Corner of Dolan Avenue @ 33.936124616999, - 118.133886158466		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476666	Curb Ramps	Southwest Corner of Dolan Avenue @ 33.936124616999, - 118.133886158466		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476667	Curb Ramps	Southwest Corner of Dolan Avenue @ 33.936124616999, - 118.133886158466		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476668	Curb Ramps	Southwest Corner of Dolan Avenue @ 33.936124616999, - 118.133886158466	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476692	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476693	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476694	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476697	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476695	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476696	Curb Ramps	Northeast Corner of Dolan Avenue @ 33.936186926014, - 118.133616596460	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476716	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476717	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476718	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476719	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476720	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Davis Street - Downey Avenue to Brookshire Avenue - Downey Avenue to Brookshire Avenue Downey, CA 90242	476721	Curb Ramps	Southeast Corner of Dolan Avenue @ 33.936035604041, - 118.133717179298	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347816	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.934101774565, - 118.138962239027		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347817	Curb Ramps	Northeast Corner Of Gurley Avenue @ 33.934101774565, - 118.138962239027	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347837	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.934170761182, - 118.139100372791		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347838	Curb Ramps	Northwest Corner Of Gurley Avenue @ 33.934170761182, - 118.139100372791	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347856	Curb Ramps	North Side East Of Paramount Boulevard - 1st @ 33.934793863578, - 118.140351623297		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347857	Curb Ramps	North Side East Of Paramount Boulevard - 1st @ 33.934793863578, - 118.140351623297		Curb Ramp Width	Provide a compliant curb ramp.		6/30/21
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street Downey, CA 90242	347858	Curb Ramps	North Side East Of Paramount Boulevard - 1st @ 33.934793863578, - 118.140351623297		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347859	Curb Ramps	North Side East Of Paramount Boulevard - 1st @ 33.934793863578, - 118.140351623297	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347860	Curb Ramps	North Side East Of Paramount Boulevard - 1st @ 33.934793863578, - 118.140351623297	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347861	Curb Ramps	North Side East Of Paramount Boulevard - 2nd @ 33.934751581774, - 118.140255063772		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347862	Curb Ramps	North Side East Of Paramount Boulevard - 2nd @ 33.934751581774, - 118.140255063772		Curb Ramp Width	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347863	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.935757437949, - 118.142879605293		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347864	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.935757437949, - 118.142879605293		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Downey Avenue To Paramount Boulevard - Alameda Street	347865	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.935886507129, - 118.142785727978		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard	415451	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, - 118.143063336611		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415452	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, -118.143063336611		Curb Ramp Width	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415453	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, -118.143063336611		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415454	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, -118.143063336611		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415455	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, -118.143063336611	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415456	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.936038942029, -118.143063336611	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415457	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, -118.143182694912		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415458	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, - 118.143182694912		Curb Ramp Width	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415459	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, - 118.143182694912		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415460	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, - 118.143182694912		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415462	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, - 118.143182694912	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
De Palma Street - Morning Avenue To Paramount Boulevard - Morning Avenue To Paramount Boulevard	415461	Curb Ramps	Southwest Corner Of Southwest Corner Of Paramount Boulevard @ 33.935905422423, - 118.143182694912	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Deming Avenue - Gardendale Street To Lakewood Boulevard - Gardendale Street To Lakewood Boulevard	312428	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.910832294133, - 118.143534064293	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Deming Avenue - Gardendale Street To Lakewood Boulevard - Gardendale Street To Lakewood Boulevard Downey, CA 90242	312429	Curb Ramps	Southwest Corner Of Gardendale Street @ 33.910926898381, - 118.143672198057	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Deming Avenue - Rosecrans Avenue To End - Rosecrans Avenue To End Downey, CA 90242	312437	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904046113106, - 118.145250678062		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Deming Avenue - Rosecrans Avenue To End - Rosecrans Avenue To End Downey, CA 90242	312438	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904046113106, - 118.145250678062	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/21	
Deming Avenue - Rosecrans Avenue To End - Rosecrans Avenue To End Downey, CA 90242	312439	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904046113106, - 118.145250678062	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/21	
Dempster Avenue - Golden Street To Prichard Street - Golden Street To Prichard Street Downey, CA 90242	310502	Curb Ramps	Northwest Corner Of Prichard Street @ 33.908121003029, - 118.150494396687		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Dempster Avenue - Golden Street To Prichard Street - Golden Street To Prichard Street Downey, CA 90242	310507	Curb Ramps	Southeast Corner Of Golden Street @ 33.909533422826, - 118.149328976870		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/21	
Dempster Avenue - Golden Street To Prichard Street - Golden Street To Prichard Street Downey, CA 90242	310508	Curb Ramps	Southeast Corner Of Golden Street @ 33.909533422826, - 118.149328976870		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/21	
Dempster Avenue - Golden Street To Prichard Street - Golden Street To Prichard Street Downey, CA 90242	310509	Curb Ramps	Southeast Corner Of Golden Street @ 33.909533422826, - 118.149328976870	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/21	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dempster Avenue - Golden Street To Prichard Street - Golden Street To Prichard Street Downey, CA 90242	310510	Curb Ramps	Southeast Corner Of Golden Street @ 33.909533422826, - 118.149328976870	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Dempster Avenue - Prichard Street To Downey Avenue - Prichard Street To Downey Avenue Downey, CA 90242	310462	Curb Ramps	Southwest Corner Of Prichard Street @ 33.907986326634, - 118.150588274002		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/21
Dempster Avenue - Prichard Street To Downey Avenue - Prichard Street To Downey Avenue Downey, CA 90242	310463	Curb Ramps	Southwest Corner Of Prichard Street @ 33.907986326634, - 118.150588274002		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/21
Dempster Avenue - Prichard Street To Downey Avenue - Prichard Street To Downey Avenue Downey, CA 90242	310464	Curb Ramps	Southwest Corner Of Prichard Street @ 33.907986326634, - 118.150588274002	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/21
Dempster Avenue - Prichard Street To Downey Avenue - Prichard Street To Downey Avenue Downey, CA 90242	310466	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.906494854799, - 118.151392936707	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/21
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361649	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.938206381011, - 118.147283792496		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/21
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361650	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.938206381011, - 118.147283792496		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/21
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361651	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.938206381011, - 118.147283792496		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361652	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.938206381011, - 118.147283792496		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361653	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.938206381011, - 118.147283792496	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361662	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.938081765891, - 118.147369623184		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Depalma Street - Horton Avenue To Rives Avenue - Horton Avenue To Rives Avenue Downey, CA 90241	361663	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.938081765891, - 118.147369623184	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328187	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.919899355815, - 118.154933452606		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Devenir Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328188	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.919899355815, - 118.154933452606		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Devenir Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328189	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.919899355815, - 118.154933452606		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328190	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.919899355815, - 118.154933452606		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328191	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.919899355815, - 118.154933452606	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328210	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.917526676766, - 118.149912357330	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328209	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.917526676766, - 118.149912357330	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328211	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.917384224890, - 118.150019645691		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328212	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.917384224890, - 118.150019645691		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328213	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.917384224890, - 118.150019645691		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328215	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.917384224890, - 118.150019645691	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328214	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.917384224890, - 118.150019645691	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328216	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328217	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328218	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328220	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328221	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Devenir Avenue - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue - Paramount	328219	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.919997288614, - 118.154820799828	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	
Devenir Street - Brookshire Avenue To Barlin Avenue - Brookshire Avenue To Barlin Avenue	400338	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.914436085327, - 118.143803626299		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Devenir Street - Brookshire Avenue To Barlin Avenue - Brookshire Avenue To Barlin Avenue	400339	Curb Ramps	Northwest Corner Of Barlin Avenue @ 33.914568525646, - 118.143732547760		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dinsdale Street - Downey Avenue to End - Downey Avenue to End	468124	Curb Ramps	Southeast Corner of Downey Avenue @ 33.952286714743, - 118.124973177910		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357871	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357872	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259		Detectable Warnings Width	Provide compliant detectable warnings that are full width of the curb ramp.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357873	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357874	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357875	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357876	Curb Ramps	Southwest Corner Of Tweedy Lane @ 33.955182373220, - 118.131265640259	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357891	Curb Ramps	Northwest Corner Of Tweedy Lane @ 33.955321424643, - 118.131154328585		Detectable Warnings Width	Provide compliant detectable warnings that are full width of the curb ramp.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357893	Curb Ramps	Northwest Corner Of Tweedy Lane @ 33.955321424643, - 118.131154328585	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dinsdale Street - Smallwood Avenue to Tweedy Lane - Smallwood Avenue to Tweedy Lane	357892	Curb Ramps	Northwest Corner Of Tweedy Lane @ 33.955321424643, - 118.131154328585	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358446	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358447	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358448	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358449	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358450	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358451	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358452	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.950221982213, - 118.152723312378	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358453	Curb Ramps	Northeast Corner Of Rio Hondo Drive @ 33.952513654271, - 118.156564235687		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358454	Curb Ramps	Northeast Corner Of Rio Hondo Drive @ 33.952513654271, - 118.156564235687		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358455	Curb Ramps	Northeast Corner Of Rio Hondo Drive @ 33.952513654271, - 118.156564235687	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358456	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358457	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358458	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358459	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358460	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358461	Curb Ramps	Southwest Corner Of Old River School Road @ 33.948023698988, - 118.148646354675	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dinwiddie Street - Old River School Road To Rio Hondo Drive - Old River School Road To Rio Hondo Drive	358482	Curb Ramps	Northwest Corner Of Old River School Road @ 33.948166099621, - 118.148506879807		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/23
Dolan Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471763	Curb Ramps	Northwest Corner of 5th Street @ 33.943176372853, - 118.128431886435	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dolan Avenue - 6th Street to 5th Street - 6th Street to 5th Street	471762	Curb Ramps	Northwest Corner of 5th Street @ 33.943176372853, - 118.128431886435	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479107	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479108	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479109	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479110	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479111	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479112	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479113	Curb Ramps	Southeast Corner of Iowa Street @ 33.936874547473, - 118.133070766926	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479114	Curb Ramps	Southwest Corner of Iowa Street @ 33.936954658350, - 118.133257180452		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479115	Curb Ramps	Southwest Corner of Iowa Street @ 33.936954658350, - 118.133257180452		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479116	Curb Ramps	Southwest Corner of Iowa Street @ 33.936954658350, - 118.133257180452	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479117	Curb Ramps	Southwest Corner of Iowa Street @ 33.936954658350, - 118.133257180452	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479118	Curb Ramps	Southwest Corner of Iowa Street @ 33.936954658350, - 118.133257180452	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479119	Curb Ramps	Northwest Corner of Iowa Street @ 33.937093739554, - 118.133135139942		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479120	Curb Ramps	Northwest Corner of Iowa Street @ 33.937093739554, - 118.133135139942		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479121	Curb Ramps	Northwest Corner of Iowa Street @ 33.937093739554, - 118.133135139942		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479122	Curb Ramps	Northwest Corner of Iowa Street @ 33.937093739554, - 118.133135139942	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479123	Curb Ramps	Northwest Corner of Iowa Street @ 33.937093739554, - 118.133135139942	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479152	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479153	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479154	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479155	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479158	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479156	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dolan Avenue - Galt Drive to Firestone Boulevard - Galt Drive to Firestone Boulevard	479157	Curb Ramps	Northeast Corner of Iowa Street @ 33.937001389660, - 118.132976889610	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361505	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361506	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361507	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361508	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361511	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361509	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dolan Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	361510	Curb Ramps	Northwest Corner Of Cheyenne Street @ 33.914902407889, - 118.149196207523	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End	356402	Curb Ramps	Southeast Corner of Fairford Avenue @ 33.935216680464, - 118.094807714224	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End	356403	Curb Ramps	Southeast Corner of Fairford Avenue @ 33.935216680464, - 118.094807714224	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End	356417	Curb Ramps	Northeast Corner of Fairford Avenue @ 33.935359102522, - 118.094735294580	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End	356429	Curb Ramps	Northwest Corner of Fairford Avenue @ 33.935376905262, - 118.094924390316		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356430	Curb Ramps	Northwest Corner of Fairford Avenue @ 33.935376905262, -118.094924390316	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356432	Curb Ramps	Southwest Corner of Fairford Avenue @ 33.935196652343, -118.095002174377	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356431	Curb Ramps	Southwest Corner of Fairford Avenue @ 33.935196652343, -118.095002174377	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356433	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, -118.096934705973		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356434	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, -118.096934705973		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356435	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, -118.096934705973		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356439	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, -118.096934705973	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356436	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, -118.096934705973	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356437	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, - 118.096934705973	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Dollison Avenue - Studebaker Road to End - Dollison Avenue - Studebaker Road to End Downey, CA 90424	356438	Curb Ramps	Curb Ramp West of Fairford Avenue @ 33.935214455118, - 118.096934705973	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Donovan Street & Lakewood Boulevard - Donovan Street & Lakewood Boulevard Downey, CA 90242	357456	Curb Ramps	Northwest Corner @ 33.920557061434, - 118.135255426168		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Donovan Street & Lakewood Boulevard - Donovan Street & Lakewood Boulevard Downey, CA 90242	357457	Curb Ramps	Northwest Corner @ 33.920557061434, - 118.135255426168	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Donovan Street & Lakewood Boulevard - Donovan Street & Lakewood Boulevard Downey, CA 90242	357459	Curb Ramps	Northeast Corner @ 33.920432420489, - 118.134983181953	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/23
Donovan Street & Lakewood Boulevard - Donovan Street & Lakewood Boulevard Downey, CA 90242	357458	Curb Ramps	Northeast Corner @ 33.920432420489, - 118.134983181953	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Donovan Street & Lakewood Boulevard - Donovan Street & Lakewood Boulevard Downey, CA 90242	357460	Curb Ramps	Southwest Corner @ 33.920387905821, - 118.135386854410	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Donovan Street & Lakewood Boulevard · Donovan Street & Lakewood Boulevard · Downey, CA 90242	357461	Curb Ramps	Southeast Corner @ 33.920233217170, - 118.135099858046	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/23
Donovan Street & Lakewood Boulevard · Donovan Street & Lakewood Boulevard · Downey, CA 90242	357462	Curb Ramps	Southeast Corner @ 33.920233217170, - 118.135099858046	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard · Downey, CA 90242	356635	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard · Downey, CA 90242	356636	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard · Downey, CA 90242	356637	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard · Downey, CA 90242	356638	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356639	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356640	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.922360996134, - 118.138694018126	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356662	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356663	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356664	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Donovan Street - Birchdale Avenue To Lakewood Boulevard - Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356665	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356669	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356666	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/23	
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356667	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Donovan Street - Birchdale Avenue To Lakewood Boulevard · Birchdale Avenue To Lakewood Boulevard Downey, CA 90242	356668	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.922220778026, - 118.138793259859	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/23	
Dorion Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	310790	Curb Ramps	Southwest Corner Of Blodgett Avenue @ 33.905597733053, - 118.147262334824	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dorion Street - Barlin Avenue To Blodgett Avenue - Barlin Avenue To Blodgett Avenue Downey, CA 90242	310791	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.905724621813, - 118.147168457508	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street Downey, CA 90242	347866	Curb Ramps	Northwest Corner @ 33.933496470239, - 118.137798160315		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347867	Curb Ramps	Northwest Corner @ 33.933496470239, -118.137798160315		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347868	Curb Ramps	Northwest Corner @ 33.933496470239, -118.137798160315		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347869	Curb Ramps	Northwest Corner @ 33.933496470239, -118.137798160315	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347870	Curb Ramps	Northwest Corner @ 33.933496470239, -118.137798160315	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347871	Curb Ramps	Northwest Corner @ 33.933496470239, -118.137798160315	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347872	Curb Ramps	Southeast Corner @ 33.933203830758, -118.137708306313		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347873	Curb Ramps	Southeast Corner @ 33.933203830758, -118.137708306313		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347874	Curb Ramps	Southeast Corner @ 33.933203830758, -118.137708306313		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347876	Curb Ramps	Southeast Corner @ 33.933203830758, -118.137708306313	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347877	Curb Ramps	Southeast Corner @ 33.933203830758, -118.137708306313	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347878	Curb Ramps	Southeast Corner @ 33.933203830758, - 118.137708306313	Top Landing	Top Landing Right Side Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347875	Curb Ramps	Southeast Corner @ 33.933203830758, - 118.137708306313	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347879	Curb Ramps	Southwest Corner To South Crossing @ 33.933305086358, - 118.137896060944		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347880	Curb Ramps	Southwest Corner To South Crossing @ 33.933305086358, - 118.137896060944		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347881	Curb Ramps	Southwest Corner To South Crossing @ 33.933305086358, - 118.137896060944		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347882	Curb Ramps	Southwest Corner To South Crossing @ 33.933305086358, - 118.137896060944	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347883	Curb Ramps	Southwest Corner To South Crossing @ 33.933305086358, - 118.137896060944	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347884	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347885	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street - Downey, CA 90242	347888	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street Downey, CA 90242	347889	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street Downey, CA 90242	347886	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue & De Palma Street - Downey Avenue & De Palma Street Downey, CA 90242	347887	Curb Ramps	Southwest Corner To West Crossing @ 33.933376299015, - 118.137881308794	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435091	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.940064459827, - 118.133347034454		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435092	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.939948748318, - 118.133129775524		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435093	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.939948748318, - 118.133129775524	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435094	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.939948748318, - 118.133129775524	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435095	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.940298107586, - 118.133183419704		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435096	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.940197972910, - 118.132960796356	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue & Firestone Boulevard - Downey Avenue & Firestone Boulevard Downey, CA 90240	435097	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.940197972910, - 118.132960796356	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue & Gardendale Street - Downey Avenue & Gardendale Street Downey, CA 90242	350020	Curb Ramps	Northeast Corner @ 33.914923553720, - 118.151539117098		Grade Break	Provide a compliant curb ramp.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434986	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.931906413194, - 118.138689994812		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434987	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.931906413194, - 118.138689994812		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434988	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.931906413194, - 118.138689994812	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434989	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.932242452916, - 118.138778507710		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434990	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.932242452916, - 118.138778507710		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434991	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.932242452916, - 118.138778507710	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434992	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.931906413194, - 118.138689994812		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434993	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.931906413194, -118.138689994812		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434994	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.931906413194, -118.138689994812		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434995	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.931906413194, -118.138689994812	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	434996	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.931906413194, -118.138689994812	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	435089	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.932242452916, -118.138778507710		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue & Stewart And Gray Road - Downey Avenue & Stewart And Gray Road Downey, CA 90240	435090	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.932242452916, -118.138778507710	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347328	Curb Ramps	Southeast Corner Of Lexington Road @ 33.950582424044, -118.126217722893	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348125	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348126	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348127	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348128	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348129	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348130	Curb Ramps	Northeast Corner Of 3rd Street @ 33.941855742928, -118.131674677134	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348131	Curb Ramps	Southeast Corner Of 6th Street @ 33.944877474216, -118.130978708		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348132	Curb Ramps	Southeast Corner Of 6th Street @ 33.944877474216, -118.130978708		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348133	Curb Ramps	Southeast Corner Of 6th Street @ 33.944877474216, -118.130978708		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348135	Curb Ramps	Southeast Corner Of 6th Street @ 33.944877474216, -118.130978708	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348134	Curb Ramps	Southeast Corner Of 6th Street @ 33.944877474216, -118.130978708	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348136	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348137	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348138	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348139	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348142	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348140	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, -118.125724196434	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348141	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.951263254448, - 118.125724196434	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348184	Curb Ramps	Northwest Corner Of 2nd Street @ 33.941084716996, - 118.132465928793		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348185	Curb Ramps	Northwest Corner Of 2nd Street @ 33.941084716996, - 118.132465928793	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348295	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941016848578, - 118.132326453924		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348296	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941016848578, - 118.132326453924		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348297	Curb Ramps	Northeast Corner Of La Villa Street @ 33.943167472299, - 118.130648732185		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348298	Curb Ramps	Northeast Corner Of La Villa Street @ 33.943167472299, - 118.130648732185		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348299	Curb Ramps	East Side South Of Lexington Road @ 33.948793549574, - 118.127532005310	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348300	Curb Ramps	Northeast Corner Of 6th Street @ 33.945049918826, - 118.129958063364		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348301	Curb Ramps	Northeast Corner Of 6th Street @ 33.945049918826, - 118.129958063364		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348302	Curb Ramps	Northeast Corner Of 6th Street @ 33.945049918826, - 118.129958063364		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348304	Curb Ramps	Northeast Corner Of 6th Street @ 33.945049918826, - 118.129958063364	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348303	Curb Ramps	Northeast Corner Of 6th Street @ 33.945049918826, - 118.129958063364	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348305	Curb Ramps	Southeast Corner Of 2nd Street @ 33.940893350170, - 118.132423013449		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348306	Curb Ramps	Southeast Corner Of 2nd Street @ 33.940893350170, - 118.132423013449		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348307	Curb Ramps	Southeast Corner Of 2nd Street @ 33.940893350170, - 118.132423013449	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348308	Curb Ramps	Southwest Corner Of 5th Street @ 33.943780495804, - 118.130517303944		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348309	Curb Ramps	Southwest Corner Of 5th Street @ 33.943780495804, - 118.130517303944		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348312	Curb Ramps	Southwest Corner Of 5th Street @ 33.943780495804, - 118.130517303944	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348310	Curb Ramps	Southwest Corner Of 5th Street @ 33.943780495804, - 118.130517303944	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348311	Curb Ramps	Southwest Corner Of 5th Street @ 33.943780495804, - 118.130517303944	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348313	Curb Ramps	Northeast Corner Of Firestone Boulevard @ 33.940167932485, - 118.132978230715	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348314	Curb Ramps	Southwest Corner Of 2nd Street - Right @ 33.940997934419, - 118.132551759481		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348315	Curb Ramps	Southwest Corner Of 2nd Street - Right @ 33.940997934419, - 118.132551759481		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348317	Curb Ramps	Southwest Corner Of 2nd Street - Right @ 33.940997934419, - 118.132551759481	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348316	Curb Ramps	Southwest Corner Of 2nd Street - Right @ 33.940997934419, - 118.132551759481	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348318	Curb Ramps	Northwest Corner Of 4th Street		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348319	Curb Ramps	Northwest Corner Of 4th Street		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348320	Curb Ramps	Northwest Corner Of 4th Street	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348321	Curb Ramps	Southeast Corner Of La Villa Street @ 33.943052877578, - 118.130727857351		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348322	Curb Ramps	Southeast Corner Of La Villa Street @ 33.943052877578, - 118.130727857351		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348323	Curb Ramps	Southeast Corner Of La Villa Street @ 33.943052877578, - 118.130727857351	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348324	Curb Ramps	Southwest Corner Of 3rd Street @ 33.941819027566, - 118.131932169199		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348325	Curb Ramps	Southwest Corner Of 3rd Street @ 33.941819027566, - 118.131932169199		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348326	Curb Ramps	Southwest Corner Of 3rd Street @ 33.941819027566, - 118.131932169199	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348327	Curb Ramps	West Side North Of 7th Street @ 33.948893674138, - 118.127730488777		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348328	Curb Ramps	Southeast Corner Of 5th Street @ 33.943678140099, - 118.130317479372		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348329	Curb Ramps	Southeast Corner Of 5th Street @ 33.943678140099, - 118.130317479372		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348330	Curb Ramps	Southeast Corner Of 5th Street @ 33.943678140099, - 118.130317479372	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348331	Curb Ramps	Southeast Corner Of 5th Street @ 33.943678140099, - 118.130317479372	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348332	Curb Ramps	Northwest Corner Of 5th Street @ 33.943945154723, - 118.130494505167		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348333	Curb Ramps	Northwest Corner Of 5th Street @ 33.943945154723, - 118.130494505167		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348334	Curb Ramps	Northwest Corner Of 5th Street @ 33.943945154723, - 118.130494505167	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348336	Curb Ramps	Southeast Corner Of Cherokee Drive @ 33.947517507308, - 118.128426522017	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348335	Curb Ramps	Southeast Corner Of Cherokee Drive @ 33.947517507308, - 118.128426522017	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348337	Curb Ramps	Northeast Corner Of 5th Street @ 33.943816097759, - 118.130243718624		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348338	Curb Ramps	Northeast Corner Of 5th Street @ 33.943816097759, - 118.130243718624		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348340	Curb Ramps	Northeast Corner Of 5th Street @ 33.943816097759, - 118.130243718624	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348339	Curb Ramps	Northeast Corner Of 5th Street @ 33.943816097759, - 118.130243718624	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348341	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348342	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348343	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348344	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348345	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348346	Curb Ramps	Southwest Corner Of Florence Avenue @ 33.951368938418, - 118.125956207514	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348347	Curb Ramps	Northwest Corner Of Firestone Boulevard @ 33.940303670620, - 118.133147209883	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348348	Curb Ramps	Southeast Corner Of 3rd Street @ 33.941725570208, - 118.131769895554		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348349	Curb Ramps	Southeast Corner Of 3rd Street @ 33.941725570208, - 118.131769895554		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348350	Curb Ramps	Southwest Corner Of 2nd Street - Left @ 33.940942304515, - 118.132555782795		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348351	Curb Ramps	Southwest Corner Of 2nd Street - Left @ 33.940942304515, - 118.132555782795	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	348352	Curb Ramps	Southwest Corner Of 4th Street @ 33.942628987030, - 118.131272345781		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gainford Street/ Valdina Drive to Florence Avenue - Gainford Street/ Valdina Drive to Florence Avenue	471189	Curb Ramps	West Side North of Valdina Drive @ 33.954206782043, -118.123870795		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Gallatin Road to Gainford Street/ Valdina Drive - Gallatin Road to Gainford Street/ Valdina Drive	471244	Curb Ramps	West Side North of Gainford Street/ Valdina Drive @ 33.954285764185, - 118.123815804720		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352680	Curb Ramps	Northwest Corner Of Priscilla Avenue @ 33.915583523608, - 118.151368796825		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352681	Curb Ramps	Southwest Corner Of Priscilla Avenue @ 33.915452197798, - 118.151459991932		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352703	Curb Ramps	West Side Alley North Curb Ramp North Of Priscilla Avenue @ 33.915846174620, - 118.151174336672		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352704	Curb Ramps	West Side Alley North Curb Ramp North Of Priscilla Avenue @ 33.915846174620, - 118.151174336672	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	352705	Curb Ramps	Southwest Corner Of Cheyenne Avenue @ 33.916054291584, - 118.151026815176		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356016	Curb Ramps	Southeast Corner Of Devenir Street @ 33.917232869510, - 118.149794340134		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356017	Curb Ramps	Southeast Corner Of Cheyenne Avenue @ 33.915672557940, - 118.150978535414	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356018	Curb Ramps	Northeast Corner Of Cheyenne Avenue @ 33.915820577311, - 118.150880634785	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356019	Curb Ramps	Northeast Corner Of Cheyenne Avenue @ 33.915820577311, - 118.150880634785	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356020	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.920663896386, - 118.147235512733		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356021	Curb Ramps	Northeast Corner Of Puritan Street @ 33.916433797682, - 118.150427341461		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356060	Curb Ramps	Southeast Corner Of Comolette Avenue @ 33.917854982918, - 118.149353116751		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/23
Downey Avenue - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	356061	Curb Ramps	Southeast Corner Of Comolette Avenue @ 33.917854982918, - 118.149353116751	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street	476054	Curb Ramps	East Side South of Texas Street - 2nd @ 33.935633931912, - 118.135934025049		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street	476055	Curb Ramps	East Side South of Texas Street - 2nd @ 33.935633931912, - 118.135934025049		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476056	Curb Ramps	East Side South of Texas Street - 2nd @ 33.935633931912, - 118.135934025049	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476057	Curb Ramps	East Side South of Texas Street - 2nd @ 33.935633931912, - 118.135934025049	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476058	Curb Ramps	West Side North of Stewart & Gray Road - 1st @ 33.932695325544, - 118.138377517462		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476059	Curb Ramps	West Side North of Stewart & Gray Road - 1st @ 33.932695325544, - 118.138377517462	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476060	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476061	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476062	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476063	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476064	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476065	Curb Ramps	Southeast Corner of Texas Street @ 33.936025590078, - 118.135641664267	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476066	Curb Ramps	West Side North of Stewart & Gray Road - 2nd @ 33.932797694452, - 118.138302415609		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476067	Curb Ramps	West Side North of Stewart & Gray Road - 2nd @ 33.932797694452, - 118.138302415609	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476068	Curb Ramps	East Side South of Texas Street - 1st @ 33.935699579287, - 118.135899156332		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476069	Curb Ramps	East Side South of Texas Street - 1st @ 33.935699579287, - 118.135899156332		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476071	Curb Ramps	East Side South of Texas Street - 1st @ 33.935699579287, - 118.135899156332	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart & Gray Road to Texas Street - Stewart & Gray Road to Texas Street Downey, CA 90242	476070	Curb Ramps	East Side South of Texas Street - 1st @ 33.935699579287, - 118.135899156332	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	324998	Curb Ramps	Northeast Corner Of Donovan Street @ 33.925281041423, - 118.143705725670		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	324999	Curb Ramps	Northeast Corner Of Donovan Street @ 33.925281041423, - 118.143705725670		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325000	Curb Ramps	Northeast Corner Of Donovan Street @ 33.925281041423, - 118.143705725670		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325001	Curb Ramps	Northeast Corner Of Donovan Street @ 33.925281041423, - 118.143705725670		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325002	Curb Ramps	Northeast Corner Of Donovan Street @ 33.925281041423, - 118.143705725670	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325003	Curb Ramps	Southeast Corner Of Everest Street @ 33.923527245739, - 118.145052194595	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326604	Curb Ramps	Northeast Corner Of Leeds Street @ 33.922636980307, - 118.145706653595		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326605	Curb Ramps	Northeast Corner Of Leeds Street @ 33.922636980307, - 118.145706653595		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325011	Curb Ramps	Northeast Corner Of Leeds Street @ 33.922636980307, - 118.145706653595	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325012	Curb Ramps	Southeast Corner Of Alameda Street @ 33.927635700164, - 118.141908645630		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325013	Curb Ramps	Southeast Corner Of Alameda Street @ 33.927635700164, - 118.141908645630		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325014	Curb Ramps	Southeast Corner Of Alameda Street @ 33.927635700164, - 118.141908645630		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325015	Curb Ramps	Southeast Corner Of Alameda Street @ 33.927635700164, - 118.141908645630		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325016	Curb Ramps	Northeast Corner Of Everest Street @ 33.923642979562, - 118.144966363907		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325017	Curb Ramps	Northeast Corner Of Everest Street @ 33.923642979562, - 118.144966363907	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326606	Curb Ramps	Southeast Corner Of Donovan Street @ 33.925134151292, - 118.143818378448		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326607	Curb Ramps	Southeast Corner Of Donovan Street @ 33.925134151292, - 118.143818378448		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326608	Curb Ramps	Southeast Corner Of Donovan Street @ 33.925134151292, - 118.143818378448		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325025	Curb Ramps	Southeast Corner Of Donovan Street @ 33.925134151292, - 118.143818378448	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325026	Curb Ramps	Southeast Corner Of Donovan Street @ 33.925134151292, - 118.143818378448	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325027	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325028	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325029	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325030	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325031	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325032	Curb Ramps	Northeast Corner Of Alameda Street @ 33.927755879488, - 118.141779899597	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326609	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.931930892954, - 118.138625621796		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326610	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.931930892954, - 118.138625621796		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326611	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.931930892954, - 118.138625621796		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325036	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.931930892954, - 118.138625621796	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	325037	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.931930892954, - 118.138625621796	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326612	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326613	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326614	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326615	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326616	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326617	Curb Ramps	Northwest Corner Of Donovan Street @ 33.925343358372, - 118.143979310989	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326618	Curb Ramps	Southwest Corner Of Quoit Street @ 33.923892251877, - 118.145116567612		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326619	Curb Ramps	Southwest Corner Of Quoit Street @ 33.923892251877, - 118.145116567612		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326620	Curb Ramps	Southwest Corner Of Quoit Street @ 33.923892251877, - 118.145116567612	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326621	Curb Ramps	Northwest Corner Of Hondo Street @ 33.924862626443, - 118.144311904907		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326622	Curb Ramps	Northwest Corner Of Quoit Street @ 33.924025790317, - 118.144987821579		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326623	Curb Ramps	Northwest Corner Of Quoit Street @ 33.924025790317, - 118.144987821579		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326624	Curb Ramps	Northwest Corner Of Quoit Street @ 33.924025790317, - 118.144987821579	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326625	Curb Ramps	Northwest Corner Of Quoit Street @ 33.924025790317, - 118.144987821579	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326626	Curb Ramps	Southeast Corner Of Leeds Street @ 33.922503439690, - 118.145835399628		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326627	Curb Ramps	Southeast Corner Of Leeds Street @ 33.922503439690, - 118.145835399628		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326628	Curb Ramps	Southeast Corner Of Leeds Street @ 33.922503439690, - 118.145835399628		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326630	Curb Ramps	Southeast Corner Of Leeds Street @ 33.922503439690, - 118.145835399628	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326629	Curb Ramps	Southeast Corner Of Leeds Street @ 33.922503439690, - 118.145835399628	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326631	Curb Ramps	Northwest Corner Of Lankin Street @ 33.923366998648, - 118.145502805710		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326632	Curb Ramps	Northwest Corner Of Lankin Street @ 33.923366998648, - 118.145502805710		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326634	Curb Ramps	Northwest Corner Of Lankin Street @ 33.923366998648, - 118.145502805710	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326633	Curb Ramps	Northwest Corner Of Lankin Street @ 33.923366998648, - 118.145502805710	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326635	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326636	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326637	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326638	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326640	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326639	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.932011008482, -118.138915300369	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326641	Curb Ramps	Northwest Corner Of Boyne Street @ 33.929028879695, -118.141211271286		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326642	Curb Ramps	Southwest Corner Of Alameda Street @ 33.927729172987, - 118.142187595367		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326643	Curb Ramps	Southwest Corner Of Alameda Street @ 33.927729172987, - 118.142187595367		Curb Ramp Width	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326644	Curb Ramps	Southwest Corner Of Alameda Street @ 33.927729172987, - 118.142187595367		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326645	Curb Ramps	Southwest Corner Of Alameda Street @ 33.927729172987, - 118.142187595367		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326646	Curb Ramps	Southwest Corner Of Alameda Street @ 33.927729172987, - 118.142187595367	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326647	Curb Ramps	Northwest Corner Of Alameda Street @ 33.927871607566, - 118.142058849335		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326648	Curb Ramps	Northwest Corner Of Alameda Street @ 33.927871607566, - 118.142058849335		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326649	Curb Ramps	Northwest Corner Of Alameda Street @ 33.927871607566, - 118.142058849335		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326650	Curb Ramps	Northwest Corner Of Alameda Street @ 33.927871607566, - 118.142058849335	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326670	Curb Ramps	Southwest Corner Of Lankin Street @ 33.923206751255, - 118.145620822906		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326671	Curb Ramps	Southwest Corner Of Lankin Street @ 33.923206751255, - 118.145620822906		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326672	Curb Ramps	Southwest Corner Of Lankin Street @ 33.923206751255, - 118.145620822906	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326673	Curb Ramps	Southwest Corner Of Boyne Street @ 33.928815230640, - 118.141340017319		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326674	Curb Ramps	Southwest Corner Of Boyne Street @ 33.928815230640, - 118.141340017319		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326675	Curb Ramps	Southwest Corner Of Boyne Street @ 33.928815230640, - 118.141340017319		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90241	326676	Curb Ramps	Southwest Corner Of Boyne Street @ 33.928815230640, - 118.141340017319	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476109	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476110	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091		Curb Ramp Width	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476111	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476112	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476113	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard Downey, CA 90242	476114	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476115	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476116	Curb Ramps	Southeast Corner of Davis Street @ 33.936746592444, - 118.135113269091	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476185	Curb Ramps	West Side North of Phlox Avenue - 4th @ 33.939419143636, - 118.133798986673		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476119	Curb Ramps	West Side North of Phlox Avenue - 4th @ 33.939419143636, - 118.133798986673	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476157	Curb Ramps	West Side North of Phlox Avenue - 1st @ 33.939254475963, - 118.133894205093		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476158	Curb Ramps	West Side North of Phlox Avenue - 1st @ 33.939254475963, - 118.133894205093	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476159	Curb Ramps	Northeast Corner of Davis Street @ 33.936924616780, - 118.135001957417		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476160	Curb Ramps	Northeast Corner of Davis Street @ 33.936924616780, - 118.135001957417		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476162	Curb Ramps	Northeast Corner of Davis Street @ 33.936924616780, - 118.135001957417	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476163	Curb Ramps	Northeast Corner of Davis Street @ 33.936924616780, - 118.135001957417	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476161	Curb Ramps	Northeast Corner of Davis Street @ 33.936924616780, - 118.135001957417	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476164	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476165	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476166	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476167	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476168	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476169	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476170	Curb Ramps	Northeast Corner of Texas Street @ 33.936171348764, - 118.135539740324	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476171	Curb Ramps	West Side North of Phlox Avenue - 2nd @ 33.939419143636, - 118.133798986673		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476172	Curb Ramps	West Side North of Phlox Avenue - 2nd @ 33.939419143636, - 118.133798986673		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476173	Curb Ramps	West Side North of Phlox Avenue - 2nd @ 33.939419143636, - 118.133798986673		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476174	Curb Ramps	West Side North of Phlox Avenue - 2nd @ 33.939419143636, - 118.133798986673	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476175	Curb Ramps	West Side North of Phlox Avenue - 3rd @ 33.939419143636, - 118.133798986673		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Downey Avenue - Texas Street to Firestone Boulevard - Texas Street to Firestone Boulevard	476176	Curb Ramps	West Side North of Phlox Avenue - 3rd @ 33.939419143636, - 118.133798986673	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315698	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315699	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315700	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315701	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315702	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315703	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914032085437, - 118.121137619019	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315704	Curb Ramps	Northwest Corner Of Spry Street @ 33.920633849069, - 118.121148347855		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315705	Curb Ramps	Northwest Corner Of Spry Street @ 33.920633849069, - 118.121148347855		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315706	Curb Ramps	Northwest Corner Of Spry Street @ 33.920633849069, - 118.121148347855		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315707	Curb Ramps	Northwest Corner Of Spry Street @ 33.920633849069, - 118.121148347855	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315708	Curb Ramps	Northwest Corner Of Spry Street @ 33.920633849069, - 118.121148347855	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315709	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315710	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315711	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315712	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315713	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315714	Curb Ramps	Southeast Corner Of Spry Street @ 33.920638300524, - 118.120955228806	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315715	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315716	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315717	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315718	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315721	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315719	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315720	Curb Ramps	Southwest Corner Of Spry Street @ 33.920622720431, - 118.121151030064	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315722	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916818866657, - 118.121140301228	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315723	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916818866657, - 118.121140301228	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315724	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315725	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315726	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315729	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315727	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315728	Curb Ramps	Southwest Corner Of Angell Street @ 33.912774442663, - 118.121129572392	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315730	Curb Ramps	Southeast Corner Of Washburn Road @ 33.924250579552, - 118.121014237404		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315731	Curb Ramps	Southeast Corner Of Washburn Road @ 33.924250579552, - 118.121014237404		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315732	Curb Ramps	Southeast Corner Of Washburn Road @ 33.924250579552, - 118.121014237404		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315733	Curb Ramps	Southeast Corner Of Washburn Rroad @ 33.924250579552, - 118.121014237404		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315736	Curb Ramps	Southeast Corner Of Washburn Rroad @ 33.924250579552, - 118.121014237404	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315734	Curb Ramps	Southeast Corner Of Washburn Rroad @ 33.924250579552, - 118.121014237404	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315735	Curb Ramps	Southeast Corner Of Washburn Rroad @ 33.924250579552, - 118.121014237404	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315737	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315738	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315739	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315742	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315740	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315741	Curb Ramps	Northeast Corner Of Spry Street @ 33.920807455640, - 118.120947182179	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315752	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914154509848, - 118.121116161346		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315753	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914154509848, - 118.121116161346		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315754	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914154509848, - 118.121116161346		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road	315755	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914154509848, - 118.121116161346	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315756	Curb Ramps	Northwest Corner Of Angell Street @ 33.912896868881, - 118.121132254601		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315757	Curb Ramps	Northwest Corner Of Angell Street @ 33.912896868881, - 118.121132254601		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315758	Curb Ramps	Northwest Corner Of Angell Street @ 33.912896868881, - 118.121132254601		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315759	Curb Ramps	Northwest Corner Of Angell Street @ 33.912896868881, - 118.121132254601	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315760	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315761	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315762	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315765	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315766	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315763	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315764	Curb Ramps	Southwest Corner Of Priscilla Street @ 33.911541266949, - 118.121132254601	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315767	Curb Ramps	Southwest Corner Of Foster Road		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315768	Curb Ramps	Southwest Corner Of Foster Road		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/23	
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315769	Curb Ramps	Southwest Corner Of Foster Road @ 33.909882906855, - 118.121137619019	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315770	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315771	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315772	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315773	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315775	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315776	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	315774	Curb Ramps	Southwest Corner Of Washburn Road @ 33.924235120, - 118.121148347855	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316853	Curb Ramps	Southeast Corner Of Angell Street @ 33.912790024191, - 118.120923042297		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316854	Curb Ramps	Southeast Corner Of Angell Street @ 33.912790024191, - 118.120923042297		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316855	Curb Ramps	Southeast Corner Of Angell Street @ 33.912790024191, - 118.120923042297		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316856	Curb Ramps	Southeast Corner Of Angell Street @ 33.912790024191, - 118.120923042297	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316857	Curb Ramps	Southeast Corner Of Imperial Highway Service Road @ 33.916825544138, - 118.120944499969		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316858	Curb Ramps	Southeast Corner Of Imperial Highway Service Road @ 33.916825544138, - 118.120944499969	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316859	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316860	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316861	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316862	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316863	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316864	Curb Ramps	Southeast Corner Of Adoree Street @ 33.914036537237, - 118.120928406715	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316865	Curb Ramps	Northeast Corner Of Angell Street @ 33.912954743032, - 118.120936453342		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316866	Curb Ramps	Northeast Corner Of Angell Street @ 33.912954743032, - 118.120936453342		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316867	Curb Ramps	Northeast Corner Of Angell Street @ 33.912954743032, - 118.120936453342		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316868	Curb Ramps	Northeast Corner Of Angell Street @ 33.912954743032, - 118.120936453342		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316869	Curb Ramps	Northeast Corner Of Foster Road		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316870	Curb Ramps	Northeast Corner Of Foster Road		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316871	Curb Ramps	Northeast Corner Of Foster Road @ 33.909891810888, - 118.120925724506	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	326317	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	326318	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	326319	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316877	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316878	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Dunrobin Avenue - Foster Road to Washburn Road - Dunrobin Avenue - Foster Road to Washburn Road Downey, CA 90424	316876	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914185672398, - 118.120928406715	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310753	Curb Ramps	Southeast Corner Of Prichard Street @ 33.907246159172, - 118.148992359638	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310756	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.905761352735, - 118.149988800287		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/23
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310757	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.905761352735, - 118.149988800287		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310758	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.905761352735, - 118.149988800287	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310759	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.905761352735, - 118.149988800287	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310760	Curb Ramps	Southwest Corner Of Golden Street @ 33.908871180052, - 118.147895336151	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310761	Curb Ramps	Southwest Corner Of Golden Street @ 33.908871180052, - 118.147895336151	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310762	Curb Ramps	Southwest Corner Of Golden Street @ 33.908871180052, - 118.147895336151	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310763	Curb Ramps	Northwest Corner Of Century Boulevard @ 33.905828136189, - 118.150136321783		Appurtenances	Provide a compliant curb ramp free of appurtenances.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310764	Curb Ramps	Northwest Corner Of Century Boulevard @ 33.905828136189, - 118.150136321783	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310765	Curb Ramps	Northwest Corner Of Century Boulevard @ 33.905828136189, - 118.150136321783	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Earnshaw Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310766	Curb Ramps	Southeast Corner Of Golden Street @ 33.908866727982, - 118.147889971733	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326324	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326325	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326326	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326327	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318778	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318776	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318777	Curb Ramps	Southeast Corner Of Angell Street @ 33.912899094811, - 118.120054006577	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326328	Curb Ramps	Southeast Corner Of Foster Road @ 33.912903546670, - 118.120054006577		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318780	Curb Ramps	Southeast Corner Of Foster Road @ 33.912903546670, - 118.120054006577	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318781	Curb Ramps	Northeast Corner Of Foster Road @ 33.909871776813, - 118.120027184486	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326330	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326331	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326332	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	326333	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318790	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318788	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Eastbrook Avenue - Foster Road to Angell Street - Eastbrook Avenue - Foster Road to Angell Street Downey, CA 90424	318789	Curb Ramps	Southwest Corner Of Angell Street @ 33.912919128175, - 118.119842112064	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street Downey, CA 90424	316917	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914201253668, - 118.119844794273		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street Downey, CA 90424	316918	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914201253668, - 118.119844794273		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316919	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914201253668, - 118.119844794273		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316920	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914201253668, - 118.119844794273	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316921	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914201253668, - 118.119844794273	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316938	Curb Ramps	Northeast Corner Of Cheddar Street @ 33.915325323518, - 118.119858205318		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316939	Curb Ramps	Northeast Corner Of Cheddar Street @ 33.915325323518, - 118.119858205318		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316940	Curb Ramps	Northeast Corner Of Cheddar Street @ 33.915325323518, - 118.119858205318		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316941	Curb Ramps	Northeast Corner Of Cheddar Street @ 33.915325323518, - 118.119858205318	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Eastbrook Avenue - Imperial Highway Service Road to Adoree Street - Eastbrook Avenue - Imperial Highway Service Road to Adoree Street	316942	Curb Ramps	Northeast Corner Of Cheddar Street @ 33.915325323518, - 118.119858205318	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End	356457	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End	356458	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End	356459	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End	356460	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356461	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356462	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932125618064, - 118.095661997795	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356463	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356464	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356465	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356470	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356471	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356466	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356467	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/23
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356468	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Elmcroft Avenue - Cecilia Street to End - Elmcroft Avenue - Cecilia Street to End Downey, CA 90424	356469	Curb Ramps	Northwest Corner of Cecilia Street @ 33.932126730778, - 118.095855116844	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466001	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466002	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466003	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466004	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466005	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466006	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street Downey, CA 90242	466007	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466008	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466009	Curb Ramps	Northwest Corner of Flores Street @ 33.924399696836, - 118.161494135857	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466010	Curb Ramps	East Side South of Amigos Avenue @ 33.925272138998, - 118.160399794579		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466011	Curb Ramps	East Side South of Amigos Avenue @ 33.925272138998, - 118.160399794579		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466012	Curb Ramps	East Side South of Amigos Avenue @ 33.925272138998, - 118.160399794579		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466013	Curb Ramps	East Side South of Amigos Avenue @ 33.925272138998, - 118.160399794579	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466014	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466015	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466016	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466017	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466019	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466018	Curb Ramps	Southwest Corner of Imperial Highway @ 33.927297416712, - 118.159278631210	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466020	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927226198972, - 118.159375190735		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466021	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927226198972, - 118.159375190735		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466022	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927226198972, - 118.159375190735		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466023	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466024	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466025	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466028	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466026	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466027	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927141627828, - 118.159407377243	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466029	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466030	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466031	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466032	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466036	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466033	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466034	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466035	Curb Ramps	Southwest Corner of Flores Street @ 33.924123718374, - 118.161579966545	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466052	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466053	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466054	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466055	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466056	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466060	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466057	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466058	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Erickson Avenue - Imperial Highway to Flores Street - Imperial Highway to Flores Street	466059	Curb Ramps	Southeast Corner of Imperial Highway @ 33.927146078943, - 118.159058690071	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue	352549	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue	352550	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396		Curb Ramp Width	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	352551	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	352552	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	352553	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	352554	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Eucalyptus Street - Birchdale Avenue To Brookshire Avenue - Birchdale Avenue To Brookshire Avenue Downey, CA 90242	352555	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.921673257490, - 118.139428943396	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Everest Street - Brookshire Avenue To Birchdale Avenue - Brookshire Avenue To Birchdale Avenue Downey, CA 90242	351455	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.920814132809, - 118.140068650246		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/23
Everest Street - Brookshire Avenue To Birchdale Avenue - Brookshire Avenue To Birchdale Avenue Downey, CA 90242	351456	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.920814132809, - 118.140068650246		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Everest Street - Brookshire Avenue To Birchdale Avenue - Brookshire Avenue To Birchdale Avenue Downey, CA 90242	351457	Curb Ramps	Northwest Corner Of Birchdale Avenue @ 33.920937660337, - 118.139970749617	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357316	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357317	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388		Curb Ramp Width	Provide a compliant curb ramp.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357318	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357319	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357320	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357321	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357322	Curb Ramps	Southeast Corner of Muller Street @ 33.933374073620, - 118.094796985388	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357323	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932092236648, - 118.094813078642		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357324	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932092236648, - 118.094813078642		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357325	Curb Ramps	Northeast Corner of Cecilia Street @ 33.932092236648, - 118.094813078642		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357342	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357343	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357344	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357345	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357346	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357347	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357348	Curb Ramps	Northeast Corner of Buell Street @ 33.932794356338, - 118.094817101955	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357355	Curb Ramps	Northeast Corner of Quinn Street @ 33.934180775364, - 118.094821125269		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357356	Curb Ramps	Northeast Corner of Quinn Street @ 33.934180775364, - 118.094821125269		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357357	Curb Ramps	Northeast Corner of Quinn Street @ 33.934180775364, - 118.094821125269		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357358	Curb Ramps	Northeast Corner of Quinn Street @ 33.934180775364, - 118.094821125269	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357359	Curb Ramps	Northeast Corner of Quinn Street @ 33.934180775364, - 118.094821125269	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357360	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357361	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357362	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357363	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357364	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357365	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357366	Curb Ramps	Southeast Corner of Buell Street @ 33.932677522243, - 118.094855993986	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357367	Curb Ramps	Northeast Corner of Muller Street @ 33.933499808326, - 118.094819784164		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357368	Curb Ramps	Northeast Corner of Muller Street @ 33.933499808326, - 118.094819784164		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357369	Curb Ramps	Northeast Corner of Muller Street @ 33.933499808326, - 118.094819784164		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357371	Curb Ramps	Northeast Corner of Muller Street @ 33.933499808326, - 118.094819784164	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357370	Curb Ramps	Northeast Corner of Muller Street @ 33.933499808326, - 118.094819784164	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357372	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357373	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357374	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357375	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357376	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/23
Fairford Avenue - Florance Avenue to Cecilia Street - Fairford Avenue - Florance Avenue to Cecilia Street Downey, CA 90424	357377	Curb Ramps	Southeast Corner of Quinn Street @ 33.934045027467, - 118.094813078642	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/23
Farm Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	460699	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Farm Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue Downey, CA 90242	460700	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809		Curb Ramp Width	Provide a compliant curb ramp.		6/30/23



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460701	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460702	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460311	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460312	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.950384403721, - 118.132530301809	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460705	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.950252019090, - 118.132641613483		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460706	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.950252019090, - 118.132641613483		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount	460707	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.950252019090, - 118.132641613483		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Farm Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460330	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.950252019090, - 118.132641613483	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Farm Street - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460331	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.950252019090, - 118.132641613483	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane	322328	Curb Ramps	Northwest Corner Of Foster Road @ 33.909898488912, - 118.115132153034		Curb Ramp Width	Provide a compliant curb ramp.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane	322329	Curb Ramps	Northwest Corner Of Foster Road @ 33.909898488912, - 118.115132153034		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane	319607	Curb Ramps	Northwest Corner Of Foster Road @ 33.909898488912, - 118.115132153034	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane	322330	Curb Ramps	Northwest Corner Of Laurelwood Lane @ 33.913350957318, - 118.115566670895		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane	322331	Curb Ramps	Northwest Corner Of Laurelwood Lane @ 33.913350957318, - 118.115566670895		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	322332	Curb Ramps	Northwest Corner Of Laurelwood Lane @ 33.913350957318, - 118.115566670895		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	319612	Curb Ramps	Northwest Corner Of Laurelwood Lane @ 33.913350957318, - 118.115566670895	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	319611	Curb Ramps	Northwest Corner Of Laurelwood Lane @ 33.913350957318, - 118.115566670895	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	322333	Curb Ramps	Southeast Corner Of Laurelwood Lane @ 33.913255242800, - 118.115545213223		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	322334	Curb Ramps	Southeast Corner Of Laurelwood Lane @ 33.913255242800, - 118.115545213223		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	322335	Curb Ramps	Southeast Corner Of Laurelwood Lane @ 33.913255242800, - 118.115545213223		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	319628	Curb Ramps	Southeast Corner Of Laurelwood Lane @ 33.913255242800, - 118.115545213223	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Faust Avenue - Foster Road to Laurelwood Lane - Faust Avenue - Foster Road to Laurelwood Lane Downey, CA 90424	319629	Curb Ramps	Southeast Corner Of Laurelwood Lane @ 33.913255242800, - 118.115545213223	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/23	
Fidler Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313336	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.131410479546		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/23	
Fidler Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313337	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.131410479546		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Fidler Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313338	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.131410479546		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/23	
Fidler Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313339	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.131410479546	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/23	
Fidler Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	313340	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.131410479546	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/23	
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415722	Curb Ramps	Southeast Corner @ 33.938917351287, - 118.121813535690		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/23	
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415723	Curb Ramps	Southeast Corner @ 33.938917351287, - 118.121813535690		Grade Break	Provide a compliant curb ramp.	6/30/23	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415724	Curb Ramps	Southeast Corner @ 33.938917351287, - 118.121813535690	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415725	Curb Ramps	Southeast Corner @ 33.938917351287, - 118.121813535690	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415726	Curb Ramps	Southeast Corner @ 33.938917351287, - 118.121813535690	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415727	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415728	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415729	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415730	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard · Fifth Street & Lakewood Boulevard Downey, CA 90242	415731	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415732	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415733	Curb Ramps	Southwest Corner @ 33.939075343876, - 118.122105896473	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415734	Curb Ramps	Northeast Corner @ 33.939089807971, - 118.121700882912		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415735	Curb Ramps	Northeast Corner @ 33.939089807971, - 118.121700882912		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415736	Curb Ramps	Northeast Corner @ 33.939089807971, - 118.121700882912	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415737	Curb Ramps	Northeast Corner @ 33.939089807971, - 118.121700882912	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415739	Curb Ramps	Northwest Corner @ 33.939227773067, - 118.122012019157	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/23
Fifth Street & Lakewood Boulevard - Fifth Street & Lakewood Boulevard Downey, CA 90242	415738	Curb Ramps	Northwest Corner @ 33.939227773067, - 118.122012019157	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Arnett Street - Firestone Boulevard & Arnett Street Downey, CA 90242	420539	Curb Ramps	Southwest Corner @ 33.947059150926, - 118.151866346598	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Firestone Boulevard & Arnett Street - Firestone Boulevard & Arnett Street Downey, CA 90242	420538	Curb Ramps	Southwest Corner @ 33.947059150926, - 118.151866346598	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Firestone Boulevard & Arnett Street - Firestone Boulevard & Arnett Street Downey, CA 90242	420540	Curb Ramps	Southeast Corner @ 33.947059150926, - 118.151866346598	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Firestone Boulevard & Arnett Street - Firestone Boulevard & Arnett Street Downey, CA 90242	420541	Curb Ramps	Southeast Corner @ 33.947059150926, - 118.151866346598	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/23
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426170	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.938099568062, - 118.129594624043		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/23
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426171	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.938099568062, - 118.129594624043	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/23
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426172	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.938357699125, - 118.129353225231		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/23
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426173	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.938357699125, - 118.129353225231		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/23
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426174	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.938357699125, - 118.129353225231		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426175	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.938357699125, - 118.129353225231	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426283	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.938448934918, - 118.129608035088		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426284	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.938448934918, - 118.129608035088		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Firestone Boulevard & Brookshire Avenue - Firestone Boulevard & Brookshire Avenue Downey, CA 90241	426285	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.938448934918, - 118.129608035088	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426050	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.939256701204, - 118.131217360497		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426051	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.939256701204, - 118.131217360497		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426053	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.939256701204, - 118.131217360497	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426052	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.939256701204, - 118.131217360497	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426161	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.939325683645, - 118.131402432919		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426162	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.939325683645, - 118.131402432919		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426163	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.939325683645, - 118.131402432919	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426164	Curb Ramps	Southwest Corner of Firestone Boulevard - 1st @ 33.939109835176, - 118.131552636623		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426165	Curb Ramps	Southwest Corner of Firestone Boulevard - 1st @ 33.939109835176, - 118.131552636623	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426166	Curb Ramps	Southwest Corner of Firestone Boulevard - 1st @ 33.939109835176, - 118.131552636623	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426167	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.939031951574, - 118.131421208382		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426168	Curb Ramps	Southwest Corner of Firestone Boulevard - 2nd @ 33.939109835176, - 118.131552636623		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Dolan Avenue - Firestone Boulevard & Dolan Avenue Downey, CA 90241	426169	Curb Ramps	Southwest Corner of Firestone Boulevard - 2nd @ 33.939109835176, - 118.131552636623	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/25
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425877	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.935489284975, - 118.124248981476		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425878	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.935489284975, -118.124248981476	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425978	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.935825310559, -118.124096095562		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425979	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.935825310559, -118.124096095562		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425980	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.935825310559, -118.124096095562		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425981	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.935825310559, -118.124096095562	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425982	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.935346863135, -118.123860061169		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425983	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.935346863135, -118.123860061169	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425984	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.935346863135, - 118.123860061169	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425985	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.935671762609, - 118.123733997345		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425986	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.935671762609, - 118.123733997345		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425987	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.935671762609, - 118.123733997345	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/25
Firestone Boulevard & Lakewood Boulevard - Firestone Boulevard & Lakewood Boulevard Downey, CA 90241	425988	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.935671762609, - 118.123733997345	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400295	Curb Ramps	Southwest Corner @ 33.937275101104, - 118.127827048302		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400296	Curb Ramps	Northwest Corner @ 33.937482053074, - 118.127703666687	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400297	Curb Ramps	Northeast Corner @ 33.937390816246, - 118.127518594265		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400298	Curb Ramps	Northeast Corner @ 33.937390816246, - 118.127518594265	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400299	Curb Ramps	Northeast Corner @ 33.937390816246, - 118.127518594265	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Firestone Boulevard & Patton Road - Firestone Boulevard & Patton Road Downey, CA 90242	400300	Curb Ramps	Northeast Corner @ 33.937390816246, - 118.127518594265	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426399	Curb Ramps	Northwest Corner of Firestone Boulevard - Right @ 33.945086632795, - 118.142053484917		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426400	Curb Ramps	Northwest Corner of Firestone Boulevard - Right @ 33.945086632795, - 118.142053484917	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426401	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.944772894733, - 118.142082989216		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426402	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.944772894733, - 118.142082989216	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426504	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.944970928112, - 118.141868412495	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426505	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.944841872704, - 118.142289519310	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426506	Curb Ramps	Northwest Corner of Firestone Boulevard - Left @ 33.945084407706, - 118.142115175724		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426507	Curb Ramps	Northwest Corner of Firestone Boulevard - Left @ 33.945084407706, - 118.142115175724	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Firestone Boulevard & Rives Avenue - Firestone Boulevard & Rives Avenue Downey, CA 90241	426508	Curb Ramps	Northwest Corner of Firestone Boulevard - Left @ 33.945084407706, - 118.142115175724	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426509	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426510	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426511	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967		Curb Ramp Slope	Provide a compliant curb ramp.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426514	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426512	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426513	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947536420018, - 118.154386281967	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426515	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426516	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426517	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426518	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426519	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426520	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947821222677, - 118.154356777668	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426521	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426522	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426523	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426524	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426525	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426526	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947852372910, - 118.154547214508	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426527	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.947587595566, - 118.154638409615		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Firestone Boulevard & Ryerson Avenue - Firestone Boulevard & Ryerson Avenue Downey, CA 90241	426528	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.947587595566, - 118.154638409615	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425989	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.934065055859, - 118.120571672916		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425990	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.933842517908, - 118.120764791965	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425991	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.933949336197, - 118.120279312134		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425992	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.933949336197, - 118.120279312134		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425993	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.933949336197, - 118.120279312134		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Firestone Boulevard & Stonewood Center - Firestone Boulevard & Stonewood Center Downey, CA 90241	425994	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.933949336197, - 118.120279312134	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479392	Curb Ramps	Northwest Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673		Grade Break	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479393	Curb Ramps	Northwest Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479394	Curb Ramps	Northeast Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479395	Curb Ramps	Northeast Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479396	Curb Ramps	Northeast Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard	479397	Curb Ramps	Northeast Corner of Embassy Suites Driveway @ 33.938847255890, - 118.130436837673	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479667	Curb Ramps	Southeast Corner of Albertsons Driveway @ 33.945689629652, - 118.143780827522		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479668	Curb Ramps	Southeast Corner of Albertsons Driveway @ 33.945689629652, - 118.143780827522		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479669	Curb Ramps	Southeast Corner of Albertsons Driveway @ 33.945689629652, - 118.143780827522		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479670	Curb Ramps	Southeast Corner of Albertsons Driveway @ 33.945689629652, - 118.143780827522	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479671	Curb Ramps	Northwest Corner of Nova Storage Driveway @ 33.948537675151, - 118.158205747604		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479674	Curb Ramps	Northwest Corner of Nova Storage Driveway @ 33.948537675151, - 118.158205747604	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479672	Curb Ramps	Northwest Corner of Nova Storage Driveway @ 33.948537675151, - 118.158205747604	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479673	Curb Ramps	Northwest Corner of Nova Storage Driveway @ 33.948537675151, - 118.158205747604	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479675	Curb Ramps	Southwest Corner of Albertsons Driveway @ 33.945689629652, - 118.143780827522		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479676	Curb Ramps	Southeast Corner of Mcdonald's Driveway @ 33.945162285772, - 118.142866194248		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479677	Curb Ramps	Northeast Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479678	Curb Ramps	Northeast Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479679	Curb Ramps	Northeast Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479680	Curb Ramps	Northeast Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479681	Curb Ramps	Northeast Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479682	Curb Ramps	Northeast Corner of Home Depot Driveway @ 33.948388600134, - 118.157299160957		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479683	Curb Ramps	Northeast Corner of Home Depot Driveway @ 33.948388600134, - 118.157299160957		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479684	Curb Ramps	Northeast Corner of Home Depot Driveway @ 33.948388600134, - 118.157299160957	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479685	Curb Ramps	Northeast Corner of Home Depot Driveway @ 33.948388600134, - 118.157299160957	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479686	Curb Ramps	Northwest Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479689	Curb Ramps	Northwest Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479687	Curb Ramps	Northwest Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479688	Curb Ramps	Northwest Corner of Taco Bell Drive @ 33.948203924749, - 118.156333565712	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479826	Curb Ramps	Northwest Corner of Office Max Driveway @ 33.948203924749, - 118.156333565712		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479827	Curb Ramps	Northwest Corner of Office Max Driveway @ 33.948203924749, - 118.156333565712	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479828	Curb Ramps	Northeast Corner of Office Max Driveway @ 33.948157199588, - 118.156089484692		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479829	Curb Ramps	Northeast Corner of Office Max Driveway @ 33.948157199588, - 118.156089484692	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479830	Curb Ramps	Northeast Corner of Nova Storage Driveway @ 33.948504300170, - 118.158039450645		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479831	Curb Ramps	Northeast Corner of Nova Storage Driveway @ 33.948504300170, - 118.158039450645	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479832	Curb Ramps	Northwest Corner of Home Depot Driveway @ 33.948442170, - 118.157690763474		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479833	Curb Ramps	Northwest Corner of Home Depot Driveway @ 33.948442170, - 118.157690763474		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479834	Curb Ramps	Northwest Corner of Home Depot Driveway @ 33.948442170, - 118.157690763474		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479835	Curb Ramps	Northwest Corner of Home Depot Driveway @ 33.948442170, - 118.157690763474		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits	479836	Curb Ramps	Northwest Corner of Home Depot Driveway @ 33.948442170, - 118.157690763474	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit	332501	Curb Ramps	South Side West Of City Limit - 4th @ 33.928445794549, - 118.110414147377		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332502	Curb Ramps	South Side West Of City Limit - 4th @ 33.928445794549, - 118.110414147377		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332503	Curb Ramps	South Side West Of City Limit - 4th @ 33.928445794549, - 118.110414147377	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332509	Curb Ramps	South Side West Of City Limit - 3rd @ 33.928321165146, - 118.110215663910		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332510	Curb Ramps	South Side West Of City Limit - 3rd @ 33.928321165146, - 118.110215663910	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464568	Curb Ramps	Southwest Corner of Pomeroy Road @ 33.947803422539, - 118.146571666002	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	465727	Curb Ramps	Southeast Corner of Old River School Road @ 33.9485311156, - 118.147911429405		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464585	Curb Ramps	Southeast Corner of Old River School Road @ 33.9485311156, - 118.147911429405	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	465728	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	465729	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	465730	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	465731	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464590	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464591	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464592	Curb Ramps	Northeast Corner of Old River School Road @ 33.948675624935, - 118.147829622030	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464593	Curb Ramps	Northwest Corner of Pomeroy Road @ 33.947931360950, - 118.146467059851	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Firestone Place - Old River School Road to Pomeroy Road - Old River School Road to Pomeroy Road Downey, CA 90242	464594	Curb Ramps	Northwest Corner of Pomeroy Road @ 33.947931360950, - 118.146467059851	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349133	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349134	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349135	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349136	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349137	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349138	Curb Ramps	Northwest Corner @ 33.944045284991, - 118.110392689705	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue Downey, CA 90424	349139	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349140	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349141	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349142	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349143	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349146	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349147	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349144	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349145	Curb Ramps	Southeast Corner @ 33.944045284991, - 118.110392689705	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349148	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349149	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349150	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349151	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349152	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Woodruff Avenue - Florence Avenue & Woodruff Avenue - Downey, CA 90424	349153	Curb Ramps	Southwest Corner @ 33.944045284991, - 118.110392689705	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354171	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354172	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354173	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354174	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354175	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354176	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354177	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354178	Curb Ramps	Southeast Corner @ 33.936133518290, - 118.094813078642	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354179	Curb Ramps	Northwest Corner @ 33.936133518290, - 118.094813078642		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354180	Curb Ramps	Northwest Corner @ 33.936133518290, - 118.094813078642		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354181	Curb Ramps	Northwest Corner @ 33.936133518290, - 118.094813078642		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354182	Curb Ramps	Northwest Corner @ 33.936133518290, - 118.094813078642	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue & Fairford Avenue - Florence Avenue & Fairford Avenue - Downey, CA 90424	354183	Curb Ramps	Northwest Corner @ 33.936133518290, - 118.094813078642	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue - Downey, CA 90424	352515	Curb Ramps	Southwest Corner @ 33.941045776107, - 118.104405999184		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue - Downey, CA 90424	352516	Curb Ramps	Southwest Corner @ 33.941045776107, - 118.104405999184		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue - Downey, CA 90424	352517	Curb Ramps	Southwest Corner @ 33.941045776107, - 118.104405999184	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue Downey, CA 90424	352541	Curb Ramps	Northwest Corner @ 33.941045776107, - 118.104405999184		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue Downey, CA 90424	352542	Curb Ramps	Northwest Corner @ 33.941045776107, - 118.104405999184		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue & Mattock Avenue - Florence Avenue & Mattock Avenue Downey, CA 90424	352543	Curb Ramps	Northwest Corner @ 33.941045776107, - 118.104405999184	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353727	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353728	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353729	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036		Grade Break	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353730	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353731	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353732	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353733	Curb Ramps	Southwest Corner @ 33.958774276707, - 118.140720427036	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353816	Curb Ramps	Northeast Corner @ 33.958889962623, - 118.140315413475		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353817	Curb Ramps	Northeast Corner @ 33.958889962623, - 118.140315413475		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353818	Curb Ramps	Northeast Corner @ 33.958889962623, - 118.140315413475	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353819	Curb Ramps	Northeast Corner @ 33.958889962623, - 118.140315413475	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353820	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353821	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353822	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353823	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353824	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353825	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353826	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353827	Curb Ramps	Northwest Corner @ 33.959010097831, - 118.140500485897	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353828	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353829	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353830	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353831	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353832	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353833	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353834	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353835	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Old River School Road & Teacum Road - Florence Avenue & Old River School Road & Teacum Road Downey, CA 90240	353836	Curb Ramps	Southeast Corner @ 33.958643017496, - 118.140465617180	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356916	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356917	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356918	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356919	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356922	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356923	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356920	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	356921	Curb Ramps	Southwest Corner @ 33.955582840704, - 118.134445399046	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	357006	Curb Ramps	Southeast Corner @ 33.955523883110, - 118.134260326624		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue - Downey, CA 90240	357007	Curb Ramps	Southeast Corner @ 33.955523883110, - 118.134260326624		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue Downey, CA 90240	357008	Curb Ramps	Southeast Corner @ 33.955523883110, - 118.134260326624		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue Downey, CA 90240	357009	Curb Ramps	Southeast Corner @ 33.955523883110, - 118.134260326624	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/25
Florence Avenue & Rives Avenue - Florence Avenue & Rives Avenue Downey, CA 90240	357010	Curb Ramps	Southeast Corner @ 33.955523883110, - 118.134260326624	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354034	Curb Ramps	Northeast Corner - Right @ 33.937113767229, - 118.096695989370		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354035	Curb Ramps	Northeast Corner - Right @ 33.937113767229, - 118.096695989370	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354036	Curb Ramps	Southwest Corner @ 33.937113767229, - 118.096695989370	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354037	Curb Ramps	Northeast Corner -Left @ 33.937113767229, - 118.096695989370		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354038	Curb Ramps	Northeast Corner -Left @ 33.937113767229, - 118.096695989370		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354039	Curb Ramps	Northwest Corner @ 33.937113767229, - 118.096695989370		Detectable Warnings Width	Provide compliant detectable warnings that are full width of the curb ramp.		6/30/25
Florence Avenue & Studebaker Road - Florence Avenue & Studebaker Road Downey, CA 90424	354040	Curb Ramps	Northwest Corner @ 33.937113767229, - 118.096695989370		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426665	Curb Ramps	Southwest Corner of Florence Avenue @ 33.954360296561, - 118.131879866123		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426666	Curb Ramps	Southwest Corner of Florence Avenue @ 33.954360296561, - 118.131879866123		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426667	Curb Ramps	Southwest Corner of Florence Avenue @ 33.954360296561, - 118.131879866123		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426669	Curb Ramps	Southwest Corner of Florence Avenue @ 33.954360296561, - 118.131879866123	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426668	Curb Ramps	Southwest Corner of Florence Avenue @ 33.954360296561, - 118.131879866123	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426670	Curb Ramps	Northeast Corner of Florence Avenue @ 33.954475988479, - 118.131536543369	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426671	Curb Ramps	Northeast Corner of Florence Avenue @ 33.954475988479, - 118.131536543369	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Tweedy Lane - Florence Avenue & Tweedy Lane Downey, CA 90241	426672	Curb Ramps	Northeast Corner of Florence Avenue @ 33.954475988479, - 118.131536543369	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356852	Curb Ramps	Northeast Corner @ 33.957310391332, - 118.137175887823		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356853	Curb Ramps	Northeast Corner @ 33.957310391332, - 118.137175887823		Curb Ramp Width	Provide a compliant curb ramp.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356854	Curb Ramps	Northeast Corner @ 33.957310391332, -118.137175887823		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356855	Curb Ramps	Northeast Corner @ 33.957310391332, -118.137175887823		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356856	Curb Ramps	Northeast Corner @ 33.957310391332, -118.137175887823	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356857	Curb Ramps	Northeast Corner @ 33.957310391332, -118.137175887823	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356858	Curb Ramps	Northeast Corner @ 33.957310391332, -118.137175887823	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356860	Curb Ramps	Northwest Corner @ 33.957396044893, -118.137364983559		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356861	Curb Ramps	Northwest Corner @ 33.957396044893, -118.137364983559		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356862	Curb Ramps	Northwest Corner @ 33.957396044893, -118.137364983559		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue & Wiley Burke Avenue - Florence Avenue & Wiley Burke Avenue Downey, CA 90240	356863	Curb Ramps	Northwest Corner @ 33.957396044893, -118.137364983559	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351652	Curb Ramps	Southeast Corner Of Bellman Avenue @ 33.947980311247, - 118.118458092213		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351653	Curb Ramps	Southeast Corner Of Bellman Avenue @ 33.947980311247, - 118.118458092213		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351654	Curb Ramps	Southeast Corner Of Bellman Avenue @ 33.947980311247, - 118.118458092213		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351656	Curb Ramps	Southeast Corner Of Bellman Avenue @ 33.947980311247, - 118.118458092213	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351655	Curb Ramps	Southeast Corner Of Bellman Avenue @ 33.947980311247, - 118.118458092213	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351657	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.951821709309, - 118.126912415028		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351658	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.951821709309, - 118.126912415028		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351659	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.951821709309, - 118.126912415028		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351660	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.951821709309, - 118.126912415028	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351661	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.951821709309, - 118.126912415028	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351662	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.949681316604, - 118.121829628944		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351663	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.949681316604, - 118.121829628944	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	355363	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	355364	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	355365	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351668	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351669	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351670	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.949801464814, - 118.122095167637	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351671	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351672	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351673	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351676	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351674	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351675	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.951258804594, - 118.125724196434	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	355366	Curb Ramps	Southwest Corner Of Bellman Avenue @ 33.948090449314, - 118.118655234575		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351752	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.948447562672, - 118.119399547577		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351753	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.948447562672, - 118.119399547577		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351754	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.948447562672, - 118.119399547577		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351755	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.951930729949, - 118.127080053091		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351756	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.951930729949, - 118.127080053091		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351757	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.951930729949, - 118.127080053091		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351758	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.951930729949, - 118.127080053091	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351759	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.951930729949, - 118.127080053091	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351760	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351761	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351762	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351765	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351763	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351764	Curb Ramps	Southeast Corner Of Western Avenue @ 33.952318975791, - 118.127879351377	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351766	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351767	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351768	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351769	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351770	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351771	Curb Ramps	Southwest Corner Of Western Avenue @ 33.952390172544, - 118.128030896187	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351772	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351773	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351774	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351775	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351776	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351778	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351777	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.951356701334, - 118.125952184200	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351779	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.947459656639, - 118.117397278547		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351780	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.947459656639, - 118.117397278547	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351781	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.953363559676, - 118.129998296499		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351782	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.953363559676, - 118.129998296499	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351783	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.948514312666, - 118.119541704655		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351785	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.948514312666, - 118.119541704655	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351786	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.948514312666, - 118.119541704655	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351784	Curb Ramps	Southwest Corner Of Birchdale Avenue @ 33.948514312666, - 118.119541704655	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349200	Curb Ramps	Northeast Corner Of Haledon Avenue @ 33.945711880377, - 118.113394081593		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349201	Curb Ramps	Northeast Corner Of Haledon Avenue @ 33.945711880377, - 118.113394081593		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349202	Curb Ramps	Northeast Corner Of Haledon Avenue @ 33.945711880377, - 118.113394081593		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349203	Curb Ramps	Northeast Corner Of Haledon Avenue @ 33.945711880377, - 118.113394081593	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349204	Curb Ramps	Northeast Corner Of Haledon Avenue @ 33.945711880377, - 118.113394081593	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349205	Curb Ramps	Northwest Corner Of Haledon Avenue @ 33.945825358983, - 118.113589882851		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349206	Curb Ramps	Northwest Corner Of Haledon Avenue @ 33.945825358983, - 118.113589882851		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349207	Curb Ramps	Northwest Corner Of Haledon Avenue @ 33.945825358983, - 118.113589882851		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349208	Curb Ramps	Northwest Corner Of Haledon Avenue @ 33.945825358983, - 118.113589882851	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349209	Curb Ramps	Northwest Corner Of Haledon Avenue @ 33.945825358983, - 118.113589882851	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349210	Curb Ramps	Northwest Corner Of Arrington Avenue @ 33.947004637503, - 118.115883171558		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349211	Curb Ramps	Northwest Corner Of Arrington Avenue @ 33.947004637503, - 118.115883171558	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349226	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349227	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349228	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349229	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349230	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349231	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349232	Curb Ramps	Southeast Corner Of Chaney Avenue @ 33.944761769249, - 118.112103939056	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349233	Curb Ramps	Southwest Corner Of Chaney Avenue @ 33.944748418666, - 118.112090528011		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349234	Curb Ramps	Southwest Corner Of Chaney Avenue @ 33.944748418666, - 118.112090528011		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349235	Curb Ramps	Southwest Corner Of Chaney Avenue @ 33.944748418666, - 118.112090528011	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349236	Curb Ramps	Southwest Corner Of Chaney Avenue @ 33.944748418666, - 118.112090528011	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350993	Curb Ramps	Southwest Corner Of Vultee Avenue @ 33.946886710386, - 118.116218447685		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350994	Curb Ramps	Southwest Corner Of Vultee Avenue @ 33.946886710386, - 118.116218447685	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350995	Curb Ramps	Southwest Corner Of Vultee Avenue @ 33.946886710386, - 118.116218447685	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482805	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482806	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482807	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482808	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482809	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 482810	Curb Ramps	South Side West of Wiley Burke Avenue @ 33.957396044893, - 118.138023465872	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 482923	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.953992083737, - 118.130607157946		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 482924	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.953992083737, - 118.130607157946		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 482925	Curb Ramps	North Side East of Smallwood Avenue - 2nd @ 33.953992083737, - 118.130607157946	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 483004	Curb Ramps	North Side East of Smallwood Avenue - 4th @ 33.953957598467, - 118.130541443825		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 483005	Curb Ramps	North Side East of Smallwood Avenue - 4th @ 33.953957598467, - 118.130541443825		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	Downey, CA 90242 483006	Curb Ramps	North Side East of Smallwood Avenue - 4th @ 33.953957598467, - 118.130541443825	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483007	Curb Ramps	North Side East of Smallwood Avenue - 3rd @ 33.953957598467, - 118.130541443825		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483008	Curb Ramps	North Side East of Smallwood Avenue - 3rd @ 33.953957598467, - 118.130541443825	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483009	Curb Ramps	South Side West of Rives Avenue @ 33.955996655125, - 118.135223239660		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483010	Curb Ramps	South Side West of Rives Avenue @ 33.955996655125, - 118.135223239660		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483011	Curb Ramps	South Side West of Rives Avenue @ 33.955996655125, - 118.135223239660		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483012	Curb Ramps	South Side West of Rives Avenue @ 33.955996655125, - 118.135223239660		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483013	Curb Ramps	South Side West of Rives Avenue @ 33.955996655125, - 118.135223239660	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483014	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.954024344139, - 118.130668848753		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483015	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.954024344139, - 118.130668848753		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue	483016	Curb Ramps	North Side East of Smallwood Avenue - 1st @ 33.954024344139, - 118.130668848753	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350852	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350853	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350854	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350856	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350857	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350855	Curb Ramps	Northeast Corner Of Downey & Sanford Road @ 33.942872640910, - 118.107782900333	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350900	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350901	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350902	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350905	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 350903	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350904	Curb Ramps	Southwest Corner Of Sideview Drive @ 33.942523292207, - 118.107039928436	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350906	Curb Ramps	Northwest Corner Of Downey & Sanford Road @ 33.942997249018, - 118.107962608337		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350907	Curb Ramps	Northwest Corner Of Downey & Sanford Road @ 33.942997249018, - 118.107962608337		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350908	Curb Ramps	Northwest Corner Of Downey & Sanford Road @ 33.942997249018, - 118.107962608337		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350909	Curb Ramps	Northwest Corner Of Downey & Sanford Road @ 33.942997249018, - 118.107962608337	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	350910	Curb Ramps	Northwest Corner Of Downey & Sanford Road @ 33.942997249018, - 118.107962608337	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352468	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352469	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352470	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352471	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352472	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352473	Curb Ramps	Southwest Corner of Lesterford Avenue @ 33.940141229875, - 118.103026002645	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352495	Curb Ramps	Northeast Corner of Pangborn Avenue @ 33.941641013464, - 118.105995208025		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352496	Curb Ramps	Northeast Corner of Pangborn Avenue @ 33.941641013464, - 118.105995208025		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352497	Curb Ramps	Northeast Corner of Pangborn Avenue @ 33.941641013464, - 118.105995208025		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352498	Curb Ramps	Northeast Corner of Pangborn Avenue @ 33.941641013464, - 118.105995208025	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352499	Curb Ramps	Northeast Corner of Pangborn Avenue @ 33.941641013464, - 118.105995208025	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352500	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352501	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352502	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352503	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352506	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352504	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352505	Curb Ramps	Northeast Corner of Eglise Avenue @ 33.943556870681, - 118.109781146050	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352507	Curb Ramps	Florance Avenue Service Road @ 33.941637675696, - 118.106148093939		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352508	Curb Ramps	Florance Avenue Service Road @ 33.941637675696, - 118.106148093939		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352509	Curb Ramps	Florance Avenue Service Road @ 33.941637675696, - 118.106148093939		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	352511	Curb Ramps	Florance Avenue Service Road @ 33.941637675696, - 118.106148093939	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352510	Curb Ramps	Florance Avenue Service Road @ 33.941637675696, - 118.106148093939	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352512	Curb Ramps	Southeast Corner of Lesterford Avenue @ 33.940235801579, - 118.103199005127	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352513	Curb Ramps	Southwest Corner of Newville Avenue @ 33.940758725576, - 118.104230314493	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue - Woodruff Avenue to Little lake Road - Florence Avenue - Woodruff Avenue to Little lake Road	Downey, CA 90424 352514	Curb Ramps	Southwest Corner of Newville Avenue @ 33.940758725576, - 118.104230314493	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo	Downey, CA 90242 483269	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo	Downey, CA 90242 483270	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo	Downey, CA 90242 483310	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo Downey, CA 90242	483311	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo Downey, CA 90242	483271	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Florence Avenue Bridge Over Rio Hondo - Florence Avenue Bridge Over Rio Hondo Downey, CA 90242	483272	Curb Ramps	Curb Ramp West of Downey - 1st @ 33.959863275400, - 118.142836689949	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466095	Curb Ramps	North Side East of End - 4th @ 33.925459089728, - 118.163736462593		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466096	Curb Ramps	North Side East of End - 4th @ 33.925459089728, - 118.163736462593		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466097	Curb Ramps	North Side East of End - 5th @ 33.925378968037, - 118.163580894470		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466098	Curb Ramps	North Side East of End - 5th @ 33.925378968037, - 118.163580894470		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466099	Curb Ramps	North Side East of End - 5th @ 33.925378968037, - 118.163580894470	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466100	Curb Ramps	North Side East of End - 1st @ 33.925623784078, - 118.166075348854		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466101	Curb Ramps	North Side East of End - 1st @ 33.925623784078, - 118.166075348854		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466102	Curb Ramps	North Side East of End - 1st @ 33.925623784078, - 118.166075348854	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466103	Curb Ramps	North Side East of End - 2nd @ 33.925681649585, - 118.165023922920		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466104	Curb Ramps	North Side East of End - 2nd @ 33.925681649585, - 118.165023922920		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466105	Curb Ramps	North Side East of End - 2nd @ 33.925681649585, - 118.165023922920		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466106	Curb Ramps	North Side East of End - 2nd @ 33.925681649585, - 118.165023922920		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466107	Curb Ramps	North Side East of End - 2nd @ 33.925681649585, - 118.165023922920	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466115	Curb Ramps	North Side East of End - 6th @ 33.924867077677, - 118.162577748299		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466116	Curb Ramps	North Side East of End - 6th @ 33.924867077677, - 118.162577748299		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466118	Curb Ramps	North Side East of End - 6th @ 33.924867077677, - 118.162577748299	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466117	Curb Ramps	North Side East of End - 6th @ 33.924867077677, - 118.162577748299	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466119	Curb Ramps	North Side East of End - 3rd @ 33.925695003158, - 118.164900541306		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466120	Curb Ramps	North Side East of End - 3rd @ 33.925695003158, - 118.164900541306		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466121	Curb Ramps	North Side East of End - 3rd @ 33.925695003158, - 118.164900541306		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466122	Curb Ramps	North Side East of End - 3rd @ 33.925695003158, - 118.164900541306	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466123	Curb Ramps	North Side East of End - 7th @ 33.924782504191, - 118.162389993668		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466124	Curb Ramps	North Side East of End - 7th @ 33.924782504191, - 118.162389993668		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466126	Curb Ramps	North Side East of End - 7th @ 33.924782504191, - 118.162389993668	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Flores Street - Erickson Avenue to End - Erickson Avenue to End Downey, CA 90242	466125	Curb Ramps	North Side East of End - 7th @ 33.924782504191, - 118.162389993668	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408217	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408218	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408219	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408220	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408221	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408222	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408223	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.932707565311, - 118.138056993485	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408244	Curb Ramps	North Side East Of Downey Avenue @ 33.932521743200, - 118.137649297714		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408245	Curb Ramps	North Side East Of Downey Avenue @ 33.932521743200, - 118.137649297714		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408246	Curb Ramps	North Side East Of Downey Avenue @ 33.932521743200, - 118.137649297714	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408247	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408248	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408249	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408252	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408253	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408250	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fontana Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue To Downey Avenue Downey, CA 90242	408251	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.932589618389, - 118.138145506382	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482760	Curb Ramps	North Side East of Ardis Avenue - 4th @ 33.909843951700, - 118.133015781641	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482761	Curb Ramps	North Side East of Ardis Avenue - 4th @ 33.909843951700, - 118.133015781641	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482759	Curb Ramps	North Side East of Ardis Avenue - 4th @ 33.909843951700, - 118.133015781641	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482762	Curb Ramps	North Side East of Ardis Avenue - 2nd @ 33.909842838695, - 118.132543712854	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482763	Curb Ramps	North Side East of Ardis Avenue - 1st @ 33.909862872778, - 118.132435083389		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482764	Curb Ramps	North Side East of Ardis Avenue - 1st @ 33.909862872778, - 118.132435083389		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482765	Curb Ramps	North Side East of Ardis Avenue - 1st @ 33.909862872778, - 118.132435083389	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Foster Road - Bellflower Boulevard to Hanwell Avenue - Bellflower Boulevard to Hanwell Avenue Downey, CA 90242	482766	Curb Ramps	North Side East of Ardis Avenue - 1st @ 33.909862872778, - 118.132435083389	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Foster Road - Woodruff Avenue to End - Woodruff Avenue to End Downey, CA 90242	482714	Curb Ramps	North Side East of Faust Avenue @ 33.909863985782, - 118.111104816198		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Foster Road - Woodruff Avenue to End - Woodruff Avenue to End Downey, CA 90242	482715	Curb Ramps	North Side East of Faust Avenue @ 33.909863985782, - 118.111104816198	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/25
Fostoria Street - Old River School Road to Rives Road - Old River School Road to Rives Road Downey, CA 90242	463234	Curb Ramps	Southeast Corner of Old River School Road @ 33.951210968646, - 118.145996332169		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Fostoria Street - Old River School Road to Rives Road - Old River School Road to Rives Road Downey, CA 90242	463235	Curb Ramps	Northeast Corner of Old River School Road @ 33.951417886739, - 118.145842105150		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Fostoria Street - Old River School Road to Rives Road - Old River School Road to Rives Road	463236	Curb Ramps	Northeast Corner of Old River School Road @ 33.951417886739, - 118.145842105150		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gainford Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive	468723	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.952376823157, - 118.119828701019		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gainford Street - Brookshire Avenue to Bellder Drive - Brookshire Avenue to Bellder Drive	468724	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.952376823157, - 118.119828701019		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue	470104	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue	470105	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue	470106	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue	470107	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue	470108	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue Downey, CA 90242	470109	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.952364143, - 118.120188117027	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue Downey, CA 90242	470111	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.952449132310, - 118.120080828667		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gainford Street - Brookshire Avenue to Dolan Avenue - Brookshire Avenue to Dolan Avenue Downey, CA 90242	470112	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.952449132310, - 118.120080828667	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gainford Street - Downey Avenue to Dolan Avenue - Downey Avenue to Dolan Avenue Downey, CA 90242	468111	Curb Ramps	Southeast Corner of Downey Avenue @ 33.954150048346, - 118.123642802238	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gainford Street - Downey Avenue to Dolan Avenue - Downey Avenue to Dolan Avenue Downey, CA 90242	468114	Curb Ramps	Northeast Corner of Downey Avenue @ 33.954277977216, - 118.123530149460		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gainford Street - Downey Avenue to Dolan Avenue - Downey Avenue to Dolan Avenue Downey, CA 90242	468115	Curb Ramps	Northeast Corner of Downey Avenue @ 33.954277977216, - 118.123530149460	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard Downey, CA 90242	406253	Curb Ramps	Northwest Corner @ 33.962348231455, - 118.123208284378		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard Downey, CA 90242	406254	Curb Ramps	Northwest Corner @ 33.962348231455, - 118.123208284378	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard	406255	Curb Ramps	Northwest Corner @ 33.962348231455, - 118.123208284378	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard	406351	Curb Ramps	Southwest Corner @ 33.962220314720, - 118.123358488083	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard	406350	Curb Ramps	Southwest Corner @ 33.962220314720, - 118.123358488083	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard	406352	Curb Ramps	Southeast Corner @ 33.962011198250, - 118.123131841421	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road & Paramount Boulevard - Gallatin Road & Paramount Boulevard	406353	Curb Ramps	Northeast Corner @ 33.962171372613, - 118.122954815626	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane	448713	Curb Ramps	Northeast Corner of Parrot Avenue @ 33.961541796645, - 118.122250735760		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane	448714	Curb Ramps	Northeast Corner of Parrot Avenue @ 33.961541796645, - 118.122250735760		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448715	Curb Ramps	Northeast Corner of Whittle Court @ 33.955138989129, - 118.114686906338		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448716	Curb Ramps	Northeast Corner of Whittle Court @ 33.955138989129, - 118.114686906338		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448717	Curb Ramps	Northwest Corner of Parrot Avenue @ 33.961659703453, - 118.122392892838		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448718	Curb Ramps	Northwest Corner of Parrot Avenue @ 33.961659703453, - 118.122392892838		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448719	Curb Ramps	Northwest Corner of Parrot Avenue @ 33.961659703453, - 118.122392892838	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448720	Curb Ramps	Northeast Corner of La Reina Avenue @ 33.959768725504, - 118.120284676552		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448721	Curb Ramps	Northeast Corner of La Reina Avenue @ 33.959768725504, - 118.120284676552		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448722	Curb Ramps	Northeast Corner of La Reina Avenue @ 33.959768725504, - 118.120284676552		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448723	Curb Ramps	Northeast Corner of La Reina Avenue @ 33.959768725504, - 118.120284676552	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448724	Curb Ramps	Northeast Corner of Orizaba Avenue @ 33.960253709739, - 118.120826482773		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448725	Curb Ramps	Northeast Corner of Orizaba Avenue @ 33.960253709739, - 118.120826482773		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448726	Curb Ramps	Northeast Corner of Orizaba Avenue @ 33.960253709739, - 118.120826482773	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448727	Curb Ramps	Northeast Corner of Brock Avenue @ 33.960967832868, - 118.121647238731		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448728	Curb Ramps	Northeast Corner of Brock Avenue @ 33.960967832868, - 118.121647238731		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448729	Curb Ramps	Northeast Corner of Brock Avenue @ 33.960967832868, - 118.121647238731	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448730	Curb Ramps	Northwest Corner of Kristin Drive @ 33.963243643218, - 118.124168515205		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448731	Curb Ramps	Northwest Corner of Kristin Drive @ 33.963243643218, - 118.124168515205		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448732	Curb Ramps	Northwest Corner of Kristin Drive @ 33.963243643218, - 118.124168515205		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448733	Curb Ramps	Northwest Corner of Kristin Drive @ 33.963243643218, - 118.124168515205	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448789	Curb Ramps	Northeast Corner of Downey Avenue @ 33.959112435097, - 118.119541704655		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448790	Curb Ramps	Northeast Corner of Downey Avenue @ 33.959112435097, - 118.119541704655		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448791	Curb Ramps	Northeast Corner of Downey Avenue @ 33.959112435097, - 118.119541704655		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448792	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448793	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448794	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448795	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448796	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448797	Curb Ramps	Northeast Corner of Kristin Drive @ 33.963090144728, - 118.124010264874	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448798	Curb Ramps	Northwest Corner of Mel Dar Avenue @ 33.957228074841, - 118.117462992668		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448801	Curb Ramps	Northwest Corner of Mel Dar Avenue @ 33.957228074841, - 118.117462992668	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448799	Curb Ramps	Northwest Corner of Mel Dar Avenue @ 33.957228074841, - 118.117462992668	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448800	Curb Ramps	Northwest Corner of Mel Dar Avenue @ 33.957228074841, - 118.117462992668	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448802	Curb Ramps	Northeast Corner of Mel Dar Avenue @ 33.957110161891, - 118.117344975472		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448803	Curb Ramps	Northeast Corner of Mel Dar Avenue @ 33.957110161891, - 118.117344975472		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448804	Curb Ramps	Northeast Corner of Mel Dar Avenue @ 33.957110161891, - 118.117344975472		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448805	Curb Ramps	Northeast Corner of Mel Dar Avenue @ 33.957110161891, - 118.117344975472	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448806	Curb Ramps	Northeast Corner of Mel Dar Avenue @ 33.957110161891, - 118.117344975472	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448807	Curb Ramps	Northwest Corner of La Reina Avenue @ 33.959822118399, - 118.120365142822		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448808	Curb Ramps	Northwest Corner of Manzanar Avenue @ 33.956665205890, - 118.116832673550		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448809	Curb Ramps	Northwest Corner of Manzanar Avenue @ 33.956665205890, - 118.116832673550		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448810	Curb Ramps	Northwest Corner of Manzanar Avenue @ 33.956665205890, - 118.116832673550		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448811	Curb Ramps	Northwest Corner of Manzanar Avenue @ 33.956665205890, - 118.116832673550	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448812	Curb Ramps	Northeast Corner of Brookshire @ 33.956026689964, - 118.115993142128		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448813	Curb Ramps	Northeast Corner of Brookshire @ 33.956026689964, - 118.115993142128		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448814	Curb Ramps	Northeast Corner of Brookshire @ 33.956026689964, - 118.115993142128		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448815	Curb Ramps	Northwest Corner of Brock Avenue @ 33.961092414482, - 118.121767938137		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448816	Curb Ramps	Northwest Corner of Brock Avenue @ 33.961092414482, - 118.121767938137		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448817	Curb Ramps	Northwest Corner of Brock Avenue @ 33.961092414482, - 118.121767938137	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448818	Curb Ramps	Northeast Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448819	Curb Ramps	Northeast Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448820	Curb Ramps	Northeast Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448821	Curb Ramps	Northeast Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448822	Curb Ramps	Northeast Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448823	Curb Ramps	Northwest Corner of Orizaba Avenue @ 33.960391640530, - 118.120976686478		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448824	Curb Ramps	Northwest Corner of Orizaba Avenue @ 33.960391640530, - 118.120976686478		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448825	Curb Ramps	Northwest Corner of Orizaba Avenue @ 33.960391640530, - 118.120976686478		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448826	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448827	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448828	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448829	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448830	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448831	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448832	Curb Ramps	Northwest Corner of Downey Avenue @ 33.959221446396, - 118.119675815105	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448833	Curb Ramps	Northwest Corner of Whittle Court @ 33.955138989129, - 118.114686906338		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448834	Curb Ramps	Northwest Corner of Whittle Court @ 33.955138989129, - 118.114686906338		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448835	Curb Ramps	Northwest Corner of Whittle Court @ 33.955138989129, - 118.114686906338		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448836	Curb Ramps	Northwest Corner of Stoakes Avenue @ 33.957757568716, - 118.118061125278		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448837	Curb Ramps	Northwest Corner of Brookshire @ 33.956131255618, - 118.116154074669		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448839	Curb Ramps	Northwest Corner of Brookshire @ 33.956131255618, - 118.116154074669	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448838	Curb Ramps	Northwest Corner of Brookshire @ 33.956131255618, - 118.116154074669	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448840	Curb Ramps	Northeast Corner of Manzanar Avenue @ 33.956551741738, - 118.116695880890		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448841	Curb Ramps	Northeast Corner of Manzanar Avenue @ 33.956551741738, - 118.116695880890		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448842	Curb Ramps	Northeast Corner of Manzanar Avenue @ 33.956551741738, -118.116695880890	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448843	Curb Ramps	Northeast Corner of Tweedy Lane @ 33.963724158440, -118.124766647816		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448844	Curb Ramps	Northeast Corner of Tweedy Lane @ 33.963724158440, -118.124766647816		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448847	Curb Ramps	Northeast Corner of Tweedy Lane @ 33.963724158440, -118.124766647816	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448845	Curb Ramps	Northeast Corner of Tweedy Lane @ 33.963724158440, -118.124766647816	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	448846	Curb Ramps	Northeast Corner of Tweedy Lane @ 33.963724158440, -118.124766647816	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449215	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.956020015556, - 118.116406202316		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449216	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.956020015556, - 118.116406202316	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449217	Curb Ramps	Southeast Corner of Stamps Road @ 33.958420543795, - 118.119136691093		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449218	Curb Ramps	Southeast Corner of Stamps Road @ 33.958420543795, - 118.119136691093		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449220	Curb Ramps	Southeast Corner of Stamps Road @ 33.958420543795, - 118.119136691093	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449219	Curb Ramps	Southeast Corner of Stamps Road @ 33.958420543795, - 118.119136691093	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449221	Curb Ramps	Southwest Corner of Downey Avenue @ 33.959681961978, - 118.120526075363		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449222	Curb Ramps	Southwest Corner of Downey Avenue @ 33.959681961978, - 118.120526075363	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449223	Curb Ramps	Southwest Corner of Stamps Road @ 33.958542904402, - 118.119257390499		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449224	Curb Ramps	Southwest Corner of Stamps Road @ 33.958542904402, - 118.119257390499		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449226	Curb Ramps	Southwest Corner of Stamps Road @ 33.958542904402, - 118.119257390499	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449225	Curb Ramps	Southwest Corner of Stamps Road @ 33.958542904402, - 118.119257390499	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449227	Curb Ramps	Southeast Corner of Downey Avenue @ 33.958912209896, - 118.119697272778		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449228	Curb Ramps	Southeast Corner of Downey Avenue @ 33.958912209896, - 118.119697272778	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449229	Curb Ramps	Southeast Corner of Downey Avenue @ 33.958912209896, - 118.119697272778	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449230	Curb Ramps	Southwest Corner of Brock Avenue @ 33.960954484827, - 118.121939599514		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449231	Curb Ramps	Southwest Corner of Brock Avenue @ 33.960954484827, - 118.121939599514		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449232	Curb Ramps	Southwest Corner of Brock Avenue @ 33.960954484827, - 118.121939599514		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449233	Curb Ramps	Southwest Corner of Brock Avenue @ 33.960954484827, - 118.121939599514	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449234	Curb Ramps	Southwest Corner of Stoakes Avenue @ 33.957757568716, - 118.118404448032		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449235	Curb Ramps	Southwest Corner of Stoakes Avenue @ 33.957757568716, - 118.118404448032		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449237	Curb Ramps	Southwest Corner of Stoakes Avenue @ 33.957757568716, - 118.118404448032	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449236	Curb Ramps	Southwest Corner of Stoakes Avenue @ 33.957757568716, - 118.118404448032	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449238	Curb Ramps	Southeast Corner of Stoakes Avenue @ 33.957641881260, - 118.118289113045		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449239	Curb Ramps	Southeast Corner of Stoakes Avenue @ 33.957641881260, - 118.118289113045		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449240	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.959681961978, - 118.120526075363		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449310	Curb Ramps	Southeast Corner of Brock Avenue @ 33.960821004303, - 118.121794760227		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449311	Curb Ramps	Southeast Corner of Brock Avenue @ 33.960821004303, - 118.121794760227		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449312	Curb Ramps	Southeast Corner of Brock Avenue @ 33.960821004303, - 118.121794760227	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449313	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.955850930384, - 118.116186261177		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449314	Curb Ramps	Southeast Corner of La Reina Avenue @ 33.959586299526, - 118.120391964912		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449315	Curb Ramps	Southeast Corner of La Reina Avenue @ 33.959586299526, - 118.120391964912		Curb Ramp Width	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Tweedy Lane - Lakewood Boulevard to Tweedy Lane Downey, CA 90240	449316	Curb Ramps	Southeast Corner of La Reina Avenue @ 33.959586299526, - 118.120391964912		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346767	Curb Ramps	Northwest Corner Of Shellyfield Road		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346768	Curb Ramps	Northwest Corner Of Shellyfield Road		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346769	Curb Ramps	Northwest Corner Of Shellyfield Road		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346771	Curb Ramps	Northwest Corner Of Shellyfield Road	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346770	Curb Ramps	Northwest Corner Of Shellyfield Road	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346772	Curb Ramps	Northeast Corner Of Arrington Avenue		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346773	Curb Ramps	Northeast Corner Of Arrington Avenue		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346774	Curb Ramps	Northeast Corner Of Arrington Avenue		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346775	Curb Ramps	Northeast Corner Of Arrington Avenue		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346776	Curb Ramps	Northeast Corner Of Arrington Avenue	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346777	Curb Ramps	Northeast Corner Of Arrington Avenue	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346778	Curb Ramps	Northeast Corner Of Arrington Avenue	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346779	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346780	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346781	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346782	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346783	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346784	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346785	Curb Ramps	Southeast Corner Of Cord Avenue @ 33.948737924765, - 118.105030953884	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346786	Curb Ramps	Northeast Corner Of Clancy Avenue @ 33.952364143, - 118.110280036926		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346787	Curb Ramps	Northeast Corner Of Clancy Avenue @ 33.952364143, - 118.110280036926		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346788	Curb Ramps	Northeast Corner Of Clancy Avenue @ 33.952364143, -118.110280036926		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346789	Curb Ramps	Northeast Corner Of Clancy Avenue @ 33.952364143, -118.110280036926	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346832	Curb Ramps	Southwest Corner Of Cord Avenue @ 33.948855849316, -118.105207979679		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346833	Curb Ramps	Southwest Corner Of Cord Avenue @ 33.948855849316, -118.105207979679		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346834	Curb Ramps	Southwest Corner Of Cord Avenue @ 33.948855849316, -118.105207979679		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346835	Curb Ramps	Northwest Corner Of Arrington Avenue		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/25	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346836	Curb Ramps	Northwest Corner Of Arrington Avenue		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346837	Curb Ramps	Northwest Corner Of Arrington Avenue		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346839	Curb Ramps	Northwest Corner Of Arrington Avenue	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346840	Curb Ramps	Northwest Corner Of Arrington Avenue	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346838	Curb Ramps	Northwest Corner Of Arrington Avenue	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346841	Curb Ramps	Northwest Corner Of Clancy Avenue @ 33.952364586218, -118.110371232033		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346842	Curb Ramps	Northwest Corner Of Clancy Avenue @ 33.952364586218, - 118.110371232033		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346844	Curb Ramps	Northwest Corner Of Clancy Avenue @ 33.952364586218, - 118.110371232033	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346843	Curb Ramps	Northwest Corner Of Clancy Avenue @ 33.952364586218, - 118.110371232033	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346846	Curb Ramps	Southeast Corner Of Lemoran Avenue @ 33.950533475243, - 118.107758760452	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346847	Curb Ramps	Southeast Corner Of Lemoran Avenue @ 33.950533475243, - 118.107758760452	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/25	
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346845	Curb Ramps	Southeast Corner Of Lemoran Avenue @ 33.950533475243, - 118.107758760452	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346848	Curb Ramps	Northeast Corner Of Shellyfield Road		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346849	Curb Ramps	Northeast Corner Of Shellyfield Road		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346851	Curb Ramps	Northeast Corner Of Shellyfield Road	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346852	Curb Ramps	Northeast Corner Of Shellyfield Road	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/25
Gallatin Road - Lakewood Boulevard to Cul-de-sac - Gallatin Road - Lakewood Boulevard to Cul-de-sac Downey, CA 90242	346850	Curb Ramps	Northeast Corner Of Shellyfield Road	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/25
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349829	Curb Ramps	Northeast Corner @ 33.911974216051, - 118.145278841257		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/25
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349830	Curb Ramps	Northeast Corner @ 33.911974216051, - 118.145278841257		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/25

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349831	Curb Ramps	Southeast Corner @ 33.911806156378, - 118.145435750484	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349832	Curb Ramps	Northwest Corner @ 33.912065480105, - 118.145461231470		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/25	
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349833	Curb Ramps	Northwest Corner @ 33.912065480105, - 118.145461231470	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gardendale Street & Barlin Avenue - Gardendale Street & Barlin Avenue Downey, CA 90242	349834	Curb Ramps	Southwest Corner @ 33.911877387008, - 118.145619481802	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349932	Curb Ramps	Southwest Corner @ 33.913559080376, - 118.149292767048	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/25	
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349933	Curb Ramps	Southeast Corner @ 33.913451123559, - 118.148956149817		Detectable Warnings Depth	Provide compliant detectable warnings.	6/30/25	
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349934	Curb Ramps	Southeast Corner @ 33.913451123559, - 118.148956149817	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/25	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350017	Curb Ramps	Northwest Corner @ 33.913651455689, - 118.148864954710		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/25
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350018	Curb Ramps	Northwest Corner @ 33.913651455689, - 118.148864954710	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346238	Curb Ramps	North Side East Of City Limit @ 33.919337352912, - 118.161024749279	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346239	Curb Ramps	North Side East Of City Limit @ 33.919337352912, - 118.161024749279	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346240	Curb Ramps	Southeast Corner Of Laureldale Avenue @ 33.912890191092, - 118.147794753313		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346241	Curb Ramps	Southeast Corner Of Laureldale Avenue @ 33.912890191092, - 118.147794753313		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346242	Curb Ramps	Southeast Corner Of Laureldale Avenue @ 33.912890191092, - 118.147794753313	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346243	Curb Ramps	Southeast Corner Of Laureldale Avenue @ 33.912890191092, - 118.147794753313	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346244	Curb Ramps	Southeast Corner Of Laureldale Avenue @ 33.912890191092, - 118.147794753313	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347131	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.916601848229, - 118.155089020729		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347132	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.916601848229, - 118.155089020729	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347133	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.916601848229, - 118.155089020729	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347134	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.914012052335, - 118.149618655443	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347135	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347136	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347137	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347138	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347139	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347140	Curb Ramps	Northeast Corner Of Gneiss Avenue @ 33.915806109263, - 118.153364360332	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347141	Curb Ramps	Northeast Corner Of Hoover Avenue @ 33.918560558639, - 118.159399330616	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	347142	Curb Ramps	Northeast Corner Of Hoover Avenue @ 33.918560558639, - 118.159399330616	Bottom Landing	Bottom Landing Change in Level due to Overlayment - Beveled	Ensure the change in elevation is within the recommended height.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	347143	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.911573543436, - 118.144447356462		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	347144	Curb Ramps	Northeast Corner Of Airpoint Avenue @ 33.911573543436, - 118.144447356462	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	347145	Curb Ramps	Northwest Corner Of Gneiss @ 33.915890691660, - 118.153545409441		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	347146	Curb Ramps	Northwest Corner Of Gneiss @ 33.915890691660, - 118.153545409441	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347147	Curb Ramps	Northwest Corner Of Gneiss @ 33.915890691660, - 118.153545409441	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347148	Curb Ramps	Northwest Corner Of Gneiss @ 33.915890691660, - 118.153545409441	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347149	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.916703123564, - 118.155266046524		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347151	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.916703123564, - 118.155266046524	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347150	Curb Ramps	Northwest Corner Of Brock Avenue @ 33.916703123564, - 118.155266046524	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue	349609	Curb Ramps	Northwest Corner Of Blodgett Avenue @ 33.911279715654, - 118.143881410360	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437208	Curb Ramps	Southwest Corner of Gardendale Avenue - North @ 33.922910737918, - 118.169170618057		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437209	Curb Ramps	Southwest Corner of Gardendale Avenue - North @ 33.922910737918, - 118.169170618057		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437210	Curb Ramps	Southwest Corner of Gardendale Avenue - North @ 33.922910737918, - 118.169170618057	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437290	Curb Ramps	Southeast Corner of Gardendale Avenue @ 33.922705976210, - 118.168787062168		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437291	Curb Ramps	Southeast Corner of Gardendale Avenue @ 33.922705976210, - 118.168787062168	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437292	Curb Ramps	Southwest Corner of Gardendale Avenue - South @ 33.922890706903, - 118.169133067131		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437293	Curb Ramps	Northwest Corner of Gardendale Avenue @ 33.923193397292, - 118.169210851192		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/27	
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue	437294	Curb Ramps	Northwest Corner of Gardendale Avenue @ 33.923193397292, - 118.169210851192	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Garfield Avenue & Gardendale Avenue - Garfield Avenue & Gardendale Avenue Downey, CA 90240	437295	Curb Ramps	Northwest Corner of Gardendale Avenue @ 33.923193397292, - 118.169210851192	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330859	Curb Ramps	Northwest Corner Of Borson Street @ 33.914895730257, - 118.137107491493		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330860	Curb Ramps	Northwest Corner Of Borson Street @ 33.914895730257, - 118.137107491493		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330861	Curb Ramps	Northwest Corner Of Borson Street @ 33.914895730257, - 118.137107491493		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	327682	Curb Ramps	Northwest Corner Of Borson Street @ 33.914895730257, - 118.137107491493	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330862	Curb Ramps	Northeast Corner Of Borson Street @ 33.914886826747, - 118.136941194534		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330863	Curb Ramps	Northeast Corner Of Borson Street @ 33.914886826747, - 118.136941194534		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street Downey, CA 90242	330864	Curb Ramps	Northeast Corner Of Borson Street @ 33.914886826747, - 118.136941194534		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Glenshire Avenue - Imperial Highway To Borson Street - Imperial Highway To Borson Street	327699	Curb Ramps	Northeast Corner Of Borson Street @ 33.914886826747, - 118.136941194534	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	349127	Curb Ramps	Southwest Corner Of Donovan Street @ 33.924721299643, - 118.143028467894		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	349128	Curb Ramps	Southwest Corner Of Donovan Street @ 33.924721299643, - 118.143028467894		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	347955	Curb Ramps	Southwest Corner Of Donovan Street @ 33.924721299643, - 118.143028467894	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	347954	Curb Ramps	Southwest Corner Of Donovan Street @ 33.924721299643, - 118.143028467894	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	349130	Curb Ramps	Northwest Corner Of Donovan Street @ 33.924851498357, - 118.142931908369		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	349131	Curb Ramps	Northwest Corner Of Donovan Street @ 33.924851498357, - 118.142931908369		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	347970	Curb Ramps	Northwest Corner Of Donovan Street @ 33.924851498357, - 118.142931908369	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	347972	Curb Ramps	Northwest Corner Of Donovan Street @ 33.924851498357, - 118.142931908369	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Glynn Avenue - Eucalyptus Street To Cul-de-sac - Eucalyptus Street To Cul-de-sac	349132	Curb Ramps	Northwest Corner Of Donovan Street @ 33.924851498357, - 118.142931908369	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Gneiss Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	360018	Curb Ramps	East Side South Of Priscilla Avenue @ 33.915998645387, - 118.153247684240	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gneiss Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	360016	Curb Ramps	East Side South Of Priscilla Avenue @ 33.915998645387, - 118.153247684240	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27
Gneiss Avenue - Gardendale Street To Adoree Street - Gardendale Street To Adoree Street	360017	Curb Ramps	East Side South Of Priscilla Avenue @ 33.915998645387, - 118.153247684240	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End	311839	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End	311840	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End	311841	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311843	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311844	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311842	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.907619026290, - 118.145367354155	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311845	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311846	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311847	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311849	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311850	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golden Street - Castana Avenue To End - Castana Avenue To End Downey Avenue, CA 90242	311848	Curb Ramps	Northwest Corner Of Castana Avenue @ 33.907762607522, - 118.145261406899	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464747	Curb Ramps	Southeast Corner of Dahlia Street @ 33.923789872265, - 118.158892393112		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464748	Curb Ramps	Southeast Corner of Dahlia Street @ 33.923789872265, - 118.158892393112		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464749	Curb Ramps	Southeast Corner of Dahlia Street @ 33.923789872265, - 118.158892393112		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464751	Curb Ramps	Southeast Corner of Dahlia Street @ 33.923789872265, - 118.158892393112	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464750	Curb Ramps	Southeast Corner of Dahlia Street @ 33.923789872265, - 118.158892393112	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464752	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.924769150475, - 118.160818219185		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464753	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.924769150475, - 118.160818219185		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464754	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.924769150475, - 118.160818219185		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464755	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.924769150475, - 118.160818219185	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464756	Curb Ramps	Southeast Corner of Erickson Avenue @ 33.924769150475, - 118.160818219185	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464757	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.924858175209, - 118.160748481750		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464758	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.924858175209, - 118.160748481750		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464760	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.924858175209, - 118.160748481750	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464761	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.924858175209, - 118.160748481750	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Golondrin Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464759	Curb Ramps	Northeast Corner of Erickson Avenue @ 33.924858175209, - 118.160748481750	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464762	Curb Ramps	South Side West of Dahlia Street - 3rd @ 33.924595551977, - 118.160453438759		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464763	Curb Ramps	South Side West of Dahlia Street - 3rd @ 33.924595551977, - 118.160453438759		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464764	Curb Ramps	South Side West of Dahlia Street - 3rd @ 33.924595551977, - 118.160453438759		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464765	Curb Ramps	South Side West of Dahlia Street - 3rd @ 33.924595551977, - 118.160453438759	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464766	Curb Ramps	South Side West of Dahlia Street - 3rd @ 33.924595551977, - 118.160453438759	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464767	Curb Ramps	North Side East of Erickson Avenue @ 33.924684576892, - 118.160389065742		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464768	Curb Ramps	North Side East of Erickson Avenue @ 33.924684576892, - 118.160389065742		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464769	Curb Ramps	North Side East of Erickson Avenue @ 33.924684576892, - 118.160389065742		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464770	Curb Ramps	North Side East of Erickson Avenue @ 33.924684576892, - 118.160389065742	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464771	Curb Ramps	North Side East of Erickson Avenue @ 33.924684576892, - 118.160389065742	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	465721	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	465722	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	465723	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464780	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464781	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464782	Curb Ramps	South Side West of Dahlia Street - 1st @ 33.924306220360, - 118.159906268120	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464783	Curb Ramps	South Side West of Dahlia Street - 2nd @ 33.924546588234, - 118.160399794579		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464784	Curb Ramps	South Side West of Dahlia Street - 2nd @ 33.924546588234, - 118.160399794579		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464785	Curb Ramps	South Side West of Dahlia Street - 2nd @ 33.924546588234, - 118.160399794579		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464786	Curb Ramps	South Side West of Dahlia Street - 2nd @ 33.924546588234, - 118.160399794579	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464787	Curb Ramps	South Side West of Dahlia Street - 2nd @ 33.924546588234, - 118.160399794579	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464795	Curb Ramps	Northeast Corner of Dahlia Street @ 33.923901154446, - 118.158838748932		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464796	Curb Ramps	Northeast Corner of Dahlia Street @ 33.923901154446, - 118.158838748932		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464797	Curb Ramps	Northeast Corner of Dahlia Street @ 33.923901154446, - 118.158838748932		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Golondrinas Street - Rives Avenue to Erickson Avenue - Rives Avenue to Erickson Avenue Downey, CA 90242	464798	Curb Ramps	Northeast Corner of Dahlia Street @ 33.923901154446, - 118.158838748932	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Gotham Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	446274	Curb Ramps	Northeast Corner of Lakewood Boulevard @ 33.942775846986, - 118.119490742683	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Gotham Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	446281	Curb Ramps	Southeast Corner of Lakewood Boulevard @ 33.942627874453, - 118.119568526745	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420699	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420700	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420701	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420703	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420704	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420702	Curb Ramps	Northwest Corner Of Hasty Avenue @ 33.938411105455, - 118.110910356045	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420718	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420719	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420720	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420721	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420722	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	420723	Curb Ramps	South Side West Of Casanes Avenue @ 33.938315419091, - 118.110980093479	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue	422607	Curb Ramps	North Side East Of Woodruff Avenue - 2nd @ 33.939392440792, - 118.112860321999		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420736	Curb Ramps	North Side East Of Woodruff Avenue - 2nd @ 33.939392440792, - 118.112860321999	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420737	Curb Ramps	North Side East Of Woodruff Avenue - 2nd @ 33.939392440792, - 118.112860321999	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420738	Curb Ramps	North Side East Of Woodruff Avenue - 1st @ 33.939392440792, - 118.112860321999	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420739	Curb Ramps	Southeast Corner Of Eglise Avenue - 1st @ 33.939207745890, - 118.112795948982	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420740	Curb Ramps	Southeast Corner Of Eglise Avenue - 1st @ 33.939207745890, - 118.112795948982	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	420741	Curb Ramps	Southeast Corner Of Eglise Avenue - 1st @ 33.939207745890, - 118.112795948982	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	422608	Curb Ramps	Southeast Corner Of Eglise Avenue - 2nd @ 33.939192169193, - 118.112785220146		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue Downey, CA 90241	422609	Curb Ramps	Southeast Corner Of Eglise Avenue - 2nd @ 33.939192169193, - 118.112785220146		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	420744	Curb Ramps	Southeast Corner Of Eglise Avenue - 2nd @ 33.939192169193, - 118.112785220146	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	422610	Curb Ramps	Southwest Corner Of Eglise Avenue - 2nd @ 33.939281178851, - 118.112943470478		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	422611	Curb Ramps	Southwest Corner Of Eglise Avenue - 2nd @ 33.939281178851, - 118.112943470478		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	422612	Curb Ramps	Southwest Corner Of Eglise Avenue - 2nd @ 33.939281178851, - 118.112943470478		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	420748	Curb Ramps	Southwest Corner Of Eglise Avenue - 2nd @ 33.939281178851, - 118.112943470478	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	420749	Curb Ramps	Southwest Corner Of Eglise Avenue - 2nd @ 33.939281178851, - 118.112943470478	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	420751	Curb Ramps	Southwest Corner Of Eglise Avenue - 1st @ 33.939274503129, - 118.112927377224	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gotham Street - Pangborn Avenue To Woodruff Avenue - Pangborn Avenue To Woodruff Avenue - Downey, CA 90241	420750	Curb Ramps	Southwest Corner Of Eglise Avenue - 1st @ 33.939274503129, - 118.112927377224	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312390	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312391	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312392	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312393	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312394	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312395	Curb Ramps	Northwest Corner Of Rosecrans Avenue @ 33.904010494526, - 118.146122395992	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312396	Curb Ramps	Northeast Corner Of Rosecrans Avenue @ 33.904012720688, - 118.145950734615		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312397	Curb Ramps	Northeast Corner Of Rosecrans Avenue @ 33.904012720688, - 118.145950734615		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312398	Curb Ramps	Northeast Corner Of Rosecrans Avenue @ 33.904012720688, - 118.145950734615	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gunderson Avenue - Rosecrans Avenue To Reydon Street - Rosecrans Avenue To Reydon Street - Downey, CA 90242	312399	Curb Ramps	Northeast Corner Of Rosecrans Avenue @ 33.904012720688, - 118.145950734615	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347922	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347923	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347924	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347926	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347927	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street - Downey, CA 90242	347925	Curb Ramps	Southwest Corner Of Manatee Street @ 33.936194714638, - 118.137547373772	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347935	Curb Ramps	West Side North Of De Palma Street - 2nd @ 33.934657003978, - 118.138735592365		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347936	Curb Ramps	West Side North Of De Palma Street - 2nd @ 33.934657003978, - 118.138735592365		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347937	Curb Ramps	West Side North Of De Palma Street - 2nd @ 33.934657003978, - 118.138735592365	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347938	Curb Ramps	West Side North Of De Palma Street - 2nd @ 33.934657003978, - 118.138735592365	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347939	Curb Ramps	West Side North Of De Palma Street - 1st @ 33.934563538759, - 118.138813376427		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347940	Curb Ramps	West Side North Of De Palma Street - 1st @ 33.934563538759, - 118.138813376427		Curb Ramp Width	Provide a compliant curb ramp.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347941	Curb Ramps	West Side North Of De Palma Street - 1st @ 33.934563538759, - 118.138813376427		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Gurley Avenue - De Palma Street To Arnett Street - De Palma Street To Arnett Street	347942	Curb Ramps	West Side North Of De Palma Street - 1st @ 33.934563538759, - 118.138813376427	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Haledon Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street	446206	Curb Ramps	Northeast Corner of Cecilia Street @ 33.937653424, - 118.118985146284		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Haledon Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street	446209	Curb Ramps	Northwest Corner of Cecilia Street @ 33.937726834326, - 118.119125962257		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Haledon Avenue - Cecilia Street to Baysinger Street - Cecilia Street to Baysinger Street	446210	Curb Ramps	Northwest Corner of Cecilia Street @ 33.937726834326, - 118.119125962257	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue	330527	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.931516961526, - 118.122709393501		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue	330528	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.931516961526, - 118.122709393501		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue	317401	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.931516961526, - 118.122709393501	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue	317402	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.931516961526, - 118.122709393501	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	330529	Curb Ramps	Southeast Corner Of Lakewood Boulevard @ 33.931499157979, - 118.126759529114		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317405	Curb Ramps	Southeast Corner Of Lakewood Boulevard @ 33.931499157979, - 118.126759529114	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317406	Curb Ramps	Southeast Corner Of Lakewood Boulevard @ 33.931499157979, - 118.126759529114	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	330530	Curb Ramps	Northeast Corner Of Lakewood Boulevard @ 33.931686095041, - 118.126673698425		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317408	Curb Ramps	Northeast Corner Of Lakewood Boulevard @ 33.931686095041, - 118.126673698425	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317409	Curb Ramps	Northeast Corner Of Lakewood Boulevard @ 33.931686095041, - 118.126673698425	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317471	Curb Ramps	Southeast Corner Of Adenmoor Avenue @ 33.931490256204, - 118.123953938484	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317472	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.931499157979, - 118.124109506607	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317473	Curb Ramps	Southwest Corner Of Coldbrook Avenue @ 33.931508059753, - 118.122870326042		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317474	Curb Ramps	Southwest Corner Of Coldbrook Avenue @ 33.931508059753, - 118.122870326042		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317476	Curb Ramps	Southwest Corner Of Coldbrook Avenue @ 33.931508059753, - 118.122870326042	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Hall Road - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90241	317475	Curb Ramps	Southwest Corner Of Coldbrook Avenue @ 33.931508059753, - 118.122870326042	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402246	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402247	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402248	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402249	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402250	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402251	Curb Ramps	Southwest Corner Of Adoree Street @ 33.913665924102, - 118.137700259686	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402260	Curb Ramps	Northwest Corner Of Angell Street @ 33.912375999753, - 118.137702941895		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402261	Curb Ramps	Northwest Corner Of Angell Street @ 33.912375999753, - 118.137702941895		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402262	Curb Ramps	Northwest Corner Of Angell Street @ 33.912375999753, - 118.137702941895		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402263	Curb Ramps	Northwest Corner Of Angell Street @ 33.912375999753, - 118.137702941895	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402264	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402265	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402266	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402267	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402268	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402269	Curb Ramps	Northeast Corner Of Adoree Street @ 33.912374886782, - 118.137540668249	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402270	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402271	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402272	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402273	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402274	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Hanwell Avenue - Angell Street To Adoree Street - Angell Street To Adoree Street Downey, CA 90242	402275	Curb Ramps	Southeast Corner Of Adoree Street @ 33.913660359328, - 118.137533962727	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hanwell Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	314109	Curb Ramps	Northwest Corner Of Foster Road @ 33.909074861991, - 118.138683289289		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/27
Hanwell Avenue - Angell Street To Foster Road - Angell Street To Foster Road Downey, CA 90242	314110	Curb Ramps	Northwest Corner Of Foster Road @ 33.909074861991, - 118.138683289289	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Haro Avenue - Neo Street To Cul-de-sac - Neo Street To Cul-de-sac	410823	Curb Ramps	Northwest Corner Of Neo Street @ 33.946082354091, - 118.152829259634		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Haro Avenue - Neo Street To Cul-de-sac - Neo Street To Cul-de-sac	410824	Curb Ramps	Northwest Corner Of Neo Street @ 33.946082354091, - 118.152829259634		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Haro Avenue - Neo Street To Cul-de-sac - Neo Street To Cul-de-sac	410825	Curb Ramps	Northwest Corner Of Neo Street @ 33.946082354091, - 118.152829259634	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Haro Avenue - Stewart & Gray Road To End - Stewart & Gray Road To End	410838	Curb Ramps	Northwest Corner Of Stewart & Gray Road @ 33.940907813957, - 118.155192285776	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Haro Avenue - Stewart & Gray Road To End - Stewart & Gray Road To End	410841	Curb Ramps	Northeast Corner Of Stewart & Gray Road @ 33.940821031200, - 118.155027329922		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Haro Avenue - Stewart & Gray Road To End - Stewart & Gray Road To End	410842	Curb Ramps	Northeast Corner Of Stewart & Gray Road @ 33.940821031200, - 118.155027329922	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348538	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348539	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348540	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348541	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348542	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348543	Curb Ramps	Southwest Corner Of Smallwood Avenue - 2nd @ 33.950303193005, - 118.136200904846	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348544	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348545	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348546	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348547	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348549	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348550	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348548	Curb Ramps	Southeast Corner Of Smallwood Avenue - 2nd @ 33.950205295054, - 118.136046677828	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348551	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348552	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348553	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348554	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348555	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348556	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348557	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.948942623882, - 118.133577704430	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348558	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348559	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348560	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828		Curb Ramp Width	Provide a compliant curb ramp.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348561	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348562	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348563	Curb Ramps	Southeast Corner Of Smallwood Avenue - 1st @ 33.950205295054, - 118.136046677828	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348564	Curb Ramps	Southwest Corner Of Smallwood Avenue - 1st @ 33.950303193005, - 118.136200904846		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348565	Curb Ramps	Southwest Corner Of Smallwood Avenue - 1st @ 33.950303193005, - 118.136200904846		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348566	Curb Ramps	Southwest Corner Of Smallwood Avenue - 1st @ 33.950303193005, - 118.136200904846		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348567	Curb Ramps	Southwest Corner Of Smallwood Avenue - 1st @ 33.950303193005, - 118.136200904846	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348568	Curb Ramps	Southwest Corner Of Smallwood Avenue - 1st @ 33.950303193005, - 118.136200904846	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348569	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348570	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348571	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348572	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348573	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Harper Avenue - Rives Avenue To Cul-de-Sac - Rives Avenue To Cul-de-Sac	348574	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.949077235534, - 118.133489191532	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	449669	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	449670	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	449671	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	449672	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road	449674	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hasty Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	449673	Curb Ramps	Northeast Corner of Brookpark Road @ 33.950738170042, - 118.102046996355	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449733	Curb Ramps	Southeast Corner of Telegraph Road @ 33.953966497893, - 118.100260645151		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449734	Curb Ramps	Southeast Corner of Telegraph Road @ 33.953966497893, - 118.100260645151		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449735	Curb Ramps	Southeast Corner of Telegraph Road @ 33.953966497893, - 118.100260645151		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449736	Curb Ramps	Southeast Corner of Telegraph Road @ 33.953966497893, - 118.100260645151		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449737	Curb Ramps	Southeast Corner of Telegraph Road @ 33.953966497893, - 118.100260645151	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449738	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449739	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449740	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449741	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449743	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hasty Avenue - Cedartree Road to Telegraph Road - Cedartree Road to Telegraph Road Downey, CA 90242	449742	Curb Ramps	Southwest Corner of Telegraph Road @ 33.954105551303, - 118.100384026766	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418946	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418947	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418948	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418949	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418950	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418951	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941815689805, - 118.157410472631	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418952	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418953	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418954	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418955	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418956	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418957	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Heritage Circle - Stewart & Gray Road To Heritage Circle - Stewart & Gray Road To Heritage Circle Downey, CA 90242	418958	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941724457620, - 118.157276362181	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	405629	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.929880132330, - 118.153702318668		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	405630	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.929880132330, - 118.153702318668	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	405631	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.929880132330, - 118.153702318668	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	405632	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.929748828557, - 118.153810948133		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405633	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.929748828557, - 118.153810948133	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405634	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405635	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405636	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405637	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405639	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405638	Curb Ramps	Northeast Corner Of Old River School Road @ 33.932815497728, - 118.159388882	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405659	Curb Ramps	Southeast Corner Of Old River School Road @ 33.932693100131, - 118.159414082766		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405660	Curb Ramps	Southeast Corner Of Old River School Road @ 33.932693100131, - 118.159414082766		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405661	Curb Ramps	Southeast Corner Of Old River School Road @ 33.932693100131, - 118.159414082766		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405663	Curb Ramps	Southeast Corner Of Old River School Road @ 33.932693100131, - 118.159414082766	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Hondo Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	405662	Curb Ramps	Southeast Corner Of Old River School Road @ 33.932693100131, - 118.159414082766	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405618	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.929638666761, - 118.153651356697		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405619	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.929638666761, - 118.153651356697		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405620	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.929638666761, - 118.153651356697	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405621	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.929638666761, - 118.153651356697	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405622	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929810029493, - 118.153526633978		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405623	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929810029493, - 118.153526633978		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405624	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929810029493, - 118.153526633978	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Hondo Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue	405625	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929810029493, - 118.153526633978	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Horley Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street	404261	Curb Ramps	Southwest Corner Of Arnett Street @ 33.942805886492, - 118.145105838776	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Horley Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street	404268	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941409594574, - 118.146137148142	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Horley Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street	404269	Curb Ramps	Northeast Corner Of Arnett Street @ 33.942726893696, - 118.144977092743		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Horley Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street	404270	Curb Ramps	Northeast Corner Of Arnett Street @ 33.942726893696, - 118.144977092743	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Horley Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404271	Curb Ramps	Northeast Corner Of Arnett Street @ 33.942726893696, - 118.144977092743	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457585	Curb Ramps	Northwest Corner of Florence Avenue @ 33.956724162694, - 118.135984987020		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457586	Curb Ramps	Northwest Corner of Florence Avenue @ 33.956724162694, - 118.135984987020		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457587	Curb Ramps	Northwest Corner of Florence Avenue @ 33.956724162694, - 118.135984987020		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457588	Curb Ramps	Northwest Corner of Florence Avenue @ 33.956724162694, - 118.135984987020		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457275	Curb Ramps	Northwest Corner of Florence Avenue @ 33.956724162694, - 118.135984987020	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457589	Curb Ramps	Northeast Corner of Florence Avenue @ 33.956619597769, - 118.135834783316		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457590	Curb Ramps	Northeast Corner of Florence Avenue @ 33.956619597769, - 118.135834783316		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457278	Curb Ramps	Northeast Corner of Florence Avenue @ 33.956619597769, -118.135834783316	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Horley Avenue - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457279	Curb Ramps	Northeast Corner of Florence Avenue @ 33.956619597769, -118.135834783316	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412825	Curb Ramps	Southeast Corner Of Pivot Street @ 33.944778457475, -118.145632892847	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412826	Curb Ramps	Southwest Corner Of Pivot Street @ 33.944848547989, -118.14577732134	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412827	Curb Ramps	Northeast Corner Of Phlox Street @ 33.944286709708, -118.146355482		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412828	Curb Ramps	Northeast Corner Of Arnett Street @ 33.943685928037, -118.146454989910		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412829	Curb Ramps	Northeast Corner Of Arnett Street @ 33.943685928037, -118.146454989910		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Horton Avenue - Pivot Street To Adwen Street - Pivot Street To Adwen Street Downey, CA 90242	412830	Curb Ramps	Northeast Corner Of Arnett Street @ 33.943685928037, -118.146454989910	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Horton Avenue - Pivot Street To Adwen Street - Pivot Street	412831	Curb Ramps	Southeast Corner Of Phlox Street @ 33.944168778826, - 118.146098256111		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Horton Avenue - Pivot Street To Adwen Street - Pivot Street	412832	Curb Ramps	Southeast Corner Of Phlox Street @ 33.944168778826, - 118.146098256111		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Horton Avenue - Pivot Street To Adwen Street - Pivot Street	412833	Curb Ramps	Southeast Corner Of Phlox Street @ 33.944168778826, - 118.146098256111	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Horton Avenue - Pivot Street To Adwen Street - Pivot Street	412834	Curb Ramps	Southeast Corner Of Phlox Street @ 33.944168778826, - 118.146098256111	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Horton Avenue - Pivot Street To Adwen Street - Pivot Street	412835	Curb Ramps	Southeast Corner Of Phlox Street @ 33.944168778826, - 118.146098256111	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard	436337	Curb Ramps	Northeast Corner @ 33.913799478571, - 118.139842003584		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard	436338	Curb Ramps	Northeast Corner @ 33.913799478571, - 118.139842003584		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436340	Curb Ramps	Northeast Corner @ 33.913799478571, - 118.139842003584	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436341	Curb Ramps	Northeast Corner @ 33.913799478571, - 118.139842003584	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436339	Curb Ramps	Northeast Corner @ 33.913799478571, - 118.139842003584	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436342	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436343	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436344	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
I 105 East Ramp & Lakewood Boulevard - I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436345	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
I 105 East Ramp & Lakewood Boulevard · I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436346	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
I 105 East Ramp & Lakewood Boulevard · I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436347	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
I 105 East Ramp & Lakewood Boulevard · I 105 East Ramp & Lakewood Boulevard Downey, CA 90242	436348	Curb Ramps	Southeast Corner @ 33.913629196586, -118.142936125	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
I 105 West Ramp & Lakewood Boulevard · I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427978	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
I 105 West Ramp & Lakewood Boulevard · I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427979	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
I 105 West Ramp & Lakewood Boulevard · I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427980	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
I 105 West Ramp & Lakewood Boulevard · I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427981	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427982	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427983	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427984	Curb Ramps	Northwest Corner @ 33.913809495147, - 118.140304684639	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427985	Curb Ramps	Southwest Corner @ 33.913485625237, - 118.140562176704		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427986	Curb Ramps	Southwest Corner @ 33.913485625237, - 118.140562176704		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427987	Curb Ramps	Southwest Corner @ 33.913485625237, - 118.140562176704		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427988	Curb Ramps	Southwest Corner @ 33.913485625237, - 118.140562176704	Bottom Landing	Bottom Landing Change in Level due to Overlayment - Beveled	Ensure the change in elevation is within the recommended height.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
I 105 West Ramp & Lakewood Boulevard - I 105 West Ramp & Lakewood Boulevard Downey, CA 90242	427989	Curb Ramps	Southwest Corner @ 33.913485625237, - 118.140562176704	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318731	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318732	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318733	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318734	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318737	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street Downey, CA 90424	318738	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318735	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318736	Curb Ramps	Southeast Corner Of Angell Street @ 33.913099428238, - 118.117731213570	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318739	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318740	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318741	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318742	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	Downey, CA 90424	318744	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	318745	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Ibbetson Avenue - Belcher Street to Angell Street - Ibbetson Avenue - Belcher Street to Angell Street	318743	Curb Ramps	Southwest Corner Of Angell Street @ 33.913046006036, - 118.117935061455	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317386	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914388228691, - 118.117725849152		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317387	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914388228691, - 118.117725849152		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317388	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914388228691, - 118.117725849152		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317390	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914388228691, - 118.117725849152	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317389	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914388228691, - 118.117725849152	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317393	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317394	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317395	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317396	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317397	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Ibbetson Avenue - Imperial Highway Service Road to Adoree Street - Ibbetson Avenue - Imperial Highway Service Road to Adoree Street	317398	Curb Ramps	Northwest Corner Of @ 33.914365969781, - 118.117932379246	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Adris Avenue - Imperial Highway & Adris Avenue	427593	Curb Ramps	Northeast Corner @ 33.917172772447, - 118.129642903805		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Adris Avenue - Imperial Highway & Adris Avenue	427693	Curb Ramps	Northwest Corner @ 33.917172772447, - 118.129908442497		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Adris Avenue - Imperial Highway & Adris Avenue	427694	Curb Ramps	Northwest Corner @ 33.917172772447, - 118.129908442497	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Adris Avenue - Imperial Highway & Adris Avenue	427695	Curb Ramps	Southwest Corner @ 33.916909012611, - 118.129868209362	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Adris Avenue - Imperial Highway & Adris Avenue	427696	Curb Ramps	Southwest Corner @ 33.916909012611, - 118.129868209362	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road	402100	Curb Ramps	Southwest Corner @ 33.918161029887, - 118.141074478626	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road - Downey, CA 90242	402101	Curb Ramps	Northeast Corner @ 33.918297915994, - 118.140776753426	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road - Downey, CA 90242	402154	Curb Ramps	Southeast Corner @ 33.918075336847, - 118.140939027071		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road - Downey, CA 90242	402155	Curb Ramps	Southeast Corner @ 33.918075336847, - 118.140939027071		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road - Downey, CA 90242	402156	Curb Ramps	Southeast Corner @ 33.918075336847, - 118.140939027071		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway & Barlin Road - Imperial Highway & Barlin Road - Downey, CA 90242	402157	Curb Ramps	Southeast Corner @ 33.918075336847, - 118.140939027071	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue - Downey, CA 90242	351925	Curb Ramps	Southeast Corner @ 33.919654523323, - 118.143804967403		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue - Downey, CA 90242	351926	Curb Ramps	Southeast Corner @ 33.919654523323, - 118.143804967403		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue - Downey, CA 90242	351927	Curb Ramps	Southeast Corner @ 33.919654523323, - 118.143804967403		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue - Downey, CA 90242	352033	Curb Ramps	Northeast Corner @ 33.919886001333, - 118.143634647131	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue - Downey, CA 90242	352034	Curb Ramps	Northwest Corner @ 33.920019546053, - 118.143857270479	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue Downey, CA 90242	352035	Curb Ramps	Northwest Corner @ 33.920019546053, - 118.143857270479	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue Downey, CA 90242	352036	Curb Ramps	Southwest Corner @ 33.919794745654, - 118.144036978483		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue Downey, CA 90242	352037	Curb Ramps	Southwest Corner @ 33.919794745654, - 118.144036978483		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue Downey, CA 90242	352039	Curb Ramps	Southwest Corner @ 33.919794745654, - 118.144036978483	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Brookshire Avenue - Imperial Highway & Brookshire Avenue Downey, CA 90242	352038	Curb Ramps	Southwest Corner @ 33.919794745654, - 118.144036978483	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Columbia Way - Imperial Highway & Columbia Way Downey, CA 90242	434165	Curb Ramps	Northeast Corner @ 33.917171659538, - 118.133986741304	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356271	Curb Ramps	Southwest Corner @ 33.921334950360, - 118.147042393684	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356272	Curb Ramps	Southwest Corner @ 33.921334950360, - 118.147042393684	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356273	Curb Ramps	Southeast Corner @ 33.921273743334, - 118.146748691797	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356274	Curb Ramps	Northeast Corner Left Curb Ramp @ 33.921525248286, - 118.146581053734		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356275	Curb Ramps	Northeast Corner Left Curb Ramp @ 33.921525248286, - 118.146581053734	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356276	Curb Ramps	Northeast Corner Left Curb Ramp @ 33.921525248286, - 118.146581053734	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356277	Curb Ramps	Northeast Corner Left Curb Ramp @ 33.921525248286, - 118.146581053734	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356391	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356392	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356393	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644		Grade Break	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356396	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356394	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356395	Curb Ramps	Northeast Corner Right Curb Ramp @ 33.921482959895, - 118.146554231644	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue Downey, CA 90242	356397	Curb Ramps	Northwest Corner @ 33.921629856322, - 118.146809041500		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue - Downey, CA 90242	356398	Curb Ramps	Northwest Corner @ 33.921629856322, - 118.146809041500		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue - Downey, CA 90242	356399	Curb Ramps	Northwest Corner @ 33.921629856322, - 118.146809041500	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue - Downey, CA 90242	356400	Curb Ramps	Northwest Corner @ 33.921629856322, - 118.146809041500	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Downey Avenue - Imperial Highway & Downey Avenue - Downey, CA 90242	356401	Curb Ramps	Northwest Corner @ 33.921629856322, - 118.146809041500	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427795	Curb Ramps	Southwest Corner @ 33.916936835417, - 118.121156394482	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427796	Curb Ramps	Northwest Corner @ 33.917199482258, - 118.121155053377		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427797	Curb Ramps	Northwest Corner @ 33.917199482258, - 118.121155053377		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427799	Curb Ramps	Northwest Corner @ 33.917199482258, - 118.121155053377	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427798	Curb Ramps	Northwest Corner @ 33.917199482258, - 118.121155053377	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue - Downey, CA 90242	427800	Curb Ramps	Northeast Corner @ 33.917062594387, - 118.120932430029		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue Downey, CA 90242	427801	Curb Ramps	Northeast Corner @ 33.917062594387, - 118.120932430029		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue Downey, CA 90242	427802	Curb Ramps	Northeast Corner @ 33.917062594387, - 118.120932430029	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Dunrobin Avenue - Imperial Highway & Dunrobin Avenue Downey, CA 90242	427803	Curb Ramps	Southeast Corner @ 33.916926819208, - 118.120944499969	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421707	Curb Ramps	Southwest Corner @ 33.928719533493, - 118.161778450012		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421708	Curb Ramps	Southwest Corner @ 33.928719533493, - 118.161778450012		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421709	Curb Ramps	Southwest Corner @ 33.928719533493, - 118.161778450012		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421710	Curb Ramps	Southwest Corner @ 33.928719533493, - 118.161778450012		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421711	Curb Ramps	Southwest Corner @ 33.928719533493, - 118.161778450012	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421712	Curb Ramps	Southwest Corner @ 33.928719533493, -118.161778450012	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421713	Curb Ramps	Southwest Corner @ 33.928719533493, -118.161778450012	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421714	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421715	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421716	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421717	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421718	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421719	Curb Ramps	Northeast Corner @ 33.928915378701, -118.161401599646	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421720	Curb Ramps	Southeast Corner @ 33.928601581048, - 118.161514252424		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421721	Curb Ramps	Southeast Corner @ 33.928601581048, - 118.161514252424		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421722	Curb Ramps	Southeast Corner @ 33.928601581048, - 118.161514252424		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421723	Curb Ramps	Southeast Corner @ 33.928601581048, - 118.161514252424	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421814	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421815	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421816	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road	421817	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421821	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421818	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421819	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Old River School Road - Imperial Highway & Old River School Road Downey, CA 90242	421820	Curb Ramps	Northwest Corner @ 33.929026654187, - 118.161634951830	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Paramount Boulevard - Imperial Highway & Paramount Boulevard Downey, CA 90242	421608	Curb Ramps	Northwest Corner @ 33.924251692369, - 118.152039349079		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Paramount Boulevard - Imperial Highway & Paramount Boulevard Downey, CA 90242	421609	Curb Ramps	Northeast Corner @ 33.924105913281, - 118.151759058237		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Paramount Boulevard - Imperial Highway & Paramount Boulevard Downey, CA 90242	421610	Curb Ramps	Northeast Corner @ 33.924105913281, - 118.151759058237	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Paramount Boulevard - Imperial Highway & Paramount Boulevard Downey, CA 90242	421611	Curb Ramps	Southwest Corner @ 33.924011323663, -118.152213692665		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Paramount Boulevard - Imperial Highway & Paramount Boulevard Downey, CA 90242	421612	Curb Ramps	Southwest Corner @ 33.924011323663, -118.152213692665	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416111	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416112	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416113	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416114	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416115	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416116	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416117	Curb Ramps	Southeast Corner @ 33.925528083346, -118.155215084553	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416118	Curb Ramps	Southeast Corner @ 33.925528083346, - 118.155215084553	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416168	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416169	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416170	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416171	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416174	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416172	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416173	Curb Ramps	Southwest Corner @ 33.925615994487, - 118.155373334885	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416175	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416176	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416177	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416178	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416180	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway & Smallwood Avenue - Imperial Highway & Smallwood Avenue Downey, CA 90242	416179	Curb Ramps	Northeast Corner @ 33.925738402255, - 118.155059516430	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480402	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480403	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480404	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479586	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479587	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479584	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479585	Curb Ramps	Northwest Corner of Imperial Highway Frontage Road @ 33.917217288794, - 118.114201426506	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479588	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479589	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479590	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479591	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479592	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479593	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	479594	Curb Ramps	Northeast Corner of Imperial Highway Frontage Road @ 33.917227304969, - 118.114016354084	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480013	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480014	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432		Curb Ramp Width	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480015	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480016	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480017	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480018	Curb Ramps	Southeast Corner of Imperial Highway Frontage Road @ 33.916947964537, - 118.114238977432	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480041	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480042	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480043	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480044	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480045	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480046	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480047	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway - City of Norwalk to Woodruff Avenue - City of Norwalk to Woodruff Avenue Downey, CA 90242	480048	Curb Ramps	Southwest Corner of Imperial Highway Frontage Road @ 33.916955754920, - 118.114441484213	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327515	Curb Ramps	Northwest Corner Of Benedict Avenue @ 33.917232869510, - 118.118938207626		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327516	Curb Ramps	Northwest Corner Of Benedict Avenue @ 33.917232869510, - 118.118938207626		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327517	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.916903448049, - 118.122596740723		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327518	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.916903448049, - 118.122596740723		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327519	Curb Ramps	Southeast Corner Of Coldbrook Avenue @ 33.916903448049, - 118.122596740723	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327520	Curb Ramps	North Side East Of Caring Way - 1st @ 33.917197256441, - 118.128497600555		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327521	Curb Ramps	Southwest Corner Of Coldbrook Avenue @ 33.916930157944, - 118.122940063477	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327522	Curb Ramps	Northeast Corner Of Dunrobin Avenue @ 33.917206159709, - 118.120912313461		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327523	Curb Ramps	Northeast Corner Of Dunrobin Avenue @ 33.917206159709, - 118.120912313461		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327524	Curb Ramps	Northeast Corner Of Dunrobin Avenue @ 33.917206159709, - 118.120912313461		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327525	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.916921254647, - 118.123819828033		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327526	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.916921254647, - 118.123819828033		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327527	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.916921254647, - 118.123819828033		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327528	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.916921254647, - 118.123819828033	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327529	Curb Ramps	Southwest Corner Of Adenmoor Avenue @ 33.916921254647, - 118.123819828033	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327530	Curb Ramps	Northeast Corner Of Caring Way @ 33.917179449900, - 118.129613399506		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327531	Curb Ramps	Northeast Corner Of Caring Way @ 33.917179449900, - 118.129613399506		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327532	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.916876738145, - 118.121223449707		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327533	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.916876738145, - 118.121223449707		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327534	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.916876738145, - 118.121223449707	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327535	Curb Ramps	Northeast Corner Of Benedict Avenue @ 33.917179449900, - 118.118723630905		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327536	Curb Ramps	Northeast Corner Of Benedict Avenue @ 33.917179449900, - 118.118723630905		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327537	Curb Ramps	Northeast Corner Of Benedict Avenue @ 33.917179449900, - 118.118723630905		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327538	Curb Ramps	Northwest Corner Of Dunrobin Avenue @ 33.917215062977, - 118.121191263199		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327539	Curb Ramps	Northwest Corner Of Dunrobin Avenue @ 33.917215062977, - 118.121191263199		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327540	Curb Ramps	Northwest Corner Of Dunrobin Avenue @ 33.917215062977, - 118.121191263199	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327541	Curb Ramps	Northwest Corner Of Woodruff Avenue @ 33.917223966244, - 118.116921186447		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327542	Curb Ramps	Northwest Corner Of Woodruff Avenue @ 33.917223966244, - 118.116921186447		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327543	Curb Ramps	Northwest Corner Of Woodruff Avenue @ 33.917223966244, - 118.116921186447		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327544	Curb Ramps	Northwest Corner Of Woodruff Avenue @ 33.917223966244, - 118.116921186447		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327545	Curb Ramps	Northwest Corner Of Woodruff Avenue @ 33.917223966244, - 118.116921186447	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327546	Curb Ramps	North Side East Of Caring Way - 4th @ 33.917250676039, - 118.126738071442		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327547	Curb Ramps	North Side East Of Caring Way - 4th @ 33.917250676039, - 118.126738071442		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327548	Curb Ramps	North Side East Of Caring Way - 4th @ 33.917250676039, - 118.126738071442		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327549	Curb Ramps	North Side East Of Caring Way - 4th @ 33.917250676039, - 118.126738071442	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327550	Curb Ramps	Northwest Corner Of Caring Way @ 33.917206159709, - 118.129935264587		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327551	Curb Ramps	Northwest Corner Of Caring Way @ 33.917206159709, - 118.129935264587	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327552	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327553	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327554	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327555	Curb Ramps	Northwest Corner Of Bellflower Boulevard @ 33.917223966244, - 118.125568628311		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327556	Curb Ramps	Northwest Corner Of Bellflower Boulevard @ 33.917223966244, - 118.125568628311		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327557	Curb Ramps	Northwest Corner Of Bellflower Boulevard @ 33.917223966244, - 118.125568628311	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327558	Curb Ramps	North Side East Of Caring Way - 3rd @ 33.917170546629, - 118.127027750015		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327559	Curb Ramps	North Side East Of Caring Way - 3rd @ 33.917170546629, - 118.127027750015		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327560	Curb Ramps	North Side East Of Caring Way - 3rd @ 33.917170546629, - 118.127027750015	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327561	Curb Ramps	Southwest Corner Of Ardis Avenue @ 33.916921254647, - 118.129935264587		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327562	Curb Ramps	Southwest Corner Of Ardis Avenue @ 33.916921254647, - 118.129935264587		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327563	Curb Ramps	Southwest Corner Of Ardis Avenue @ 33.916921254647, - 118.129935264587	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327564	Curb Ramps	Southwest Corner Of Woodruff Avenue @ 33.916867834841, - 118.116867542267	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327599	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327600	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327601	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327676	Curb Ramps	North Side East Of Caring Way - 2nd @ 33.917223966244, - 118.128165006638		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/27	
Imperial Highway - Lakewood Boulevard To Woodruff Avenue · Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327677	Curb Ramps	North Side East Of Caring Way - 2nd @ 33.917223966244, - 118.128165006638	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324076	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324077	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324078	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324079	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324080	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324081	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324082	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324083	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324084	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324085	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324086	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324087	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324088	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324089	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.921608712155, - 118.146843910217		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324090	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.921608712155, - 118.146843910217		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324091	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.921608712155, - 118.146843910217		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324092	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.921608712155, - 118.146843910217	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324093	Curb Ramps	Northwest Corner Of Dolan Avenue @ 33.920740683924, - 118.145148754120		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324094	Curb Ramps	Northwest Corner Of Dolan Avenue @ 33.920740683924, - 118.145148754120		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324095	Curb Ramps	Northwest Corner Of Dolan Avenue @ 33.920740683924, - 118.145148754120		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324096	Curb Ramps	Northwest Corner Of Dolan Avenue @ 33.920740683924, - 118.145148754120		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330836	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330837	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330838	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330839	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324635	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.921533038250, - 118.146597146988		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324636	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.921533038250, - 118.146597146988		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324637	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.921533038250, - 118.146597146988		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324638	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.921533038250, - 118.146597146988		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324105	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.921533038250, - 118.146597146988	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324106	Curb Ramps	Northwest Corner Of Bellder Drive @ 33.919512075004, - 118.142911791801		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324107	Curb Ramps	Northwest Corner Of Bellder Drive @ 33.919512075004, - 118.142911791801		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330840	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330841	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324111	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324112	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.920642751979, - 118.145046830177		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324113	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.920642751979, - 118.145046830177		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324114	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.920642751979, - 118.145046830177		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324115	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.920642751979, - 118.145046830177		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324116	Curb Ramps	Northeast Corner Of Dolan Avenue @ 33.920642751979, - 118.145046830177	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/27



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324117	Curb Ramps	Northeast Corner Of Citizenship Court Road @ 33.922636980307, - 118.148844838142		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324118	Curb Ramps	Northeast Corner Of Citizenship Court Road @ 33.922636980307, - 118.148844838142	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330842	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.924097010733, - 118.151736259460		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330843	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.924097010733, - 118.151736259460		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324123	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.924097010733, - 118.151736259460	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324124	Curb Ramps	Northwest Corner Of Citizenship Court Road @ 33.922734909960, - 118.149075508118		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330844	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330845	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330846	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330847	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324129	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324131	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324132	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324133	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324134	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324642	Curb Ramps	Southwest Corner Of Gurley Avenue @ 33.921724448584, - 118.147798776627	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324643	Curb Ramps	Southwest Corner Of Gurley Avenue @ 33.921724448584, - 118.147798776627	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324644	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.923869995450, - 118.151913285255		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324645	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.923869995450, - 118.151913285255		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324646	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.923869995450, - 118.151913285255		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324647	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.923869995450, - 118.151913285255	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324648	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.922779423401, - 118.149949908257		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324650	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.922779423401, - 118.149949908257	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324649	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.922779423401, - 118.149949908257	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324651	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324652	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324653	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324654	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324655	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/27
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324656	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/27

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324657	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324658	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324659	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324660	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324661	Curb Ramps	Southeast Corner Of La Reina Avenue @ 33.922325385208, - 118.149070143700	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/27	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324662	Curb Ramps	Southwest Corner Of Brock Avenue @ 33.923180043327, - 118.150652647018	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/27	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324663	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324664	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324665	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324666	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324667	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324668	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.922434819, - 118.148399591446		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324669	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.922434819, - 118.148399591446		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324670	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.922434819, - 118.148399591446		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324672	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.922434819, - 118.148399591446	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324671	Curb Ramps	Southeast Corner Of Gneiss Avenue @ 33.922434819, - 118.148399591446	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324673	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.922694847843, - 118.149805068970		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324674	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.922694847843, - 118.149805068970		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324675	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.922694847843, - 118.149805068970	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324676	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.922694847843, - 118.149805068970	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330848	Curb Ramps	Southeast Corner Of Gurley Avenue @ 33.921639871978, - 118.147664666176		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330849	Curb Ramps	Southeast Corner Of Gurley Avenue @ 33.921639871978, - 118.147664666176		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330850	Curb Ramps	Southeast Corner Of Gurley Avenue @ 33.921639871978, - 118.147664666176		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330851	Curb Ramps	Southeast Corner Of Gurley Avenue @ 33.921639871978, - 118.147664666176	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324681	Curb Ramps	Southeast Corner Of Gurley Avenue @ 33.921639871978, - 118.147664666176	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324682	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.922423315219, - 118.149241805077		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324683	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.922423315219, - 118.149241805077		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324684	Curb Ramps	Southwest Corner Of La Reina Avenue @ 33.922423315219, - 118.149241805077	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330852	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.923064308875, - 118.150475621223		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330853	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.923064308875, - 118.150475621223		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324687	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.923064308875, - 118.150475621223	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330854	Curb Ramps	South Side West Of Brookshire Avenue - 2nd @ 33.920567077217, - 118.145384788513		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330855	Curb Ramps	South Side West Of Brookshire Avenue - 2nd @ 33.920567077217, - 118.145384788513		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330856	Curb Ramps	South Side West Of Brookshire Avenue - 2nd @ 33.920567077217, - 118.145384788513		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330857	Curb Ramps	South Side West Of Brookshire Avenue - 2nd @ 33.920567077217, - 118.145384788513		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324693	Curb Ramps	South Side West Of Brookshire Avenue - 2nd @ 33.920567077217, - 118.145384788513	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324696	Curb Ramps	South Side West Of Brookshire Avenue - 1st @ 33.920420178957, - 118.145207762718	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324697	Curb Ramps	South Side West Of Brookshire Avenue - 1st @ 33.920420178957, - 118.145207762718	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324698	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.922049425, - 118.148485422134		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324699	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.922049425, - 118.148485422134		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324700	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.922049425, - 118.148485422134		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324702	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.922049425, - 118.148485422134	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324701	Curb Ramps	Southwest Corner Of Gneiss Avenue @ 33.922049425, - 118.148485422134	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330858	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.921346078905, - 118.147053122520		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324705	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.921346078905, - 118.147053122520	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324706	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.921346078905, - 118.147053122520	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324707	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.921346078905, - 118.147053122520	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324708	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.921265953346, - 118.146752715111		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324709	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.921265953346, - 118.146752715111		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324710	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.921265953346, - 118.146752715111		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324712	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.921265953346, - 118.146752715111	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324711	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.921265953346, - 118.146752715111	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Frontage Road - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483028	Curb Ramps	South Side East of End @ 33.923276859527, - 118.150911480188		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Frontage Road - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483029	Curb Ramps	South Side East of End @ 33.923276859527, - 118.150911480188	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Frontage Road - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483030	Curb Ramps	South Side East of End @ 33.923276859527, - 118.150911480188	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Imperial Highway Frontage Road - End to Downey Avenue - End to Downey Avenue Downey, CA 90242	483031	Curb Ramps	South Side East of Gurley Avenue - 1st @ 33.921497426978, - 118.147384375334	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	330865	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.926331521040, - 118.156167268753		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	330866	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.926331521040, - 118.156167268753		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327898	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327899	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327900	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327901	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327902	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327903	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.926180181555, - 118.156623244286	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327904	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.924034692873, - 118.152272701263	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327905	Curb Ramps	Southeast Corner Of Smallwood Avenue @ 33.925503601746, - 118.155126571655		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327906	Curb Ramps	Southeast Corner Of Smallwood Avenue @ 33.925503601746, - 118.155126571655		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount								
Boulevard To Old River School Road Downey, CA 90242	327907	Curb Ramps	Southeast Corner Of Smallwood Avenue @ 33.925503601746, - 118.155126571655		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327909	Curb Ramps	Southeast Corner Of Smallwood Avenue @ 33.925503601746, - 118.155126571655	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327908	Curb Ramps	Southeast Corner Of Smallwood Avenue @ 33.925503601746, - 118.155126571655	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	330867	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.925361163206, - 118.154171705246		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	330868	Curb Ramps	Northeast Corner Of Smallwood Avenue @ 33.925361163206, - 118.154171705246		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327915	Curb Ramps	North Side East Of Old River School Road -2nd @ 33.927782585982, - 118.158586621284		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327916	Curb Ramps	North Side East Of Old River School Road -2nd @ 33.927782585982, - 118.158586621284		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327917	Curb Ramps	North Side East Of Old River School Road -2nd @ 33.927782585982, - 118.158586621284		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330869	Curb Ramps	Southeast Corner Of Old River School Road @ 33.928597139, - 118.161537051201		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330870	Curb Ramps	Southeast Corner Of Old River School Road @ 33.928597139, - 118.161537051201		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330871	Curb Ramps	Southeast Corner Of Old River School Road @ 33.928597139, - 118.161537051201		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330872	Curb Ramps	Northeast Corner Of Old River School Road @ 33.928904251145, - 118.161370754242		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330873	Curb Ramps	Northeast Corner Of Old River School Road @ 33.928904251145, - 118.161370754242		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330874	Curb Ramps	Northeast Corner Of Old River School Road @ 33.928904251145, - 118.161370754242		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330875	Curb Ramps	Northeast Corner Of Old River School Road @ 33.928904251145, - 118.161370754242		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327925	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327926	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327927	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327928	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327930	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327929	Curb Ramps	Southwest Corner Of Smallwood Avenue @ 33.925610430494, - 118.155448436737	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330876	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.924243902653, - 118.152036666870		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330877	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.924243902653, - 118.152036666870		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330878	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.924243902653, - 118.152036666870		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327935	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.924243902653, - 118.152036666870	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327938	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327939	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327940	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327941	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327943	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327942	Curb Ramps	Southeast Corner Of Erickson Avenue @ 33.927181687854, - 118.159037232399	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327944	Curb Ramps	Northwest Corner Of Old River School Road @ 33.929011075628, - 118.161628246307		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327945	Curb Ramps	Northwest Corner Of Old River School Road @ 33.929011075628, - 118.161628246307		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327946	Curb Ramps	Northwest Corner Of Old River School Road @ 33.929011075628, - 118.161628246307		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327947	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.926469506806, - 118.156371116638		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327948	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.926469506806, - 118.156371116638	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330879	Curb Ramps	Southwest Corner Of Erickson Avenue @ 33.927279612283, - 118.159283995628		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330880	Curb Ramps	Southwest Corner Of Erickson Avenue @ 33.927279612283, - 118.159283995628		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330881	Curb Ramps	Southwest Corner Of Erickson Avenue @ 33.927279612283, - 118.159283995628		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327953	Curb Ramps	Southwest Corner Of Erickson Avenue @ 33.927279612283, - 118.159283995628	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327964	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327965	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327966	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327967	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327968	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327969	Curb Ramps	Southwest Corner Of Old River School Road @ 33.928730661074, - 118.161799907684	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327989	Curb Ramps	North Side East Of Old River School Road @ 33.927889411872, - 118.158822655678		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327990	Curb Ramps	North Side East Of Old River School Road @ 33.927889411872, - 118.158822655678		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount	327991	Curb Ramps	North Side East Of Old River School Road @ 33.927889411872, - 118.158822655678		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327993	Curb Ramps	North Side East Of Old River School Road @ 33.927889411872, - 118.158822655678	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327992	Curb Ramps	North Side East Of Old River School Road @ 33.927889411872, - 118.158822655678	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327994	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.926091158203, - 118.156371116638		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327995	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.926091158203, - 118.156371116638		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327996	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.926091158203, - 118.156371116638		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327997	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.926091158203, - 118.156371116638	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Iowa Street & Brookshire Avenue - Iowa Street & Brookshire Avenue Downey, CA 90242	415833	Curb Ramps	Northeast Corner @ 33.936084561179, - 118.131161034107		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Iowa Street & Brookshire Avenue - Iowa Street & Brookshire Avenue Downey, CA 90242	415834	Curb Ramps	Northwest Corner @ 33.936189151335, - 118.131421208382	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Iowa Street & Brookshire Avenue - Iowa Street & Brookshire Avenue Downey, CA 90242	415835	Curb Ramps	Northwest Corner @ 33.936189151335, - 118.131421208382	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Iowa Street & Brookshire Avenue - Iowa Street & Brookshire Avenue Downey, CA 90242	415934	Curb Ramps	Southwest Corner @ 33.936023364752, - 118.131527155638		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Iowa Street & Brookshire Avenue - Iowa Street & Brookshire Avenue Downey, CA 90242	415935	Curb Ramps	Southwest Corner @ 33.936023364752, - 118.131527155638	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479235	Curb Ramps	Southeast Corner of Downey Avenue @ 33.937627809268, - 118.134556710720		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479236	Curb Ramps	Southeast Corner of Downey Avenue @ 33.937627809268, - 118.134556710720	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479237	Curb Ramps	Southeast Corner of Downey Avenue @ 33.937627809268, - 118.134556710720	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479238	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479239	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479240	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479241	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479242	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479243	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479244	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Iowa Street - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	479245	Curb Ramps	Northeast Corner of Downey Avenue @ 33.937785804249, - 118.134468197823	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460234	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460235	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460236	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460237	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460239	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460238	Curb Ramps	Southwest Corner of Rives Avenue @ 33.954058829382, - 118.135574609041	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460683	Curb Ramps	Northeast Corner of Old River School Road @ 33.957382696292, - 118.141416460276		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Irvinggrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue Downey, CA 90242	460684	Curb Ramps	Northeast Corner of Old River School Road @ 33.957382696292, - 118.141416460276		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460685	Curb Ramps	Northeast Corner of Old River School Road @ 33.957382696292, - 118.141416460276		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460261	Curb Ramps	Northeast Corner of Old River School Road @ 33.957382696292, - 118.141416460276	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460686	Curb Ramps	Southeast Corner of Old River School Road @ 33.957226962455, - 118.141533136368		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460687	Curb Ramps	Southeast Corner of Old River School Road @ 33.957226962455, - 118.141533136368		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460688	Curb Ramps	Southeast Corner of Old River School Road @ 33.957226962455, - 118.141533136368		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460689	Curb Ramps	Southeast Corner of Old River School Road @ 33.957226962455, - 118.141533136368		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvingrove Drive - Old River School Road to Rives Avenue - Old River School Road to Rives Avenue	Downey, CA 90242 460266	Curb Ramps	Southeast Corner of Old River School Road @ 33.957226962455, - 118.141533136368	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459276	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459277	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459278	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459279	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459280	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459281	Curb Ramps	Southwest Corner of Old River School Road @ 33.957359336235, - 118.141747713089	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Irvingrove Drive - Old River School Road to Sherry Avenue - Old River School Road to Sheery Avenue Downey, CA 90242	459311	Curb Ramps	Northwest Corner of Old River School Road @ 33.957496159336, - 118.141660541296	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460268	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460269	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460270	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460271	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460272	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460273	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.951956316406, - 118.131441324949	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	Downey, CA 90242 460274	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952088698385, - 118.131299167871		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460275	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952088698385, - 118.131299167871		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460276	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952088698385, - 118.131299167871		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460277	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952088698385, - 118.131299167871		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Irvingrove Drive - Paramount Boulevard to Rives Avenue - Paramount Boulevard to Rives Avenue	460278	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.952088698385, - 118.131299167871	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	316901	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914121121390, - 118.121824264526		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	316902	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914121121390, - 118.121824264526		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	Downey, CA 90424 316903	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914121121390, - 118.121824264526		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	Downey, CA 90424 316904	Curb Ramps	Northeast Corner Of Adoree Street @ 33.914121121390, - 118.121824264526	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	Downey, CA 90424 316912	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.121977150440		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	Downey, CA 90424 316913	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.121977150440		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	Downey, CA 90424 316914	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.121977150440		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	316915	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.121977150440	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Izetta Avenue - Imperial Highway Service Road to Adoree Street - Izetta Avenue - Imperial Highway Service Road to Adoree Street	316916	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914114443697, - 118.121977150440	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Izetta Avenue - Priscilla Street to Angell Street - Izetta Avenue - Priscilla Street to Angell Street	326341	Curb Ramps	Southwest Corner Of Angell Street @ 33.912725472126, - 118.121961057186		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Izetta Avenue - Priscilla Street to Angell Street - Izetta Avenue - Priscilla Street to Angell Street	326342	Curb Ramps	Southwest Corner Of Angell Street @ 33.912725472126, - 118.121961057186		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Izetta Avenue - Priscilla Street to Angell Street - Izetta Avenue - Priscilla Street to Angell Street	326343	Curb Ramps	Southwest Corner Of Angell Street @ 33.912725472126, - 118.121961057186		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Izetta Avenue - Priscilla Street to Angell Street - Izetta Avenue - Priscilla Street to Angell Street	319006	Curb Ramps	Southwest Corner Of Angell Street @ 33.912725472126, - 118.121961057186	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Izetta Avenue - Priscilla Street to Angell Street - Izetta Avenue - Priscilla Street to Angell Street	319007	Curb Ramps	Southwest Corner Of Angell Street @ 33.912725472126, - 118.121961057186	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	349043	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	349044	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	349045	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	347456	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	347457	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	347458	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/32	
Julius Avenue - Florence Avenue To Quinn Street - Florence Avenue To Quinn Street	347459	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.957388258209, - 118.138019442558	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361628	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939025275834, -118.151425123215		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361629	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939025275834, -118.151425123215		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361630	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939025275834, -118.151425123215		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361631	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939025275834, -118.151425123215	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361632	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939176592493, -118.151575326920		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361633	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939176592493, -118.151575326920		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361634	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939176592493, -118.151575326920		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361636	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939176592493, - 118.151575326920	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Julius Avenue - Stewart and Gray Road To Benares Street - Stewart and Gray Road To Benares Street Downey, CA 90241	361635	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939176592493, - 118.151575326920	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Kingbee Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue Downey, CA 90242	404949	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.931070758998, - 118.152582496405		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Kingbee Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue Downey, CA 90242	404950	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.931070758998, - 118.152582496405		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
Kingbee Street - Rives Avenue To Samoline Avenue - Rives Avenue To Samoline Avenue Downey, CA 90242	404951	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.931070758998, - 118.152582496405		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/32	
Klinedale Avenue - True Avenue to Cedartree Road - True Avenue to Cedartree Road Downey, CA 90242	450826	Curb Ramps	Southwest Corner of True Avenue @ 33.950163020904, - 118.098379075527		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Klondike Avenue - Century Boulevard To Downey Avenue - Century Boulevard To Downey Avenue Downey, CA 90242	313037	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.909166129150, - 118.151956200600	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352395	Curb Ramps	Northwest Corner Of Gallatin Road @ 33.963570660817, - 118.123889565468		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352396	Curb Ramps	Northwest Corner Of Gallatin Road @ 33.963570660817, - 118.123889565468		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352397	Curb Ramps	Northwest Corner Of Gallatin Road @ 33.963570660817, - 118.123889565468		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352398	Curb Ramps	Northwest Corner Of Gallatin Road @ 33.963570660817, - 118.123889565468		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352399	Curb Ramps	Northwest Corner Of Gallatin Road @ 33.963570660817, - 118.123889565468	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352400	Curb Ramps	Northeast Corner Of Gallatin Road @ 33.963112390904, - 118.124007582664		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352401	Curb Ramps	Northeast Corner Of Gallatin Road @ 33.963112390904, - 118.124007582664		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352402	Curb Ramps	Northeast Corner Of Gallatin Road @ 33.963112390904, - 118.124007582664		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Kristen Drive - Gallatin Road to Cul-de-sac - Gallatin Road to Cul-de-sac Downey, CA 90240	352403	Curb Ramps	Northeast Corner Of Gallatin Road @ 33.963112390904, - 118.124007582664	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473803	Curb Ramps	Northeast Corner of 3rd Street @ 33.942788085305, - 118.133443593979		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473804	Curb Ramps	Northeast Corner of 3rd Street @ 33.942788085305, - 118.133443593979		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473805	Curb Ramps	Northeast Corner of 3rd Street @ 33.942788085305, - 118.133443593979		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473632	Curb Ramps	Northeast Corner of 3rd Street @ 33.942788085305, - 118.133443593979	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473633	Curb Ramps	Northeast Corner of 3rd Street @ 33.942788085305, - 118.133443593979	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473634	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473635	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473636	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473638	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473639	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473637	Curb Ramps	Southeast Corner of 2nd Street @ 33.941822365326, - 118.134178519249	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473681	Curb Ramps	Southwest Corner of 2nd Street @ 33.941913597406, - 118.134340792894		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473682	Curb Ramps	Southwest Corner of 2nd Street @ 33.941913597406, - 118.134340792894	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473683	Curb Ramps	Southwest Corner of 2nd Street @ 33.941913597406, - 118.134340792894	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473684	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473685	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473686	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473688	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473689	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473690	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473687	Curb Ramps	Northwest Corner of 3rd Street @ 33.942879316349, - 118.133604526520	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473691	Curb Ramps	Northeast Corner of 2nd Street @ 33.941961438579, - 118.134072571993		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473692	Curb Ramps	Northeast Corner of 2nd Street @ 33.941961438579, - 118.134072571993	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473693	Curb Ramps	Northeast Corner of 2nd Street @ 33.941961438579, - 118.134072571993	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473694	Curb Ramps	Northeast Corner of 2nd Street @ 33.941961438579, - 118.134072571993	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473807	Curb Ramps	Southeast Corner of 3rd Street @ 33.942650125978, - 118.133540153503		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473808	Curb Ramps	Southeast Corner of 3rd Street @ 33.942650125978, - 118.133540153503		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473809	Curb Ramps	Southeast Corner of 3rd Street @ 33.942650125978, - 118.133540153503		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473698	Curb Ramps	Southeast Corner of 3rd Street @ 33.942650125978, - 118.133540153503	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473699	Curb Ramps	Southeast Corner of 3rd Street @ 33.942650125978, - 118.133540153503	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473700	Curb Ramps	Southwest Corner of 3rd Street @ 33.942736906871, - 118.133701086044		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473701	Curb Ramps	Southwest Corner of 3rd Street @ 33.942736906871, - 118.133701086044	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473702	Curb Ramps	Northwest Corner of 2nd Street @ 33.942052670510, - 118.134236186743		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473703	Curb Ramps	Northwest Corner of 2nd Street @ 33.942052670510, - 118.134236186743	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473704	Curb Ramps	Northwest Corner of 2nd Street @ 33.942052670510, - 118.134236186743	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 5th Street to Firestone Boulevard - 5th Street to Firestone Boulevard Downey, CA 90242	473705	Curb Ramps	Northwest Corner of 2nd Street @ 33.942052670510, - 118.134236186743	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468089	Curb Ramps	Northwest Corner of 6th Street @ 33.945720780665, - 118.131431937218		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468090	Curb Ramps	Northwest Corner of 6th Street @ 33.945720780665, - 118.131431937218		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468021	Curb Ramps	Northwest Corner of 6th Street @ 33.945720780665, - 118.131431937218	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468036	Curb Ramps	Northeast Corner of 6th Street @ 33.945763057022, - 118.131194561720		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468037	Curb Ramps	Northeast Corner of 6th Street @ 33.945763057022, - 118.131194561720	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468038	Curb Ramps	Southwest Corner of 6th Street @ 33.945720780665, - 118.131431937218		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468039	Curb Ramps	Southwest Corner of 6th Street @ 33.945720780665, - 118.131431937218		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468040	Curb Ramps	Southwest Corner of 6th Street @ 33.945720780665, - 118.131431937218		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468041	Curb Ramps	Southwest Corner of 6th Street @ 33.945720780665, - 118.131431937218	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468092	Curb Ramps	Northwest Corner of 5th Street @ 33.944762881797, - 118.132121264935		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468094	Curb Ramps	Northeast Corner of 5th Street @ 33.944677215520, - 118.131968379021		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468095	Curb Ramps	Northeast Corner of 5th Street @ 33.944677215520, - 118.131968379021		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468058	Curb Ramps	Northeast Corner of 5th Street @ 33.944677215520, - 118.131968379021	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
La Reina Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468059	Curb Ramps	Northeast Corner of 5th Street @ 33.944677215520, - 118.131968379021	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429713	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429714	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429715	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429716	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429717	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429718	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429719	Curb Ramps	Southwest Corner of Florence Avenue @ 33.951915155581, - 118.127084076405	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429786	Curb Ramps	Southeast Corner of Florence Avenue @ 33.951830608958, - 118.126904368401		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429787	Curb Ramps	Southeast Corner of Florence Avenue @ 33.951830608958, - 118.126904368401		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429788	Curb Ramps	Southeast Corner of Florence Avenue @ 33.951830608958, - 118.126904368401	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
La Reina Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429789	Curb Ramps	Southeast Corner of Florence Avenue @ 33.951830608958, - 118.126904368401	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349695	Curb Ramps	Northeast Corner Of 5th Street @ 33.944678328069, - 118.131969720125		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349696	Curb Ramps	Northeast Corner Of 5th Street @ 33.944678328069, - 118.131969720125		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349697	Curb Ramps	Northeast Corner Of 5th Street @ 33.944678328069, - 118.131969720125		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349698	Curb Ramps	Northeast Corner Of 6th Street @ 33.945781970122, - 118.131178468466		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349699	Curb Ramps	Northeast Corner Of 6th Street @ 33.945781970122, - 118.131178468466	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349700	Curb Ramps	Northeast Corner Of 6th Street @ 33.945781970122, - 118.131178468466	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349701	Curb Ramps	Southeast Corner Of 3rd Street @ 33.942651238555, - 118.133533447981		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349702	Curb Ramps	Southeast Corner Of 3rd Street @ 33.942651238555, - 118.133533447981		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349703	Curb Ramps	Southeast Corner Of 3rd Street @ 33.942651238555, - 118.133533447981		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349705	Curb Ramps	Southeast Corner Of 3rd Street @ 33.942651238555, - 118.133533447981	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349704	Curb Ramps	Southeast Corner Of 3rd Street @ 33.942651238555, - 118.133533447981	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355309	Curb Ramps	Northeast Corner Of 3rd Street @ 33.942786972730, - 118.133435547352		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355310	Curb Ramps	Northeast Corner Of 3rd Street @ 33.942786972730, - 118.133435547352		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349775	Curb Ramps	Northeast Corner Of 3rd Street @ 33.942786972730, - 118.133435547352	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349776	Curb Ramps	Northeast Corner Of 3rd Street @ 33.942786972730, - 118.133435547352	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355311	Curb Ramps	Southeast Corner Of 5th Street @ 33.944557060076, - 118.132064938545		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355312	Curb Ramps	Southeast Corner Of 5th Street @ 33.944557060076, - 118.132064938545		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349780	Curb Ramps	Southeast Corner Of 5th Street @ 33.944557060076, - 118.132064938545	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	349779	Curb Ramps	Southeast Corner Of 5th Street @ 33.944557060076, - 118.132064938545	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351531	Curb Ramps	Southwest Corner Of 3rd Street @ 33.942755820644, - 118.133701086044		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351532	Curb Ramps	Southwest Corner Of 3rd Street @ 33.942755820644, - 118.133701086044		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351533	Curb Ramps	Southwest Corner Of 5th Street @ 33.944641613925, - 118.132228553295	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351534	Curb Ramps	Northeast Corner Of Firestone Boulevard @ 33.941111419309, - 118.134741783142		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351535	Curb Ramps	Northeast Corner Of Firestone Boulevard @ 33.941111419309, - 118.134741783142		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351536	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941953650483, - 118.134068548679		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351538	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941953650483, - 118.134068548679	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351539	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941953650483, - 118.134068548679	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351537	Curb Ramps	Northeast Corner Of 2nd Street @ 33.941953650483, - 118.134068548679	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355313	Curb Ramps	Southwest Corner Of 2nd Street @ 33.941920272920, - 118.134336769581		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351541	Curb Ramps	Southwest Corner Of 2nd Street @ 33.941920272920, - 118.134336769581	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351542	Curb Ramps	Southwest Corner Of 2nd Street @ 33.941920272920, - 118.134336769581	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	355314	Curb Ramps	Northwest Corner Of Firestone Boulevard @ 33.941194863985, - 118.134887963533		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351545	Curb Ramps	Northwest Corner Of Firestone Boulevard @ 33.941194863985, - 118.134887963533	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351546	Curb Ramps	Southeast Corner Of 2nd Street @ 33.941820140153, - 118.134171813726		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351547	Curb Ramps	Southeast Corner Of 2nd Street @ 33.941820140153, - 118.134171813726		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351548	Curb Ramps	Southeast Corner Of 2nd Street @ 33.941820140153, - 118.134171813726	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351549	Curb Ramps	Southeast Corner Of 2nd Street @ 33.941820140153, - 118.134171813726	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351550	Curb Ramps	Southeast Corner Of 2nd Street @ 33.941820140153, - 118.134171813726	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351551	Curb Ramps	Southwest Corner Of 6th Street @ 33.945727455881, - 118.131426572800		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351552	Curb Ramps	Southwest Corner Of 6th Street @ 33.945727455881, - 118.131426572800		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351553	Curb Ramps	Southwest Corner Of 6th Street @ 33.945727455881, - 118.131426572800	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351631	Curb Ramps	Northwest Corner Of 6th Street @ 33.945830921656, - 118.131346106529		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351632	Curb Ramps	Northwest Corner Of 6th Street @ 33.945830921656, - 118.131346106529	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351633	Curb Ramps	Northwest Corner Of 4th Street @ 33.943722642595, - 118.132940679789		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351634	Curb Ramps	Northwest Corner Of 4th Street @ 33.943722642595, - 118.132940679789		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351635	Curb Ramps	Northwest Corner Of 4th Street @ 33.943722642595, - 118.132940679789		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351637	Curb Ramps	Northwest Corner Of 4th Street @ 33.943722642595, - 118.132940679789	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	351636	Curb Ramps	Northwest Corner Of 4th Street @ 33.943722642595, - 118.132940679789	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351638	Curb Ramps	Southwest Corner Of 4th Street @ 33.943606936058, - 118.133034557104		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351639	Curb Ramps	Southwest Corner Of 4th Street @ 33.943606936058, - 118.133034557104		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351640	Curb Ramps	Southwest Corner Of 4th Street @ 33.943606936058, - 118.133034557104		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	355315	Curb Ramps	Northwest Corner Of 5th Street @ 33.944767331991, - 118.132131993771		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351643	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351644	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351645	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351646	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351647	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351648	Curb Ramps	Northwest Corner Of 3rd Street @ 33.942883766641, - 118.133603185415	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351649	Curb Ramps	Northwest Corner Of 2nd Street @ 33.942049332758, - 118.134252279997		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351650	Curb Ramps	Northwest Corner Of 2nd Street @ 33.942049332758, - 118.134252279997	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351651	Curb Ramps	Northwest Corner Of 2nd Street @ 33.942049332758, - 118.134252279997	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	426286	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.940921165143, - 118.134910762310		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	426287	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.940921165143, - 118.134910762310		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	426288	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.94092371430, - 118.135031461716		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
La Reina Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	426289	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.940992371430, - 118.135031461716	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483131	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.940598510906, - 118.135176301003		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483132	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.940598510906, - 118.135176301003		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483133	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.940598510906, - 118.135176301003		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483134	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.940598510906, - 118.135176301003	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483143	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.940533979912, - 118.135236650705		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483144	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.940533979912, - 118.135236650705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
La Reina Avenue - Nance Street to Firestone Boulevard - Nance Street to Firestone Boulevard	483145	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.940533979912, - 118.135236650705	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Columbia Way - Lakewood Boulevard & Columbia Way Downey, CA 90240	436611	Curb Ramps	Northeast Corner of Columbia Way @ 33.921768962553, - 118.133988082409		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lakewood Boulevard & Columbia Way - Lakewood Boulevard & Columbia Way Downey, CA 90240	436612	Curb Ramps	Northeast Corner of Columbia Way @ 33.921768962553, - 118.133988082409	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & Florence Avenue - Lakewood Boulevard & Florence Avenue Downey, CA 90424	350747	Curb Ramps	Northeast Corner @ 33.947469669257, - 118.117181360722	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Florence Avenue - Lakewood Boulevard & Florence Avenue Downey, CA 90424	350748	Curb Ramps	Southeast Corner @ 33.947469669257, - 118.117181360722	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Florence Avenue - Lakewood Boulevard & Florence Avenue Downey, CA 90424	350851	Curb Ramps	Southwest Corner @ 33.947469669257, - 118.117181360722	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & gallatin Road - Lakewood Boulevard & gallatin Road Downey, CA 90242	346950	Curb Ramps	Northeast Corner @ 33.954364746253, - 118.113643527031	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & gallatin Road - Lakewood Boulevard & gallatin Road Downey, CA 90242	346951	Curb Ramps	Southeast Corner @ 33.954364746253, - 118.113643527031	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Gallatin Road - Lakewood Boulevard & Gallatin Road Downey, CA 90242	346952	Curb Ramps	Southeast Corner @ 33.954364746253, - 118.113643527031	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard & Gallatin Road - Lakewood Boulevard & Gallatin Road Downey, CA 90242	346953	Curb Ramps	Southwest Corner @ 33.954364746253, - 118.113643527031		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard & Gallatin Road - Lakewood Boulevard & Gallatin Road Downey, CA 90242	346954	Curb Ramps	Southwest Corner @ 33.954364746253, - 118.113643527031	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349610	Curb Ramps	Northeast Corner @ 33.910513977889, - 118.142323046923		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349611	Curb Ramps	Northeast Corner @ 33.910513977889, - 118.142323046923		Grade Break	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349612	Curb Ramps	Northeast Corner @ 33.910513977889, - 118.142323046923		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349614	Curb Ramps	Northeast Corner @ 33.910513977889, - 118.142323046923	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349613	Curb Ramps	Northeast Corner @ 33.910513977889, - 118.142323046923	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349615	Curb Ramps	Southwest Corner @ 33.910462780060, - 118.142718672752		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & Gardendale Street - Lakewood Boulevard & Gardendale Street Downey, CA 90242	349616	Curb Ramps	Southwest Corner @ 33.910462780060, - 118.142718672752	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437884	Curb Ramps	Northeast Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437885	Curb Ramps	Northeast Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/32	
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437973	Curb Ramps	Northwest Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437974	Curb Ramps	Northwest Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437975	Curb Ramps	Northwest Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437976	Curb Ramps	Northwest Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437977	Curb Ramps	Northwest Corner of I-5 North Ramp @ 33.959234794709, - 118.111245632172	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437978	Curb Ramps	Southeast Corner of I-5 North Ramp @ 33.958892187351, - 118.111057877541		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437979	Curb Ramps	Southwest Corner of I-5 North Ramp @ 33.959039019245, - 118.111347556114		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437980	Curb Ramps	Southwest Corner of I-5 North Ramp @ 33.959039019245, - 118.111347556114		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437981	Curb Ramps	Southwest Corner of I-5 North Ramp @ 33.959039019245, - 118.111347556114		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437982	Curb Ramps	Southwest Corner of I-5 North Ramp @ 33.959039019245, - 118.111347556114		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & I-5 North Ramp - Lakewood Boulevard & I-5 North Ramp Downey, CA 90240	437983	Curb Ramps	Southwest Corner of I-5 North Ramp @ 33.959039019245, - 118.111347556114	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	437984	Curb Ramps	Southwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	437985	Curb Ramps	Southwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	437986	Curb Ramps	Southwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	437987	Curb Ramps	Southwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	437988	Curb Ramps	Southwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438040	Curb Ramps	Northwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438041	Curb Ramps	Northwest Corner of West I-5 on Ramp @ 33.956705252025, - 118.112077116966	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438042	Curb Ramps	Southeast Corner of East I-5 on Ramp @ 33.956705252025, - 118.112077116966		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438043	Curb Ramps	Southeast Corner of East I-5 on Ramp @ 33.956705252025, - 118.112077116966		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438044	Curb Ramps	Southeast Corner of East I-5 on Ramp @ 33.956705252025, - 118.112077116966	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & I-5 South Ramp - Lakewood Boulevard & I-5 South Ramp Downey, CA 90240	438045	Curb Ramps	Southeast Corner of East I-5 on Ramp @ 33.956705252025, - 118.112077116966	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434977	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917174998265, - 118.137810230255	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434976	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917174998265, -118.137810230255	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434979	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916890093098, -118.137590289116	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434978	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916890093098, -118.137590289116	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434980	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917177224082, -118.137308657169		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434981	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917177224082, -118.137308657169	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434982	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917177224082, -118.137308657169	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434983	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917177224082, -118.137308657169	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434984	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916814415003, - 118.138150870800		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lakewood Boulevard & Imperial Highway - Lakewood Boulevard & Imperial Highway Downey, CA 90240	434985	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916814415003, - 118.138150870800	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435810	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.927911667249, - 118.129286176		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435811	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.927911667249, - 118.129286176		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435812	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.927911667249, - 118.129286176	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435813	Curb Ramps	Southeast Corner of Stewart And Gray Road @ 33.927911667249, - 118.129286176	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435814	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.928174280257, - 118.129441738129		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435815	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435816	Curb Ramps	Northwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435817	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435818	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435819	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435820	Curb Ramps	Southwest Corner of Stewart And Gray Road @ 33.928174280257, -118.129441738129	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435913	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.928192084499, -118.129221796989		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435914	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.928192084499, -118.129221796989		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435916	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.928192084499, -118.129221796989	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435917	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.928192084499, -118.129221796989	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard & Stewart And Gray Road - Lakewood Boulevard & Stewart And Gray Road Downey, CA 90240	435915	Curb Ramps	Northeast Corner of Stewart And Gray Road @ 33.928192084499, -118.129221796989	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435918	Curb Ramps	Southeast Corner of Stonewood Street @ 33.937316269009, -118.123390674591		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435919	Curb Ramps	Southeast Corner of Stonewood Street @ 33.937316269009, -118.123390674591		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435920	Curb Ramps	Southwest Corner of Stonewood Street @ 33.937316269009, -118.123390674591		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435921	Curb Ramps	Southwest Corner of Stonewood Street @ 33.937316269009, - 118.123390674591		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435991	Curb Ramps	Northwest Corner of Stonewood Street @ 33.937494292154, - 118.123229742050		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435992	Curb Ramps	Northwest Corner of Stonewood Street @ 33.937494292154, - 118.123229742050		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435993	Curb Ramps	Northwest Corner of Stonewood Street @ 33.937494292154, - 118.123229742050	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435994	Curb Ramps	Northeast Corner of Stonewood Street @ 33.937316269009, - 118.123390674591		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435995	Curb Ramps	Northeast Corner of Stonewood Street @ 33.937316269009, - 118.123390674591		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lakewood Boulevard & Stonewood Street - Lakewood Boulevard & Stonewood Street Downey, CA 90240	435996	Curb Ramps	Northeast Corner of Stonewood Street @ 33.937316269009, - 118.123390674591		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480004	Curb Ramps	Northwest Corner of Pepboys Driveway @ 33.946352698756, - 118.117975294590		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480005	Curb Ramps	Northwest Corner of Pepboys Driveway @ 33.946352698756, - 118.117975294590		Grade Break	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480006	Curb Ramps	Southwest Corner of Pepboys Driveway @ 33.946232545677, - 118.118020892143		Grade Break	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480007	Curb Ramps	Southwest Corner of Pepboys Driveway @ 33.946232545677, - 118.118020892143	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Lakewood Boulevard - Gardendale Street to Century Boulevard - Gardendale Street to Century Boulevard Downey, CA 90242	482323	Curb Ramps	Northwest Corner of Rosecrans Avenue @ 33.902574608129, - 118.143072724342	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard - Gardendale Street to Century Boulevard - Gardendale Street to Century Boulevard Downey, CA 90242	482322	Curb Ramps	Northwest Corner of Rosecrans Avenue @ 33.902574608129, - 118.143072724342	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482463	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482464	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482465	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482468	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482466	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482467	Curb Ramps	Southeast Corner of I-105 East on Ramp @ 33.912384903526, - 118.140941709280	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482496	Curb Ramps	Southwest Corner of I-105 East on Ramp @ 33.911482278855, - 118.142066895962	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482497	Curb Ramps	Northeast Corner of I-105 East on Ramp @ 33.912501765454, - 118.140890747309		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482498	Curb Ramps	Northeast Corner of I-105 East on Ramp @ 33.912501765454, - 118.140890747309		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482499	Curb Ramps	Northeast Corner of I-105 East on Ramp @ 33.912501765454, - 118.140890747309		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482500	Curb Ramps	Northeast Corner of I-105 East on Ramp @ 33.912501765454, - 118.140890747309	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482501	Curb Ramps	Northeast Corner of I-105 East on Ramp @ 33.912501765454, - 118.140890747309	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482502	Curb Ramps	Northwest Corner of I-105 East on Ramp @ 33.911585786238, - 118.142062872648		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482503	Curb Ramps	Northwest Corner of I-105 East on Ramp @ 33.911585786238, - 118.142062872648		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482506	Curb Ramps	Northwest Corner of I-105 East on Ramp @ 33.911585786238, - 118.142062872648	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482504	Curb Ramps	Northwest Corner of I-105 East on Ramp @ 33.911585786238, - 118.142062872648	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482505	Curb Ramps	Northwest Corner of I-105 East on Ramp @ 33.911585786238, - 118.142062872648	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482507	Curb Ramps	Southeast Corner of Priscilla Street @ 33.911090507835, - 118.141997158527		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lakewood Boulevard - Gardendale Street to Imperial Highway - Gardendale Street to Imperial Highway Downey, CA 90242	482508	Curb Ramps	Southeast Corner of Priscilla Street @ 33.911090507835, - 118.141997158527	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480857	Curb Ramps	West Side North of Buckles Street @ 33.930065960205, - 118.128230720758	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482046	Curb Ramps	West Side North of Stewart & Gray Road - 1st @ 33.934694835109, - 118.124792128801		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482047	Curb Ramps	West Side North of Stewart & Gray Road - 1st @ 33.934694835109, - 118.124792128801		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481869	Curb Ramps	West Side North of Stewart & Gray Road - 1st @ 33.934694835109, - 118.124792128801	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482048	Curb Ramps	West Side North of Stewart & Gray Road - 2nd @ 33.934694835109, - 118.124792128801		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327027	Curb Ramps	East Side South Of Stewart and Gray Road - 5th @ 33.925085187859, - 118.131458759308		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327028	Curb Ramps	East Side South Of Stewart and Gray Road - 4th @ 33.925717259108, - 118.130986690521		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327029	Curb Ramps	East Side South Of Stewart and Gray Road - 4th @ 33.925717259108, - 118.130986690521		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327030	Curb Ramps	East Side South Of Stewart and Gray Road - 4th @ 33.925717259108, - 118.130986690521	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327031	Curb Ramps	East Side South Of Stewart and Gray Road - 1st @ 33.926847853729, - 118.130106925964		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327032	Curb Ramps	East Side South Of Stewart and Gray Road - 1st @ 33.926847853729, - 118.130106925964	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327093	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, - 118.129420280457		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327094	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, - 118.129420280457		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327095	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, -118.129420280457		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327096	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, -118.129420280457		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327037	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, -118.129420280457	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327038	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.927898314023, -118.129420280457	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327045	Curb Ramps	East Side South Of Stewart and Gray Road -6th @ 33.924996163362, -118.131555318832		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327046	Curb Ramps	East Side South Of Stewart and Gray Road -6th @ 33.924996163362, -118.131555318832	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327047	Curb Ramps	East Side South Of Stewart and Gray Road - 3rd @ 33.925930915934, - 118.130900859833		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327048	Curb Ramps	Northeast Corner Of Apollo Way @ 33.922993087596, - 118.133025169373		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327049	Curb Ramps	Northeast Corner Of Apollo Way @ 33.922993087596, - 118.133025169373	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327114	Curb Ramps	West Side North Of Alameda Street @ 33.927030349880, - 118.130466341972		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327115	Curb Ramps	West Side North Of Alameda Street @ 33.927030349880, - 118.130466341972		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327116	Curb Ramps	West Side North Of Alameda Street @ 33.927030349880, - 118.130466341972		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327117	Curb Ramps	West Side North Of Alameda Street @ 33.927030349880, - 118.130466341972	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327118	Curb Ramps	Northeast Corner Of Rose Avenue @ 33.920313343700, - 118.135014044	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327119	Curb Ramps	Northwest Corner Of Donovan Street @ 33.920553722840, - 118.135267496109		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327120	Curb Ramps	Northwest Corner Of Donovan Street @ 33.920553722840, - 118.135267496109		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327121	Curb Ramps	Northwest Corner Of Donovan Street @ 33.920553722840, - 118.135267496109	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327122	Curb Ramps	Southeast Corner Of Columbia Way @ 33.921332724650, - 118.134312629700	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327123	Curb Ramps	Southwest Corner Of Donovan Street @ 33.920340052527, - 118.135396242142		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327124	Curb Ramps	Southwest Corner Of Donovan Street @ 33.920340052527, - 118.135396242142		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327125	Curb Ramps	Southwest Corner Of Alameda Street @ 33.923549502256, - 118.133035898209		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327126	Curb Ramps	Southwest Corner Of Alameda Street @ 33.923549502256, - 118.133035898209		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327128	Curb Ramps	Southwest Corner Of Alameda Street @ 33.923549502256, - 118.133035898209	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327129	Curb Ramps	Southwest Corner Of Alameda Street @ 33.923549502256, - 118.133035898209	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327127	Curb Ramps	Southwest Corner Of Alameda Street @ 33.923549502256, - 118.133035898209	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327130	Curb Ramps	Northwest Corner Of Imperial Highway @ 33.917117126980, - 118.137820959091	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327131	Curb Ramps	West Side North Of Donovan Street @ 33.922285322898, - 118.133947849274		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327132	Curb Ramps	West Side North Of Donovan Street @ 33.922285322898, - 118.133947849274		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327133	Curb Ramps	West Side North Of Donovan Street @ 33.922285322898, - 118.133947849274		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327134	Curb Ramps	Northwest Corner Of Meadow Road @ 33.918105385065, - 118.137112855911		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327135	Curb Ramps	Northwest Corner Of Meadow Road @ 33.918105385065, - 118.137112855911	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327136	Curb Ramps	Southeast Corner Of Rose Avenue @ 33.920161993524, - 118.135138750076		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327137	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.928094161120, - 118.129720687866		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327138	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.928094161120, - 118.129720687866		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327139	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.928094161120, - 118.129720687866		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327140	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.928094161120, - 118.129720687866	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327141	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917152740083, - 118.137284517288		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327142	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917152740083, - 118.137284517288		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327143	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917152740083, - 118.137284517288	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327144	Curb Ramps	Southwest Corner Of Meadow Road @ 33.917945127776, - 118.137246966362		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327145	Curb Ramps	Southwest Corner Of Meadow Road @ 33.917945127776, - 118.137246966362	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327182	Curb Ramps	Northwest Corner Of Alameda Street @ 33.923696395119, - 118.132960796356		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401108	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401109	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401110	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401111	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401112	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lakewood Boulevard Frontage Road- Donovan Street To Meadow Road - Donovan Street To Meadow Road Downey, CA 90242	401113	Curb Ramps	West Side South Of Donovan Street @ 33.918448156589, - 118.136988133192	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407527	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407528	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407529	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407530	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407531	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407532	Curb Ramps	Northeast Corner @ 33.937808057040, -118.155577182770	Top Landing	Top Landing Right Side Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407536	Curb Ramps	Northwest Corner @ 33.937939348387, -118.155763596296		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407537	Curb Ramps	Northwest Corner @ 33.937939348387, -118.155763596296	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407538	Curb Ramps	Northwest Corner @ 33.937939348387, -118.155763596296	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407539	Curb Ramps	Northwest Corner @ 33.937939348387, -118.155763596296	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407540	Curb Ramps	Northwest Corner @ 33.937939348387, - 118.155763596296	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407541	Curb Ramps	Southeast Corner @ 33.937699018310, - 118.155667036772		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407542	Curb Ramps	Southeast Corner @ 33.937699018310, - 118.155667036772		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407543	Curb Ramps	Southeast Corner @ 33.937699018310, - 118.155667036772	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Laura Street & Old River School Road - Laura Street & Old River School Road Downey, CA 90242	407544	Curb Ramps	Southeast Corner @ 33.937699018310, - 118.155667036772	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road Downey, CA 90242	407498	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road Downey, CA 90242	407499	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road Downey, CA 90242	407500	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road Downey, CA 90242	407502	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407503	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407501	Curb Ramps	Southwest Corner Of Pomeroy Road @ 33.936940193892, - 118.154230713844	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407510	Curb Ramps	Southeast Corner Of Pomeroy Road @ 33.936856745046, - 118.154081851244		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407511	Curb Ramps	Southeast Corner Of Pomeroy Road @ 33.936856745046, - 118.154081851244		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407512	Curb Ramps	Southeast Corner Of Pomeroy Road @ 33.936856745046, - 118.154081851244		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407513	Curb Ramps	Southeast Corner Of Pomeroy Road @ 33.936856745046, - 118.154081851244	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Laura Street - Julius Avenue To Old River School Road - Julius Avenue To Old River School Road	407514	Curb Ramps	Southeast Corner Of Pomeroy Road @ 33.936856745046, - 118.154081851244	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street	311851	Curb Ramps	Northwest Corner Of Somerset Ranch Road @ 33.912461698525, - 118.148308396339		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311852	Curb Ramps	Northwest Corner Of Somerset Ranch Road @ 33.912461698525, - 118.148308396339		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311853	Curb Ramps	Northwest Corner Of Somerset Ranch Road @ 33.912461698525, - 118.148308396339		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311854	Curb Ramps	Northwest Corner Of Somerset Ranch Road @ 33.912461698525, - 118.148308396339	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311855	Curb Ramps	Northwest Corner Of Somerset Ranch Road @ 33.912461698525, - 118.148308396339	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311856	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.912897981846, - 118.147833645344		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311857	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.912897981846, - 118.147833645344		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311858	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.912897981846, - 118.147833645344	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311882	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311883	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311884	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311887	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311888	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311885	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311886	Curb Ramps	Southwest Corner Of Somerset Ranch Road @ 33.912263589545, - 118.148541748524	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311889	Curb Ramps	Southwest Corner Of Gardendale Street @ 33.912993696765, - 118.147983849049		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Laureldale Avenue - Golden Avenue To Gardendale Street - Golden Avenue To Gardendale Street - Downey, CA 90242	311890	Curb Ramps	Southwest Corner Of Gardendale Street @ 33.912993696765, - 118.147983849049		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444656	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444657	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444658	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444659	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444660	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lesterford Avenue - Cecilia Street to Florence Avenue - Cecilia Street to Florence Avenue	444661	Curb Ramps	Southwest Corner of Quinn Street @ 33.935645058589, - 118.106567859650	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue	470120	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.948832486918, - 118.122781813145		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue	470121	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.948832486918, - 118.122781813145	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	470141	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.948979336172, - 118.122718781233		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	470142	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.948979336172, - 118.122718781233		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	470143	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.948979336172, - 118.122718781233		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	470144	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.948979336172, - 118.122718781233	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lexington Road - Brookshire Avenue to Downey Avenue - Brookshire Avenue to Downey Avenue Downey, CA 90242	470145	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.948979336172, - 118.122718781233	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lindell Avenue - Telegraph Road to I-5 Off Ramp - Telegraph Road to I-5 Off Ramp Downey, CA 90242	476890	Curb Ramps	Southeast Corner of Telegraph Road @ 33.960229238123, - 118.109205812216		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448330	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448331	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448334	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448335	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448332	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448333	Curb Ramps	Southeast Corner of Cedartree Road @ 33.956499459185, - 118.105956315994	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448346	Curb Ramps	West Side North of Cedartree Road - 1st @ 33.955865391629, - 118.106491416693		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448895	Curb Ramps	Southwest Corner of Cedartree Road @ 33.956609586226, - 118.106122612953		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448348	Curb Ramps	Southwest Corner of Cedartree Road @ 33.956609586226, - 118.106122612953	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lindsey Avenue - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	448349	Curb Ramps	Southwest Corner of Cedartree Road @ 33.956609586226, - 118.106122612953	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350911	Curb Ramps	Northeast Corner @ 33.938268688502, -118.098939657211		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350978	Curb Ramps	Northwest Corner @ 33.938268688502, -118.098939657211	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350979	Curb Ramps	Southwest Corner @ 33.938268688502, -118.098939657211		Curb Ramp Slope	Provide a compliant curb ramp.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350980	Curb Ramps	Southwest Corner @ 33.938268688502, -118.098939657211		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350981	Curb Ramps	Southwest Corner @ 33.938268688502, -118.098939657211		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350982	Curb Ramps	Southwest Corner @ 33.938268688502, -118.098939657211	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350983	Curb Ramps	Southwest Corner @ 33.938268688502, -118.098939657211	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350984	Curb Ramps	Southeast Corner @ 33.938268688502, -118.098939657211		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350985	Curb Ramps	Southeast Corner @ 33.938268688502, -118.098939657211		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Little Lake Road & Florence Avenue - Little Lake Road & Florence Avenue Downey, CA 90424	350986	Curb Ramps	Southeast Corner @ 33.938268688502, -118.098939657211		Appurtenances	Provide a compliant curb ramp free of appurtenances.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 465740	Curb Ramps	Southwest Corner of Park Driveway @ 33.935976632905, - 118.100152015686		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 464508	Curb Ramps	Southwest Corner of Park Driveway @ 33.935976632905, - 118.100152015686	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 464507	Curb Ramps	Southwest Corner of Park Driveway @ 33.935976632905, - 118.100152015686	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 465741	Curb Ramps	Northwest Corner of Park Driveway @ 33.936067871249, - 118.100127875805		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 465742	Curb Ramps	Northwest Corner of Park Driveway @ 33.936067871249, - 118.100127875805		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Little Lake Road - Cecilia Street to I-605 South Ramp - Cecilia Street to I-605 South Ramp	Downey, CA 90240 464529	Curb Ramps	Northwest Corner of Park Driveway @ 33.936067871249, - 118.100127875805	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	Downey, CA 90240 353603	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965110073711, - 118.122736215591		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	Downey, CA 90240 353604	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965110073711, - 118.122736215591		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353605	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965110073711, - 118.122736215591		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353607	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965110073711, - 118.122736215591	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353606	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965110073711, - 118.122736215591	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353614	Curb Ramps	Northwest Corner Of Allengrove Street @ 33.965223526450, - 118.122856914997		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353615	Curb Ramps	Northwest Corner Of Allengrove Street @ 33.965223526450, - 118.122856914997		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353616	Curb Ramps	Northwest Corner Of Allengrove Street @ 33.965223526450, - 118.122856914997		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lowman Avenue - Allengrove Street to Danvers Street - Allengrove Street to Danvers Street	353617	Curb Ramps	Northwest Corner Of Allengrove Street @ 33.965223526450, - 118.122856914997		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455161	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455162	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455163	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455010	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455011	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455012	Curb Ramps	Southeast Corner of Telegraph Road @ 33.968368998966, - 118.117171972990	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455164	Curb Ramps	Southwest Corner of Telegraph Road @ 33.968494681979, - 118.117295354605		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455165	Curb Ramps	Southwest Corner of Telegraph Road @ 33.968494681979, - 118.117295354605		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455016	Curb Ramps	Southwest Corner of Telegraph Road @ 33.968494681979, - 118.117295354605	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455015	Curb Ramps	Southwest Corner of Telegraph Road @ 33.968494681979, - 118.117295354605	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455166	Curb Ramps	Northeast Corner of Brookpark Road @ 33.966730653858, - 118.121027648449		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455167	Curb Ramps	Northeast Corner of Brookpark Road @ 33.966730653858, - 118.121027648449		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455168	Curb Ramps	Northeast Corner of Brookpark Road @ 33.966730653858, - 118.121027648449		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455020	Curb Ramps	Northeast Corner of Brookpark Road @ 33.966730653858, - 118.121027648449	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455021	Curb Ramps	Northeast Corner of Brookpark Road @ 33.966730653858, - 118.121027648449	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455171	Curb Ramps	Northwest Corner of Brookpark Road @ 33.966884145778, - 118.121073246002		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road	455172	Curb Ramps	Northwest Corner of Brookpark Road @ 33.966884145778, - 118.121073246002		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455173	Curb Ramps	Northwest Corner of Brookpark Road @ 33.966884145778, - 118.121073246002		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455054	Curb Ramps	Northwest Corner of Brookpark Road @ 33.966884145778, - 118.121073246002	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lowman Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road - Downey, CA 90242	455053	Curb Ramps	Northwest Corner of Brookpark Road @ 33.966884145778, - 118.121073246002	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard - Downey, CA 90242	406047	Curb Ramps	Northeast Corner @ 33.956759759235, - 118.127431422472		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard - Downey, CA 90242	406048	Curb Ramps	Northeast Corner @ 33.956759759235, - 118.127431422472	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard - Downey, CA 90242	406049	Curb Ramps	Northwest Corner @ 33.956895470911, - 118.127710372210	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard - Downey, CA 90242	406148	Curb Ramps	Southwest Corner @ 33.956750860101, - 118.127827048302		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard - Downey, CA 90242	406149	Curb Ramps	Southeast Corner @ 33.956610698620, - 118.127546757460		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lubec Street & Paramount Boulevard - Lubec Street & Paramount Boulevard	406150	Curb Ramps	Southeast Corner @ 33.956610698620, - 118.127546757460	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	457973	Curb Ramps	Northwest Corner of Samoline Avenue @ 33.957304829409, - 118.128543198109	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	457974	Curb Ramps	Northwest Corner of Samoline Avenue @ 33.957304829409, - 118.128543198109	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	458037	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.957238086310, - 118.128414452076		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	458038	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.957238086310, - 118.128414452076		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	457987	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.957238086310, - 118.128414452076	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Lubec Street - Tweedy Lane to Paramount Boulevard - Tweedy Lane to Paramount Boulevard	457988	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.957238086310, - 118.128414452076	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318451	Curb Ramps	Southwest Corner Of Patton Road @ 33.932558462571, - 118.134151697159		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318452	Curb Ramps	Southwest Corner Of Patton Road @ 33.932558462571, - 118.134151697159		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318453	Curb Ramps	Southwest Corner Of Patton Road @ 33.932558462571, - 118.134151697159	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318454	Curb Ramps	Northwest Corner Of Patton Road @ 33.931703898549, - 118.132565529		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318455	Curb Ramps	Northwest Corner Of Patton Road @ 33.931703898549, - 118.132565529		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318456	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.932580716728, - 118.134157061577	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318457	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934058379729, - 118.137053847313		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue	318458	Curb Ramps	Northeast Corner Of Downey Avenue @ 33.934058379729, - 118.137053847313	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue Downey, CA 90421	318466	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.933915955496, - 118.137161135674		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Luxor Street - Patton Road To Downey Avenue - Patton Road To Downey Avenue Downey, CA 90421	318467	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.933915955496, - 118.137161135674		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360393	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.945553900105, - 118.159165978432		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360394	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.945553900105, - 118.159165978432		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360395	Curb Ramps	Northeast Corner Of Mitla Avenue @ 33.945553900105, - 118.159165978432	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360396	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360397	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue Downey, CA 90421	360398	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362		Detectable Warnings Width	Provide compliant detectable warnings that are full width of the curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360399	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362		Detectable Warnings Depth	Provide compliant detectable warnings.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360400	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360402	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360403	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360401	Curb Ramps	Southeast Corner Of Old River School Road @ 33.941869093965, - 118.152658939362	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360404	Curb Ramps	Northwest Corner Of Ryerson Avenue @ 33.944120938893, - 118.156489133835		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360405	Curb Ramps	Northwest Corner Of Ryerson Avenue @ 33.944120938893, - 118.156489133835	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360406	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.940591835288, - 118.150330781937		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360407	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.940591835288, - 118.150330781937		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360408	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.940591835288, - 118.150330781937	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360409	Curb Ramps	Southeast Corner Of Julius Avenue @ 33.940591835288, - 118.150330781937	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360429	Curb Ramps	Southeast Corner Of Horton Avenue @ 33.940169045093, - 118.149542212486		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360430	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.938878409407, - 118.146752715111		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360431	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.938878409407, - 118.146752715111	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360432	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360433	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360436	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360437	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360434	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360435	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.939047528300, - 118.146650791168	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360438	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360439	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165		Curb Ramp Slope	Provide a compliant curb ramp.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360440	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360442	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360443	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360441	Curb Ramps	Northeast Corner Of Old River School Road @ 33.942015955232, - 118.152540922165	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360444	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942038206917, - 118.152852058411		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360445	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942038206917, - 118.152852058411		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360446	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942038206917, - 118.152852058411		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360447	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942038206917, - 118.152852058411	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360448	Curb Ramps	Southwest Corner Of Old River School Road @ 33.942038206917, - 118.152852058411	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360469	Curb Ramps	Northwest Corner Of Old River School Road @ 33.942158365916, - 118.152809143066		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360470	Curb Ramps	Northwest Corner Of Old River School Road @ 33.942158365916, - 118.152809143066		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360471	Curb Ramps	Northwest Corner Of Old River School Road @ 33.942158365916, - 118.152809143066		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360472	Curb Ramps	Northwest Corner Of Old River School Road @ 33.942158365916, - 118.152809143066	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360473	Curb Ramps	Northwest Corner Of Old River School Road @ 33.942158365916, - 118.152809143066	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360474	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360475	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360476	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360478	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360479	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360477	Curb Ramps	Southwest Corner Of Ryerson Avenue @ 33.944782664, - 118.156574964523	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360480	Curb Ramps	Northwest Corner Of Norlain Avenue @ 33.941726682797, - 118.152020573616		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Luxor Street - Rives Avenue To Mitla Avenue - Rives Avenue To Mitla Avenue	360481	Curb Ramps	Northwest Corner Of Norlain Avenue @ 33.941726682797, - 118.152020573616		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400301	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400302	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400303	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400306	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400304	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400305	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400331	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400332	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400335	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400336	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400337	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400333	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Lyndora Street - Barlin Avenue To Cul-de-sac - Barlin Avenue To Cul-de-sac	400334	Curb Ramps	Northeast Corner Of Barlin Avenue @ 33.917585660677, - 118.141286373138	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	318420	Curb Ramps	Southwest Corner Of Patton Road @ 33.933346256182, - 118.130911588669		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	318421	Curb Ramps	Southwest Corner Of Patton Road @ 33.933346256182, - 118.130911588669		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	318422	Curb Ramps	Southwest Corner Of Patton Road @ 33.933346256182, - 118.130911588669	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	330773	Curb Ramps	North Side East Of Brookshire Avenue - 1st @ 33.933519836846, - 118.131040334702		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	330774	Curb Ramps	North Side East Of Brookshire Avenue - 1st @ 33.933519836846, - 118.131040334702		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	330775	Curb Ramps	North Side East Of Brookshire Avenue - 1st @ 33.933519836846, - 118.131040334702		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue	318426	Curb Ramps	North Side East Of Brookshire Avenue - 1st @ 33.933519836846, - 118.131040334702	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue Downey, CA 90241	318427	Curb Ramps	Northwest Corner Of Patton Road @ 33.933430821165, - 118.130713105202		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue Downey, CA 90241	330776	Curb Ramps	North Side East Of Brookshire Avenue - 2nd @ 33.933488681368, - 118.130847215652		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Manatee Street - Patton Road To Brookshire Avenue - Patton Road To Brookshire Avenue Downey, CA 90241	330777	Curb Ramps	North Side East Of Brookshire Avenue - 2nd @ 33.933488681368, - 118.130847215652		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Manzanar Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	453611	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961544021303, - 118.111049830914		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Manzanar Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	453612	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961544021303, - 118.111049830914	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Marbel Avenue - Alameda Street To McCallum Street - Alameda Street To McCallum Street Downey, CA 90242	385635	Curb Ramps	Southeast Corner Of McCallum Street @ 33.927281837837, - 118.131971061230		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Marbel Avenue - Alameda Street To McCallum Street - Alameda Street To McCallum Street Downey, CA 90242	385636	Curb Ramps	Southeast Corner Of McCallum Street @ 33.927281837837, - 118.131971061230		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Marbel Avenue - Alameda Street To McCallum Street - Alameda Street To McCallum Street Downey, CA 90242	385637	Curb Ramps	Southeast Corner Of McCallum Street @ 33.927281837837, - 118.131971061230	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Marbel Avenue - Alameda Street To McCallum Street - Alameda Street To McCallum Street Downey, CA 90242	385638	Curb Ramps	Southeast Corner Of McCallum Street @ 33.927281837837, - 118.131971061230	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356625	Curb Ramps	Southwest Corner Of Mory Street @ 33.922586902600, - 118.134944289923		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356626	Curb Ramps	Southwest Corner Of Mory Street @ 33.922586902600, - 118.134944289923		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356627	Curb Ramps	Southwest Corner Of Mory Street @ 33.922586902600, - 118.134944289923		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356629	Curb Ramps	Southwest Corner Of Mory Street @ 33.922586902600, - 118.134944289923	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356628	Curb Ramps	Southwest Corner Of Mory Street @ 33.922586902600, - 118.134944289923	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356630	Curb Ramps	Northwest Corner Of Donovan Street @ 33.921008883334, - 118.136121779680		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356631	Curb Ramps	Northwest Corner Of Donovan Street @ 33.921008883334, - 118.136121779680		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356632	Curb Ramps	Northwest Corner Of Donovan Street @ 33.921008883334, - 118.136121779680		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356633	Curb Ramps	Northwest Corner Of Donovan Street @ 33.921008883334, - 118.136121779680	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Marbel Avenue - Donovan Street To Mory Street - Donovan Street To Mory Street Downey, CA 90242	356634	Curb Ramps	Northwest Corner Of Donovan Street @ 33.921008883334, - 118.136121779680	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477601	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.936402781892, - 118.125362098217		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477602	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.936402781892, - 118.125362098217		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477603	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.936402781892, - 118.125362098217	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477604	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.936336022401, - 118.125213235617		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477605	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.936336022401, - 118.125213235617	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Marbel Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477606	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.936336022401, - 118.125213235617	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Margaret Street - Lakewood Boulevard to Adenmoor Avenue - Lakewood Boulevard to Adenmoor Avenue Downey, CA 90242	476994	Curb Ramps	Northeast Corner of Lakewood Boulevard @ 33.933731248714, - 118.125088512897	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356601	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.924801421952, - 118.136840611696		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356602	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.924801421952, - 118.136840611696	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356603	Curb Ramps	Northeast Corner Of Birchdale Avenue @ 33.924801421952, - 118.136840611696	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356610	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.924703494675, - 118.136937171221		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356611	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.924703494675, - 118.136937171221		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356612	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.924703494675, - 118.136937171221		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356614	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.924703494675, - 118.136937171221	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Melva Street - Birchdale Avenue To Blodgett Avenue - Birchdale Avenue To Blodgett Avenue Downey, CA 90242	356613	Curb Ramps	Southeast Corner Of Birchdale Avenue @ 33.924703494675, - 118.136937171221	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357476	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357477	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357478	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357482	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357483	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357479	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357480	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357481	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.922937445930, - 118.133663535118	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357484	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357485	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357486	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357487	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357488	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357489	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357490	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357491	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Melva Street - Lakewood Boulevard To Marbel Avenue - Lakewood Boulevard To Marbel Avenue Downey, CA 90242	357492	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922815034138, - 118.133753389120	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409290	Curb Ramps	Northwest Corner Of De Palma Street @ 33.944841872704, - 118.159903585911		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409291	Curb Ramps	Northwest Corner Of De Palma Street @ 33.944841872704, - 118.159903585911		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409292	Curb Ramps	Northwest Corner Of De Palma Street @ 33.944841872704, - 118.159903585911		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409293	Curb Ramps	Northwest Corner Of De Palma Street @ 33.944841872704, - 118.159903585911	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409320	Curb Ramps	Southeast Corner Of Adwen Street @ 33.947353967814, - 118.157883882523		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409321	Curb Ramps	Southeast Corner Of Adwen Street @ 33.947353967814, - 118.157883882523		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409322	Curb Ramps	Southeast Corner Of Adwen Street @ 33.947353967814, - 118.157883882523		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409323	Curb Ramps	Southeast Corner Of Adwen Street @ 33.947353967814, - 118.157883882523	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409324	Curb Ramps	Northeast Corner Of Adwen Street @ 33.947494144542, - 118.157787322998		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End Downey, CA 90242	409325	Curb Ramps	Northeast Corner Of Adwen Street @ 33.947494144542, - 118.157787322998		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Mitla Avenue - De Palma Street To End - De Palma Street To End	409326	Curb Ramps	Northeast Corner Of Adwen Street @ 33.947494144542, - 118.157787322998		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End	409327	Curb Ramps	Northeast Corner Of Adwen Street @ 33.947494144542, - 118.157787322998		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Mitla Avenue - De Palma Street To End - De Palma Street To End	409328	Curb Ramps	Northeast Corner Of Adwen Street @ 33.947494144542, - 118.157787322998	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Mory Street - Blodgett Avenue To Lakewood Boulevard - Blodgett Avenue To Lakewood Boulevard	356677	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.922204085379, - 118.134228140116	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Mueller Street - Pangborn Avenue To Lesterford Avenue - Pangborn Avenue To Lesterford Avenue	419719	Curb Ramps	Northwest Corner Of Lesterford Avenue @ 33.934096211126, - 118.107683658600		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Mueller Street - Pangborn Avenue To Lesterford Avenue - Pangborn Avenue To Lesterford Avenue	419726	Curb Ramps	Southwest Corner Of Lesterford Avenue @ 33.933984942264, - 118.107769489288		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Mueller Street - Pangborn Avenue To Lesterford Avenue - Pangborn Avenue To Lesterford Avenue	419727	Curb Ramps	Southwest Corner Of Lesterford Avenue @ 33.933984942264, - 118.107769489288	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue	446259	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue Downey, CA 90242	446260	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue Downey, CA 90242	446261	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue Downey, CA 90242	446262	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue Downey, CA 90242	446263	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Muller Street - Lakewood Boulevard to Chaney Avenue - Lakewood Boulevard to Chaney Avenue Downey, CA 90242	446264	Curb Ramps	Northeast Corner of Arrington Avenue @ 33.940965669079, - 118.119868934155	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474140	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474141	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474142	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474143	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474144	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474145	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Muller Street - Tristan Drive to Cul-De-Sac - Tristan Drive to Cul-De-Sac Downey, CA 90242	474146	Curb Ramps	Northeast Corner of Birchdale Avenue @ 33.943214200199, - 118.124421983957	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Muller Street - Wiley Burke Avenue to Rives Avenue - Wiley Burke Avenue to Rives Avenue Downey, CA 90242	461668	Curb Ramps	Northwest Corner of Rives Avenue @ 33.950470064254, - 118.138173669577	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Muller Street - Wiley Burke Avenue to Rives Avenue - Wiley Burke Avenue to Rives Avenue Downey, CA 90242	461669	Curb Ramps	Northwest Corner of Rives Avenue @ 33.950470064254, - 118.138173669577	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Muller Street - Wiley Burke Avenue to Rives Avenue - Wiley Burke Avenue to Rives Avenue Downey, CA 90242	461752	Curb Ramps	North Side East of Wiley Burke Avenue @ 33.950859429228, - 118.138954192400		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Muller Street - Wiley Burke Avenue to Rives Avenue - Wiley Burke Avenue to Rives Avenue Downey, CA 90242	461671	Curb Ramps	North Side East of Wiley Burke Avenue @ 33.950859429228, - 118.138954192400	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Muller Street - Wiley Burke Avenue to Rives Avenue - Wiley Burke Avenue to Rives Avenue Downey, CA 90242	461672	Curb Ramps	North Side East of Wiley Burke Avenue @ 33.950859429228, - 118.138954192400	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Muller Street/ Rio Hondo Golf Club Drive & Old River School Road - Muller Street/ Rio Hondo Golf Club Drive & Old River School Road Downey, CA 90242	463230	Curb Ramps	Southeast Corner @ 33.953245641371, - 118.144494295120		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Muller Street/ Rio Hondo Golf Club Drive & Old River School Road - Muller Street/ Rio Hondo Golf Club Drive & Old River School Road Downey, CA 90242	462492	Curb Ramps	Northeast Corner @ 33.953371346728, - 118.144389688969	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Muller Street/ Rio Hondo Golf Club Drive & Old River School Road - Muller Street/ Rio Hondo Golf Club Drive & Old River School Road Downey, CA 90242	463231	Curb Ramps	Northwest Corner @ 33.953495939466, - 118.144597560167		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Muller Street/ Rio Hondo Golf Club Drive & Old River School Road - Muller Street/ Rio Hondo Golf Club Drive & Old River School Road Downey, CA 90242	463232	Curb Ramps	Northwest Corner @ 33.953495939466, - 118.144597560167		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Muller Street/ Rio Hondo Golf Club Drive & Old River School Road - Muller Street/ Rio Hondo Golf Club Drive & Old River School Road	463233	Curb Ramps	Southwest Corner @ 33.953341310952, - 118.144712895155		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473362	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.942143902342, - 118.136627376080		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472489	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.942143902342, - 118.136627376080	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473363	Curb Ramps	West Side North of Firestone Boulevard @ 33.942786972730, - 118.135946094990		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473364	Curb Ramps	West Side North of Firestone Boulevard @ 33.942786972730, - 118.135946094990		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472492	Curb Ramps	West Side North of Firestone Boulevard @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472493	Curb Ramps	West Side North of Firestone Boulevard @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472494	Curb Ramps	West Side North of Firestone Boulevard @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473365	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473366	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473367	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473368	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472513	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472514	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472515	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472516	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472517	Curb Ramps	Southwest Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473369	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473370	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473371	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473372	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472524	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472525	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472526	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472522	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472523	Curb Ramps	Southeast Corner of 2nd Street @ 33.942786972730, - 118.135946094990	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	473373	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.942074922185, - 118.136505335569		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Myrtle Street - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard	472528	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.942074922185, - 118.136505335569	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473197	Curb Ramps	Southeast Corner of 4th Street @ 33.944788470409, - 118.134381026030	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473196	Curb Ramps	Southeast Corner of 4th Street @ 33.944788470409, - 118.134381026030	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473375	Curb Ramps	Northeast Corner of 2nd Street @ 33.942894892371, - 118.135860264301		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473376	Curb Ramps	Northeast Corner of 2nd Street @ 33.942894892371, - 118.135860264301		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473377	Curb Ramps	Northeast Corner of 2nd Street @ 33.942894892371, - 118.135860264301		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473201	Curb Ramps	Southwest Corner of 3rd Street @ 33.943687040600, - 118.135445863009	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473202	Curb Ramps	Northwest Corner of 3rd Street @ 33.943789396294, - 118.135309070349	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473203	Curb Ramps	Northwest Corner of 3rd Street @ 33.943789396294, - 118.135309070349	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473204	Curb Ramps	Northeast Corner of 3rd Street @ 33.943732655653, - 118.135213851929	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473205	Curb Ramps	Southeast Corner of 3rd Street @ 33.943602485803, - 118.135301023722	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473206	Curb Ramps	Southeast Corner of 3rd Street @ 33.943602485803, - 118.135301023722	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473378	Curb Ramps	Southeast Corner of 5th Street @ 33.945460446848, - 118.133849948645		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473208	Curb Ramps	Southeast Corner of 5th Street @ 33.945460446848, - 118.133849948645	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473209	Curb Ramps	Southeast Corner of 5th Street @ 33.945460446848, - 118.133849948645	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473210	Curb Ramps	Southeast Corner of 5th Street @ 33.945460446848, - 118.133849948645	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473211	Curb Ramps	Southwest Corner of 4th Street @ 33.943789396294, - 118.135309070349	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473379	Curb Ramps	Northwest Corner of 2nd Street @ 33.942967209580, - 118.135987669230		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473380	Curb Ramps	Northwest Corner of 2nd Street @ 33.942967209580, - 118.135987669230		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473214	Curb Ramps	Northwest Corner of 2nd Street @ 33.942967209580, - 118.135987669230	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473382	Curb Ramps	Northeast Corner of 4th Street @ 33.944901950246, - 118.134279102087		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473234	Curb Ramps	Northeast Corner of 4th Street @ 33.944901950246, - 118.134279102087	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473235	Curb Ramps	Northwest Corner of 4th Street @ 33.944968703021, - 118.134395778179	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473383	Curb Ramps	Southwest Corner of 5th Street @ 33.945531649339, - 118.133977353573		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473384	Curb Ramps	Southwest Corner of 5th Street @ 33.945531649339, - 118.133977353573		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Myrtle Street - 5th Street to 2nd Street - 5th Street to 2nd Street	473238	Curb Ramps	Southwest Corner of 5th Street @ 33.945531649339, - 118.133977353573	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483157	Curb Ramps	West Side North of End - 2nd @ 33.941603185419, - 118.137061893940		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483158	Curb Ramps	West Side North of End - 2nd @ 33.941603185419, - 118.137061893940	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483159	Curb Ramps	West Side North of End - 2nd @ 33.941603185419, - 118.137061893940	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483160	Curb Ramps	West Side North of End - 1st @ 33.941603185419, - 118.137061893940		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483161	Curb Ramps	West Side North of End - 1st @ 33.941603185419, - 118.137061893940		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483162	Curb Ramps	West Side North of End - 1st @ 33.941603185419, - 118.137061893940	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Myrtle Street - Firestone Boulevard to End - Firestone Boulevard to End	483163	Curb Ramps	West Side North of End - 1st @ 33.941603185419, - 118.137061893940	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nada Street - Mitla Avenue To Cul-de-sac - Mitla Avenue To Cul-de-sac	419085	Curb Ramps	Northeast Corner Of Pernell Avenue @ 33.941698868088, - 118.169533167	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Nada Street - Mitla Avenue To Cul-de-sac - Mitla Avenue To Cul-de-sac	419086	Curb Ramps	Northwest Corner Of Pernell Avenue @ 33.941776749250, - 118.160161077976	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410847	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410848	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410849	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410850	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410853	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410854	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410851	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410852	Curb Ramps	Northwest Corner Of Old River School Road @ 33.939393391, - 118.154824823141	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410872	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410873	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410874	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410875	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410878	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue Downey, CA 90242	410876	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nada Street - Old River School Road To Susan Avenue - Old River School Road To Susan Avenue	410877	Curb Ramps	Southwest Corner Of Old River School Road @ 33.939157677925, - 118.154941499233	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477552	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477553	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477554	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477486	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477487	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477484	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Nance Avenue - Woodruff Avenue to Pangborn Avenue - Woodruff Avenue to Pangborn Avenue	477485	Curb Ramps	Northwest Corner of Woodruff Avenue @ 33.929726573660, - 118.114865273237	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483106	Curb Ramps	South Side East of Myrtle Street - 2nd @ 33.940488363145, - 118.135723471642		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483107	Curb Ramps	South Side East of Myrtle Street - 2nd @ 33.940488363145, - 118.135723471642		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483108	Curb Ramps	South Side East of Myrtle Street - 2nd @ 33.940488363145, - 118.135723471642	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483109	Curb Ramps	Southwest Corner of La Reina Avenue @ 33.940263616766, - 118.135465979576		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483110	Curb Ramps	Southeast Corner of La Reina Avenue @ 33.940263616766, - 118.135465979576		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483128	Curb Ramps	South Side East of Myrtle Street - 1st @ 33.940540655534, - 118.135806620121		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483129	Curb Ramps	South Side East of Myrtle Street - 1st @ 33.940540655534, - 118.135806620121		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Nance Street - Myrtle Street to Downey Avenue - Myrtle Street to Downey Avenue	483130	Curb Ramps	South Side East of Myrtle Street - 1st @ 33.940540655534, - 118.135806620121	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477556	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.935639495251, - 118.125038892031		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477557	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.935639495251, - 118.125038892031	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477558	Curb Ramps	Northwest Corner of Mccahill Street @ 33.935332398404, - 118.125415742397		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477559	Curb Ramps	Northwest Corner of Mccahill Street @ 33.935332398404, - 118.125415742397		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477560	Curb Ramps	Northwest Corner of Mccahill Street @ 33.935332398404, - 118.125415742397	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477561	Curb Ramps	Northwest Corner of Mccahill Street @ 33.935332398404, - 118.125415742397	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477562	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.935919887057, - 118.124981224537		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477563	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.935919887057, - 118.124981224537		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477564	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.935919887057, - 118.124981224537	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477573	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.935826423224, - 118.124887347221		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477590	Curb Ramps	Southwest Corner of Mccahill Street @ 33.935246722637, - 118.125465363264		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477592	Curb Ramps	Southwest Corner of Mccahill Street @ 33.935246722637, - 118.125465363264	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Nash Avenue - Firestone Boulevard to End - Firestone Boulevard to End Downey, CA 90242	477591	Curb Ramps	Southwest Corner of Mccahill Street @ 33.935246722637, - 118.125465363264	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410799	Curb Ramps	Northeast Corner Of Old River School Drive @ 33.944995404116, - 118.150767982006		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410800	Curb Ramps	Northeast Corner Of Old River School Drive @ 33.944995404116, - 118.150767982006		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410801	Curb Ramps	Northeast Corner Of Old River School Drive @ 33.944995404116, - 118.150767982006	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410802	Curb Ramps	Northeast Corner Of Old River School Drive @ 33.944995404116, - 118.150767982006	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410803	Curb Ramps	Northeast Corner Of Old River School Drive @ 33.944995404116, - 118.150767982006	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410804	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410805	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410806	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725		Grade Break	Provide a compliant curb ramp.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410807	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410808	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Neo Street - Old River School Drive To End - Old River School Drive To End Downey, CA 90242	410809	Curb Ramps	Southwest Corner Of Old River School Drive @ 33.944838535062, - 118.150892704725	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411925	Curb Ramps	Southeast Corner Of Old School River Road @ 33.944551497320, - 118.150772005320		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411926	Curb Ramps	Southeast Corner Of Old School River Road @ 33.944551497320, - 118.150772005320		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411927	Curb Ramps	Southeast Corner Of Old School River Road @ 33.944551497320, - 118.150772005320		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411928	Curb Ramps	Southeast Corner Of Old School River Road @ 33.944551497320, - 118.150772005320	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411929	Curb Ramps	Southeast Corner Of Old School River Road @ 33.944551497320, - 118.150772005320	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411930	Curb Ramps	Northeast Corner Of Old River School Road @ 33.944672765321, - 118.150652647018		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411931	Curb Ramps	Northeast Corner Of Old River School Road @ 33.944672765321, - 118.150652647018		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411932	Curb Ramps	Northeast Corner Of Old River School Road @ 33.944672765321, - 118.150652647018		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411934	Curb Ramps	Northeast Corner Of Old River School Road @ 33.944672765321, - 118.150652647018	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Neo Street - Old River School Road To Norlain Avenue - Old River School Road To Norlain Avenue Downey, CA 90242	411933	Curb Ramps	Northeast Corner Of Old River School Road @ 33.944672765321, - 118.150652647018	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street Downey, CA 90242	471779	Curb Ramps	Southwest Corner of 5th Street @ 33.944045284991, - 118.131052404642		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471780	Curb Ramps	Southwest Corner of 5th Street @ 33.944045284991, - 118.131052404642		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471781	Curb Ramps	Southwest Corner of 5th Street @ 33.944045284991, - 118.131052404642	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471782	Curb Ramps	Northeast Corner of 5th Street @ 33.944157653262, - 118.130926340818		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471783	Curb Ramps	Northeast Corner of 5th Street @ 33.944157653262, - 118.130926340818	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471784	Curb Ramps	Northeast Corner of 5th Street @ 33.944157653262, - 118.130926340818	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471785	Curb Ramps	Northeast Corner of 5th Street @ 33.944157653262, - 118.130926340818	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471786	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471787	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471788	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471789	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471790	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471791	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471792	Curb Ramps	Southeast Corner of 6th Street @ 33.945073282263, - 118.130267858505	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471838	Curb Ramps	Northwest Corner of 2nd Street @ 33.941569807719, - 118.133356422186		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471839	Curb Ramps	Northwest Corner of 2nd Street @ 33.941569807719, - 118.133356422186		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471840	Curb Ramps	Northwest Corner of 2nd Street @ 33.941569807719, - 118.133356422186	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471841	Curb Ramps	Northwest Corner of 2nd Street @ 33.941569807719, - 118.133356422186	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471842	Curb Ramps	Northeast Corner of 4th Street @ 33.943127419793, - 118.131840974092		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471844	Curb Ramps	Northeast Corner of 4th Street @ 33.943127419793, - 118.131840974092	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471843	Curb Ramps	Northeast Corner of 4th Street @ 33.943127419793, - 118.131840974092	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471845	Curb Ramps	Northeast Corner of 2nd Street @ 33.941481913045, - 118.133229017258		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471846	Curb Ramps	Northeast Corner of 2nd Street @ 33.941481913045, - 118.133229017258		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471847	Curb Ramps	Northeast Corner of 2nd Street @ 33.941481913045, - 118.133229017258	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471848	Curb Ramps	Northeast Corner of 2nd Street @ 33.941481913045, - 118.133229017258	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471849	Curb Ramps	Northwest Corner of 5th Street @ 33.944218843843, - 118.131088614464	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471850	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471851	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471852	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471853	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471855	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471854	Curb Ramps	Northeast Corner of 3rd Street @ 33.942301888943, - 118.132535666227	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471883	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471884	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471885	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471886	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471887	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471888	Curb Ramps	Southeast Corner of 3rd Street @ 33.942182842729, - 118.132642954588	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471889	Curb Ramps	Northwest Corner of 3rd Street @ 33.942380882133, - 118.132699280977		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471890	Curb Ramps	Northwest Corner of 3rd Street @ 33.942380882133, - 118.132699280977		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471891	Curb Ramps	Northwest Corner of 3rd Street @ 33.942380882133, - 118.132699280977		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471892	Curb Ramps	Northwest Corner of 3rd Street @ 33.942380882133, - 118.132699280977	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471893	Curb Ramps	Northwest Corner of 3rd Street @ 33.942380882133, - 118.132699280977	Top Landing	Top Landing Right Side Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471894	Curb Ramps	Southwest Corner of 3rd Street @ 33.942251822798, - 118.132795840502		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471895	Curb Ramps	Southwest Corner of 3rd Street @ 33.942251822798, - 118.132795840502		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471896	Curb Ramps	Southeast Corner of 5th Street @ 33.944045284991, - 118.131052404642	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471897	Curb Ramps	Northwest Corner of 4th Street @ 33.943210862492, - 118.131989836693		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471898	Curb Ramps	Northwest Corner of 4th Street @ 33.943210862492, - 118.131989836693		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471899	Curb Ramps	Northwest Corner of 4th Street @ 33.943210862492, - 118.131989836693		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471900	Curb Ramps	Northwest Corner of 4th Street @ 33.943210862492, - 118.131989836693	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
New Street - 6th Street to 2nd Street - 6th Street to 2nd Street	471901	Curb Ramps	Northwest Corner of 4th Street @ 33.943210862492, - 118.131989836693	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Newville Avenue - Farm Street To Florence Avenue - Farm Street To Florence Avenue Downey, CA 90241	420691	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.940763175979, - 118.104234337807	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Newville Avenue - Farm Street To Florence Avenue - Farm Street To Florence Avenue Downey, CA 90241	420692	Curb Ramps	Southeast Corner Of Florence Avenue @ 33.940763175979, - 118.104234337807	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Noreon Street - Downey Avenue to La Reina Avenue - Downey Avenue to La Reina Avenue Downey, CA 90242	471212	Curb Ramps	Southwest Corner of Downey Avenue @ 33.956738623791, - 118.121852427721	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Norlain Avenue - Arnett Street To Neo Street - Arnett Street To Neo Street Downey, CA 90242	411858	Curb Ramps	Southwest Corner Of Arnett Street @ 33.945272427485, - 118.149465769529	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436434	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436435	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436436	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436437	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436438	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436439	Curb Ramps	Curb Ramp Next to Railroad Tracks @ 33.947182640388, - 118.148713409901	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436440	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436441	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436442	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436443	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436444	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436445	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436449	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436450	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436446	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436447	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436448	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.947064713518, - 118.148938715458	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436451	Curb Ramps	Southeast Corner of Northeast Median @ 33.947516394795, - 118.148598074913		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436452	Curb Ramps	Southeast Corner of Northeast Median @ 33.947516394795, - 118.148598074913	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436453	Curb Ramps	North Corner of Northeast Median @ 33.947516394795, - 118.148598074913		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436454	Curb Ramps	North Corner of Northeast Median @ 33.947516394795, - 118.148598074913		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436455	Curb Ramps	North Corner of Northeast Median @ 33.947516394795, - 118.148598074913	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436456	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436457	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436458	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436459	Curb Ramps	Southwest Corner of Firestone Boulevard @ 33.946891160469, - 118.149437606335	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Old River School Road & Firestone Boulevard - Old River School Road & Firestone Boulevard Downey, CA 90240	436573	Curb Ramps	Southwest Corner of Northeast Median @ 33.947483019414, - 118.148670494556		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway Downey, CA 90242	480408	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480409	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480410	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480413	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480411	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480412	Curb Ramps	West Side North of Amigos Avenue - 2nd @ 33.927239552303, - 118.162634074688	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480414	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480415	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480416	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480417	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480418	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480419	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480420	Curb Ramps	West Side North of Amigos Avenue - 1st @ 33.927084876093, - 118.162753432989	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480421	Curb Ramps	East Side South of Imperial Highway - 2nd @ 33.927281837837, - 118.162214308977		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480422	Curb Ramps	East Side South of Imperial Highway - 2nd @ 33.927281837837, - 118.162214308977		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480423	Curb Ramps	East Side South of Imperial Highway - 2nd @ 33.927281837837, - 118.162214308977	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480424	Curb Ramps	East Side South of Imperial Highway - 2nd @ 33.927281837837, - 118.162214308977	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480425	Curb Ramps	East Side South of Imperial Highway - 2nd @ 33.927281837837, - 118.162214308977	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480442	Curb Ramps	East Side South of Imperial Highway - 1st @ 33.927349717202, - 118.162149935961		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480443	Curb Ramps	East Side South of Imperial Highway - 1st @ 33.927349717202, - 118.162149935961		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480444	Curb Ramps	East Side South of Imperial Highway - 1st @ 33.927349717202, - 118.162149935961	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway	480445	Curb Ramps	East Side South of Imperial Highway - 1st @ 33.927349717202, - 118.162149935961	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Amigos Avenue to Imperial Highway - Amigos Avenue to Imperial Highway Downey, CA 90242	480446	Curb Ramps	East Side South of Imperial Highway - 1st @ 33.927349717202, - 118.162149935961	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480456	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480457	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480458	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480460	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480461	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480459	Curb Ramps	Northwest Corner of Emily Lane @ 33.930517731672, - 118.160953670740	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480462	Curb Ramps	West Side North of Quill Drive - 2nd @ 33.936909039666, - 118.156541436911		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480463	Curb Ramps	West Side North of Quill Drive - 2nd @ 33.936909039666, - 118.156541436911		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480465	Curb Ramps	Southeast Corner of Leeds Street @ 33.930474335009, - 118.160661309958	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480464	Curb Ramps	Southeast Corner of Leeds Street @ 33.930474335009, - 118.160661309958	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480466	Curb Ramps	West Side North of Quill Drive - 1st @ 33.936909039666, - 118.156541436911		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480467	Curb Ramps	West Side North of Quill Drive - 1st @ 33.936909039666, - 118.156541436911		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480468	Curb Ramps	East Side South of Quill Drive - 1st @ 33.931399012955, - 118.160209357738	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480469	Curb Ramps	East Side South of Quill Drive - 1st @ 33.931399012955, - 118.160209357738	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480470	Curb Ramps	West Side North of Quill Drive - 3rd @ 33.937683441337, - 118.156128376722		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480471	Curb Ramps	West Side North of Quill Drive - 3rd @ 33.937683441337, - 118.156128376722		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480472	Curb Ramps	West Side North of Quill Drive - 3rd @ 33.937683441337, - 118.156128376722		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480596	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480597	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480598	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480600	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480601	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480599	Curb Ramps	Southwest Corner of Emily Lane @ 33.930364174151, - 118.161015361547	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480602	Curb Ramps	East Side South of Quill Drive - 2nd @ 33.931399012955, - 118.160209357738		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Old River School Road - Imperial Highway to Stewart & Gray Road - Imperial Highway to Stewart & Gray Road Downey, CA 90242	480603	Curb Ramps	East Side South of Quill Drive - 2nd @ 33.931399012955, - 118.160209357738	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Old River School Road - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480760	Curb Ramps	West Side North of Adwen Street @ 33.944528133740, - 118.151091188192		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Old River School Road - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480761	Curb Ramps	West Side North of Adwen Street @ 33.944528133740, - 118.151091188192		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Old River School Road - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480762	Curb Ramps	West Side North of Adwen Street @ 33.944528133740, - 118.151091188192	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard Downey, CA 90242	320369	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.927791488145, - 118.145159482956		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320370	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.927791488145, - 118.145159482956		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320371	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.927791488145, - 118.145159482956		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320372	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.927791488145, - 118.145159482956	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320373	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.927791488145, - 118.145159482956	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320374	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.929166861092, - 118.147922158241		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320375	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.929166861092, - 118.147922158241		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320376	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.929166861092, - 118.147922158241		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320377	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.929166861092, - 118.147922158241	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320378	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.929166861092, - 118.147922158241	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320396	Curb Ramps	Southeast Corner Of Montgomery Street @ 33.928570423771, - 118.146790266037	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320397	Curb Ramps	Southeast Corner Of Montgomery Street @ 33.928570423771, - 118.146790266037	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320413	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.927862705412, - 118.145309686661		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320414	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.927862705412, - 118.145309686661		Curb Ramp Slope	Provide a compliant curb ramp.		
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320415	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.927862705412, - 118.145309686661		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320416	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.927862705412, - 118.145309686661		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320417	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.927862705412, - 118.145309686661	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320418	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758		No Detectable Warnings	Provide compliant detectable warnings to surface.		
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320419	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758		Curb Ramp Slope	Provide a compliant curb ramp.		

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320420	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320422	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320423	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	320421	Curb Ramps	Southwest Corner Of Montgomery Street @ 33.928699503844, - 118.147004842758	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	330801	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.929309293268, - 118.147825598717		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	330802	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.929309293268, - 118.147825598717		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orange Street - Caladre Avenue To Paramount Boulevard - Caladre Avenue To Paramount Boulevard	330803	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.929309293268, -118.147825598717		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349089	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349090	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349091	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349092	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349093	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Orange Street - Glynn Avenue To Brookshire Avenue - Glynn Avenue To Brookshire Avenue	349094	Curb Ramps	Northeast Corner Of Planett Avenue @ 33.924828129372, -118.140664100647	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property	345759	Curb Ramps	Northeast Corner Of Lankin Street @ 33.924539911358, -118.147891312838		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345760	Curb Ramps	Northeast Corner Of Lankin Street @ 33.924539911358, - 118.147891312838	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345769	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345770	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345771	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345772	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345773	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345774	Curb Ramps	Southeast Corner Of Lankin Street @ 33.924425291568, - 118.148001283407	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345775	Curb Ramps	Southwest Corner Of Quoit Street @ 33.925189791523, - 118.147649914026		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345776	Curb Ramps	Southwest Corner Of Quoit Street @ 33.925189791523, - 118.147649914026		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345777	Curb Ramps	Southwest Corner Of Quoit Street @ 33.925189791523, - 118.147649914026		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Orizaba Avenue - Quoit Street To Private Property - Quoit Street To Private Property Downey, CA 90242	345778	Curb Ramps	Southwest Corner Of Quoit Street @ 33.925189791523, - 118.147649914026	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Otto Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	470098	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.951018512119, - 118.121137619019		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Otto Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	470099	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.951018512119, - 118.121137619019		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Otto Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	470101	Curb Ramps	Norththwest Corner of Brookshire Avenue @ 33.951096384755, - 118.121075928211		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Otto Street - Downey Avenue to Dolan Avenue - Downey Avenue to Dolan Avenue Downey, CA 90242	468120	Curb Ramps	Northeast Corner of Downey Avenue @ 33.953043177484, - 118.124434053898	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Otto Street - La Reina Avenue to Downey Avenue - La Reina Avenue to Downey Avenue Downey, CA 90242	467273	Curb Ramps	Southwest Corner of Downey Avenue @ 33.953035390401, - 118.124767988920	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Otto Street - La Reina Avenue to Downey Avenue - La Reina Avenue to Downey Avenue	467274	Curb Ramps	Southwest Corner of Downey Avenue @ 33.953035390401, - 118.124767988920	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Otto Street - La Reina Avenue to Downey Avenue - La Reina Avenue to Downey Avenue	467386	Curb Ramps	Northwest Corner of Downey Avenue @ 33.953157758754, - 118.124658018351		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Otto Street - La Reina Avenue to Downey Avenue - La Reina Avenue to Downey Avenue	467387	Curb Ramps	Northwest Corner of Downey Avenue @ 33.953157758754, - 118.124658018351		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Otto Street - La Reina Avenue to Downey Avenue - La Reina Avenue to Downey Avenue	467277	Curb Ramps	Northwest Corner of Downey Avenue @ 33.953157758754, - 118.124658018351	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street	418488	Curb Ramps	Southeast Corner Of Ardine Street @ 33.932115603641, - 118.112712800503		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street	418489	Curb Ramps	Southeast Corner Of Ardine Street @ 33.932115603641, - 118.112712800503	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street	418490	Curb Ramps	Southeast Corner Of Ardine Street @ 33.932115603641, - 118.112712800503	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street	418491	Curb Ramps	Southeast Corner Of Ardine Street @ 33.932115603641, - 118.112712800503	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418492	Curb Ramps	Southeast Corner Of Ardine Street @ 33.932115603641, - 118.112712800503	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418557	Curb Ramps	Southwest Corner Of Buell Street @ 33.935108751090, - 118.110789656639		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418558	Curb Ramps	Southwest Corner Of Buell Street @ 33.935108751090, - 118.110789656639	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418559	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.934134042506, - 118.111272454262	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418560	Curb Ramps	Northwest Corner Of Buell Street @ 33.935240046599, - 118.110698461533	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418562	Curb Ramps	Northwest Corner Of Cecilia Street @ 33.934211930588, - 118.111436069012	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Pangborn Avenue - Firestone Boulevard To Gotham Street - Firestone Boulevard To Gotham Street Downey, CA 90241	418563	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.934027224448, - 118.111352920532	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pangborn Avenue - Washburn Road To Seaaca Street - Washburn Road To Seaaca Street Downey, CA 90424	316990	Curb Ramps	Northeast Corner Of Washburn Road @ 33.922007111894, - 118.113337755203		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pangborn Avenue - Washburn Road To Seaaca Street - Washburn Road To Seaaca Street Downey, CA 90424	316991	Curb Ramps	Northeast Corner Of Washburn Road @ 33.922007111894, - 118.113337755203		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pangborn Avenue - Washburn Road To Seaaca Street - Washburn Road To Seaaca Street Downey, CA 90424	316992	Curb Ramps	Northeast Corner Of Washburn Road @ 33.922007111894, - 118.113337755203	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332397	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332398	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332399	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332402	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332400	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & 3rd Street - Paramount Boulevard & 3rd Street Downey, CA 90241	332401	Curb Ramps	Northwest Corner @ 33.944454705305, - 118.136900961399	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332403	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332404	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332405	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332406	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332407	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332408	Curb Ramps	Northeast Corner @ 33.944454705305, - 118.136536180973	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332409	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street	332410	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & 3rd Street - Paramount								
Paramount Boulevard & 3rd Street - Paramount	332411	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332414	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332415	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332412	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332413	Curb Ramps	Southwest Corner @ 33.944383501914, - 118.136951923370	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332417	Curb Ramps	Southeast Corner @ 33.944290047372, - 118.136630058289	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard & 3rd Street - Paramount	332416	Curb Ramps	Southeast Corner @ 33.944290047372, - 118.136630058289	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & Alameda Street - Paramount	332035	Curb Ramps	Southwest Corner @ 33.930383090672, - 118.147369623184		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332036	Curb Ramps	Southwest Corner @ 33.930383090672, -118.147369623184		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332037	Curb Ramps	Southwest Corner @ 33.930383090672, -118.147369623184	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332038	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332039	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332040	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332041	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street Downey, CA 90241	332042	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date	
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street	Downey, CA 90241	332043	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street	Downey, CA 90241	332044	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street	Downey, CA 90241	332045	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street	Downey, CA 90241	332046	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Alameda Street - Paramount Boulevard & Alameda Street	Downey, CA 90241	332047	Curb Ramps	Southeast Corner @ 33.930243998508, -118.147161178	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road	Downey, CA 90241	332215	Curb Ramps	Southeast Corner @ 33.937801381204, -118.141413778067		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road	Downey, CA 90241	332216	Curb Ramps	Southeast Corner @ 33.937801381204, -118.141413778067		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332217	Curb Ramps	Southeast Corner @ 33.937801381204, - 118.141413778067		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332220	Curb Ramps	Southeast Corner @ 33.937801381204, - 118.141413778067	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332218	Curb Ramps	Southeast Corner @ 33.937801381204, - 118.141413778067	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332219	Curb Ramps	Southeast Corner @ 33.937801381204, - 118.141413778067	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332221	Curb Ramps	Northwest Corner @ 33.938117370229, - 118.141541182995		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Paramount Boulevard & Brookmill Road - Paramount Boulevard & Brookmill Road Downey, CA 90241	332222	Curb Ramps	Northwest Corner @ 33.938117370229, - 118.141541182995	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Firestone Boulevard - Paramount Boulevard & Firestone Boulevard Downey, CA 90241	332292	Curb Ramps	Southwest Corner @ 33.942696854162, - 118.138203173876	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Firestone Boulevard - Paramount Boulevard & Firestone Boulevard	Downey, CA 90241	332395	Curb Ramps	Southeast Corner #1 @ 33.942513279007, - 118.137925565243	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard & Firestone Boulevard - Paramount Boulevard & Firestone Boulevard	Downey, CA 90241	332396	Curb Ramps	Northeast Corner @ 33.942740244596, - 118.137748539448	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32
Paramount Boulevard & Gardendale Street - Paramount Boulevard & Gardendale Street	Downey, CA 90242	351518	Curb Ramps	Northeast Corner @ 33.917424289504, - 118.156819045544	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway	Downey, CA 90241	331827	Curb Ramps	Northeast Corner @ 33.924109251736, - 118.151768445969		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway	Downey, CA 90241	331828	Curb Ramps	Northeast Corner @ 33.924109251736, - 118.151768445969		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway	Downey, CA 90241	331830	Curb Ramps	Northeast Corner @ 33.924109251736, - 118.151768445969	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway	Downey, CA 90241	331829	Curb Ramps	Northeast Corner @ 33.924109251736, - 118.151768445969	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331831	Curb Ramps	Southeast Corner @ 33.923883349307, - 118.151928037405		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331832	Curb Ramps	Southeast Corner @ 33.923883349307, - 118.151928037405		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331834	Curb Ramps	Southeast Corner @ 33.923883349307, - 118.151928037405	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331833	Curb Ramps	Southeast Corner @ 33.923883349307, - 118.151928037405	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331935	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331936	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331937	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331939	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331940	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331941	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331938	Curb Ramps	Northwest Corner @ 33.924252805185, - 118.152040690184	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331942	Curb Ramps	Southwest Corner @ 33.924013549302, - 118.152225762606		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331943	Curb Ramps	Southwest Corner @ 33.924013549302, - 118.152225762606		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331944	Curb Ramps	Southwest Corner @ 33.924013549302, - 118.152225762606		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331945	Curb Ramps	Southwest Corner @ 33.924013549302, - 118.152225762606	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Paramount Boulevard & Imperial Highway - Paramount Boulevard & Imperial Highway Downey, CA 90241	331946	Curb Ramps	Southwest Corner @ 33.924013549302, - 118.152225762606	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331947	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331948	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331949	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331950	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331951	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331952	Curb Ramps	Northeast Corner @ 33.926874560508, - 118.149662911892	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331953	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331954	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331955	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331956	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331957	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331958	Curb Ramps	Southeast Corner @ 33.926732124261, - 118.149770200253	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331959	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331960	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331961	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331962	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331963	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331964	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard & Quill Drive_Quoit Street - Paramount								
Paramount Boulevard & Quill Drive_Quoit Street Downey, CA 90241	331965	Curb Ramps	Northwest Corner @ 33.927018109297, - 118.149971365929	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331966	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331967	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331968	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331971	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331969	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Quill Drive_Quoit Street - Paramount	331970	Curb Ramps	Southwest Corner @ 33.926876786072, - 118.150069266558	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount	332199	Curb Ramps	Southeast Corner @ 33.934601369932, - 118.143771439791		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332200	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332201	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332202	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332203	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332204	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332205	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332206	Curb Ramps	Northeast Corner @ 33.934816117151, - 118.143610507250	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332207	Curb Ramps	Southwest Corner @ 33.934799426972, - 118.144018203020		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332208	Curb Ramps	Southwest Corner @ 33.934799426972, - 118.144018203020		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332209	Curb Ramps	Southwest Corner @ 33.934799426972, - 118.144018203020	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332210	Curb Ramps	Northwest Corner @ 33.934995258199, - 118.143849223852		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332211	Curb Ramps	Northwest Corner @ 33.934995258199, - 118.143849223852		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332212	Curb Ramps	Northwest Corner @ 33.934995258199, - 118.143849223852		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332214	Curb Ramps	Northwest Corner @ 33.934995258199, - 118.143849223852	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard & Stewart & Gray Road - Paramount Boulevard & Stewart & Gray Road Downey, CA 90241	332213	Curb Ramps	Northwest Corner @ 33.934995258199, - 118.143849223852	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351921	Curb Ramps	East Side South Of Florence Avenue - 2nd @ 33.953056526766, - 118.130230307579		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351922	Curb Ramps	East Side South Of Florence Avenue - 2nd @ 33.953056526766, - 118.130230307579		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351923	Curb Ramps	East Side South Of Florence Avenue - 1st @ 33.953141072170, - 118.130172640085		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351924	Curb Ramps	East Side South Of Florence Avenue - 1st @ 33.953141072170, - 118.130172640085	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352773	Curb Ramps	Southeast Corner Of 5th Street @ 33.946181369315, - 118.135247379541		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352774	Curb Ramps	Southeast Corner Of 5th Street @ 33.946181369315, - 118.135247379541		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352777	Curb Ramps	Southeast Corner Of 5th Street @ 33.946181369315, - 118.135247379541	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352775	Curb Ramps	Southeast Corner Of 5th Street @ 33.946181369315, - 118.135247379541	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352776	Curb Ramps	Southeast Corner Of 5th Street @ 33.946181369315, - 118.135247379541	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352887	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352888	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352889	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352892	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352893	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352890	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352891	Curb Ramps	Northeast Corner Of 4th Street @ 33.945749706596, - 118.135557174683	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	352894	Curb Ramps	Southeast Corner Of 3rd Street @ 33.944311185908, - 118.136616647244	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353094	Curb Ramps	Northeast Corner Of 7th Street @ 33.948466475175, - 118.133548200130		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353095	Curb Ramps	Northeast Corner Of 7th Street @ 33.948466475175, - 118.133548200130		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353096	Curb Ramps	Northeast Corner Of 7th Street @ 33.948466475175, - 118.133548200130		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353097	Curb Ramps	Northeast Corner Of 7th Street @ 33.948466475175, - 118.133548200130		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353098	Curb Ramps	Northeast Corner Of 7th Street @ 33.948466475175, - 118.133548200130	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353099	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353100	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353101	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353102	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353103	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353104	Curb Ramps	Northeast Corner Of 2nd Street @ 33.943593585294, - 118.137135654688	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353105	Curb Ramps	Northeast Corner Of 5th Street @ 33.946328223142, - 118.135136067867		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353106	Curb Ramps	Northeast Corner Of 5th Street @ 33.946328223142, - 118.135136067867		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353108	Curb Ramps	Northeast Corner Of 5th Street @ 33.946328223142, - 118.135136067867	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353107	Curb Ramps	Northeast Corner Of 5th Street @ 33.946328223142, - 118.135136067867	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	359800	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	359801	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	359802	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	359803	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	359804	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353195	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353192	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353193	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353194	Curb Ramps	Northeast Corner Of 3rd Street @ 33.944430229146, - 118.136533498764	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353196	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353197	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353198	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353201	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	Top Landing	Top Landing Clear Length - Landings Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353199	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	Bottom Landing	Bottom Landing Slope Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353200	Curb Ramps	Southeast Corner Of 7th Street @ 33.948353091, -118.133628666401	Bottom Landing	Bottom Landing Change in Level Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353202	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353203	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353204	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353207	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353205	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353206	Curb Ramps	Southeast Corner Of 4th Street @ 33.945569475638, - 118.135657757521	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353314	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353315	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353316	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353319	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353320	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353317	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard	Downey, CA 90241	353318	Curb Ramps	Southeast Corner Of 2nd Street @ 33.943464527797, - 118.137232214212	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361593	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361594	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361595	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905	Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361598	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905	Top Landing	Top Landing Clear Length - Landings Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361596	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905	Bottom Landing	Bottom Landing Slope Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361597	Curb Ramps	Northwest Corner Of Consuelo Street @ 33.918750862762, - 118.156271874905	Bottom Landing	Bottom Landing Change in Level Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361599	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361600	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	Downey, CA 90242	361601	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361604	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361602	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361603	Curb Ramps	Northwest Corner Of Puritan Street @ 33.919196016945, - 118.155857473612	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361605	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361606	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361607	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361609	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361610	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361608	Curb Ramps	Southwest Corner Of Puritan Street @ 33.919100308992, - 118.155984878540	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361611	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361612	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361613	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361616	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361617	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361614	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361615	Curb Ramps	Southwest Corner Of Consuelo Street @ 33.918610638713, - 118.156320154667	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361939	Curb Ramps	East Side South Of Imperial Highway @ 33.923274274, - 118.152461796999		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361940	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.923254602939, - 118.152783662081		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361942	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.923254602939, - 118.152783662081	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361943	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.923254602939, - 118.152783662081	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361941	Curb Ramps	Northwest Corner Of Lyndora Street @ 33.923254602939, - 118.152783662081	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361944	Curb Ramps	Southwest Corner Of Lyndora Street @ 33.923141094250, - 118.152873516083		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361945	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361946	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361949	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361950	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361947	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361948	Curb Ramps	Northeast Corner Of Borson Street @ 33.922036045881, - 118.153719753027	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361951	Curb Ramps	Southeast Corner Of Lyndora Street @ 33.922871788718, - 118.152692466974		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361952	Curb Ramps	Southeast Corner Of Lyndora Street @ 33.922871788718, - 118.152692466974		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361954	Curb Ramps	Southeast Corner Of Lyndora Street @ 33.922871788718, - 118.152692466974	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361955	Curb Ramps	Southeast Corner Of Lyndora Street @ 33.922871788718, - 118.152692466974	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361953	Curb Ramps	Southeast Corner Of Lyndora Street @ 33.922871788718, - 118.152692466974	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361956	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361957	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361960	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361961	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361958	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361959	Curb Ramps	Southwest Corner Of Borson Street @ 33.921871344594, - 118.153847157955	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361962	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361963	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway Downey, CA 90242	361964	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361965	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361969	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361970	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361966	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361967	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Paramount Boulevard - Gardendale Street To Imperial Highway - Gardendale Street To Imperial Highway	361968	Curb Ramps	Northeast Corner Of Lyndora Street @ 33.922997538928, - 118.152595907450	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard	482094	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.942338604097, - 118.138067722321		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482095	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.942338604097, -	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482096	Curb Ramps	East Side South of Firestone Boulevard - 2nd @ 33.942338604097, -	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482221	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.942338604097, -		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482222	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.942338604097, -		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482223	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.942338604097, -	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard	482224	Curb Ramps	East Side South of Firestone Boulevard - 1st @ 33.942338604097, -	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321356	Curb Ramps	Southeast Corner Of Conrad Street @ 33.927925020472, - 118.148882389069		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321357	Curb Ramps	Southeast Corner Of Conrad Street @ 33.927925020472, - 118.148882389069		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321358	Curb Ramps	Southeast Corner Of Conrad Street @ 33.927925020472, - 118.148882389069		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330805	Curb Ramps	Southwest Corner Of Springer Street @ 33.928263301432, - 118.148989677429		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330806	Curb Ramps	Southwest Corner Of Springer Street @ 33.928263301432, - 118.148989677429		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330807	Curb Ramps	Southwest Corner Of Springer Street @ 33.928263301432, - 118.148989677429		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321363	Curb Ramps	Southwest Corner Of Springer Street @ 33.928263301432, - 118.148989677429	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321364	Curb Ramps	Northwest Corner Of Springer Street @ 33.928423539312, - 118.148925304413		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321365	Curb Ramps	Northwest Corner Of Springer Street @ 33.928423539312, - 118.148925304413		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321366	Curb Ramps	Northwest Corner Of Springer Street @ 33.928423539312, - 118.148925304413		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321368	Curb Ramps	Northwest Corner Of Springer Street @ 33.928423539312, - 118.148925304413	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321367	Curb Ramps	Northwest Corner Of Springer Street @ 33.928423539312, - 118.148925304413	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321369	Curb Ramps	Southwest Corner Of Melva Street @ 33.929794451077, - 118.147766590118		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321370	Curb Ramps	Southwest Corner Of Melva Street @ 33.929794451077, - 118.147766590118		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321371	Curb Ramps	Southwest Corner Of Melva Street @ 33.929794451077, - 118.147766590118		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321372	Curb Ramps	Southwest Corner Of Melva Street @ 33.929794451077, - 118.147766590118	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321373	Curb Ramps	Northwest Corner Of Melva Street @ 33.929981391881, - 118.147712945938		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321374	Curb Ramps	Northwest Corner Of Melva Street @ 33.929981391881, - 118.147712945938		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330808	Curb Ramps	Southeast Corner Of Leeds Street @ 33.924960553538, - 118.151146173477		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330809	Curb Ramps	Southeast Corner Of Leeds Street @ 33.924960553538, - 118.151146173477		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330810	Curb Ramps	Southeast Corner Of Leeds Street @ 33.924960553538, - 118.151146173477		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321379	Curb Ramps	Southeast Corner Of Leeds Street @ 33.924960553538, - 118.151146173477	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321380	Curb Ramps	Northeast Corner Of Albia Street @ 33.931169791681, - 118.14636112595	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330812	Curb Ramps	Northeast Corner Of Leeds Street @ 33.925058480520, - 118.150974512100		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330813	Curb Ramps	Northeast Corner Of Leeds Street @ 33.925058480520, - 118.150974512100		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330814	Curb Ramps	Northeast Corner Of Leeds Street @ 33.925058480520, - 118.150974512100		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321445	Curb Ramps	Northeast Corner Of Leeds Street @ 33.925058480520, - 118.150974512100	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321446	Curb Ramps	Southwest Corner Of Albia Street @ 33.931254358825, - 118.146725893021		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321447	Curb Ramps	Southwest Corner Of Albia Street @ 33.931254358825, - 118.146725893021		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321448	Curb Ramps	Southwest Corner Of Albia Street @ 33.931254358825, - 118.146725893021		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321474	Curb Ramps	Northeast Corner Of Conrad Street @ 33.928067454724, - 118.148753643036		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321475	Curb Ramps	Northeast Corner Of Conrad Street @ 33.928067454724, - 118.148753643036	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330815	Curb Ramps	Northwest Corner Of Albia Street @ 33.931405689294, - 118.146618604660		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330816	Curb Ramps	Northwest Corner Of Albia Street @ 33.931405689294, - 118.146618604660		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330817	Curb Ramps	Northwest Corner Of Albia Street @ 33.931405689294, - 118.146618604660		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330818	Curb Ramps	Northwest Corner Of Albia Street @ 33.931405689294, - 118.146618604660		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395670	Curb Ramps	Southwest Corner Of Boyne Street @ 33.926944665760, - 118.135520964861		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395671	Curb Ramps	Southwest Corner Of Boyne Street @ 33.926944665760, - 118.135520964861		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395672	Curb Ramps	Southwest Corner Of Boyne Street @ 33.926944665760, - 118.135520964861	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395673	Curb Ramps	Southwest Corner Of Boyne Street @ 33.926944665760, - 118.135520964861	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395674	Curb Ramps	Southwest Corner Of Boyne Street @ 33.926944665760, - 118.135520964861	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395675	Curb Ramps	Northwest Corner Of Albia Street @ 33.926164602475, - 118.136090934277	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395687	Curb Ramps	Southeast Corner Of Cavel Street @ 33.927281837837, - 118.135085105896	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395688	Curb Ramps	Northeast Corner Of Nada Street @ 33.929224724192, - 118.133625984192		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395689	Curb Ramps	Northeast Corner Of Nada Street @ 33.929224724192, - 118.133625984192		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395691	Curb Ramps	Northeast Corner Of Nada Street @ 33.929224724192, - 118.133625984192	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395692	Curb Ramps	Northeast Corner Of Nada Street @ 33.929224724192, - 118.133625984192	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395690	Curb Ramps	Northeast Corner Of Nada Street @ 33.929224724192, - 118.133625984192	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395693	Curb Ramps	Northwest Corner Of Cole Street @ 33.928874206735, - 118.134087324142	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395694	Curb Ramps	Southwest Corner Of Cole Street @ 33.928754028988, - 118.134161084890		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395695	Curb Ramps	Southwest Corner Of Cole Street @ 33.928754028988, - 118.134161084890	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395696	Curb Ramps	Southwest Corner Of Albia Street @ 33.926035518560, - 118.136192858219	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395697	Curb Ramps	Southeast Corner Of Nada Street @ 33.929094532162, - 118.133723884821	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Alameda Street To Stewart & Gray Road - Alameda Street To Stewart & Gray Road Downey, CA 90242	395717	Curb Ramps	Northeast Corner Of Cavel Street @ 33.927389777130, - 118.134999275208	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	397031	Curb Ramps	West Side North Of Mantee Street - 2nd @ 33.936017801438, - 118.128745704889		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	397032	Curb Ramps	West Side North Of Mantee Street - 2nd @ 33.936017801438, - 118.128745704889	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	398958	Curb Ramps	West Side North Of Mantee Street - 1st @ 33.934840596074, - 118.129610717297		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	398959	Curb Ramps	West Side North Of Mantee Street - 1st @ 33.934840596074, - 118.129610717297		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	397035	Curb Ramps	West Side North Of Mantee Street - 1st @ 33.934840596074, - 118.129610717297	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	397036	Curb Ramps	West Side North Of Mantee Street - 1st @ 33.934840596074, - 118.129610717297	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	399029	Curb Ramps	Southeast Corner Of Firestone Boulevard @ 33.937271763164, - 118.127831071615	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	399030	Curb Ramps	East Side South Of Firestone Boulevard - 1st @ 33.935816409236, - 118.128690719604		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	399031	Curb Ramps	East Side South Of Firestone Boulevard - 1st @ 33.935816409236, - 118.128690719604	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	399032	Curb Ramps	East Side South Of Firestone Boulevard - 1st @ 33.935816409236, - 118.128690719604	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard	399033	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399034	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399035	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399036	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399037	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399038	Curb Ramps	East Side South Of Firestone Boulevard - 3rd @ 33.934790525542, - 118.129451125860	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399039	Curb Ramps	East Side South Of Firestone Boulevard - 2nd @ 33.935746311286, - 118.128741681576		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399040	Curb Ramps	East Side South Of Firestone Boulevard - 2nd @ 33.935746311286, - 118.128741681576		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Patton Road - Cleta Street To Firestone Boulevard - Cleta Street To Firestone Boulevard Downey, CA 90242	399041	Curb Ramps	East Side South Of Firestone Boulevard - 2nd @ 33.935746311286, - 118.128741681576	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396961	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396962	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992	Curb Ramp Slope		Provide a compliant curb ramp.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396963	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396964	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396965	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396966	Curb Ramps	Southeast Corner Of Fontana Steet @ 33.930485462361, - 118.132673799992	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396967	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242	396968	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879	Side Flare Slope		Provide curb ramp side flares with a compliant slope.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396971	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396972	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396969	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396970	Curb Ramps	Northwest Corner Of Fontana Street @ 33.930386428882, - 118.132967501879	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396973	Curb Ramps	East Side South Of Fontana Steet - 1st @ 33.930249562199, - 118.132869601250		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396974	Curb Ramps	East Side South Of Fontana Steet - 1st @ 33.930249562199, - 118.132869601250		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396975	Curb Ramps	East Side South Of Fontana Steet - 1st @ 33.930249562199, - 118.132869601250		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396976	Curb Ramps	East Side South Of Fontana Steet - 1st @ 33.930249562199, - 118.132869601250	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396977	Curb Ramps	East Side South Of Fontana Steet - 1st @ 33.930249562199, - 118.132869601250	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396978	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396979	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396980	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396981	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396982	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396983	Curb Ramps	Southwest Corner Of Fontana Street @ 33.930274042434, - 118.133078813553	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396984	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396985	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396986	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396987	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396989	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396990	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 396988	Curb Ramps	East Side South Of Fontana Steet - 2nd @ 33.930177234188, - 118.132921904325	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 397027	Curb Ramps	Northeast Corner Of Fontana Steet @ 33.930608975864, - 118.132578581572		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Patton Road - Stewart & Gray Road To Cleta Street - Stewart & Gray Road To Cleta Street	Downey, CA 90242 397028	Curb Ramps	Northeast Corner Of Fontana Steet @ 33.930608975864, - 118.132578581572		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Patton Road - Stewart & Gray Road To Clela Street - Stewart & Gray Road To Clela Street	Downey, CA 90242	397029	Curb Ramps	Northeast Corner Of Fontana Steet @ 33.930608975864, - 118.132578581572		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Patton Road - Stewart & Gray Road To Clela Street - Stewart & Gray Road To Clela Street	Downey, CA 90242	397030	Curb Ramps	Northeast Corner Of Fontana Steet @ 33.930608975864, - 118.132578581572	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418422	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418423	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418424	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418425	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418426	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418427	Curb Ramps	Southwest Corner Of Pangborn Avenue @ 33.931557019494, - 118.113235831261	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End	Downey, CA 90241	418428	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End Downey, CA 90241	418429	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End Downey, CA 90241	418430	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End Downey, CA 90241	418432	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End Downey, CA 90241	418433	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pellet Street - Pangborn Avenue To End - Pangborn Avenue To End Downey, CA 90241	418431	Curb Ramps	Northwest Corner Of Pangborn Avenue @ 33.931679418724, - 118.113171458244	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Pellet Street - Rio Hondo Drive To Old River School Road - Rio Hondo Drive To Old River School Road Downey, CA 90421	358500	Curb Ramps	Northwest Corner Of Old River School Road @ 33.949349795663, - 118.147632479668		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Pellet Street - Rio Hondo Drive To Old River School Road - Rio Hondo Drive To Old River School Road Downey, CA 90421	358501	Curb Ramps	Northwest Corner Of Old River School Road @ 33.949349795663, - 118.147632479668		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Pellet Street - Rio Hondo Drive To Old River School Road - Rio Hondo Drive To Old River School Road Downey, CA 90421	358502	Curb Ramps	Southwest Corner Of Old River School Road @ 33.949251896615, - 118.147734403610		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pellet Street - Rio Hondo Drive To Old River School Road - Rio Hondo Drive To Old River School Road	358503	Curb Ramps	Southwest Corner Of Old River School Road @ 33.949251896615, - 118.147734403610	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Pellet Street - Rio Hondo Drive To Old River School Road - Rio Hondo Drive To Old River School Road	358504	Curb Ramps	Southwest Corner Of Old River School Road @ 33.949251896615, - 118.147734403610	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	418985	Curb Ramps	Northwest Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	418986	Curb Ramps	Northwest Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	418988	Curb Ramps	Northwest Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	418987	Curb Ramps	Northwest Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	419003	Curb Ramps	Southeast Corner Of Stewart & Grey Road @ 33.942981673014, - 118.159675598145		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street	419004	Curb Ramps	Southeast Corner Of Stewart & Grey Road @ 33.942981673014, - 118.159675598145		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419005	Curb Ramps	Southeast Corner Of Stewart & Grey Road @ 33.942981673014, - 118.159675598145		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419007	Curb Ramps	Southeast Corner Of Stewart & Grey Road @ 33.942981673014, - 118.159675598145	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419006	Curb Ramps	Southeast Corner Of Stewart & Grey Road @ 33.942981673014, - 118.159675598145	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419008	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419009	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419010	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419011	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419012	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419013	Curb Ramps	Southwest Corner Of Stewart & Grey Road @ 33.943074016422, - 118.159825801849	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419027	Curb Ramps	Northeast Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419028	Curb Ramps	Northeast Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419029	Curb Ramps	Northeast Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419030	Curb Ramps	Northeast Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pernell Avenue - Cole Street To De Palma Street - Cole Street To De Palma Street Downey, CA 90242	419031	Curb Ramps	Northeast Corner Of Stewart & Grey Road @ 33.943239789276, - 118.159648776054	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434044	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434045	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434046	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434047	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434048	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434049	Curb Ramps	Southeast Corner of Paramount Boulevard @ 33.940362638759, - 118.139517456293	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434050	Curb Ramps	North Side East of Paramount Boulevard @ 33.940318134507, - 118.139046728611		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434051	Curb Ramps	North Side East of Paramount Boulevard @ 33.940318134507, - 118.139046728611		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434052	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434053	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434054	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434055	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434056	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434057	Curb Ramps	Southwest Corner of Downey Avenue @ 33.938288715901, - 118.134480267763	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434058	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434059	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434060	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434061	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue	434062	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434063	Curb Ramps	Northeast Corner of Paramount Boulevard @ 33.940513953041, - 118.139390051365	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434064	Curb Ramps	Northwest Corner of Downey Avenue @ 33.938431132820, - 118.134372979403		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434065	Curb Ramps	Northwest Corner of Downey Avenue @ 33.938431132820, - 118.134372979403		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434067	Curb Ramps	Northwest Corner of Downey Avenue @ 33.938431132820, - 118.134372979403	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Phlox Street - Paramount Boulevard to Downey Avenue - Paramount Boulevard to Downey Avenue Downey, CA 90242	434066	Curb Ramps	Northwest Corner of Downey Avenue @ 33.938431132820, - 118.134372979403	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482235	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482236	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482237	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482238	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482239	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482240	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482241	Curb Ramps	Southwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue Downey, CA 90242	482242	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue	482243	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue	482244	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue	482245	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue	482247	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Phlox Street - Paramount Boulevard to Pruess Avenue - Paramount Boulevard to Pruess Avenue	482246	Curb Ramps	Northwest Corner of Paramount Boulevard @ 33.940894462769, - 118.139490634203	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Phlox Street - Rives Avenue To Horton Avenue - Rives Avenue To Horton Avenue	412893	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.943039526727, - 118.143673539162	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pico Vista Road - Cul-De-Sac to Cul-De-Sac - Cul-De-Sac to Cul-De-Sac	451785	Curb Ramps	Southwest Corner of Brookpark Road @ 33.947330605004, - 118.098399192095		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452752	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452753	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452754	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452755	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452658	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452659	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452655	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452656	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452657	Curb Ramps	Southwest Corner of Telegraph Road @ 33.951200956468, - 118.095812201500	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452671	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452672	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452673	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452674	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452675	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452678	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452679	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452676	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452677	Curb Ramps	North Side East of Telegraph Road @ 33.950816042934, - 118.095839023590	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452758	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452759	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452760	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452685	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452686	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac - Downey, CA 90242	452683	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pico Vista Road - Telegraph Road to Cul-De-Sac - Telegraph Road to Cul-De-Sac	452684	Curb Ramps	Southeast Corner of Telegraph Road @ 33.951135321046, - 118.095649927855	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Downey, CA 90242	412900	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.943524606311, - 118.143307417631	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Downey, CA 90242	463218	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.947406255986, - 118.146582394838		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Downey, CA 90242	463219	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.947475231823, - 118.146815747023		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Downey, CA 90421	362577	Curb Ramps	Southeast Corner Of Laura Street @ 33.936871209518, - 118.154091238976		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Downey, CA 90421	362578	Curb Ramps	Southeast Corner Of Laura Street @ 33.936871209518, - 118.154091238976		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Downey, CA 90421	362579	Curb Ramps	Southeast Corner Of Laura Street @ 33.936871209518, - 118.154091238976		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Downey, CA 90421	362580	Curb Ramps	Southeast Corner Of Laura Street @ 33.936871209518, - 118.154091238976	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Downey, CA 90421	362581	Curb Ramps	Southeast Corner Of Laura Street @ 33.936871209518, - 118.154091238976	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362582	Curb Ramps	Northeast Corner Of Laura Street @ 33.937022536, -118.154123425484		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362583	Curb Ramps	Southwest Corner Of Laura Street @ 33.936915715572, -118.154225349426		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362584	Curb Ramps	Southwest Corner Of Laura Street @ 33.936915715572, -118.154225349426		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362585	Curb Ramps	Southwest Corner Of Laura Street @ 33.936915715572, -118.154225349426		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362586	Curb Ramps	Southwest Corner Of Laura Street @ 33.936915715572, -118.154225349426	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362587	Curb Ramps	Southwest Corner Of Laura Street @ 33.936915715572, -118.154225349426	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362588	Curb Ramps	Northwest Corner Of Laura Street @ 33.937093739554, -118.154236078262		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362590	Curb Ramps	Northwest Corner Of Laura Street @ 33.937093739554, -118.154236078262	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362589	Curb Ramps	Northwest Corner Of Laura Street @ 33.937093739554, -118.154236078262	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362603	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939519279228, -118.152326345444		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362604	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939519279228, -118.152326345444		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362605	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939519279228, -118.152326345444	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362606	Curb Ramps	Northeast Corner Of Stewart and Gray Road @ 33.939519279228, -118.152326345444	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362607	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939581585759, -118.152498006821		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362608	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939581585759, -118.152498006821		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362609	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939581585759, -118.152498006821		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362610	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939581585759, -118.152498006821	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362611	Curb Ramps	Northwest Corner Of Stewart and Gray Road @ 33.939581585759, -118.152498006821	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362612	Curb Ramps	Northwest Corner Of Nada Street @ 33.938353248597, -118.153356313705		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362613	Curb Ramps	Northwest Corner Of Nada Street @ 33.938353248597, -118.153356313705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362614	Curb Ramps	Northwest Corner Of Nada Street @ 33.938353248597, - 118.153356313705	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362615	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.939332359362, - 118.152428269386		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362616	Curb Ramps	Southeast Corner Of Stewart and Gray Road @ 33.939332359362, - 118.152428269386		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362634	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.939287854571, - 118.152680397034		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362635	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.939287854571, - 118.152680397034		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362636	Curb Ramps	Southwest Corner Of Stewart and Gray Road @ 33.939287854571, - 118.152680397034	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362637	Curb Ramps	Southwest Corner Of Nada Street @ 33.938219732620, - 118.153415322304		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362638	Curb Ramps	Southwest Corner Of Nada Street @ 33.938219732620, - 118.153415322304		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362639	Curb Ramps	Southwest Corner Of Nada Street @ 33.938219732620, - 118.153415322304	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Cul-de-sac To Cul-de-sac - Cul-de-sac To Cul-de-sac	Downey, CA 90421 362640	Curb Ramps	Southwest Corner Of Nada Street @ 33.938219732620, - 118.153415322304	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356742	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.958111304384, - 118.138770461082		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356743	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.958111304384, - 118.138770461082		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356746	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.958111304384, - 118.138770461082	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356744	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.958111304384, - 118.138770461082	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356745	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.958111304384, - 118.138770461082	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356765	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.958013415415, - 118.138571977615		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356766	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.958013415415, - 118.138571977615		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356767	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.958013415415, - 118.138571977615		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356768	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.958013415415, - 118.138571977615	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Pomering Road - Florence Avenue to Lubec Street - Florence Avenue to Lubec Street	356769	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.958013415415, - 118.138571977615	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pomering Road - Irvingrove Drive To Quinn Street - Irvingrove Drive To Quinn Street	349047	Curb Ramps	Southeast Corner Of Irvingrove Drive - 2nd		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Pomering Road - Irvingrove Drive To Quinn Street - Irvingrove Drive To Quinn Street	349048	Curb Ramps	Southeast Corner Of Irvingrove Drive - 1st		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Pomering Road - Irvingrove Drive To Quinn Street - Irvingrove Drive To Quinn Street	347535	Curb Ramps	Southeast Corner Of Irvingrove Drive - 1st @ 33.956407130344, - 118.139891624451	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Pomering Road - Irvingrove Drive To Quinn Street - Irvingrove Drive To Quinn Street	347536	Curb Ramps	Southeast Corner Of Irvingrove Drive - 1st @ 33.956407130344, - 118.139891624451	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313344	Curb Ramps	Southwest Corner Of Angell Street @ 33.912393807298, - 118.130692988634		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313345	Curb Ramps	Southwest Corner Of Angell Street @ 33.912393807298, - 118.130692988634		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313346	Curb Ramps	Southwest Corner Of Angell Street @ 33.912393807298, - 118.130692988634		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313347	Curb Ramps	Southwest Corner Of Angell Street @ 33.912393807298, - 118.130692988634	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313348	Curb Ramps	Southwest Corner Of Angell Street @ 33.912393807298, - 118.130692988634	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313350	Curb Ramps	Northeast Corner Of Foster Road @ 33.909965269125, - 118.130517303944		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313351	Curb Ramps	Northeast Corner Of Foster Road @ 33.909965269125, - 118.130517303944		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313353	Curb Ramps	Northeast Corner Of Foster Road @ 33.909965269125, - 118.130517303944	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313354	Curb Ramps	Northeast Corner Of Foster Road @ 33.909965269125, - 118.130517303944	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313352	Curb Ramps	Northeast Corner Of Foster Road @ 33.909965269125, - 118.130517303944	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313355	Curb Ramps	Northwest Corner Of Angell Street @ 33.909973060146, - 118.130687624216		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313356	Curb Ramps	Northwest Corner Of Angell Street @ 33.909973060146, - 118.130687624216	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313357	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.130522668362		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313358	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.130522668362		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313359	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.130522668362		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313360	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.130522668362	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Premiere Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313361	Curb Ramps	Southeast Corner Of Angell Street @ 33.912392694326, - 118.130522668362	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Prichard Street - Castana Avenue To Downey Avenue - Castana Avenue To Downey Avenue	311914	Curb Ramps	Southeast Corner Of Downey Avenue @ 33.908421519840, - 118.151572644711	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Prichard Street - Castana Avenue To Downey Avenue - Castana Avenue To Downey Avenue	311916	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.905891580421, - 118.146100938320	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Prichard Street - Castana Avenue To Downey Avenue - Castana Avenue To Downey Avenue	311915	Curb Ramps	Southwest Corner Of Castana Avenue @ 33.905891580421, - 118.146100938320	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Priscilla Street - Blodgett Avenue To Lakewood Boulevard - Blodgett Avenue To Lakewood Boulevard	313014	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.911382110299, - 118.142144680023	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Priscilla Street - Blodgett Avenue To Lakewood Boulevard - Blodgett Avenue To Lakewood Boulevard	313015	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.911247439056, - 118.142258673906		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Priscilla Street - Blodgett Avenue To Lakewood Boulevard - Blodgett Avenue To Lakewood Boulevard	313016	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.911247439056, - 118.142258673906	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Priscilla Street - Columbia Way To Hanwell Avenue - Columbia Way To Hanwell Avenue	313066	Curb Ramps	Southwest Corner Of Columbia Way @ 33.911340929859, - 118.134240210056	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Priscilla Street - Columbia Way To Hanwell Avenue - Columbia Way To Hanwell Avenue	313077	Curb Ramps	Northwest Corner Of Columbia Way @ 33.911487843771, - 118.134258985519	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Priscilla Street - Dunrobin Avenue to Adenmoor Avenue - Priscilla Street - Dunrobin Avenue to Adenmoor Avenue	Downey, CA 90424 326335	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.911536815018, - 118.123200237751		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Dunrobin Avenue to Adenmoor Avenue - Priscilla Street - Dunrobin Avenue to Adenmoor Avenue	Downey, CA 90424 326336	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.911536815018, - 118.123200237751		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Priscilla Street - Dunrobin Avenue to Adenmoor Avenue - Priscilla Street - Dunrobin Avenue to Adenmoor Avenue	Downey, CA 90424 326337	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.911536815018, - 118.123200237751		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Priscilla Street - Dunrobin Avenue to Adenmoor Avenue - Priscilla Street - Dunrobin Avenue to Adenmoor Avenue	Downey, CA 90424 318975	Curb Ramps	Southwest Corner Of Dunrobin Avenue @ 33.911536815018, - 118.123200237751	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	Downey, CA 90424 328230	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917028094157, - 118.154665231705		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	Downey, CA 90424 328231	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917028094157, - 118.154665231705		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328232	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917028094157, - 118.154665231705		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328233	Curb Ramps	Southeast Corner Of Brock Avenue @ 33.917028094157, - 118.154665231705	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328234	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.915505618491, - 118.151543140411		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328235	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.915505618491, - 118.151543140411		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328236	Curb Ramps	Northeast Corner Of Brock Avenue @ 33.917232869510, - 118.154557943344		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328237	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.915585749467, - 118.151468038559	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328238	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.916458281888, - 118.153098821640		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328239	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.916458281888, - 118.153098821640		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328240	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.916458281888, - 118.153098821640		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328241	Curb Ramps	Northwest Corner Of Gneiss Avenue @ 33.916458281888, - 118.153098821640	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328242	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.917954030967, - 118.156403303146		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue Downey, CA 90424	328243	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.917954030967, - 118.156403303146		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328244	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.917954030967, - 118.156403303146		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328245	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.917954030967, - 118.156403303146	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328246	Curb Ramps	Southeast Corner Of Paramount Boulevard @ 33.917954030967, - 118.156403303146	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328255	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328256	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328257	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328258	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328259	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Priscilla Street - Paramount Boulevard To Downey Avenue - Paramount Boulevard To Downey Avenue	328260	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918096481891, - 118.156285285950	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pruess Avenue - Brookmill Road To Phlox Street - Brookmill Road To Phlox Street	412919	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938870621029, - 118.143078088760		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pruess Avenue - Brookmill Road To Phlox Street - Brookmill Road To Phlox Street	412920	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938870621029, - 118.143078088760	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Pruess Avenue - Brookmill Road To Phlox Street - Brookmill Road To Phlox Street	412931	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938945166905, - 118.143218904734		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Pruess Avenue - Brookmill Road To Phlox Street - Brookmill Road To Phlox Street	412932	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938945166905, - 118.143218904734	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Pruess Avenue - Brookmill Road To Phlox Street - Brookmill Road To Phlox Street Downey, CA 90242	412933	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938945166905, - 118.143218904734	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328261	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.916881189796, - 118.150411248207	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328262	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.916729833523, - 118.150539994240		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328263	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.916729833523, - 118.150539994240	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328273	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328274	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328275	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328276	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328277	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328278	Curb Ramps	Northeast Corner Of Paramount Boulevard @ 33.918474866001, - 118.153683543205	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328279	Curb Ramps	Southeast Corner Of Paramount Avenue @ 33.919209371535, - 118.155480623245		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328280	Curb Ramps	Southeast Corner Of Paramount Avenue @ 33.919209371535, - 118.155480623245		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328281	Curb Ramps	Southeast Corner Of Paramount Avenue @ 33.919209371535, - 118.155480623245		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328283	Curb Ramps	Southeast Corner Of Paramount Avenue @ 33.919209371535, - 118.155480623245	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Puritan Avenue - Paramount Avenue To Downey Avenue - Paramount Avenue To Downey Avenue Downey, CA 90424	328282	Curb Ramps	Southeast Corner Of Paramount Avenue @ 33.919209371535, - 118.155480623245	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404356	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404357	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404358	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404359	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404360	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404361	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404362	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404363	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404364	Curb Ramps	Northeast Corner @ 33.932028811922, - 118.159904927015	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404365	Curb Ramps	Northwest Corner @ 33.932147872334, - 118.160166442394		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404366	Curb Ramps	Northwest Corner @ 33.932147872334, - 118.160166442394		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404367	Curb Ramps	Northwest Corner @ 33.932147872334, -118.160166442394		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404368	Curb Ramps	Northwest Corner @ 33.932147872334, -118.160166442394	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404369	Curb Ramps	Northwest Corner @ 33.932147872334, -118.160166442394	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404370	Curb Ramps	Southwest Corner @ 33.932005444906, -118.160236179829		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404371	Curb Ramps	Southwest Corner @ 33.932005444906, -118.160236179829		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404372	Curb Ramps	Southwest Corner @ 33.932005444906, -118.160236179829		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404373	Curb Ramps	Southwest Corner @ 33.932005444906, -118.160236179829	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404374	Curb Ramps	Southwest Corner @ 33.932005444906, -118.160236179829	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404437	Curb Ramps	Southeast Corner @ 33.931846326482, -118.159988075495		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404438	Curb Ramps	Southeast Corner @ 33.931846326482, -118.159988075495		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404439	Curb Ramps	Southeast Corner @ 33.931846326482, - 118.159988075495		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404440	Curb Ramps	Southeast Corner @ 33.931846326482, - 118.159988075495	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404441	Curb Ramps	Southeast Corner @ 33.931846326482, - 118.159988075495	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive & Old River School Road - Quill Drive & Old River School Road Downey, CA 90242	404442	Curb Ramps	Southeast Corner @ 33.931846326482, - 118.159988075495	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483202	Curb Ramps	South Side West of Old River School Road - 1st @ 33.932283623255, - 118.160784691572		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483203	Curb Ramps	South Side West of Old River School Road - 1st @ 33.932283623255, - 118.160784691572		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483184	Curb Ramps	South Side West of Old River School Road - 1st @ 33.932283623255, - 118.160784691572	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483185	Curb Ramps	South Side West of Old River School Road - 1st @ 33.932283623255, - 118.160784691572	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483186	Curb Ramps	South Side West of Old River School Road - 2nd @ 33.932338146105, - 118.160890638828		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quill Drive - Old River School Road to End - Old River School Road to End Downey, CA 90242	483187	Curb Ramps	South Side West of Old River School Road - 2nd @ 33.932338146105, - 118.160890638828		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive - Old River School Road to End - Old River School	483188	Curb Ramps	South Side West of Old River School Road - 2nd @ 33.932338146105, - 118.160890638828		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive - Old River School Road to End - Old River School	483190	Curb Ramps	South Side West of Old River School Road - 2nd @ 33.932338146105, - 118.160890638828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Quill Drive - Old River School Road to End - Old River School	483189	Curb Ramps	South Side West of Old River School Road - 2nd @ 33.932338146105, - 118.160890638828	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Quill Drive - Rives Avenue To Old River School Drive - Rives Avenue To Old River School Drive	405553	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.929176875862, - 118.154250830412		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive - Rives Avenue To Old River School Drive - Rives Avenue To Old River School Drive	405554	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.929176875862, - 118.154250830412	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Quill Drive - Rives Avenue To Old River School Drive - Rives Avenue To Old River School Drive	405582	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.929036668974, - 118.154347389936		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Quill Drive - Rives Avenue To Old River School Drive - Rives Avenue To Old River School Drive	405583	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.929036668974, - 118.154347389936	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive - Rives Avenue To Old River School Drive - Rives Avenue To Old River School Drive	405584	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.929036668974, - 118.154347389936	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403356	Curb Ramps	Southeast Corner Of Morning Avenue @ 33.927663519467, - 118.151610195637	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403399	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.927744751780, - 118.151760399342		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403400	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.927744751780, - 118.151760399342		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403403	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.927744751780, - 118.151760399342	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403401	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.927744751780, - 118.151760399342	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403402	Curb Ramps	Southwest Corner Of Morning Avenue @ 33.927744751780, - 118.151760399342	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403404	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.928946535852, - 118.154193162918	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403405	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.928946535852, - 118.154193162918	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403406	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929080066369, - 118.154076486826		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403408	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929080066369, - 118.154076486826	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403407	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.929080066369, - 118.154076486826	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Quill Drive - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	403409	Curb Ramps	Northeast Corner Of Samoline Avenue @ 33.927296303935, - 118.150526583195	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474032	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.945158948142, - 118.125319182873		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474033	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.945158948142, - 118.125319182873		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474034	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.945158948142, - 118.125319182873		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474016	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.945158948142, - 118.125319182873	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474017	Curb Ramps	Northwest Corner of Brookshire Avenue @ 33.945158948142, - 118.125319182873	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474036	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474037	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474038	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474039	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474029	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Quinn Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	474030	Curb Ramps	Southwest Corner of Brookshire Avenue @ 33.945026555383, - 118.125362098217	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road Downey, CA 90242	463223	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road Downey, CA 90242	463224	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road Downey, CA 90242	463225	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road Downey, CA 90242	463226	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	462055	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	462056	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	462057	Curb Ramps	Northeast Corner of Old River School Road @ 33.954098876745, - 118.143842518330	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	463227	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	463228	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	463229	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	Downey, CA 90242	462061	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	462062	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Quinn Street - Wiley Burke Avenue to Old River School Road - Wiley Burke Avenue to Old River School Road	462063	Curb Ramps	Southeast Corner of Old River School Road @ 33.953949811468, - 118.143956512213	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345793	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345794	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345795	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345796	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345798	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue	345797	Curb Ramps	Southwest Corner Of Downey Avenue @ 33.923895590341, - 118.145069628954	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Quoit Street - Orizaba Avenue To Downey Avenue - Orizaba Avenue To Downey Avenue Downey, CA 90242	345799	Curb Ramps	Northwest Corner Of Downey Avenue @ 33.924025790317, - 118.144981116056		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Raviller Drive - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	468679	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.955056670537, - 118.117041885853	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Raviller Drive - Brookshire Avenue to Birchdale Avenue - Brookshire Avenue to Birchdale Avenue Downey, CA 90242	468680	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.955179035983, - 118.116902410984	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474560	Curb Ramps	Southeast Corner of Downey Norwalk Road @ 33.925062931743, -118.112223297358		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474561	Curb Ramps	Southeast Corner of Downey Norwalk Road @ 33.925062931743, -118.112223297358		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474562	Curb Ramps	Southeast Corner of Downey Norwalk Road @ 33.925062931743, -118.112223297358	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474563	Curb Ramps	Southeast Corner of Downey Norwalk Road @ 33.925062931743, -118.112223297358	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474564	Curb Ramps	Southeast Corner of Downey Norwalk Road @ 33.925062931743, -118.112223297358	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474565	Curb Ramps	East Side South of Stewart & Gray Road - 2nd @ 33.928085258989, -118.112232880		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474566	Curb Ramps	East Side South of Stewart & Gray Road - 2nd @ 33.928085258989, -118.112232880		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474567	Curb Ramps	East Side South of Stewart & Gray Road - 2nd @ 33.928085258989, -118.112232880	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474568	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, -118.112254142761		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474569	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, -118.112254142761		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474570	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, -118.112254142761		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474571	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, - 118.112254142761	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474572	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, - 118.112254142761	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474573	Curb Ramps	East Side South of Stewart & Gray Road - 4th @ 33.926291460614, - 118.112254142761	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474574	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474575	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474576	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474579	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474580	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474577	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474578	Curb Ramps	Southwest Corner of Stewart & Gray Road @ 33.928875319491, - 118.113277405500	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474581	Curb Ramps	East Side South of Stewart & Gray Road - 1st @ 33.928223241915, - 118.112227320671		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474582	Curb Ramps	East Side South of Stewart & Gray Road - 1st @ 33.928223241915, - 118.112227320671		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474583	Curb Ramps	East Side South of Stewart & Gray Road - 1st @ 33.928223241915, - 118.112227320671		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474584	Curb Ramps	East Side South of Stewart & Gray Road - 1st @ 33.928223241915, - 118.112227320671	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474635	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474636	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474637	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474639	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474640	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474638	Curb Ramps	East Side South of Stewart & Gray Road - 6th @ 33.926063338386, - 118.112258166075	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474641	Curb Ramps	East Side South of Stewart & Gray Road - 3rd @ 33.926291460614, - 118.112254142761		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474642	Curb Ramps	East Side South of Stewart & Gray Road - 3rd @ 33.926291460614, - 118.112254142761		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474643	Curb Ramps	East Side South of Stewart & Gray Road - 3rd @ 33.926291460614, - 118.112254142761		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474644	Curb Ramps	East Side South of Stewart & Gray Road - 3rd @ 33.926291460614, - 118.112254142761	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474645	Curb Ramps	East Side South of Stewart & Gray Road - 3rd @ 33.926291460614, - 118.112254142761	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474683	Curb Ramps	East Side South of Stewart & Gray Road - 5th @ 33.926063338386, - 118.112258166075		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474684	Curb Ramps	East Side South of Stewart & Gray Road - 5th @ 33.926063338386, - 118.112258166075		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474685	Curb Ramps	East Side South of Stewart & Gray Road - 5th @ 33.926063338386, - 118.112258166075		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474686	Curb Ramps	East Side South of Stewart & Gray Road - 5th @ 33.926063338386, - 118.112258166075	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474687	Curb Ramps	East Side South of Stewart & Gray Road - 5th @ 33.926063338386, - 118.112258166075	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474688	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474689	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474690	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474691	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474692	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Regentview Avenue - Stewart & Gray Road to Washburn Road - Stewart & Gray Road to Washburn Road Downey, CA 90242	474693	Curb Ramps	Southeast Corner of Stewart & Gray Road @ 33.928991046047, - 118.112905919552	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404272	Curb Ramps	Northeast Corner Of Adwen Street @ 33.941763398199, - 118.146778196096		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404273	Curb Ramps	Northeast Corner Of Adwen Street @ 33.941763398199, - 118.146778196096		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404274	Curb Ramps	Northeast Corner Of Adwen Street @ 33.941763398199, - 118.146778196096		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404275	Curb Ramps	Northeast Corner Of Adwen Street @ 33.941763398199, - 118.146778196096	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404276	Curb Ramps	Southeast Corner Of Arnett Street @ 33.943148558618, - 118.145760297775	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404277	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404278	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404279	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404280	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404281	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404282	Curb Ramps	Northwest Corner Of Adwen Street @ 33.941844617062, - 118.146925717592	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404296	Curb Ramps	Southwest Corner Of Arnett Street @ 33.943223100748, - 118.145898431540	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Richeon Avenue - Adwen Street To Arnett Street - Adwen Street To Arnett Street Downey, CA 90242	404297	Curb Ramps	Southwest Corner Of Arnett Street @ 33.943223100748, - 118.145898431540	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street Downey, CA 90241	362641	Curb Ramps	Southwest Corner Of Hondo Street @ 33.930613426798, - 118.155512809753		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street Downey, CA 90241	362642	Curb Ramps	Southwest Corner Of Hondo Street @ 33.930613426798, - 118.155512809753		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street	362643	Curb Ramps	Southwest Corner Of Hondo Street @ 33.930613426798, - 118.155512809753		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street	362644	Curb Ramps	Southwest Corner Of Hondo Street @ 33.930613426798, - 118.155512809753	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street	362668	Curb Ramps	Northeast Corner Of Quill Drive @ 33.929910176385, - 118.155738115311		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street	362669	Curb Ramps	Northeast Corner Of Quill Drive @ 33.929910176385, - 118.155738115311		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Richeon Avenue - Quill Drive To Rundell Street - Quill Drive To Rundell Street	362670	Curb Ramps	Northeast Corner Of Quill Drive @ 33.929910176385, - 118.155738115311	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rio Flora Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463211	Curb Ramps	Northwest Corner of Old River School Road @ 33.950664746964, - 118.146688342094		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rio Flora Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463096	Curb Ramps	Northwest Corner of Old River School Road @ 33.950664746964, - 118.146688342094	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rio Flora Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463212	Curb Ramps	Southwest Corner of Old River School Road @ 33.950533475243, - 118.146831840277		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rio Flora Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463099	Curb Ramps	Southwest Corner of Old River School Road @ 33.950533475243, - 118.146831840277	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		
Rio Hondo Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463237	Curb Ramps	Southwest Corner of Old River School Road @ 33.951408987046, - 118.146134465933		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Rio Hondo Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	462514	Curb Ramps	Southwest Corner of Old River School Road @ 33.951408987046, - 118.146134465933	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Rio Hondo Place - Old River School Road to Cul-De-Sac - Old River School Road to Cul-De-Sac	463238	Curb Ramps	Northwest Corner of Old River School Road @ 33.951552494475, - 118.146051317453		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444006	Curb Ramps	East Side South of Adwen Street @ 33.940738698759, - 118.145188987255	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444007	Curb Ramps	East Side South of Adwen Street @ 33.940738698759, - 118.145188987255	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444008	Curb Ramps	Northeast Corner of Phlox Street @ 33.943216425336, - 118.143320828676		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444009	Curb Ramps	Northeast Corner of Phlox Street @ 33.943216425336, - 118.143320828676		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444010	Curb Ramps	Northeast Corner of Phlox Street @ 33.943216425336, - 118.143320828676		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444011	Curb Ramps	Northeast Corner of Phlox Street @ 33.943216425336, - 118.143320828676	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444012	Curb Ramps	Northeast Corner of Phlox Street @ 33.943216425336, - 118.143320828676	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444053	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444054	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444055	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444056	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444058	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444057	Curb Ramps	Southeast Corner of Phlox Street @ 33.943102943252, - 118.143397271633	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444059	Curb Ramps	Southeast Corner of Luxor Street @ 33.938342122273, - 118.146955221891		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444060	Curb Ramps	Southeast Corner of Luxor Street @ 33.938342122273, - 118.146955221891		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444061	Curb Ramps	Southeast Corner of Luxor Street @ 33.938342122273, - 118.146955221891	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444062	Curb Ramps	Southeast Corner of Luxor Street @ 33.938342122273, - 118.146955221891	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444089	Curb Ramps	Southwest Corner of Burns Avenue @ 33.943858375062, - 118.143045902252		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444090	Curb Ramps	Northeast Corner of Luxor Street @ 33.938456723334, - 118.146864026785		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444091	Curb Ramps	Northeast Corner of Luxor Street @ 33.938456723334, - 118.146864026785	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Burns Avenue to Stewart & Gray Road - Burns Avenue to Stewart & Gray Road	444092	Curb Ramps	Northeast Corner of Luxor Street @ 33.938456723334, - 118.146864026785	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464799	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464800	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464801	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464802	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464803	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464804	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway	464805	Curb Ramps	Southwest Corner of Amigos Avenue @ 33.924827016563, - 118.157792687416	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464820	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464821	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464822	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464825	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464826	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464823	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Rives Avenue - Golondrin Street to Imperial Highway - Golondrin Street to Imperial Highway Downey, CA 90242	464824	Curb Ramps	Northwest Corner of Amigos Avenue @ 33.925031773172, - 118.157685399055	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408072	Curb Ramps	East Side South Of Quill Drive - 1st @ 33.928268865252, - 118.154724240303		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408073	Curb Ramps	East Side South Of Quill Drive - 1st @ 33.928268865252, - 118.154724240303		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408074	Curb Ramps	East Side South Of Quill Drive - 1st @ 33.928268865252, - 118.154724240303	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408075	Curb Ramps	East Side South Of Quill Drive - 1st @ 33.928268865252, - 118.154724240303	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408087	Curb Ramps	East Side South Of Quill Drive - 2nd @ 33.928190971734, - 118.154772520065		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408088	Curb Ramps	East Side South Of Quill Drive - 2nd @ 33.928190971734, - 118.154772520065		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408089	Curb Ramps	East Side South Of Quill Drive - 2nd @ 33.928190971734, - 118.154772520065	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408090	Curb Ramps	East Side South Of Quill Drive - 3rd @ 33.927096003887, - 118.155605345964		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408091	Curb Ramps	East Side South Of Quill Drive - 3rd @ 33.927096003887, - 118.155605345964		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408092	Curb Ramps	East Side South Of Quill Drive - 3rd @ 33.927096003887, - 118.155605345964	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408093	Curb Ramps	West Side North Of Imperial Highway - 1st @ 33.927379762150, - 118.155594617128	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rives Avenue - Quill Drive To Imperial Highway - Quill Drive To Imperial Highway Downey, CA 90242	408106	Curb Ramps	East Side South Of Quill Drive - 4th @ 33.927008094273, - 118.155680447817		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rose Avenue - Lakewood Boulevard To Imperial Highway - Lakewood Boulevard To Imperial Highway Downey, CA 90242	327201	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917197256441, - 118.135031461716		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rose Avenue - Lakewood Boulevard To Imperial Highway - Lakewood Boulevard To Imperial Highway Downey, CA 90242	327202	Curb Ramps	Northeast Corner Of Imperial Highway @ 33.917197256441, - 118.135031461716		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rose Avenue - Lakewood Boulevard To Imperial Highway - Lakewood Boulevard To Imperial Highway Downey, CA 90242	327203	Curb Ramps	Northwest Corner Of West Side Imperial Highway @ 33.917183901536, - 118.135149478912		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rose Avenue - Lakewood Boulevard To Imperial Highway - Lakewood Boulevard To Imperial Highway Downey, CA 90242	327204	Curb Ramps	Northwest Corner Of West Side Imperial Highway @ 33.917183901536, - 118.135149478912		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rose Avenue - Lakewood Boulevard To Imperial Highway - Lakewood Boulevard To Imperial Highway Downey, CA 90242	327205	Curb Ramps	Northwest Corner Of West Side Imperial Highway @ 33.917183901536, - 118.135149478912		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409521	Curb Ramps	Northeast Corner @ 33.903891394792, - 118.145206421614		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409522	Curb Ramps	Northeast Corner @ 33.903891394792, - 118.145206421614		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409523	Curb Ramps	Northeast Corner @ 33.903891394792, - 118.145206421614	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409524	Curb Ramps	Southeast Corner @ 33.903634272367, - 118.145211786032	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409525	Curb Ramps	Southeast Corner @ 33.903634272367, - 118.145211786032	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rosecrans Avenue & Century Boulevard - Rosecrans Avenue & Century Boulevard Downey, CA 90242	409579	Curb Ramps	Southwest Corner @ 33.903627593852, - 118.145453184843	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409361	Curb Ramps	Southeast Corner @ 33.903647629395, - 118.142709285021		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409362	Curb Ramps	Southeast Corner @ 33.903647629395, - 118.142709285021		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409363	Curb Ramps	Southeast Corner @ 33.903647629395, - 118.142709285021		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409364	Curb Ramps	Southeast Corner @ 33.903647629395, - 118.142709285021	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409365	Curb Ramps	Southwest Corner @ 33.903638724710, - 118.143091499805		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409366	Curb Ramps	Southwest Corner @ 33.903638724710, - 118.143091499805		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409367	Curb Ramps	Southwest Corner @ 33.903638724710, - 118.143091499805		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409368	Curb Ramps	Southwest Corner @ 33.903638724710, - 118.143091499805	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409369	Curb Ramps	Northeast Corner @ 33.903920334929, - 118.142722696066		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rosecrans Avenue & Lakewood Boulevard · Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409370	Curb Ramps	Northeast Corner @ 33.903920334929, - 118.142722696066		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409371	Curb Ramps	Northeast Corner @ 33.903920334929, - 118.142722696066		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409372	Curb Ramps	Northeast Corner @ 33.903920334929, - 118.142722696066	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409516	Curb Ramps	Northwest Corner @ 33.903928126503, - 118.143099546433		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409517	Curb Ramps	Northwest Corner @ 33.903928126503, - 118.143099546433		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409518	Curb Ramps	Northwest Corner @ 33.903928126503, - 118.143099546433		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409519	Curb Ramps	Northwest Corner @ 33.903928126503, - 118.143099546433		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rosecrans Avenue & Lakewood Boulevard - Rosecrans Avenue & Lakewood Boulevard Downey, CA 90242	409520	Curb Ramps	Northwest Corner @ 33.903928126503, - 118.143099546433	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rosecrans Avenue - City of Paramount to Lakewood Boulevard · City of Paramount to Lakewood Boulevard Downey, CA 90242	482672	Curb Ramps	South Side East of City of Paramount - 2nd @ 33.903891394792, - 118.146787583828		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue - City of Paramount to Lakewood Boulevard · City of Paramount to Lakewood Boulevard Downey, CA 90242	482673	Curb Ramps	South Side East of City of Paramount - 2nd @ 33.903891394792, - 118.146787583828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rosecrans Avenue - City of Paramount to Lakewood Boulevard · City of Paramount to Lakewood Boulevard Downey, CA 90242	482674	Curb Ramps	South Side East of City of Paramount - 1st @ 33.903895847121, - 118.146975338459		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue - City of Paramount to Lakewood Boulevard · City of Paramount to Lakewood Boulevard Downey, CA 90242	482675	Curb Ramps	South Side East of City of Paramount - 1st @ 33.903895847121, - 118.146975338459		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Rosecrans Avenue - City of Paramount to Lakewood Boulevard · City of Paramount to Lakewood Boulevard Downey, CA 90242	482676	Curb Ramps	South Side East of City of Paramount - 1st @ 33.903895847121, - 118.146975338459	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road Downey, CA 90242	407131	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.932562913403, - 118.151632994413	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407143	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.932699776368, - 118.151525706053	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407144	Curb Ramps	Southeast Corner Of Old River School Road @ 33.935009722987, - 118.157630413771		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407145	Curb Ramps	Southeast Corner Of Old River School Road @ 33.935009722987, - 118.157630413771		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407146	Curb Ramps	Southeast Corner Of Old River School Road @ 33.935009722987, - 118.157630413771		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407147	Curb Ramps	Southeast Corner Of Old River School Road @ 33.935009722987, - 118.157630413771	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407148	Curb Ramps	Southeast Corner Of Old River School Road @ 33.935009722987, - 118.157630413771	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407149	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407150	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407151	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407152	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407153	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407154	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rundell Street - Rives Avenue To Old River School Road - Rives Avenue To Old River School Road	407155	Curb Ramps	Northeast Corner Of Old River School Road @ 33.935123215860, - 118.157540559769	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313389	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313390	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313391	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313392	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313393	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313394	Curb Ramps	Southwest Corner Of Angell Street @ 33.912391581355, - 118.128857016563	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313397	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313398	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313399	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313400	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313401	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	313402	Curb Ramps	Southeast Corner Of Angell Street @ 33.912402711068, - 118.128667920828	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314434	Curb Ramps	Northwest Corner Of Foster Road @ 33.909862872778, - 118.128842264414	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Rutgers Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314435	Curb Ramps	Northwest Corner Of Foster Road @ 33.909862872778, - 118.128842264414	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Ryerson Avenue - De Palma Street To Adwen Street - De Palma Street To Adwen Street	408617	Curb Ramps	Southeast Corner Of Adwen Street @ 33.945921036906, - 118.154999166727		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Ryerson Avenue - De Palma Street To Adwen Street - De Palma Street To Adwen Street	408618	Curb Ramps	Southeast Corner Of Adwen Street @ 33.945921036906, - 118.154999166727	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Salford Avenue - Stewart & Gray Road To De Palma Street - Stewart & Gray Road To De Palma Street	408654	Curb Ramps	Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Salford Avenue - Stewart & Gray Road To De Palma Street - Stewart & Gray Road To De Palma Street	408655	Curb Ramps	Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675		Grade Break	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Salford Avenue - Stewart & Gray Road To De Palma Street - Stewart & Gray Road To De Palma Street Downey, CA 90242	408656	Curb Ramps	Northwest Corner Of Stewart & Gray Road @ 33.941684404435, - 118.156679570675	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413290	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938567986353, - 118.142486661673		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413291	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938567986353, - 118.142486661673		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413292	Curb Ramps	Northwest Corner Of Brookmill Road @ 33.938567986353, - 118.142486661673		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413294	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938496778038, - 118.142345845699		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413295	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938496778038, - 118.142345845699		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413296	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938496778038, - 118.142345845699	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Samoline Avenue - Brookmill Road To Cul-de-sac - Brookmill Road To Cul-de-sac Downey, CA 90242	413297	Curb Ramps	Northeast Corner Of Brookmill Road @ 33.938496778038, - 118.142345845699	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449699	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449700	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449701	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449702	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449703	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449704	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449705	Curb Ramps	Southeast Corner of Cedartree Road @ 33.957443877364, - 118.107314854860	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449727	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449728	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449729	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449730	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449731	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Serapis Avenue - Telegraph Road to End - Telegraph Road to End Downey, CA 90242	449732	Curb Ramps	Northeast Corner of Cedartree Road @ 33.957559565089, - 118.107207566500	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Shellyfield Road - Cecilia Street to Gotham Street - Cecilia Street to Gotham Street Downey, CA 90242	444767	Curb Ramps	Northeast Corner of Cecilia Street @ 33.938481201211, - 118.120573014021		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Shellyfield Road - Cecilia Street to Gotham Street - Cecilia Street to Gotham Street Downey, CA 90242	444768	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938545733761, - 118.120709806681		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Shellyfield Road - Cecilia Street to Gotham Street - Cecilia Street to Gotham Street Downey, CA 90242	444769	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938545733761, - 118.120709806681	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Shellyfield Road - Cecilia Street to Gotham Street - Cecilia Street to Gotham Street Downey, CA 90242	444770	Curb Ramps	Northwest Corner of Cecilia Street @ 33.938545733761, - 118.120709806681	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Sidewiew Drive - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	449695	Curb Ramps	Northeast Corner of Metro Street @ 33.950108509468, - 118.101633936167		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Sidewiew Drive - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	449696	Curb Ramps	Northeast Corner of Metro Street @ 33.950108509468, - 118.101633936167		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Sidewiew Drive - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	449697	Curb Ramps	Northeast Corner of Metro Street @ 33.950108509468, - 118.101633936167		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Sidewiew Drive - Cedartree Road to Brookpark Road - Cedartree Road to Brookpark Road Downey, CA 90242	449698	Curb Ramps	Northeast Corner of Metro Street @ 33.950108509468, - 118.101633936167	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346723	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346724	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346725	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346727	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346728	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346726	Curb Ramps	Southwest Corner Of Bairnsdale Street @ 33.966235696141, - 118.124310672283	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346729	Curb Ramps	Southwest Corner Of Danvers Street @ 33.966880809, - 118.123838603497		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346730	Curb Ramps	Southwest Corner Of Danvers Street @ 33.966880809, - 118.123838603497		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346731	Curb Ramps	Southwest Corner Of Danvers Street @ 33.966880809, - 118.123838603497		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346732	Curb Ramps	Southwest Corner Of Danvers Street @ 33.966880809, - 118.123838603497	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346749	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346750	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346751	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346753	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346754	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Smallwood Avenue - Botany Street to Allengrove Street - Botany Street to Allengrove Street Downey, CA 90240	346752	Curb Ramps	Northeast Corner Of Allengrove Street @ 33.965655090385, - 118.124511837959	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357825	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.955263579279, - 118.133081495762		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357826	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.955263579279, - 118.133081495762	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357827	Curb Ramps	Northeast Corner Of Florence Avenue @ 33.955263579279, - 118.133081495762	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357828	Curb Ramps	Northwest Corner Of Florence Avenue @ 33.955348122491, - 118.133288025856	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357829	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357830	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357831	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357832	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357833	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357834	Curb Ramps	Southeast Corner Of Dinsdale Street - Left @ 33.955690744121, - 118.132181614637	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357835	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357836	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street	357839	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357840	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357837	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Smallwood Avenue - Florence Avenue to Dinsdale Street - Florence Avenue to Dinsdale Street Downey, CA 90240	357838	Curb Ramps	Southeast Corner Of Dinsdale Street - Right @ 33.955711879825, - 118.132298290730	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450786	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450787	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450788	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450789	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450790	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450791	Curb Ramps	Southeast Corner of Telegraph Road @ 33.952876311281, - 118.098860532045	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450792	Curb Ramps	Southwest Corner of Telegraph Road @ 33.953089899962, - 118.098942339420		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450793	Curb Ramps	Southwest Corner of Telegraph Road @ 33.953089899962, - 118.098942339420		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Songfest Drive - Metro Street to Telegraph Road - Metro Street to Telegraph Road Downey, CA 90242	450794	Curb Ramps	Southwest Corner of Telegraph Road @ 33.953089899962, - 118.098942339420	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90242	405606	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.930366399625, - 118.153112232685		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90242	405607	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.930366399625, - 118.153112232685	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard Downey, CA 90242	405608	Curb Ramps	Southeast Corner Of Rives Avenue @ 33.930366399625, - 118.153112232685	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	405609	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.930505491590, - 118.152996897697		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	405610	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.930505491590, - 118.152996897697		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Springer Street - Rives Avenue To Paramount Boulevard - Rives Avenue To Paramount Boulevard	405611	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.930505491590, - 118.152996897697		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Spry Street - End To Izetta Avenue - End Izetta Avenue	316975	Curb Ramps	South Side West Of End @ 33.920642751979, - 118.120389282703	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Spry Street - End To Izetta Avenue - End Izetta Avenue	316976	Curb Ramps	North Side East Of Dunrobin Avenue @ 33.920785198407, - 118.120402693748	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stamps Avenue - Downey Avenue to Gallatin Road - Downey Avenue to Gallatin Road	468128	Curb Ramps	Southeast Corner of Downey Avenue @ 33.957475024075, - 118.120885491371	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stamps Avenue - Downey Avenue to Gallatin Road - Downey Avenue to Gallatin Road	468130	Curb Ramps	Northeast Corner of Downey Avenue @ 33.957615184132, - 118.120788931847		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
Stamps Avenue - Downey Avenue to Gallatin Road - Downey Avenue to Gallatin Road	468131	Curb Ramps	Northeast Corner of Downey Avenue @ 33.957615184132, - 118.120788931847		Parallel Curb Ramp Right Side Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stamps Avenue - Downey Avenue to Gallatin Road - Downey Avenue to Gallatin Road Downey, CA 90242	468132	Curb Ramps	Northeast Corner of Downey Avenue @ 33.957615184132, - 118.120788931847	Top Landing	Top Landing Right Side Clear Length - Parallel Curb Ramp	Provide a level top landing with enough clear length.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	454111	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	454112	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	454113	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	453557	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	453558	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	453559	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Stamps Road - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	453560	Curb Ramps	Southeast Corner of Telegraph Road @ 33.963067898547, - 118.112400323153	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314417	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314418	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314419	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314420	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314421	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314422	Curb Ramps	Southwest Corner Of Angell Street @ 33.912368208952, - 118.127864599228	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314423	Curb Ramps	Northeast Corner Of Foster Road @ 33.909867324795, - 118.127667456865	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314428	Curb Ramps	Southeast Corner Of Angell Street @ 33.912363757065, - 118.127674162388		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314429	Curb Ramps	Southeast Corner Of Angell Street @ 33.912363757065, - 118.127674162388		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314430	Curb Ramps	Southeast Corner Of Angell Street @ 33.912363757065, - 118.127674162388		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314431	Curb Ramps	Southeast Corner Of Angell Street @ 33.912363757065, - 118.127674162388	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314432	Curb Ramps	Southeast Corner Of Angell Street @ 33.912363757065, - 118.127674162388	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stanbridge Avenue - Angell Street To Foster Road - Angell Street To Foster Road	314433	Curb Ramps	Northwest Corner Of Foster Road @ 33.909866211791, - 118.127845823765	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road & Brookshire Avenue - Stewart & Gray Road & Brookshire Avenue	404353	Curb Ramps	Southeast Corner @ 33.930556677375, - 118.135301023722	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Brookshire Avenue - Stewart & Gray Road & Brookshire Avenue	404354	Curb Ramps	Northwest Corner @ 33.930840424109, - 118.135405629873		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Stewart & Gray Road & Brookshire Avenue - Stewart & Gray Road & Brookshire Avenue	404355	Curb Ramps	Northwest Corner @ 33.930840424109, - 118.135405629873	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421485	Curb Ramps	Southeast Corner @ 33.931923103940, - 118.138672560453		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421486	Curb Ramps	Southeast Corner @ 33.931923103940, - 118.138672560453	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421487	Curb Ramps	Northeast Corner @ 33.932104476502, - 118.138518333435		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421488	Curb Ramps	Northeast Corner @ 33.932104476502, - 118.138518333435	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421489	Curb Ramps	Southwest Corner @ 33.932027699207, - 118.138899207115		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421490	Curb Ramps	Southwest Corner @ 33.932027699207, - 118.138899207115		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421491	Curb Ramps	Northwest Corner @ 33.932220198671, - 118.138753026724		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421492	Curb Ramps	Northwest Corner @ 33.932220198671, - 118.138753026724	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Downey Avenue - Stewart & Gray Road & Downey Avenue Downey, CA 90242	421493	Curb Ramps	Northwest Corner @ 33.932220198671, - 118.138753026724	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408431	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408432	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408433	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408434	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408435	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408436	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408437	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408438	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408439	Curb Ramps	Southeast Corner @ 33.940080036364, - 118.153989315033	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408440	Curb Ramps	Northwest Corner @ 33.940343724455, - 118.154108673334		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408441	Curb Ramps	Northwest Corner @ 33.940343724455, - 118.154108673334	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408442	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408443	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408444	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408445	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408448	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408446	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408447	Curb Ramps	Southwest Corner @ 33.940149018137, - 118.154242783785	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408547	Curb Ramps	Northeast Corner @ 33.940274742839, - 118.153841793537		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408548	Curb Ramps	Northeast Corner @ 33.940274742839, - 118.153841793537		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408549	Curb Ramps	Northeast Corner @ 33.940274742839, -118.153841793537		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408550	Curb Ramps	Northeast Corner @ 33.940274742839, -118.153841793537	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408551	Curb Ramps	Northeast Corner @ 33.940274742839, -118.153841793537	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408552	Curb Ramps	Northeast Corner @ 33.940274742839, -118.153841793537	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road & Old River School Road - Stewart & Gray Road & Old River School Road Downey, CA 90242	408553	Curb Ramps	Northeast Corner @ 33.940274742839, -118.153841793537	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395718	Curb Ramps	Northwest Corner @ 33.929983617364, -118.133259862661		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395719	Curb Ramps	Northwest Corner @ 33.929983617364, -118.133259862661		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395720	Curb Ramps	Northwest Corner @ 33.929983617364, -118.133259862661		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395721	Curb Ramps	Northwest Corner @ 33.929983617364, -118.133259862661	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395776	Curb Ramps	Southwest Corner @ 33.929795563821, -118.133402019739	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395777	Curb Ramps	Northeast Corner @ 33.929912401870, -118.133085519075		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395778	Curb Ramps	Northeast Corner @ 33.929912401870, -118.133085519075		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395779	Curb Ramps	Northeast Corner @ 33.929912401870, -118.133085519075		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395780	Curb Ramps	Northeast Corner @ 33.929912401870, -118.133085519075	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Patton Road - Stewart & Gray Road & Patton Road Downey, CA 90242	395781	Curb Ramps	Northeast Corner @ 33.929912401870, -118.133085519075	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406354	Curb Ramps	Southeast Corner @ 33.936969122806, -118.148206472397	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406410	Curb Ramps	Southwest Corner @ 33.936969122806, -118.148206472397	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406409	Curb Ramps	Southwest Corner @ 33.936969122806, - 118.148206472397	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406411	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406412	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406413	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406414	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406415	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406416	Curb Ramps	Northwest Corner @ 33.937166061691, - 118.148075044155	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406417	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406418	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406419	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406420	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406423	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406424	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406421	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart & Gray Road & Rives Avenue - Stewart & Gray Road & Rives Avenue Downey, CA 90242	406422	Curb Ramps	Northeast Corner @ 33.937059247437, - 118.147908747196	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421579	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421580	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421581	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421582	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421583	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421584	Curb Ramps	Northeast Corner @ 33.928083033456, - 118.116530925035	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421585	Curb Ramps	Southwest Corner To South Crossing @ 33.927715819733, - 118.116846084595		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421586	Curb Ramps	Southwest Corner To South Crossing @ 33.927715819733, - 118.116846084595		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421587	Curb Ramps	Southwest Corner To South Crossing @ 33.927715819733, - 118.116846084595	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421588	Curb Ramps	Northwest Corner @ 33.927935035388, - 118.116872906685		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421589	Curb Ramps	Northwest Corner @ 33.927935035388, - 118.116872906685		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421590	Curb Ramps	Northwest Corner @ 33.927935035388, - 118.116872906685		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421591	Curb Ramps	Northwest Corner @ 33.927935035388, - 118.116872906685	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421592	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421593	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421594	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421596	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421597	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421595	Curb Ramps	Southeast Corner To East Crossing @ 33.927844901101, - 118.116514831781	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421598	Curb Ramps	Southwest Corner To West Crossing @ 33.927733624071, - 118.116863518953		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421599	Curb Ramps	Southwest Corner To West Crossing @ 33.927733624071, - 118.116863518953		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421600	Curb Ramps	Southwest Corner To West Crossing @ 33.927733624071, - 118.116863518953	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421601	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421602	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421603	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421606	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421607	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421604	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stewart & Gray Road & Woodruff Avenue - Stewart & Gray Road & Woodruff Avenue Downey, CA 90242	421605	Curb Ramps	Southeast Corner To South Crossing @ 33.927844901101, - 118.116514831781	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard	479627	Curb Ramps	South Side West of Bellflower Boulevard - 1st @ 33.927700240934, - 118.126468509436		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard	479464	Curb Ramps	South Side West of Bellflower Boulevard - 1st @ 33.927700240934, - 118.126468509436	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479465	Curb Ramps	South Side West of Bellflower Boulevard - 1st @ 33.927700240934, - 118.126468509436	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479463	Curb Ramps	South Side West of Bellflower Boulevard - 1st @ 33.927700240934, - 118.126468509436	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479629	Curb Ramps	South Side West of Bellflower Boulevard - 3rd @ 33.927688447, - 118.127963840961		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479475	Curb Ramps	South Side West of Bellflower Boulevard - 3rd @ 33.927688447, - 118.127963840961	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479476	Curb Ramps	South Side West of Bellflower Boulevard - 3rd @ 33.927688447, - 118.127963840961	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479630	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.928030733416, - 118.128846287727		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479631	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.928030733416, - 118.128846287727		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479632	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.928030733416, - 118.128846287727		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479633	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.928030733416, - 118.128846287727		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479634	Curb Ramps	North Side East of Lakewood Boulevard - 2nd @ 33.928030733416, - 118.128846287727		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479635	Curb Ramps	North Side East of Lakewood Boulevard - 2nd @ 33.928030733416, - 118.128846287727		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479636	Curb Ramps	North Side East of Lakewood Boulevard - 2nd @ 33.928030733416, - 118.128846287727		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479484	Curb Ramps	North Side East of Lakewood Boulevard - 2nd @ 33.928030733416, - 118.128846287727	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479637	Curb Ramps	South Side West of Bellflower Boulevard - 4th @ 33.927669083327, - 118.128156960011		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479638	Curb Ramps	South Side West of Bellflower Boulevard - 4th @ 33.927669083327, - 118.128156960011		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479487	Curb Ramps	South Side West of Bellflower Boulevard - 4th @ 33.927669083327, - 118.128156960011	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479488	Curb Ramps	South Side West of Bellflower Boulevard - 4th @ 33.927669083327, - 118.128156960011	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479489	Curb Ramps	South Side West of Bellflower Boulevard - 2nd @ 33.927698015391, - 118.126703202724	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326744	Curb Ramps	Northeast Corner Of Pomeroy Road @ 33.939510378291, - 118.152337074280		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326745	Curb Ramps	Northeast Corner Of Pomeroy Road @ 33.939510378291, - 118.152337074280		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326746	Curb Ramps	Northeast Corner Of Pomerig Road @ 33.939510378291, - 118.152337074280		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326747	Curb Ramps	Northeast Corner Of Pomerig Road @ 33.939510378291, - 118.152337074280	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326748	Curb Ramps	Southeast Corner Of Pomerig Road @ 33.939319007927, - 118.152487277985		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326749	Curb Ramps	Southeast Corner Of Pomerig Road @ 33.939319007927, - 118.152487277985		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326750	Curb Ramps	Southeast Corner Of Pomerig Road @ 33.939319007927, - 118.152487277985		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326751	Curb Ramps	Southeast Corner Of Pomerig Road @ 33.939319007927, - 118.152487277985	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326968	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.936991375810, - 118.148254752159		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326969	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.936991375810, - 118.148254752159		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326970	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.936991375810, - 118.148254752159		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326755	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.936991375810, - 118.148254752159	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326756	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.939016374845, - 118.151441216469		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326757	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.939016374845, - 118.151441216469		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326758	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.939016374845, - 118.151441216469		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326759	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.939016374845, - 118.151441216469		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326760	Curb Ramps	Northeast Corner Of Julius Avenue @ 33.939016374845, - 118.151441216469	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326761	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.939105384687, - 118.151607513428		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326762	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.939105384687, - 118.151607513428		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326763	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.939105384687, - 118.151607513428		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326764	Curb Ramps	Northwest Corner Of Julius Avenue @ 33.939105384687, - 118.151607513428	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326765	Curb Ramps	Northwest Corner Of Old River School Road @ 33.940298107586, - 118.153828382492		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326766	Curb Ramps	Northwest Corner Of Old River School Road @ 33.940298107586, - 118.153828382492		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326767	Curb Ramps	Northwest Corner Of Old River School Road @ 33.940298107586, - 118.153828382492		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326768	Curb Ramps	Northwest Corner Of Old River School Road @ 33.940298107586, - 118.153828382492		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326769	Curb Ramps	Northwest Corner Of Old River School Road @ 33.940298107586, - 118.153828382492	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326770	Curb Ramps	Northwest Corner Of Pomerig Road @ 33.939621639933, - 118.152540922165		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326771	Curb Ramps	Northwest Corner Of Pomerig Road @ 33.939621639933, - 118.152540922165		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326772	Curb Ramps	Northwest Corner Of Pomerig Road @ 33.939621639933, - 118.152540922165		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326773	Curb Ramps	Northwest Corner Of Pomerig Road @ 33.939621639933, - 118.152540922165	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326971	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.934792750899, - 118.144038319588		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326972	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.934792750899, - 118.144038319588		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326973	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.934792750899, - 118.144038319588		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326777	Curb Ramps	Southwest Corner Of Paramount Boulevard @ 33.934792750899, - 118.144038319588	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326791	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326792	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326793	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326795	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326796	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326794	Curb Ramps	Southeast Corner Of Old River School Road @ 33.940307008440, - 118.153849840164	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326797	Curb Ramps	Southwest Corner Of Pomerig Road @ 33.939461423123, - 118.152766227722		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326798	Curb Ramps	Southwest Corner Of Pomerig Road @ 33.939461423123, - 118.152766227722		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	326799	Curb Ramps	Southwest Corner Of Pomerig Road @ 33.939461423123, - 118.152766227722	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327007	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.937160498452, - 118.148083090782		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327008	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.937160498452, - 118.148083090782		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327009	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.937160498452, - 118.148083090782		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327011	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.937160498452, - 118.148083090782	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327010	Curb Ramps	Northwest Corner Of Rives Avenue @ 33.937160498452, - 118.148083090782	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327012	Curb Ramps	Northwest Corner Of Horton Avenue @ 33.938704839667, - 118.150888681412		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327013	Curb Ramps	Northwest Corner Of Horton Avenue @ 33.938704839667, - 118.150888681412		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327014	Curb Ramps	Northwest Corner Of Horton Avenue @ 33.938704839667, - 118.150888681412	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327015	Curb Ramps	Northeast Corner Of Horton Avenue @ 33.938584675794, - 118.150684833527		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327016	Curb Ramps	Northeast Corner Of Horton Avenue @ 33.938584675794, - 118.150684833527	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327017	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.937062585384, - 118.147900700569		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327018	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.937062585384, - 118.147900700569		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327019	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.937062585384, - 118.147900700569		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327021	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.937062585384, - 118.147900700569	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327020	Curb Ramps	Northeast Corner Of Rives Avenue @ 33.937062585384, - 118.147900700569	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327022	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.934988582142, - 118.143866658211		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327023	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.934988582142, - 118.143866658211		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327024	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.934988582142, - 118.143866658211		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stewart & Gray Road - Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327025	Curb Ramps	Northwest Corner Of Paramount Boulevard @ 33.934988582142, - 118.143866658211	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480049	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480050	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480051	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480052	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480053	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480054	Curb Ramps	North Side East of Coldbrook Avenue - 1st @ 33.927781473212, - 118.120060712099	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480178	Curb Ramps	North Side East of Coldbrook Avenue - 2nd @ 33.927787037063, - 118.119846135378		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480179	Curb Ramps	North Side East of Coldbrook Avenue - 2nd @ 33.927787037063, - 118.119846135378		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480180	Curb Ramps	North Side East of Coldbrook Avenue - 2nd @ 33.927787037063, - 118.119846135378		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480181	Curb Ramps	North Side East of Coldbrook Avenue - 2nd @ 33.927787037063, - 118.119846135378		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480182	Curb Ramps	North Side East of Coldbrook Avenue - 2nd @ 33.927787037063, - 118.119846135378	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480183	Curb Ramps	South Side West of Woodruff Avenue @ 33.927724721902, - 118.122997730970		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480184	Curb Ramps	South Side West of Woodruff Avenue @ 33.927724721902, - 118.122997730970		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480185	Curb Ramps	South Side West of Woodruff Avenue @ 33.927724721902, - 118.122997730970		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480186	Curb Ramps	South Side West of Woodruff Avenue @ 33.927724721902, - 118.122997730970		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Woodruff Avenue to Bellflower Boulevard - Woodruff Avenue to Bellflower Boulevard Downey, CA 90242	480187	Curb Ramps	South Side West of Woodruff Avenue @ 33.927724721902, - 118.122997730970	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard Downey, CA 90242	479596	Curb Ramps	South Side West of Regentview Avenue - 2nd @ 33.928114190911, - 118.115682005882		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard Downey, CA 90242	479597	Curb Ramps	South Side West of Regentview Avenue - 2nd @ 33.928114190911, - 118.115682005882		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard Downey, CA 90242	479600	Curb Ramps	South Side West of Regentview Avenue - 1st @ 33.928154250480, - 118.115535825491		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard Downey, CA 90242	479601	Curb Ramps	South Side West of Regentview Avenue - 1st @ 33.928154250480, - 118.115535825491		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard Downey, CA 90242	479602	Curb Ramps	South Side West of Regentview Avenue - 1st @ 33.928154250480, - 118.115535825491		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart & Gray Road - Woodruff Avenue to Firestone Boulevard - Woodruff Avenue to Firestone Boulevard	479574	Curb Ramps	South Side West of Regentview Avenue - 1st @ 33.928154250480, - 118.115535825491	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	435997	Curb Ramps	Northwest Corner of Firestone Boulevard - East @ 33.929591931410, - 118.111693561077		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	435998	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.929249204723, - 118.111803531647		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	435999	Curb Ramps	Southeast Corner of Firestone Boulevard @ 33.929249204723, - 118.111803531647	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	436000	Curb Ramps	Curb Ramp at Median - Northeast @ 33.929471754677, - 118.112146854401		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	436001	Curb Ramps	Curb Ramp at Median - Northeast @ 33.929471754677, - 118.112146854401	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	436002	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.929516264598, - 118.111521899700		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard	436003	Curb Ramps	Northeast Corner of Firestone Boulevard @ 33.929516264598, - 118.111521899700		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard Downey, CA 90240	436101	Curb Ramps	Curb Ramp at South Median - Northwest @ 33.929562999990, - 118.112294375896		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard Downey, CA 90240	436102	Curb Ramps	Northwest Corner of Firestone Boulevard - West @ 33.929607509863, - 118.111736476421		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Stewart And Gray Road & Firestone Boulevard - Stewart And Gray Road & Firestone Boulevard Downey, CA 90240	436103	Curb Ramps	Northwest Corner of Firestone Boulevard - West @ 33.929607509863, - 118.111736476421	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320462	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.933408567230, - 118.141447305679		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320463	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.933408567230, - 118.141447305679		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320464	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.933408567230, - 118.141447305679		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320465	Curb Ramps	Southwest Corner Of Orizaba Avenue @ 33.933408567230, -118.141447305679	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320518	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.933337354600, -118.141297101974		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320519	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.933337354600, -118.141297101974		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320520	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.933337354600, -118.141297101974		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320522	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.933337354600, -118.141297101974	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stewart and Gray Road -Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	320521	Curb Ramps	Southeast Corner Of Orizaba Avenue @ 33.933337354600, - 118.141297101974	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452687	Curb Ramps	Southwest Corner of Cedrtree Road @ 33.961680837675, - 118.112011402845		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452688	Curb Ramps	Southwest Corner of Cedrtree Road @ 33.961680837675, - 118.112011402845		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452689	Curb Ramps	Southwest Corner of Cedrtree Road @ 33.961680837675, - 118.112011402845		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452690	Curb Ramps	Southwest Corner of Cedrtree Road @ 33.961680837675, - 118.112011402845	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452691	Curb Ramps	Southwest Corner of Cedrtree Road @ 33.961680837675, - 118.112011402845	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452692	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452693	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452694	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452695	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452696	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452697	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452698	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452699	Curb Ramps	Southeast Corner of Telegraph Road @ 33.961885505657, - 118.111355602741	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452761	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452762	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452763	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452764	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452765	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452705	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stoakes Avenue - Telegraph Road to Brookpark Road - Telegraph Road to Brookpark Road Downey, CA 90242	452706	Curb Ramps	Southwest Corner of Telegraph Road @ 33.961986727141, - 118.111480325460	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479056	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479057	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479058	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479059	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479038	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479036	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479037	Curb Ramps	South Side East of End - 2nd @ 33.936778859383, - 118.122282922268	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479061	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.936980249309, - 118.122138082981		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479062	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.936980249309, - 118.122138082981		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479046	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.936980249309, - 118.122138082981	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Stonewood Street - Lakewood Boulevard to End - Lakewood Boulevard to End Downey, CA 90242	479045	Curb Ramps	North Side East of Lakewood Boulevard - 1st @ 33.936980249309, - 118.122138082981	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355988	Curb Ramps	Southwest Corner @ 33.935445890846, - 118.097925782204		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355989	Curb Ramps	Southwest Corner @ 33.935445890846, - 118.097925782204		Grade Break	Provide a compliant curb ramp.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355991	Curb Ramps	Southwest Corner @ 33.935445890846, - 118.097925782204	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355990	Curb Ramps	Southwest Corner @ 33.935445890846, - 118.097925782204	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355992	Curb Ramps	Northeast Corner @ 33.935475932938, - 118.097949922085		Grade Break	Provide a compliant curb ramp.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355993	Curb Ramps	Northeast Corner @ 33.935475932938, - 118.097949922085		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355994	Curb Ramps	Northwest Corner @ 33.935445890846, - 118.097925782204		Grade Break	Provide a compliant curb ramp.	6/30/32	
Studebaker Road & I-5 on Ramp - Studebaker Road & I-5 on Ramp Downey, CA 90424	355995	Curb Ramps	Northwest Corner @ 33.935445890846, - 118.097925782204		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354006	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354007	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354008	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354012	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354013	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354009	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354010	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354011	Curb Ramps	Northeast Corner of Benfield Avenue @ 33.934471186121, - 118.098455518484	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354014	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354015	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354016	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354017	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354018	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354019	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354020	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354021	Curb Ramps	Southeast Corner of Benfield Avenue @ 33.934407763166, - 118.098515868187	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354022	Curb Ramps	Southeast Corner of Cecilia Street @ 33.932111152785, - 118.099116683006		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354023	Curb Ramps	Southeast Corner of Cecilia Street @ 33.932111152785, - 118.099116683006		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354024	Curb Ramps	Southeast Corner of Cecilia Street @ 33.932111152785, - 118.099116683006		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354026	Curb Ramps	Southeast Corner of Cecilia Street @ 33.932111152785, - 118.099116683006	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354025	Curb Ramps	Southeast Corner of Cecilia Street @ 33.932111152785, - 118.099116683006	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354027	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354028	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354029	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354033	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354030	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354031	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Studebaker Road - Cecilia Street to Florence Avenue - Studebaker Road - Cecilia Street to Florence Avenue Downey, CA 90424	354032	Curb Ramps	Southwest Corner of Cecilia Street @ 33.932104476502, - 118.099447935820	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411755	Curb Ramps	Northeast Corner Of Nada Street @ 33.940453872403, - 118.157064467669		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411756	Curb Ramps	Northeast Corner Of Nada Street @ 33.940453872403, - 118.157064467669	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411757	Curb Ramps	Northeast Corner Of Nada Street @ 33.940453872403, - 118.157064467669	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411758	Curb Ramps	Northeast Corner Of Nada Street @ 33.940453872403, - 118.157064467669	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411759	Curb Ramps	Northeast Corner Of Nada Street @ 33.940453872403, - 118.157064467669	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411760	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411761	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411762	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411763	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411764	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411765	Curb Ramps	Southwest Corner Of Stewart & Gray Road @ 33.941377329391, - 118.156619220972	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411779	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411780	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411781	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411782	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac	411783	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Susan Avenue - Stewart & Gray Road To Cul-de-sac - Stewart & Gray Road To Cul-de-sac Downey, CA 90242	411784	Curb Ramps	Southeast Corner Of Stewart & Gray Road @ 33.941302785644, - 118.156466335058	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Susan Avenue - Stewart & Gray Road To End - Stewart & Gray Road To End Downey, CA 90242	410843	Curb Ramps	Northeast Corner Of Stewart & Gray Road @ 33.941252718912, - 118.155764937401	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Susan Avenue - Stewart & Gray Road To End - Stewart & Gray Road To End Downey, CA 90242	410846	Curb Ramps	Northwest Corner Of Stewart & Gray Road @ 33.941306123425, - 118.155936598778	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard Downey, CA 90242	457577	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard Downey, CA 90242	457578	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard Downey, CA 90242	457579	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard Downey, CA 90242	457580	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard	Downey, CA 90242 457581	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard	Downey, CA 90242 457582	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard	Downey, CA 90242 457406	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879	Bottom Landing	Bottom Landing Change in Level due to Overlayment	Ensure the change in elevation is within the recommended height.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard	Downey, CA 90242 457407	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street & Bluff Road/ Foster Bridge Boulevard - Suva Street & Bluff Road/ Foster Bridge Boulevard	Downey, CA 90242 457408	Curb Ramps	Southeast Corner of Suva Street @ 33.965242435225, - 118.136329650879	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	Downey, CA 90242 406154	Curb Ramps	Northeast Corner @ 33.959906657082, - 118.125041574240		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	Downey, CA 90242 406155	Curb Ramps	Northeast Corner @ 33.959906657082, - 118.125041574240	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406156	Curb Ramps	Southwest Corner @ 33.959875511261, - 118.125455975533		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406157	Curb Ramps	Southwest Corner @ 33.959875511261, - 118.125455975533	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406158	Curb Ramps	Southwest Corner @ 33.959875511261, - 118.125455975533	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406250	Curb Ramps	Northwest Corner @ 33.960033464947, - 118.125316500664	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406249	Curb Ramps	Northwest Corner @ 33.960033464947, - 118.125316500664	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406251	Curb Ramps	Southeast Corner @ 33.959754264923, - 118.125164955854	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street & Paramount Boulevard - Suva Street & Paramount Boulevard	406252	Curb Ramps	Southeast Corner @ 33.959754264923, - 118.125164955854	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac	468686	Curb Ramps	Northeast Corner of Brookshire Avenue @ 33.954137811662, - 118.118042349815		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	468688	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.953970947605, - 118.118216693401		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Brookshire Avenue to Cul-De-Sac - Brookshire Avenue to Cul-De-Sac Downey, CA 90242	468689	Curb Ramps	Southeast Corner of Brookshire Avenue @ 33.953970947605, - 118.118216693401	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457591	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, - 118.134760558605		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457592	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, - 118.134760558605		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457593	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, - 118.134760558605		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457287	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, - 118.134760558605	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457288	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, -118.134760558605	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457285	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, -118.134760558605	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street - Guatemala Avenue to City of Bell Gardens - Guatemala Avenue to City of Bell Gardens Downey, CA 90242	457286	Curb Ramps	Southeast Corner of Guatemala Avenue @ 33.964424904939, -118.134760558605	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458160	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.960326012197, -118.126133233309		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458044	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.960326012197, -118.126133233309	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458043	Curb Ramps	Northeast Corner of Samoline Avenue @ 33.960326012197, -118.126133233309	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458045	Curb Ramps	South Side West of Paramount Boulevard - 1st @ 33.960027903203, - 118.125785887241		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458046	Curb Ramps	South Side West of Paramount Boulevard - 1st @ 33.960027903203, - 118.125785887241		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458047	Curb Ramps	South Side West of Paramount Boulevard - 1st @ 33.960027903203, - 118.125785887241		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458049	Curb Ramps	South Side West of Paramount Boulevard - 1st @ 33.960027903203, - 118.125785887241	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458048	Curb Ramps	South Side West of Paramount Boulevard - 1st @ 33.960027903203, - 118.125785887241	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458162	Curb Ramps	Southwest Corner of Samoline Avenue @ 33.960253709739, - 118.126392066479		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	458163	Curb Ramps	Southwest Corner of Samoline Avenue @ 33.960253709739, - 118.126392066479		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458075	Curb Ramps	Southwest Corner of Samoline Avenue @ 33.960253709739, - 118.126392066479	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458076	Curb Ramps	Southwest Corner of Samoline Avenue @ 33.960253709739, - 118.126392066479	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458165	Curb Ramps	Southeast Corner of Rives Avenue @ 33.961912201445, - 118.129747509956		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458166	Curb Ramps	Southeast Corner of Rives Avenue @ 33.961912201445, - 118.129747509956		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458104	Curb Ramps	Southeast Corner of Rives Avenue @ 33.961912201445, - 118.129747509956	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458167	Curb Ramps	South Side West of Paramount Boulevard - 2nd @ 33.960054599573, - 118.125863671303		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue	Downey, CA 90242	458168	Curb Ramps	South Side West of Paramount Boulevard - 2nd @ 33.960054599573, - 118.125863671303		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458169	Curb Ramps	South Side West of Paramount Boulevard - 2nd @ 33.960054599573, - 118.125863671303		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458108	Curb Ramps	South Side West of Paramount Boulevard - 2nd @ 33.960054599573, - 118.125863671303	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458170	Curb Ramps	North Side East of Samoline Avenue - 1st @ 33.960180294872, - 118.125775158405		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458110	Curb Ramps	North Side East of Samoline Avenue - 1st @ 33.960180294872, - 118.125775158405	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458171	Curb Ramps	North Side East of Samoline Avenue - 2nd @ 33.960146924457, - 118.125698715448		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458172	Curb Ramps	North Side East of Samoline Avenue - 2nd @ 33.960146924457, - 118.125698715448		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Suva Street - Paramount Boulevard to Horley Avenue - Paramount	458113	Curb Ramps	North Side East of Samoline Avenue - 2nd @ 33.960146924457, - 118.125698715448	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458114	Curb Ramps	North Side East of Samoline Avenue - 2nd @ 33.960146924457, - 118.125698715448	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458115	Curb Ramps	Northwest Corner of Samoline Avenue @ 33.960381629432, - 118.126286119223	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458116	Curb Ramps	Southwest Corner of Rives Avenue @ 33.961912201445, - 118.129747509956	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458117	Curb Ramps	Southeast Corner of Samoline Avenue @ 33.960190305994, - 118.126237839460		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458118	Curb Ramps	Southeast Corner of Samoline Avenue @ 33.960190305994, - 118.126237839460		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458119	Curb Ramps	Southeast Corner of Samoline Avenue @ 33.960190305994, - 118.126237839460	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Suva Street - Paramount Boulevard to Horley Avenue - Paramount Boulevard to Horley Avenue Downey, CA 90242	458120	Curb Ramps	Southeast Corner of Samoline Avenue @ 33.960190305994, - 118.126237839460	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415484	Curb Ramps	Southeast Corner @ 33.964631790897, - 118.113784343004		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415485	Curb Ramps	Southeast Corner @ 33.964631790897, - 118.113784343004		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415486	Curb Ramps	Southeast Corner @ 33.964631790897, - 118.113784343004	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415487	Curb Ramps	Southeast Corner @ 33.964631790897, - 118.113784343004	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415488	Curb Ramps	Southeast Corner @ 33.964631790897, - 118.113784343004	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415489	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415490	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415491	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415492	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415493	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415494	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415495	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Telegraph Road & Birchbark Avenue - Telegraph Road & Birchbark Avenue Downey, CA 90242	415496	Curb Ramps	Southwest Corner @ 33.964778612884, - 118.113917112350	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Telegraph Road & Lakewood Boulevard - Telegraph Road & Lakewood Boulevard Downey, CA 90242	415619	Curb Ramps	Southeast Corner @ 33.960783184783, - 118.110039979219		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Telegraph Road & Lakewood Boulevard - Telegraph Road & Lakewood Boulevard Downey, CA 90242	415620	Curb Ramps	Southeast Corner @ 33.960783184783, - 118.110039979219	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard Downey, CA 90242	425072	Curb Ramps	Southeast Corner @ 33.966871910925, - 118.115833550692		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard Downey, CA 90242	425074	Curb Ramps	Southeast Corner @ 33.966871910925, - 118.115833550692	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard Downey, CA 90242	425075	Curb Ramps	Southeast Corner @ 33.966871910925, - 118.115833550692	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard	Downey, CA 90242	425073	Curb Ramps	Southeast Corner @ 33.966871910925, - 118.115833550692	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard	Downey, CA 90242	425077	Curb Ramps	Southwest Corner @ 33.967102148319, - 118.116037398577	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32
Telegraph Road & Paramount Boulevard - Telegraph Road & Paramount Boulevard	Downey, CA 90242	425076	Curb Ramps	Southwest Corner @ 33.967102148319, - 118.116037398577	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Telegraph Road & Parsons Boulevard - Telegraph Road & Parsons Boulevard	Downey, CA 90242	415578	Curb Ramps	Southwest Corner To South Crossing @ 33.955759713243, - 118.102773874998		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32
Telegraph Road & Parsons Boulevard - Telegraph Road & Parsons Boulevard	Downey, CA 90242	415579	Curb Ramps	Southwest Corner To West Crossing @ 33.955781961335, - 118.102767169476	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32
Telegraph Road & Serapis Avenue - Telegraph Road & Serapis Avenue	Downey, CA 90242	415576	Curb Ramps	Southeast Corner @ 33.958313756212, - 118.106478005648		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32
Telegraph Road & Serapis Avenue - Telegraph Road & Serapis Avenue	Downey, CA 90242	415577	Curb Ramps	Southeast Corner @ 33.958313756212, - 118.106478005648		Grade Break	Provide a compliant curb ramp.	6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard	Downey, CA 90242	481977	Curb Ramps	South Side West of Hasty Avenue - 2nd @ 33.954431491606, - 118.100848048925		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	481978	Curb Ramps	South Side West of Hasty Avenue - 2nd @ 33.954431491606, - 118.100848048925		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	481979	Curb Ramps	South Side West of Hasty Avenue - 2nd @ 33.954431491606, - 118.100848048925	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	481980	Curb Ramps	South Side West of Hasty Avenue - 2nd @ 33.954431491606, - 118.100848048925	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482052	Curb Ramps	South Side West of True Avenue - 1st @ 33.953008691829, - 118.098816275597		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482053	Curb Ramps	South Side West of True Avenue - 1st @ 33.953008691829, - 118.098816275597		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	481983	Curb Ramps	South Side West of True Avenue - 1st @ 33.953008691829, - 118.098816275597	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	481984	Curb Ramps	South Side West of True Avenue - 1st @ 33.953008691829, - 118.098816275597	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482040	Curb Ramps	South Side West of Hasty Avenue - 1st @ 33.954363633831, - 118.100760877132		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482041	Curb Ramps	South Side West of Hasty Avenue - 1st @ 33.954363633831, - 118.100760877132		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482042	Curb Ramps	South Side West of Hasty Avenue - 1st @ 33.954363633831, - 118.100760877132		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482043	Curb Ramps	South Side West of Hasty Avenue - 1st @ 33.954363633831, - 118.100760877132	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482044	Curb Ramps	South Side West of Hasty Avenue - 1st @ 33.954363633831, - 118.100760877132	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tristan Drive - 5th Street to Muller Street - 5th Street to Muller Street Downey, CA 90242	474132	Curb Ramps	Northeast Corner of 5th Street @ 33.940585159669, - 118.123563677073		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tristan Drive - 5th Street to Muller Street - 5th Street to Muller Street Downey, CA 90242	474134	Curb Ramps	Northeast Corner of 5th Street @ 33.940585159669, - 118.123563677073	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Tristan Drive - 5th Street to Muller Street - 5th Street to Muller Street Downey, CA 90242	474133	Curb Ramps	Northeast Corner of 5th Street @ 33.940585159669, - 118.123563677073	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456400	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456401	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456402	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	455999	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456000	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	455997	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	455998	Curb Ramps	Southwest Corner of Telegraph Road @ 33.969531281688, - 118.118234127760	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456403	Curb Ramps	Southeast Corner of Telegraph Road @ 33.969404487981, - 118.118116110563		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456404	Curb Ramps	Southeast Corner of Telegraph Road @ 33.969404487981, - 118.118116110563		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456004	Curb Ramps	Southeast Corner of Telegraph Road @ 33.969404487981, - 118.118116110563	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Tweedy Lane - Brookpark Road to Telegraph Road - Brookpark Road to Telegraph Road Downey, CA 90242	456003	Curb Ramps	Southeast Corner of Telegraph Road @ 33.969404487981, - 118.118116110563	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458022	Curb Ramps	Southeast Corner of Suva Street @ 33.960580738832, - 118.127047866583		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458023	Curb Ramps	Southeast Corner of Suva Street @ 33.960580738832, - 118.127047866583		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457913	Curb Ramps	Southeast Corner of Suva Street @ 33.960580738832, - 118.127047866583	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457912	Curb Ramps	Southeast Corner of Suva Street @ 33.960580738832, - 118.127047866583	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458024	Curb Ramps	Northeast Corner of Lubec Street to East Crossing @ 33.957600723184, - 118.129172176123		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457916	Curb Ramps	Northeast Corner of Lubec Street to East Crossing @ 33.957600723184, - 118.129172176123	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457917	Curb Ramps	Northeast Corner of Lubec Street to East Crossing @ 33.957600723184, - 118.129172176123	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457915	Curb Ramps	Northeast Corner of Lubec Street to East Crossing @ 33.957600723184, - 118.129172176123	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458025	Curb Ramps	Southwest Corner of Suva Street @ 33.960633018876, - 118.127226233482		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458026	Curb Ramps	Southwest Corner of Suva Street @ 33.960633018876, - 118.127226233482		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458027	Curb Ramps	Southwest Corner of Suva Street @ 33.960633018876, - 118.127226233482		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457921	Curb Ramps	Southwest Corner of Suva Street @ 33.960633018876, - 118.127226233482	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458028	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458029	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458030	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458031	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457927	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457928	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457926	Curb Ramps	Southeast Corner of Lubec Street @ 33.957480585986, -118.129274165	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458034	Curb Ramps	Northeast Corner of Lubec Street to North Crossing @ 33.957625195556, -118.129188269377		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	458035	Curb Ramps	Northeast Corner of Lubec Street to North Crossing @ 33.957625195556, -118.129188269377		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457971	Curb Ramps	Northeast Corner of Lubec Street to North Crossing @ 33.957625195556, -118.129188269377	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tweedy Lane - Suva Street to Florence Avenue - Suva Street to Florence Avenue Downey, CA 90242	457972	Curb Ramps	Northeast Corner of Lubec Street to North Crossing @ 33.957625195556, - 118.129188269377	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Tweedy Lane - West Side Bangle Road to Suva Street - West Side Bangle Road to Suva Street Downey, CA 90240	449317	Curb Ramps	Curb Ramp South of Coolgrove Drive @ 33.963806468645, - 118.124892711639		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tweedy Lane - West Side Bangle Road to Suva Street - West Side Bangle Road to Suva Street Downey, CA 90240	449318	Curb Ramps	Curb Ramp South of Coolgrove Drive @ 33.963806468645, - 118.124892711639		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.		6/30/32
Tweedy Lane - West Side Bangle Road to Suva Street - West Side Bangle Road to Suva Street Downey, CA 90240	449319	Curb Ramps	Curb Ramp South of Coolgrove Drive @ 33.963806468645, - 118.124892711639	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Tweedy Lane - West Side Bangle Road to Suva Street - West Side Bangle Road to Suva Street Downey, CA 90240	449320	Curb Ramps	Curb Ramp South of Coolgrove Drive @ 33.963806468645, - 118.124892711639	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Tweedy Lane Bridge Overpass & I-5 - Tweedy Lane Bridge Overpass & I-5 Downey, CA 90242	476823	Curb Ramps	Curb Ramp Next to North Entrance @ 33.967787295525, - 118.121514469385		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Tweedy Lane Bridge Overpass & I-5 - Tweedy Lane Bridge Overpass & I-5 Downey, CA 90242	476824	Curb Ramps	Curb Ramp Next to North Entrance @ 33.967787295525, - 118.121514469385		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Tweedy Lane Bridge Overpass & I-5 - Tweedy Lane Bridge Overpass & I-5 Downey, CA 90242	476825	Curb Ramps	Curb Ramp Next to North Entrance @ 33.967787295525, - 118.121514469385		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Tweedy Lane Bridge Overpass & I-5 - Tweedy Lane Bridge Overpass & I-5 Downey, CA 90242	476827	Curb Ramps	Curb Ramp Next to North Entrance @ 33.967787295525, - 118.121514469385	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Tweedy Lane Bridge Overpass & I-5 - Tweedy Lane Bridge Overpass & I-5 Downey, CA 90242	476826	Curb Ramps	Curb Ramp Next to North Entance @ 33.967787295525, - 118.121514469385	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310468	Curb Ramps	Northwest Corner Of Century Boulevard @ 33.906157600461, - 118.150800168514	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310469	Curb Ramps	Southeast Corner Of Golden Street @ 33.909173920244, - 118.148564547300		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310470	Curb Ramps	Southeast Corner Of Golden Street @ 33.909173920244, - 118.148564547300		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310471	Curb Ramps	Southeast Corner Of Golden Street @ 33.909173920244, - 118.148564547300		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310473	Curb Ramps	Southeast Corner Of Golden Street @ 33.909173920244, - 118.148564547300	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310472	Curb Ramps	Southeast Corner Of Golden Street @ 33.909173920244, - 118.148564547300	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310475	Curb Ramps	Southwest Corner Of Prichard Street @ 33.907611235054, - 118.149787634611	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310474	Curb Ramps	Southwest Corner Of Prichard Street @ 33.907611235054, - 118.149787634611	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310476	Curb Ramps	Southeast Corner Of Prichard Street @ 33.907547792101, - 118.149646818638	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310477	Curb Ramps	Northwest Corner Of Prichard Street @ 33.907740346882, - 118.149731308222	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310478	Curb Ramps	Northwest Corner Of Prichard Street @ 33.907740346882, - 118.149731308222	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310479	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310480	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310481	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310482	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310483	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310484	Curb Ramps	Southwest Corner Of Golden Street @ 33.909242927050, - 118.148683905602	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310485	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.906074121459, - 118.150652647018		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310486	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.906074121459, - 118.150652647018		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310487	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.906074121459, - 118.150652647018		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310488	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.906074121459, - 118.150652647018		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Verdura Avenue - Golden Street To Century Boulevard - Golden Street To Century Boulevard Downey, CA 90242	310489	Curb Ramps	Northeast Corner Of Century Boulevard @ 33.906074121459, - 118.150652647018	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311164	Curb Ramps	Northwest Corner Of Golden Street @ 33.909471094314, - 118.148882389069		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311165	Curb Ramps	Northwest Corner Of Golden Street @ 33.909471094314, - 118.148882389069		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311166	Curb Ramps	Northwest Corner Of Golden Street @ 33.909471094314, - 118.148882389069		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311167	Curb Ramps	Northwest Corner Of Golden Street @ 33.909471094314, - 118.148882389069	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311168	Curb Ramps	Southwest Corner Of Gardendale Street @ 33.912458359614, - 118.146870732307	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311169	Curb Ramps	Southwest Corner Of Gardendale Street @ 33.912458359614, - 118.146870732307	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311170	Curb Ramps	Northeast Corner Of Golden Street @ 33.909399861673, - 118.148742914200		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311171	Curb Ramps	Northeast Corner Of Golden Street @ 33.909399861673, - 118.148742914200		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311172	Curb Ramps	Northeast Corner Of Golden Street @ 33.909399861673, - 118.148742914200		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311173	Curb Ramps	Northeast Corner Of Golden Street @ 33.909399861673, - 118.148742914200	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311174	Curb Ramps	Northeast Corner Of Golden Street @ 33.909399861673, - 118.148742914200	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311177	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.912344836542, - 118.146733939648	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Verdura Avenue - Golden Street To Gardendale Street - Golden Street To Gardendale Street Downey, CA 90242	311176	Curb Ramps	Southeast Corner Of Gardendale Street @ 33.912344836542, - 118.146733939648	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	365240	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	365241	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	365242	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	365243	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360368	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360369	Curb Ramps	Northwest Corner Of Susan Avenue @ 33.957768692501, - 118.144295811653	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360374	Curb Ramps	Southeast Corner Of Susan Avenue @ 33.957572913663, - 118.144220709801		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360375	Curb Ramps	Southeast Corner Of Susan Avenue @ 33.957572913663, - 118.144220709801		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360376	Curb Ramps	Southeast Corner Of Susan Avenue @ 33.957572913663, - 118.144220709801	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360377	Curb Ramps	Southeast Corner Of Susan Avenue @ 33.957572913663, - 118.144220709801	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360378	Curb Ramps	Southwest Corner Of Susan Avenue @ 33.957630757457, - 118.144370913506		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360379	Curb Ramps	Southwest Corner Of Susan Avenue @ 33.957630757457, - 118.144370913506		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360380	Curb Ramps	Southwest Corner Of Susan Avenue @ 33.957630757457, - 118.144370913506		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360381	Curb Ramps	Southwest Corner Of Susan Avenue @ 33.957630757457, - 118.144370913506	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360382	Curb Ramps	Southwest Corner Of Old River School Road @ 33.956558416104, - 118.142386078835		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360383	Curb Ramps	Southwest Corner Of Old River School Road @ 33.956558416104, - 118.142386078835		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360384	Curb Ramps	Southwest Corner Of Old River School Road @ 33.956558416104, - 118.142386078835		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360385	Curb Ramps	Southwest Corner Of Old River School Road @ 33.956558416104, - 118.142386078835	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360386	Curb Ramps	Southwest Corner Of Old River School Road @ 33.956558416104, - 118.142386078835	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360387	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360388	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360389	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360390	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue	360391	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Via Amorita - Old River School Road To Sherry Avenue - Old River School Road To Sherry Avenue Downey, CA 90421	360392	Curb Ramps	Northeast Corner Of Susan Avenue @ 33.957688601213, - 118.144113421440	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459267	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459268	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459269	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459270	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459271	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459272	Curb Ramps	Northwest Corner of Old River School Road @ 33.955846480769, - 118.142864853144	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459274	Curb Ramps	Southwest Corner of Old River School Road @ 33.955778624122, -118.142943978310		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Via Rio Nido - Old River School Road to Sherry Avenue - Old River School Road to Sherry Avenue Downey, CA 90242	459275	Curb Ramps	Southwest Corner of Old River School Road @ 33.955778624122, -118.142943978310		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424974	Curb Ramps	Southwest Corner @ 33.965928709683, -118.117898851633		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424975	Curb Ramps	Southwest Corner @ 33.965928709683, -118.117898851633		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424976	Curb Ramps	Southwest Corner @ 33.965928709683, -118.117898851633		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424977	Curb Ramps	Southwest Corner @ 33.965928709683, -118.117898851633		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424978	Curb Ramps	Southwest Corner @ 33.965928709683, -118.117898851633		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424980	Curb Ramps	Southwest Corner @ 33.965928709683, - 118.117898851633	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	424979	Curb Ramps	Southwest Corner @ 33.965928709683, - 118.117898851633	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	425060	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	425061	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629		Curb Ramp Width	Provide a compliant curb ramp.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	425062	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	425063	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard Downey, CA 90242	425064	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Vista Del Rosa Street & Paramount Boulevard - Vista Del Rosa Street & Paramount Boulevard	425065	Curb Ramps	Northwest Corner @ 33.966037712248, - 118.117719143629	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Vultee Avenue - Florance Avenue to Baysinger Street - Vultee Avenue - Florance Avenue to Baysinger Street	359413	Curb Ramps	Southeast Corner of Baysinger Street @ 33.945938837438, - 118.116711974144		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Vultee Avenue - Florance Avenue to Baysinger Street - Vultee Avenue - Florance Avenue to Baysinger Street	359414	Curb Ramps	Southeast Corner of Baysinger Street @ 33.945938837438, - 118.116711974144		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Vultee Avenue - Florance Avenue to Baysinger Street - Vultee Avenue - Florance Avenue to Baysinger Street	359415	Curb Ramps	Southeast Corner of Baysinger Street @ 33.945938837438, - 118.116711974144		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Vultee Avenue - Florance Avenue to Baysinger Street - Vultee Avenue - Florance Avenue to Baysinger Street	359417	Curb Ramps	Southeast Corner of Baysinger Street @ 33.945938837438, - 118.116711974144	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Vultee Avenue - Florance Avenue to Baysinger Street - Vultee Avenue - Florance Avenue to Baysinger Street	359416	Curb Ramps	Southeast Corner of Baysinger Street @ 33.945938837438, - 118.116711974144	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard	427893	Curb Ramps	Northeast Corner @ 33.924388568690, - 118.125282973051	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427966	Curb Ramps	Southeast Corner @ 33.924232774486, - 118.125293701887		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427967	Curb Ramps	Southeast Corner @ 33.924232774486, - 118.125293701887		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427968	Curb Ramps	Northwest Corner @ 33.924406373724, - 118.125633001328		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427969	Curb Ramps	Northwest Corner @ 33.924406373724, - 118.125633001328		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427970	Curb Ramps	Northwest Corner @ 33.924406373724, - 118.125633001328		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427971	Curb Ramps	Northwest Corner @ 33.924406373724, - 118.125633001328	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427972	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427973	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427974	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506		Curb Ramp - Cross Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427975	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427976	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road & Bellflower Boulevard - Washburn Road & Bellflower Boulevard Downey, CA 90242	427977	Curb Ramps	Southwest Corner @ 33.924238338570, - 118.125596791506	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Washburn Road & Woodruff Avenue - Washburn Road & Woodruff Avenue Downey, CA 90242	427804	Curb Ramps	Northwest Corner @ 33.924410824981, - 118.116866201162	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road & Woodruff Avenue - Washburn Road & Woodruff Avenue Downey, CA 90242	427806	Curb Ramps	Northeast Corner @ 33.924409712167, - 118.116541653872	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road & Woodruff Avenue - Washburn Road & Woodruff Avenue Downey, CA 90242	427807	Curb Ramps	Northeast Corner @ 33.924409712167, - 118.116541653872	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road & Woodruff Avenue - Washburn Road & Woodruff Avenue Downey, CA 90242	427805	Curb Ramps	Northeast Corner @ 33.924409712167, - 118.116541653872	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road & Woodruff Avenue - Washburn Road & Woodruff Avenue Downey, CA 90242	427892	Curb Ramps	Southwest Corner @ 33.924256143635, - 118.116863518953	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437669	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437670	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437671	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437674	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437672	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437673	Curb Ramps	Southwest Corner of Cornuta Avenue @ 33.924246128286, - 118.119407594204	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437675	Curb Ramps	Southeast Corner of Pangborn Avenue @ 33.924250579552, - 118.119217157364		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437676	Curb Ramps	Southeast Corner of Pangborn Avenue @ 33.924250579552, - 118.119217157364		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437677	Curb Ramps	Southeast Corner of Pangborn Avenue @ 33.924250579552, - 118.119217157364	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437678	Curb Ramps	Southeast Corner of Pangborn Avenue @ 33.924250579552, - 118.119217157364	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437679	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437680	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437681	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437682	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437683	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437684	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437685	Curb Ramps	Southwest Corner of Izetta Avenue @ 33.924232774486, - 118.122215867043	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437686	Curb Ramps	Southeast Corner of Izetta Avenue @ 33.924239451386, - 118.122022747993		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437687	Curb Ramps	Southeast Corner of Izetta Avenue @ 33.924239451386, - 118.122022747993		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437688	Curb Ramps	Southeast Corner of Izetta Avenue @ 33.924239451386, - 118.122022747993		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437689	Curb Ramps	Southeast Corner of Izetta Avenue @ 33.924239451386, - 118.122022747993	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437690	Curb Ramps	Southeast Corner of Izetta Avenue @ 33.924239451386, - 118.122022747993	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437691	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437692	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437693	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437694	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437695	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437696	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437697	Curb Ramps	Southeast Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437698	Curb Ramps	Southwest Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437699	Curb Ramps	Southwest Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437700	Curb Ramps	Southwest Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437701	Curb Ramps	Southwest Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437702	Curb Ramps	Southwest Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437703	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437704	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437705	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437706	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437707	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437708	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437709	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437710	Curb Ramps	Southwest Corner of Dunrobin Avenue @ 33.924230548852, - 118.121156394482	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437711	Curb Ramps	Southeast Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437712	Curb Ramps	Southeast Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437713	Curb Ramps	Southeast Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437714	Curb Ramps	Southeast Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard Downey, CA 90240	437715	Curb Ramps	Southeast Corner of Eastbrook Avenue @ 33.924243902653, - 118.120260536671	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437718	Curb Ramps	Southeast Corner of Cornuta Avenue @ 33.924250579552, - 118.119217157364	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437716	Curb Ramps	Southeast Corner of Cornuta Avenue @ 33.924250579552, - 118.119217157364	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Washburn Road - Regentview Avenue to Bellflower Boulevard - Regentview Avenue to Bellflower Boulevard	437717	Curb Ramps	Southeast Corner of Cornuta Avenue @ 33.924250579552, - 118.119217157364	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street	468077	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street	468078	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street	468079	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street	467970	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street	467971	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	467972	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	467973	Curb Ramps	Northeast Corner of 6th Street @ 33.946303747522, - 118.132245987654	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468080	Curb Ramps	Northeast Corner of 5th Street @ 33.945215687832, - 118.133029192686		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468081	Curb Ramps	Northeast Corner of 5th Street @ 33.945215687832, - 118.133029192686		Parallel Curb Ramp Left Side Slope	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468082	Curb Ramps	Northeast Corner of 5th Street @ 33.945215687832, - 118.133029192686		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	467977	Curb Ramps	Northeast Corner of 5th Street @ 33.945215687832, - 118.133029192686	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	467978	Curb Ramps	Northeast Corner of 5th Street @ 33.945215687832, - 118.133029192686	Top Landing	Top Landing Right Side Slope - Parallel Curb Ramp	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468085	Curb Ramps	Northwest Corner of 5th Street @ 33.945298015943, - 118.133161962032		Parallel Curb Ramp Left Side Width	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468086	Curb Ramps	Northwest Corner of 5th Street @ 33.945298015943, - 118.133161962032		Parallel Curb Ramp Left Side Cross Slope	Provide a compliant curb ramp.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468087	Curb Ramps	Northwest Corner of 5th Street @ 33.945298015943, - 118.133161962032		Parallel Curb Ramp Right Side Cross Slope	Provide a compliant curb ramp.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468088	Curb Ramps	Northwest Corner of 5th Street @ 33.945298015943, - 118.133161962032		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Western Avenue - 7th Street to 5th Street - 7th Street to 5th Street Downey, CA 90242	468018	Curb Ramps	Northwest Corner of 5th Street @ 33.945298015943, - 118.133161962032	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429611	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429612	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429613	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429616	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429617	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429614	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429615	Curb Ramps	Southeast Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429668	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429669	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429670	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429671	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429672	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429673	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.		6/30/32
Western Avenue - Florence Avenue to 7th Street - Florence Avenue to 7th Street Downey, CA 90242	429674	Curb Ramps	Southwest Corner of Florence Avenue @ 33.952321200690, - 118.127871304750	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Wiley Burke Avenue - 2nd Street to Firestone Boulevard - 2nd Street to Firestone Boulevard Downey, CA 90242	464618	Curb Ramps	Northwest Corner of Firestone Boulevard @ 33.946802158768, - 118.145243972540	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	347537	Curb Ramps	Southwest Corner Of Quinn Street - 2nd @ 33.952409084171, - 118.141079843044		Parallel Curb Ramp Right Side Width	Provide a compliant curb ramp.		6/30/32
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	347538	Curb Ramps	Southwest Corner Of Quinn Street - 2nd		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347539	Curb Ramps	Southwest Corner Of Quinn Street - 2nd @ 33.952409084171, - 118.141079843044	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347540	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347541	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347542	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347543	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347544	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	347545	Curb Ramps	Southwest Corner Of Irwingrove Drive @ 33.955546131263, - 118.138169646263	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Wiley Burke Avenue - Irwingrove Drive To Muller Street - Irwingrove Drive To Firestone Boulevard Downey, CA 90241	348359	Curb Ramps	Southeast Corner Of Cherokee Drive @ 33.953276789618, - 118.139639496803		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	348360	Curb Ramps	Southeast Corner Of Cherokee Drive @ 33.953276789618, - 118.139639496803		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	347573	Curb Ramps	Southeast Corner Of Cherokee Drive @ 33.953276789618, - 118.139639496803	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	349050	Curb Ramps	Southwest Corner Of Quinn Street - 1st		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	349051	Curb Ramps	Southwest Corner Of Quinn Street - 1st @ 33.952409084171, - 118.141079843044	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	347576	Curb Ramps	Southwest Corner Of Quinn Street - 1st @ 33.952409084171, - 118.141079843044	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	347577	Curb Ramps	Southwest Corner Of Quinn Street - 1st @ 33.952409084171, - 118.141079843044	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	348373	Curb Ramps	Northeast Corner Of Cherokee Drive @ 33.953371346728, - 118.139540255070		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Wiley Burke Avenue - Irvingrove Drive To Muller Street - Irvingrove Drive To Firestone Boulevard Downey, CA 90241	348374	Curb Ramps	Northeast Corner Of Cherokee Drive		Detectable Warning Domes Direction	Provide compliant detectable warnings with domes aligned in the direction of travel.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333396	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333397	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333398	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333399	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333403	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333400	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333401	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333402	Curb Ramps	Southeast Corner @ 33.931633797214, - 118.116513490677	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333404	Curb Ramps	Southeast Median Entrance @ 33.931708349426, - 118.116568475962		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333405	Curb Ramps	Southeast Median Entrance @ 33.931708349426, - 118.116568475962		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333459	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333460	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333461	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333462	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333463	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333464	Curb Ramps	Northeast Corner @ 33.931966499864, - 118.116441071033	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333465	Curb Ramps	Southeast Median Exit Left @ 33.931745069148, - 118.116602003574		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333466	Curb Ramps	Southeast Median Exit Left @ 33.931745069148, - 118.116602003574		Curb Ramp Width	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333467	Curb Ramps	Southeast Median Exit Left @ 33.931745069148, - 118.116602003574		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333468	Curb Ramps	Southeast Median Exit Left @ 33.931745069148, - 118.116602003574	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333469	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333470	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333471	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333472	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333473	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333474	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333475	Curb Ramps	Southwest Corner @ 33.931746181866, - 118.116864860058	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333478	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, - 118.116626143456		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333479	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, - 118.116626143456		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333480	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, - 118.116626143456		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333482	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, - 118.116626143456	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333483	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, - 118.116626143456	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Firestone Boulevard East - Woodruff Avenue & Firestone Boulevard East	333481	Curb Ramps	Southeast Median Exit Right @ 33.931742843711, -118.116626143456	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue & Foster Road - Woodruff Avenue & Foster Road	437094	Curb Ramps	Southeast Corner of Foster Road @ 33.909698147961, -118.116579632		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue & Foster Road - Woodruff Avenue & Foster Road	437095	Curb Ramps	Southwest Corner of Foster Road @ 33.909689243908, -118.116891682148		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue & Foster Road - Woodruff Avenue & Foster Road	437096	Curb Ramps	Southwest Corner of Foster Road @ 33.909689243908, -118.116891682148	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue & Foster Road - Woodruff Avenue & Foster Road	437097	Curb Ramps	Northwest Corner of Foster Road @ 33.909689243908, -118.116891682148		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway	435632	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, -118.116864860058		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway	435633	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, -118.116864860058		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway	435634	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, -118.116864860058		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway	435635	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, -118.116864860058		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435636	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, - 118.116864860058		Appurtenances	Provide a compliant curb ramp free of appurtenances.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435637	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, - 118.116864860058	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435638	Curb Ramps	Northeast Corner of Imperial Highway @ 33.917226192061, - 118.116864860058	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435734	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916952416184, - 118.116878271103	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435735	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916952416184, - 118.116878271103	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435736	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916952416184, - 118.116878271103	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435737	Curb Ramps	Southwest Corner of Imperial Highway @ 33.916952416184, - 118.116878271103	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435738	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058		No Detectable Warnings	Provide compliant detectable warnings to surface.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435739	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058		Curb Ramp Slope	Provide a compliant curb ramp.		6/30/32
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435740	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		6/30/32

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435743	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435741	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435742	Curb Ramps	Northwest Corner of Imperial Highway @ 33.917226192061, - 118.116864860058	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435744	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435745	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435746	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435749	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435747	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Woodruff Avenue & Imperial Highway - Woodruff Avenue & Imperial Highway Downey, CA 90240	435748	Curb Ramps	Southeast Corner of Imperial Highway @ 33.916925706296, - 118.116518855095	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313182	Curb Ramps	Northwest Corner Of Hall Road @ 33.929649794221, - 118.116883635521		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313183	Curb Ramps	Northwest Corner Of Hall Road @ 33.929649794221, - 118.116883635521		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313184	Curb Ramps	Northwest Corner Of Hall Road @ 33.929649794221, - 118.116883635521		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313185	Curb Ramps	Northwest Corner Of Hall Road @ 33.929649794221, - 118.116883635521	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313186	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313187	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313188	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313189	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313190	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313191	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313192	Curb Ramps	Southwest Corner Of Angell Street @ 33.913126139326, - 118.116958737373	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313193	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313194	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313195	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313196	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313197	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313198	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313199	Curb Ramps	Southwest Corner Of Imperial Highway Service Road @ 33.916816640830, - 118.116950690746	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313200	Curb Ramps	Northwest Corner Of Everest Street @ 33.919598879476, - 118.116832673550		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313201	Curb Ramps	Northwest Corner Of Everest Street @ 33.919598879476, - 118.116832673550		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313202	Curb Ramps	Northwest Corner Of Everest Street @ 33.919598879476, - 118.116832673550	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313203	Curb Ramps	Northwest Corner Of Everest Street @ 33.919598879476, - 118.116832673550	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313204	Curb Ramps	Northwest Corner Of Everest Street @ 33.919598879476, - 118.116832673550	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313288	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313289	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313290	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313291	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313293	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313292	Curb Ramps	Southwest Corner Of Hall Road @ 33.929652019713, - 118.116891682148	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313294	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313295	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313296	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313297	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313298	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313299	Curb Ramps	Southwest Corner Of Everest Street @ 33.919463108339, - 118.116843402386	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313300	Curb Ramps	Southwest Corner Of Belcher Street @ 33.911287506556, - 118.116891682148		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313301	Curb Ramps	Southwest Corner Of Belcher Street @ 33.911287506556, - 118.116891682148		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313303	Curb Ramps	Southwest Corner Of Belcher Street @ 33.911287506556, - 118.116891682148	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313302	Curb Ramps	Southwest Corner Of Belcher Street @ 33.911287506556, - 118.116891682148	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313304	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914239093885, - 118.116880953312		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313305	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914239093885, - 118.116880953312		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313306	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914239093885, - 118.116880953312		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313308	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914239093885, - 118.116880953312	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313307	Curb Ramps	Southwest Corner Of Adoree Street @ 33.914239093885, - 118.116880953312	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313309	Curb Ramps	Northwest Corner Of Imperial Highway Service Road @ 33.916916802997, - 118.116870224476	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313310	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313311	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313312	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313314	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865	Top Landing	Top Landing Change in Level	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313315	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313313	Curb Ramps	Northwest Corner Of Belcher Street @ 33.911432194592, - 118.116926550865	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313316	Curb Ramps	Northwest Corner Of Angell Street @ 33.913261920560, - 118.116856813431		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313317	Curb Ramps	Northwest Corner Of Angell Street @ 33.913261920560, - 118.116856813431		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313318	Curb Ramps	Northwest Corner Of Angell Street @ 33.913261920560, - 118.116856813431	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313319	Curb Ramps	Northwest Corner Of Angell Street @ 33.913261920560, - 118.116856813431	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313320	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914383776910, - 118.116950690746	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313321	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914383776910, - 118.116950690746	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313322	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914383776910, - 118.116950690746	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313323	Curb Ramps	Northwest Corner Of Adoree Street @ 33.914383776910, - 118.116950690746	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313431	Curb Ramps	West Side North Of Washburn Road - 1st @ 33.926295911773, - 118.116859495640		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313432	Curb Ramps	West Side North Of Washburn Road - 1st @ 33.926295911773, - 118.116859495640		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313433	Curb Ramps	West Side North Of Washburn Road - 1st @ 33.926295911773, - 118.116859495640		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313434	Curb Ramps	Southwest Corner Of Cecilia Street @ 33.936150208207, - 118.115172386169		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313435	Curb Ramps	Southwest Corner Of Cecilia Street @ 33.936150208207, - 118.115172386169		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313436	Curb Ramps	Southwest Corner Of Cecilia Street @ 33.936150208207, - 118.115172386169	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313437	Curb Ramps	Southwest Corner Of Cecilia Street @ 33.936150208207, - 118.115172386169	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313438	Curb Ramps	Southwest Corner Of Cecilia Street @ 33.936150208207, - 118.115172386169	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313439	Curb Ramps	Northwest Corner Of Cecilia Street @ 33.936308205930, - 118.115083873272	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313440	Curb Ramps	West Side North Of Washburn Road - 2nd @ 33.926471732381, - 118.116864860058		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313441	Curb Ramps	West Side North Of Washburn Road - 2nd @ 33.926471732381, - 118.116864860058		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313442	Curb Ramps	West Side North Of Washburn Road - 2nd @ 33.926471732381, - 118.116864860058	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313443	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313444	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313445	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313446	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313447	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677		Appurtenances	Provide a compliant curb ramp free of appurtenances.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313448	Curb Ramps	West Side North Of Firestone Boulevard - 2nd @ 33.934414439269, - 118.116513490677	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313449	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313450	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313451	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313452	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313456	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313453	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468	Bottom Landing	Bottom Landing Slope	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313454	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313455	Curb Ramps	West Side North Of Firestone Boulevard - 1st @ 33.934418894, - 118.116510808468	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313457	Curb Ramps	Southwest Corner Of Muller Street @ 33.937440885249, - 118.114268481731		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313458	Curb Ramps	Southwest Corner Of Muller Street @ 33.937440885249, - 118.114268481731		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313459	Curb Ramps	Southwest Corner Of Muller Street @ 33.937440885249, - 118.114268481731		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313461	Curb Ramps	Southwest Corner Of Muller Street @ 33.937440885249, - 118.114268481731	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313460	Curb Ramps	Southwest Corner Of Muller Street @ 33.937440885249, - 118.114268481731	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313462	Curb Ramps	Northwest Corner Of Muller Street @ 33.937556600166, - 118.114169239998		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313463	Curb Ramps	Northwest Corner Of Muller Street @ 33.937556600166, - 118.114169239998		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	313464	Curb Ramps	Northwest Corner Of Muller Street @ 33.937556600166, - 118.114169239998	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314437	Curb Ramps	Northeast Corner Of Fostoria Street @ 33.934939624373, - 118.115834891796		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314438	Curb Ramps	Northeast Corner Of Fostoria Street @ 33.934939624373, - 118.115834891796		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314439	Curb Ramps	Northeast Corner Of Fostoria Street @ 33.934939624373, - 118.115834891796	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314440	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.936087899165, - 118.115008771420		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314441	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.936087899165, - 118.115008771420		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314442	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.936087899165, - 118.115008771420		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314443	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.936087899165, - 118.115008771420	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314444	Curb Ramps	Southeast Corner Of Cecilia Street @ 33.936087899165, - 118.115008771420	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314445	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314446	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314447	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314448	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314449	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314450	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314451	Curb Ramps	Northeast Corner Of Muller Street @ 33.937494292154, - 118.114021718502	Top Landing	Top Landing Change in Level - Curb Ramps	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314452	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314453	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185		No Contrasting Finish	Provide the surface on the curb ramp that contrasts with the adjacent sidewalk.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314454	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314455	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314456	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314459	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314460	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314457	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314458	Curb Ramps	Southeast Corner Of Fostoria Street @ 33.934850610177, - 118.115891218185	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314461	Curb Ramps	Southeast Corner Of Farm Street @ 33.940335936210, - 118.113031983376		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314462	Curb Ramps	Southeast Corner Of Farm Street @ 33.940335936210, - 118.113031983376	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314463	Curb Ramps	Southeast Corner Of Farm Street @ 33.940335936210, - 118.113031983376	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314464	Curb Ramps	Northwest Corner Of Gotham Street @ 33.939795207804, - 118.113627433777		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314465	Curb Ramps	Northwest Corner Of Gotham Street @ 33.939795207804, - 118.113627433777		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314466	Curb Ramps	Northwest Corner Of Gotham Street @ 33.939795207804, - 118.113627433777		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314467	Curb Ramps	Northwest Corner Of Gotham Street @ 33.939795207804, - 118.113627433777	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314468	Curb Ramps	Northwest Corner Of Gotham Street @ 33.939795207804, - 118.113627433777	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314469	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.936212517203, - 118.114914894104		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314470	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.936212517203, - 118.114914894104		Not Wholly Contained Within The Marked Crossing	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314471	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.936212517203, - 118.114914894104		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314472	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.936212517203, - 118.114914894104	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314473	Curb Ramps	Northeast Corner Of Cecilia Street @ 33.936212517203, - 118.114914894104	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314474	Curb Ramps	Southeast Corner Of Buell Street @ 33.936924616780, - 118.114402592182		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314475	Curb Ramps	Southeast Corner Of Buell Street @ 33.936924616780, - 118.114402592182		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314476	Curb Ramps	Southeast Corner Of Buell Street @ 33.936924616780, - 118.114402592182		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314477	Curb Ramps	Northeast Corner Of Bigby Street @ 33.941161486124, - 118.112415075302		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314478	Curb Ramps	Northeast Corner Of Bigby Street @ 33.941161486124, - 118.112415075302		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314481	Curb Ramps	Northeast Corner Of Bigby Street @ 33.941161486124, - 118.112415075302	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314479	Curb Ramps	Northeast Corner Of Bigby Street @ 33.941161486124, - 118.112415075302	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314480	Curb Ramps	Northeast Corner Of Bigby Street @ 33.941161486124, - 118.112415075302	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314482	Curb Ramps	Southeast Corner Of Bigby Street @ 33.941103631135, - 118.112460672855		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314483	Curb Ramps	Southeast Corner Of Bigby Street @ 33.941103631135, - 118.112460672855		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314484	Curb Ramps	Southeast Corner Of Bigby Street @ 33.941103631135, - 118.112460672855		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314485	Curb Ramps	Southeast Corner Of Bigby Street @ 33.941103631135, - 118.112460672855	Bottom Landing	Bottom Landing Of Diagonal Curb Ramp - Clear Space	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314486	Curb Ramps	Southeast Corner Of Bigby Street @ 33.941103631135, - 118.112460672855	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314487	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314488	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314489	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314490	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314491	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021	Bottom Landing	Bottom Landing Change in Level - Curb Ramps	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314492	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314493	Curb Ramps	Northeast Corner Of Nance Street @ 33.930631230530, - 118.116556406021	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314555	Curb Ramps	Southeast Corner Of Nance Street @ 33.930399781717, - 118.116521537304		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314556	Curb Ramps	Southeast Corner Of Nance Street @ 33.930399781717, - 118.116521537304		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314557	Curb Ramps	Southeast Corner Of Nance Street @ 33.930399781717, - 118.116521537304		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314558	Curb Ramps	Southeast Corner Of Nance Street @ 33.930399781717, - 118.116521537304	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314559	Curb Ramps	Southeast Corner Of Nace Street @ 33.930399781717, - 118.116521537304	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314560	Curb Ramps	Northwest Corner Of Buell Street @ 33.937064810683, - 118.114327490330		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314561	Curb Ramps	Northwest Corner Of Buell Street @ 33.937064810683, - 118.114327490330		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314562	Curb Ramps	Northwest Corner Of Buell Street @ 33.937064810683, - 118.114327490330	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314563	Curb Ramps	Northwest Corner Of Buell Street @ 33.937064810683, - 118.114327490330	Top Landing	Top Landing Clear Length - Landings	Provide a level top landing with enough clear length.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314564	Curb Ramps	Northeast Corner Of Gotham Street @ 33.939739577115, - 118.113471865654		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314565	Curb Ramps	Northeast Corner Of Gotham Street @ 33.939739577115, - 118.113471865654		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314566	Curb Ramps	Northeast Corner Of Gotham Street @ 33.939739577115, - 118.113471865654		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314567	Curb Ramps	Northeast Corner Of Gotham Street @ 33.939739577115, - 118.113471865654	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314568	Curb Ramps	Northeast Corner Of Gotham Street @ 33.939739577115, - 118.113471865654	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314569	Curb Ramps	Northeast Corner Of Farm Street @ 33.940451647193, - 118.112943470478		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314570	Curb Ramps	Northeast Corner Of Farm Street @ 33.940451647193, - 118.112943470478	Bottom Landing	Bottom Landing Slope	Ensure the bottom landing slope is compliant and provides a smooth transition.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314571	Curb Ramps	Northeast Corner Of Farm Street @ 33.940451647193, - 118.112943470478	Bottom Landing	Landing Accumulates Water - Wet Conditions	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314572	Curb Ramps	Northeast Corner Of Farm Street @ 33.940451647193, - 118.112943470478	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	



Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	314573	Curb Ramps	Northeast Corner Of Farm Street @ 33.940451647193, - 118.112943470478	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315670	Curb Ramps	Northeast Corner Of Angell Street @ 33.913306438951, - 118.116497397423		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315671	Curb Ramps	Northeast Corner Of Angell Street @ 33.913306438951, - 118.116497397423		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315672	Curb Ramps	Northeast Corner Of Angell Street @ 33.913306438951, - 118.116497397423		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315674	Curb Ramps	Northeast Corner Of Angell Street @ 33.913306438951, - 118.116497397423	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315673	Curb Ramps	Northeast Corner Of Angell Street @ 33.913306438951, - 118.116497397423	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315675	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316		No Detectable Warnings	Provide compliant detectable warnings to surface.	6/30/32	

Facility	Record Number	Category	Description	Sub Description	Item	Recommendation	12/31/17	Actual Completion Date
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315676	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316		Curb Ramp Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315677	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316		Curb Ramp - Cross Slope	Provide a compliant curb ramp.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315678	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316		Side Flare Slope	Provide curb ramp side flares with a compliant slope.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315679	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316	Bottom Landing	Bottom Landing Change in Level	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	6/30/32	
Woodruff Avenue - Foster Road to Florence Avenue - Woodruff Avenue - Foster Road to Firestone Boulevard Downey, CA 90424	315680	Curb Ramps	Southeast Corner Of Angell Street @ 33.913177335554, - 118.116406202316	Top Landing	Top Landing Slope	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	6/30/32	
Yankey Street - Sarabeth Street To Rives Avenue - Sarabeth Street To Rives Avenue Downey, CA 90242	407230	Curb Ramps	Southwest Corner Of Rives Avenue @ 33.933661149048, - 118.150762617588		Side Flare Slope	Provide curb ramp side flares with a compliant slope.		Projected Completion Date