

City of Downey - Projected Completion Dates (Rev. 03/23/2018)

No.	Public Right of Way Location	No. of Findings:	Estimated Cost:	Anticipated Construction in Fiscal Year	Projected Completion
9	Telegraph Road - Songfest Avenue to Passons Boulevard	43	\$ 110,000.00	FY 18/19	6/30/2019
10	Telegraph Road - Serapis Avenue to Manzanar Avenue	27	\$ 70,000.00	FY 18/19	6/30/2019
13	Lakewood Boulevard - Cherokee Road to I-5 Freeway	89	\$ 190,000.00	FY 18/19 & 19/20	6/30/2020
11	Lakewood Boulevard - Columbia Way to Stewart and Gray Road	69	\$ 160,000.00	FY 19/20	6/30/2021
12	Lakewood Boulevard - Bellflower Boulevard to Cecilia Street	51	\$ 120,000.00	FY 19/20 & 20/21	6/30/2020
4	Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue	42	\$ 100,000.00	FY 20/21	6/30/2021
6	Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road	66	\$ 160,000.00	FY 20/21	6/30/2021
5	Florence Avenue - Western Avenue to Rives Avenue	105	\$ 240,000.00	FY 21/22	6/30/2022
1b	Imperial Highway - Smallwood Avenue to Brock Avenue	63	\$ 140,000.00	FY 21/22 & 22/23	6/30/2023
1	Imperial Highway - Columbia Way to Brookshire Avenue	107	\$ 200,000.00	FY 22/23	6/30/2023
3a	Firestone Boulevard - Stewart and Gray Road to East City Limit	10	\$ 40,000.00	FY 22/23	6/30/2023
2	Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard	46	\$ 110,000.00	FY 23/24	6/30/2024
17	Paramount Boulevard - Irwingrove Drive to Lubec Street	179	\$ 380,000.00	FY 23/24 & 24/25	6/30/2025
18	Gardendale Street - Brookshire Avenue to Garfield Avenue	221	\$ 510,000.00	FY 24/25, 25/26 & 26/27	6/30/2027
14	Downey Avenue - I-5 Freeway to Firestone Boulevard	258	\$ 490,000.00	FY 26/27 & 27/28	6/30/2028
15	Paramount Boulevard - Conrad Street to Stewart and Gray Road	84	\$ 210,000.00	FY 28/29	6/30/2029
16	Paramount Boulevard - Phlox Street to 5th Street	429	\$ 660,000.00	FY 28/29, 29/30 & 30/31	6/30/2031
3b	Firestone Boulevard - West City Limit to Stewart and Gray Road	450	\$ 910,000.00	FY 31/32, 32/33 & 33/34	6/30/2034
7	Florence Avenue - Perry Road to Tolar Avenue (City of Bell Gardens)	0	\$ -	n/a	n/a
8	Florence Avenue - Ira Avenue to West City Limit (City of Bell Gardens)	0	\$ -	n/a	n/a
		1,784	\$ 4,800,000.00		

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481979	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481983	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482043	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481977	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482040	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482052	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481978	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482042	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2019

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482053	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481984	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481980	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482044	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482041	Curb Ramps	The width of the curb ramp is less than required.	Provide a compliant curb ramp.	At least 48.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482007	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482009	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482011	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482013	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482017	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482021	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482023	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482027	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482030	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482035	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482039	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481987	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481990	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481992	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481994	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481986	Sidewalks	Sidewalk surface is not slip resistant.	Make sure that the sidewalk surface is firm, stable and slip resistant.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482024	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482006	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482008	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482010	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482012	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482016	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482020	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482022	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482025	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482026	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482029	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019

9. Telegraph Road - Songfest Avenue to Passons Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482034	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482038	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	481999	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2019

10. Telegraph Road - Serapis Avenue to Manzanar Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482070	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482072	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482077	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482079	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482083	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482086	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482088	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2019

10. Telegraph Road - Serapis Avenue to Manzanar Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - Paramount Boulevard to Lakewood Boulevard - South Side Only - Paramount Boulevard to Lakewood Boulevard Downey, CA 92040	480611	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482065	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482068	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482061	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482064	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482092	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2019
Telegraph Road - Paramount Boulevard to Lakewood Boulevard - South Side Only - Paramount Boulevard to Lakewood Boulevard Downey, CA 92040	480619	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019

10. Telegraph Road - Serapis Avenue to Manzanar Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - Paramount Boulevard to Lakewood Boulevard - South Side Only - Paramount Boulevard to Lakewood Boulevard Downey, CA 92040	480627	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482069	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482071	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482075	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482076	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482078	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard Downey, CA 90242	482082	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019

10. Telegraph Road - Serapis Avenue to Manzanar Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482084	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482085	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482087	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482089	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482060	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2019
Telegraph Road - City of Santa Fe Springs to Lakewood Boulevard - City of Santa Fe Springs to Lakewood Boulevard - Downey, CA 90242	482063	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2019

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480005	Curb Ramps	Curb ramp run surface has a grade break.	Provide a compliant curb ramp.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480006	Curb Ramps	Curb ramp run surface has a grade break.	Provide a compliant curb ramp.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480004	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480007	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479962	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479994	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480280	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480289	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480318	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480328	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480339	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479928	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479930	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479931	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479939	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479942	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479944	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480256	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480272	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480275	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480301	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480303	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480307	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480315	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480258	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480264	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480266	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480271	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480274	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480314	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480255	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480300	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480295	Sidewalks	Sidewalk surface is not slip resistant.	Make sure that the sidewalk surface is firm, stable and slip resistant.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480276	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue - Downey, CA 92040	479921	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue - Downey, CA 92040	479924	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479941	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479977	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480257	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480261	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480263	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480267	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480277	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480312	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479951	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479952	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479955	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479961	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479963	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479984	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479985	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479993	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479997	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479998	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480000	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	480001	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480279	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480281	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480282	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480283	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480284	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480288	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480292	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480293	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480316	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480317	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480321	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480322	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480326	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480327	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480329	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480330	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480331	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480332	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480333	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480334	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480335	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480336	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480337	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road - Downey, CA 92040	480338	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue - Downey, CA 92040	479979	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020

13. Lakewood Boulevard - Cherokee Road to I-5 Freeway

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479943	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479969	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479978	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480262	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480268	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480309	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480310	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Florence Avenue to Telegraph Road - Florence Avenue to Telegraph Road Downey, CA 92040	480306	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation not exceed a .5 beveled inch.	Up to 0.50 inches	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327032	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327037	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327122	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327140	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327029	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327048	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327095	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327114	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327115	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327125	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327132	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327133	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327027	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327028	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327045	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327047	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327093	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327137	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327031	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327094	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327182	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327117	Curb Ramps	The slope at the bottom landing is greater than allowed.	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327127	Curb Ramps	The slope at the bottom landing is greater than allowed.	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327030	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327038	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327046	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327049	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327128	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327129	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327096	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327138	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327131	Curb Ramps	The width of the curb ramp is less than required.	Provide a compliant curb ramp.	At least 48.00 inches	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327116	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327126	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327139	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327042	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327043	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327044	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327153	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327155	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327157	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327161	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327165	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327167	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327170	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327172	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327174	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327177	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327179	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327181	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327039	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327176	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327041	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327152	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327154	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327156	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327160	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327164	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327166	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327168	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327169	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327171	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327173	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327175	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020

11. Lakewood Boulevard - Columbia Way to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327178	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327180	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327040	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327097	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020
Lakewood Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	327148	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2020

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482047	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482046	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482048	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481869	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480858	Path of Travel	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481870	Path of Travel	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479959	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481905	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479982	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479983	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479974	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479981	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480865	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479914	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479919	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479966	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479967	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479918	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480862	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481878	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479945	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479949	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481885	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481916	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479973	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481883	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479960	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479958	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479953	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479999	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479987	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479957	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479991	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479965	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481904	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481911	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	480894	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481910	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479976	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479925	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479936	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479933	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479923	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479938	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479929	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479926	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479927	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Firestone Boulevard to Florence Avenue - Firestone Boulevard to Florence Avenue Downey, CA 92040	479947	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481889	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	481886	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021

12. Lakewood Boulevard - Bellflower Boulevard to Cecilia Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Lakewood Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	483200	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350994	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351780	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351784	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350993	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	355366	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349210	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351652	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351752	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351783	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351653	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351753	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349211	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350995	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351785	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351654	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351754	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351655	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351656	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351786	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351779	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350989	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350991	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351744	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351749	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351702	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351684	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351687	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349261	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349273	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349276	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349277	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350988	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350990	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350992	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351711	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351728	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021

4. Florence Avenue - Vultee/Arrington Avenue to Birchdale Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351740	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351743	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351748	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349256	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	349252	Sidewalks	There is a curb on the designated path of travel.	Provide a compliant curb ramp.	See Recommendation	6/30/2021
Florence Avenue - Lakewood Boulevard to Woodruff Avenue - Florence Avenue - Lakewood Boulevard to Woodruff Avenue Downey, CA 90424	350987	Sidewalks	There is a curb on the designated path of travel.	Provide a compliant curb ramp.	See Recommendation	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482876	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482878	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482887	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482892	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482911	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482921	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482964	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482966	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482971	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482973	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482977	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482981	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482986	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482996	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483001	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482820	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482814	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482816	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482818	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482823	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482824	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482930	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482936	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482937	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482822	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482875	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482877	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482886	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482891	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482910	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482920	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482962	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482963	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482965	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482969	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482970	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482972	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482976	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482980	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482985	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482995	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482999	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483000	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482835	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482829	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482842	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482844	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482845	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482848	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482859	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482864	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482867	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482945	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482946	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482947	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482953	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482956	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482957	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482960	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482961	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482846	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482849	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482853	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021

6. Florence Avenue - West City Limit (Susan Avenue) to Pomeroy Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482854	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482855	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2021
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482811	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2021

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351763	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351769	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351782	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482924	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483005	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483015	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351760	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351766	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351781	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482923	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483004	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483007	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483014	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351761	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351767	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482925	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483006	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483008	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483016	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351762	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351768	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351764	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351770	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351765	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351771	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351710	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351730	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351751	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482880	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482882	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482885	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482896	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482898	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482904	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482906	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482913	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482915	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482968	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482975	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482979	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482983	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482988	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482990	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482992	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482994	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482998	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483003	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482928	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482851	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482954	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351688	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482815	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482819	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482821	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482826	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482927	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482929	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482932	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482938	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482939	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482909	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351709	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351729	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351750	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482879	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482881	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482884	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482888	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482895	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482897	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482903	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482905	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482912	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482914	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482967	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482974	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482978	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482982	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482987	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482989	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482991	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482993	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482997	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	483002	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2022
Florence Avenue - Lakewood Boulevard To Paramount Boulevard - Lakewood Boulevard To Paramount Boulevard Downey, CA 90241	351701	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482830	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482833	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482837	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482838	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482839	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482840	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482852	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482858	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482862	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482871	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482943	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482949	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482955	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482959	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482834	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482847	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482950	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482952	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482958	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2022

5. Florence Avenue - Western Avenue to Rives Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Florence Avenue - Paramount Boulevard to Sherry Avenue - Paramount Boulevard to Sherry Avenue Downey, CA 90242	482926	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2022

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324123	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324135	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324136	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324140	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324143	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324144	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324149	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324150	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324160	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324161	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324629	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324630	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324631	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324632	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324644	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324645	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324646	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324647	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324662	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324687	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327904	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327905	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327906	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327907	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327908	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327909	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327925	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327926	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327927	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327928	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327929	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327930	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327935	Curb Ramps	The slope at the bottom landing is greater than allowed.	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	Up to 2.08 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327954	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327958	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327959	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327960	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327961	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327962	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327973	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327974	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327975	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327976	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327977	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327978	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327979	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327980	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327981	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327982	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327983	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327984	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327985	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327987	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	327988	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330842	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330843	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023

1b. Imperial Highway - Smallwood Avenue to Brock Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330852	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330853	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330867	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330868	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330876	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330877	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway Paramount Boulevard To Old River School Road - Paramount Boulevard To Old River School Road Downey, CA 90242	330878	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324083	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324129	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324655	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330839	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324078	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324082	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324086	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324107	Curb Ramps	Northwest Corner Of Bellder Drive @ 33.919512075004, - 118.142911791801	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324132	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324653	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324665	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330841	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330846	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324076	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324651	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324663	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327552	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327599	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330836	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330844	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324077	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324081	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324085	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324106	Curb Ramps	Northwest Corner Of Bellder Drive @ 33.919512075004, - 118.142911791801	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324131	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324652	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324664	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327553	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327600	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330837	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330840	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330845	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324080	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324084	Curb Ramps	Northeast Corner Of Bellder Drive @ 33.919423044683, - 118.142772316933	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324088	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324111	Curb Ramps	Southwest Corner Of Barlin Avenue @ 33.918167707263, - 118.141146898270	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324133	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324667	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327601	Curb Ramps	Southwest Corner Of Glenshire Road @ 33.916912351348, - 118.137177228928	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324079	Curb Ramps	Southeast Corner Of Barlin Avenue @ 33.918060869182, - 118.140932321548	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324087	Curb Ramps	Northwest Corner Of Lakewood Boulevard @ 33.917166094992, - 118.137885332108	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324654	Curb Ramps	Southwest Corner Of Brookshire Avenue @ 33.919761359406, - 118.144086599350	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324666	Curb Ramps	Southeast Corner Of Brookshire Avenue @ 33.919574396173, - 118.143796920776	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327554	Curb Ramps	Southeast Corner Of Glenshire Road @ 33.916894544748, - 118.136941194534	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330838	Curb Ramps	Southeast Corner Of Vendura Avenue @ 33.918710798772, - 118.142123222351	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330847	Curb Ramps	Southwest Corner Of Vendura Avenue @ 33.918835442236, - 118.142305612564	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324134	Curb Ramps	Southwest Corner Of Lakewood Boulevard @ 33.916689768582, - 118.138260841370	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324075	Sidewalks	Alley West Of Barlin Avenue @ 33.918541639493, - 118.141822814941	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327671	Sidewalks	Lakewood Boulevard North Crossing @ 33.917206159709, - 118.137531280518	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324065	Sidewalks	Driveway East Of Barlin Avenue @ 33.918621767614, - 118.141994476318	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324067	Sidewalks	Driveway West Of Barlin Avenue @ 33.918541639493, - 118.141790628433	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324069	Sidewalks	Driveway West Of Barlin Avenue @ 33.918310157830, - 118.141393661499	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324071	Sidewalks	Driveway West Of Lakewood Boulevard @ 33.916974674418, - 118.138968944550	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324073	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917428741127, - 118.139902353287	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324146	Sidewalks	Driveway East Of Brookshire Avenue @ 33.919770262407, - 118.143394589424	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324152	Sidewalks	Driveway East Of Bellder Drive @ 33.917339708630, - 118.138850927353	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324156	Sidewalks	Driveway East Of Bellder Drive @ 33.917161643356, - 118.138169646263	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324158	Sidewalks	Driveway East Of Bellder Drive @ 33.919307305128, - 118.142530918121	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324163	Sidewalks	Driveway East Of Bellder Drive @ 33.918403640885, - 118.140878677368	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327575	Sidewalks	Driveway West Of Ardis Avenue @ 33.916956867832, - 118.133400678635	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327577	Sidewalks	Driveway West Of Ardis Avenue @ 33.916867834841, - 118.133851289749	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327592	Sidewalks	Driveway West Of Columbia Way @ 33.916867834841, - 118.136050701141	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327595	Sidewalks	Driveway West Of Glenshire Road @ 33.916885641447, - 118.137230873108	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327598	Sidewalks	Driveway West Of Columbia Way @ 33.916876738145, - 118.134924173355	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327627	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917152740083, - 118.135621547699	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327629	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917072610580, - 118.136973381042	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327641	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917161643356, - 118.135846853256	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327643	Sidewalks	Driveway East Of Rose Avenue @ 33.917170546629, - 118.133604526520	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327647	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917152740083, - 118.136554956436	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327662	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917179449900, - 118.135213851929	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327673	Sidewalks	Driveway East Of Rose Avenue @ 33.917188353171, - 118.13336305618	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327615	Sidewalks	Tree East Of Columbia Way @ 33.917117126980, - 118.133615255356	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327569	Sidewalks	Sidewalk West Of Ardis Avenue @ 33.916912351348, - 118.133229017258	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327604	Sidewalks	Sidewalk East Of Columbia Way @ 33.917161643356, - 118.133797645569	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324074	Sidewalks	Alley West Of Barlin Avenue @ 33.918541639493, - 118.141822814941	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327593	Sidewalks	Glenshire Road South Crossing @ 33.916930157944, - 118.137037754059	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324064	Sidewalks	Driveway East Of Barlin Avenue @ 33.918621767614, - 118.141994476318	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324066	Sidewalks	Driveway West Of Barlin Avenue @ 33.918541639493, - 118.141790628433	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324068	Sidewalks	Driveway West Of Barlin Avenue @ 33.918310157830, - 118.141393661499	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324070	Sidewalks	Driveway West Of Lakewood Boulevard @ 33.916974674418, - 118.138968944550	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324072	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917428741127, - 118.139902353287	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324145	Sidewalks	Driveway East Of Brookshire Avenue @ 33.919770262407, - 118.143394589424	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324151	Sidewalks	Driveway East Of Bellder Drive @ 33.917339708630, - 118.138850927353	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324155	Sidewalks	Driveway East Of Bellder Drive @ 33.917161643356, - 118.138169646263	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324157	Sidewalks	Driveway East Of Bellder Drive @ 33.919307305128, - 118.142530918121	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324162	Sidewalks	Driveway East Of Bellder Drive @ 33.918403640885, - 118.140878677368	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327574	Sidewalks	Driveway West Of Ardis Avenue @ 33.916956867832, - 118.133400678635	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327576	Sidewalks	Driveway West Of Ardis Avenue @ 33.916867834841, - 118.133851289749	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327585	Sidewalks	Driveway West Of Ardis Avenue @ 33.916912351348, - 118.133229017258	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327591	Sidewalks	Driveway West Of Columbia Way @ 33.916867834841, - 118.136050701141	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327594	Sidewalks	Driveway West Of Glenshire Road @ 33.916885641447, - 118.137230873108	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327596	Sidewalks	Driveway West Of Columbia Way @ 33.916903448049, - 118.134591579437	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327597	Sidewalks	Driveway West Of Columbia Way @ 33.916876738145, - 118.134924173355	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327626	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917152740083, - 118.135621547699	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327628	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917072610580, - 118.136973381042	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327640	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917161643356, - 118.135846853256	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327642	Sidewalks	Driveway East Of Rose Avenue @ 33.917170546629, - 118.133604526520	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327646	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917152740083, - 118.136554956436	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327661	Sidewalks	Driveway East Of Lakewood Boulevard @ 33.917179449900, - 118.135213851929	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327672	Sidewalks	Driveway East Of Rose Avenue @ 33.917188353171, - 118.133336305618	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324137	Sidewalks	Change In Level East Of Dolan Avenue @ 33.920095221302, - 118.143990039825	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023

1. Imperial Highway - Columbia Way to Brookshire Avenue

Facility	Record Number	Category	Description	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324138	Sidewalks	Change In Level East Of Bellder Drive @ 33.919080277082, - 118.142144680023	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	324625	Sidewalks	Change In Level West Of Brookshire Avenue @ 33.919917161787, - 118.144252896309	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327609	Sidewalks	Change In Level East Of Rose Avenue @ 33.917143836808, - 118.133786916733	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327608	Sidewalks	Change In Level East Of Lakewood Boulevard @ 33.917161643356, - 118.136276006699	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023
Imperial Highway - Lakewood Boulevard To Woodruff Avenue - Lakewood Boulevard To Woodruff Avenue Downey, CA 90242	327602	Sidewalks	North Side @ 33.917223966244, - 118.137402534485	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2023
Imperial Highway - Paramount Boulevard To Lakewood Boulevard - Paramount Boulevard To Lakewood Boulevard Downey, CA 90242	330835	Sidewalks	South Side @ 33.916939061241, - 118.138529062271	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2023

3a. Firestone Boulevard - Stewart and Gray Road to East City Limit

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332501	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332509	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332510	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332503	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332502	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332508	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332504	Sidewalks	Sidewalk drop off has no guardrail.	Provide a compliant guardrail at the drop off.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332506	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332507	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2023
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332505	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2023

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479463	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479627	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479632	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479636	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479638	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479630	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479634	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479635	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479637	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479464	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479475	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479484	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479487	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479629	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479631	Curb Ramps	The width of the curb ramp is less than required.	Provide a compliant curb ramp.	At least 48.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479465	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479476	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479488	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479489	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479633	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479505	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479473	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479499	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479501	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479468	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479491	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479492	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479493	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479494	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479495	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479496	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479497	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479467	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479469	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479500	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479506	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479470	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479471	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479498	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479502	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479503	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479504	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024

2. Stewart & Gray Road - Bellflower Boulevard (Corrigan Avenue) to Lakewood Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479640	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479641	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479628	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2024
Stewart & Gray Road - Bellflower Boulevard to Lakewood Boulevard - Bellflower Boulevard to Lakewood Boulevard Downey, CA 90242	479639	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2024

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351887	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351890	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351894	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351897	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351898	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351902	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351905	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351907	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351909	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351910	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351913	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351914	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351915	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351916	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351917	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351918	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351919	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351920	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351921	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351922	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351923	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351924	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353208	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353209	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353210	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353211	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353212	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353213	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353214	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353215	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353216	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353217	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353218	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353219	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353220	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353221	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353222	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353223	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353224	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353225	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353226	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353227	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353228	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353229	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353230	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353231	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353232	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353233	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353234	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353235	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353236	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353237	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353238	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353239	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353240	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353241	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353242	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353243	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353244	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353245	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353246	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353247	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353248	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353249	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353250	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353251	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353252	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353253	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353254	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353255	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353256	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353257	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353258	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353259	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353260	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353261	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353262	Intersections	Push button distance from curb is not compliant.	Provide a compliant push button.	17.00 - 120.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353263	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353264	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353265	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353266	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353267	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353268	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353269	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353270	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353271	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353272	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353273	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353274	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353275	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353276	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353277	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353278	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353279	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353280	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353281	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353282	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353283	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353284	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353285	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353286	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353287	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353288	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353289	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353290	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353291	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353292	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353293	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353294	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353295	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353296	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353297	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353298	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353299	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353300	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353301	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353302	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353303	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353304	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353305	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353306	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353307	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353308	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353309	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353310	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353311	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353312	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353313	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467177	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467178	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467179	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467180	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467181	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467182	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467183	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467184	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467185	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467186	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467187	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467188	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467189	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467190	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467191	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467192	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467193	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467194	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467195	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467197	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467198	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467199	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467200	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467201	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467202	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467203	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467204	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467205	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467206	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467207	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467208	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467209	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467210	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467211	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467212	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467213	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467214	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467215	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467216	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467217	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467218	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467219	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467220	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025

17. Paramount Boulevard - Irwingrove Drive to Lubec Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467221	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467222	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467223	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467224	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467225	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467226	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467380	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2025
Paramount Boulevard - Lubec Street to Florence Avenue - Lubec Street to Florence Avenue Downey, CA 90242	467381	Sidewalks	Turn area is not level.	Make sure that the turn area is level.	See Recommendation	6/30/2025

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349933	Curb Ramps	Depth of detectable warnings is not compliant.	Provide compliant detectable warnings.	At least 36.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346238	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347137	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347141	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347146	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349934	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350017	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347138	Curb Ramps	The curb ramp landing accumulates water.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347150	Curb Ramps	The curb ramp landing accumulates water.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347142	Curb Ramps	The overlayment causes a noncompliant change in level.	Ensure the change in elevation is within the recommended height.	0.25 - 0.50 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347135	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347145	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347132	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347134	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347139	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347147	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347151	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349932	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350018	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347131	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347149	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346239	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347133	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347140	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347148	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347136	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349935	Intersections	Detectable warning width at median entrance is not compliant.	Provide compliant detectable warnings at the median.	At least 71.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349936	Intersections	Detectable warning width at median exit is not compliant.	Provide compliant detectable warnings at the median.	At least 71.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349947	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349959	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349971	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349984	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349996	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350009	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349940	Intersections	Intersection walking surface slope is not compliant.	Repave the walking surface with recommended slope.	Up to 5.00 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349951	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349963	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349975	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349988	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350000	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350013	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349946	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349958	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349970	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349983	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349995	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350008	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349952	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349964	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349976	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349989	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350001	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350014	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349944	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349968	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349981	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349942	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349956	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349979	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349992	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350005	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349943	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349967	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349980	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350006	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349957	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350007	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349955	Intersections	Push button is not located at least 10 feet from other accessible pedestrian signals.	Push button must be located at least 10 feet from other accessible pedestrian signals.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350004	Intersections	Push button is not located at least 10 feet from other accessible pedestrian signals.	Push button must be located at least 10 feet from other accessible pedestrian signals.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349954	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349966	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349978	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349991	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350003	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350016	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349945	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349969	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349982	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349994	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349949	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349961	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349973	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349986	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349998	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350011	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349950	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349962	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349974	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349987	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349999	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350012	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349948	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349960	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349972	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349985	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349997	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350010	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349953	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349965	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349977	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349990	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350002	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	350015	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349993	Intersections	There is not enough clear ground space at the push button.	Provide compliant clear ground space at the push button.	At least 32.00 inches	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349937	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349938	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349939	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2027
Gardendale Street & Brookshire Avenue/N Somerset Ranch Road - Gardendale Street & Brookshire Avenue/N Somerset Ranch Road Downey, CA 90242	349941	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346170	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346173	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346215	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346218	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346221	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346224	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346230	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346234	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346237	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347111	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347115	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347118	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347124	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347127	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347128	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347063	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347070	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347081	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347098	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347100	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347103	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347106	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347107	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347108	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346158	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346159	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346160	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346161	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346178	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346181	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346186	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346193	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346194	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347055	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347056	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347057	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347058	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347059	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347061	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347062	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347065	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347066	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347075	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347077	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347078	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347079	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347080	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347084	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347086	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347087	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347091	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347092	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347093	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347071	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347072	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347074	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347076	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347085	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347090	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347060	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347073	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346162	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346163	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346164	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346165	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346166	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346167	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346168	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346195	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346199	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346200	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346211	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347094	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347099	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347102	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346214	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346217	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346220	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346223	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346229	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346233	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346236	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347113	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347123	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347126	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346231	Sidewalks	Surface is not firm, stable or slip resistant.	Provide compliant surface at vehicular traffic.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347095	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346169	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346171	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346172	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346213	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346216	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346219	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346222	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346228	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346232	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346235	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347110	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347112	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347114	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347116	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347117	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347119	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347120	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347121	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347122	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347125	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347129	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027

18. Gardendale Street - Brookshire Avenue to Garfield Avenue

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347130	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346196	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	346204	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347104	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2027
Gardendale Street - City Limit To Hanwell Avenue - City Limit To Hanwell Avenue Lawewood Boulevard To Downey Avenue Downey, CA 90242	347105	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2027

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348130	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348140	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348185	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348303	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348307	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348311	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348313	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348316	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348345	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348347	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348351	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348125	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348131	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348136	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348184	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348295	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348297	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348300	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348305	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348308	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348314	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348318	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348321	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348324	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348328	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348341	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348348	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348350	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348352	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348126	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348137	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348296	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348298	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348306	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348309	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348315	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348319	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348322	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348325	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348329	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348332	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348337	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348342	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348349	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348127	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348132	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348138	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348301	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348343	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348330	Curb Ramps	The slope at the bottom landing is greater than allowed.	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	Up to 2.08 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348334	Curb Ramps	The slope at the bottom landing is greater than allowed.	Provide a compliant bottom landing that does not exceed the maximum slope requirements.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347328	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348299	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348312	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348317	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348323	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348340	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348128	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348133	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348139	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348302	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348344	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348134	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348141	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348331	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348333	Curb Ramps	The width of the curb ramp is less than required.	Provide a compliant curb ramp.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348129	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348310	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348326	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348335	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348339	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348135	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348142	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348304	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348320	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348336	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348346	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348327	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348338	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348195	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348208	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348221	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348233	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348246	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348258	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348270	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348281	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348200	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348213	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348225	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348238	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348250	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348262	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348273	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348287	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348186	Intersections	Intersection walking surface slope is not compliant.	Repave the walking surface with recommended slope.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348193	Intersections	Intersection walking surface slope is not compliant.	Repave the walking surface with recommended slope.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348204	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348217	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348229	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348242	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348254	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348266	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348277	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348291	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348199	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348212	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348224	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348237	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348249	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348261	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348272	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348286	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348205	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348218	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348230	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348243	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348255	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348267	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348278	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348292	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348198	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348211	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348236	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348196	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348209	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348222	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348234	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348247	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348259	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348271	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348282	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348197	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348210	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348223	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348235	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348248	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348283	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348284	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348207	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348220	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348232	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348245	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348257	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348269	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348280	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348294	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348260	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348285	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348202	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348215	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348227	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348240	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348252	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348264	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348275	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348289	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348188	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348190	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348192	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348203	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348216	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348228	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348241	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348253	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348265	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348276	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348290	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348201	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348214	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348226	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348239	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348251	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348263	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348274	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348288	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348206	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348219	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348231	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348244	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348256	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348268	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348279	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348293	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348187	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348189	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348191	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348194	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347332	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348118	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348120	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348174	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348177	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348180	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348182	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348101	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348113	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348116	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348160	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347330	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348110	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348115	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348100	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348102	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348103	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348104	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348105	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348106	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348107	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348108	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348143	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348145	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348146	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348147	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348148	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348149	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348150	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348151	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348152	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348153	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348154	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348155	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348144	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348158	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348168	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348169	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348123	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347331	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348117	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348119	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348121	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348122	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348124	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348172	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348173	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348175	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348176	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348178	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348179	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348181	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348183	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	347329	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348109	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348111	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348114	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348156	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348157	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348159	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028

14. Downey Avenue - I-5 Freeway to Firestone Boulevard

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348163	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348166	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348167	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348171	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348112	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348161	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348162	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348164	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348165	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028
Downey Avenue - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	348170	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2028

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321363	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321367	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321380	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321365	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330806	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330817	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321356	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321364	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321369	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321373	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321446	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321474	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330805	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330815	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321357	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321370	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321447	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330816	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321475	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321358	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321366	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321371	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321374	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321448	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330807	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330818	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321368	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321372	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321393	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321397	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321401	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321403	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321406	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321409	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321413	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321415	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321417	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321423	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321425	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321427	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321430	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321432	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321434	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321438	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321440	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321465	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321473	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321452	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321453	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321454	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321383	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321391	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321392	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321396	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321398	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321399	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321400	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321402	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321405	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321408	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321412	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321414	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321416	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321418	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321422	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321424	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321426	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321428	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321429	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321431	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321433	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321435	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321437	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321439	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321464	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321469	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321472	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321384	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321385	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321387	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029

15. Paramount Boulevard - Conrad Street to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321388	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321389	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	321451	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2029
Paramount Boulevard - Stewart and Gray Road To Imperial Highway - Stewart and Gray Road To Imperial Highway Downey, CA 90242	330811	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2029

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352776	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352890	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352894	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353102	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353107	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353193	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353205	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353317	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353105	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	359803	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352887	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353099	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353202	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353314	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	359800	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482094	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482221	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352773	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	359801	Curb Ramps	The curb ramp is not wholly contained within the marked crossing.	Provide a marked crossing on the path of travel; make certain the curb ramp is wholly contained within the marked crossing.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352888	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353100	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353203	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353315	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	359802	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482222	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353108	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353195	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353207	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353319	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482095	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482223	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352889	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353101	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353204	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353316	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	359804	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352891	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353103	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353194	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353206	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353318	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352892	Curb Ramps	The transition from the top of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482096	Curb Ramps	The transition from the top of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482224	Curb Ramps	The transition from the top of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the top of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352775	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353192	Curb Ramps	There is less than the required clear space.	Provide sufficient clear space at the bottom of the curb ramp that does not accumulate water.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352777	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352893	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353104	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353320	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352774	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353106	Curb Ramps	Utilities, gratings or other appurtenances are located on the curb ramp.	Provide a compliant curb ramp free of appurtenances.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352786	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352799	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352813	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352826	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352838	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352849	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352861	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352874	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352985	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352999	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353013	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353027	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353041	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353054	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353067	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353080	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353111	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353124	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353137	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353150	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353163	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353175	Intersections	Ambient sound level at the signal is not compliant.	Provide compliant pedestrian signal.	2.00 - 5.00 decibels	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352791	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352805	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352818	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352830	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352841	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352853	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352866	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352879	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352991	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353005	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353019	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353033	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353046	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353059	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353072	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353086	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353116	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353129	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353142	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353155	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353167	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353179	Intersections	Either universal tactile or universal symbol is not provided at the signal.	Universal tactile and universal symbol must be provided at the signal (3 braille dots forming an equilateral triangle).	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352780	Intersections	Intersection walking surface slope is not compliant.	Repave the walking surface with recommended slope.	Up to 5.00 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352795	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352809	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352822	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352834	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352845	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352857	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352870	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352883	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352995	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353009	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353023	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353037	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353050	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353063	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353076	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353090	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353120	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353133	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353146	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353159	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353171	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353183	Intersections	No locator tone provided for the pedestrian signal indicator.	Provide locator tone for the indicator.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352790	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352804	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352817	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352829	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352840	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352852	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352865	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352878	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352990	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353004	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353018	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353032	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353045	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353058	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353071	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353085	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353115	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353128	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353141	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353154	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353166	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353178	Intersections	No tactile arrow provided for the signal.	Provide a compliant tactile arrow at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352796	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352810	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352823	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352835	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352846	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352858	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352871	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352884	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352996	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353010	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353024	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353038	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353051	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353064	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353077	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353091	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353121	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353134	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353147	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353160	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353172	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353184	Intersections	No walk interval tone provided for the pedestrian signal indicator.	Provide compliant walk interval tone.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352789	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352801	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353139	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353152	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353177	Intersections	Push button diameter is not compliant.	Provide a compliant push button.	At least 2.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352788	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352800	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352814	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352827	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352839	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352851	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352863	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352875	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352986	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353000	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353014	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353028	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353042	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353055	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353068	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353081	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353112	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353126	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353138	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353164	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353176	Intersections	Push button distance from crosswalk is not compliant.	Provide a compliant push button.	Up to 60.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352850	Intersections	Push button distance from curb is not compliant.	Provide a compliant push button.	17.00 - 120.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353125	Intersections	Push button distance from curb is not compliant.	Provide a compliant push button.	17.00 - 120.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352988	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353002	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353016	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353030	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353043	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353056	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353069	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353083	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353151	Intersections	Push button does not contrast in color.	Push button must contrast in color.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352815	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352864	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352987	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353001	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353015	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353029	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353082	Intersections	Push button face is not parallel to crosswalk.	Push button face must be parallel to crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352802	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352828	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352876	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352989	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353003	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353017	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353031	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353044	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353057	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353070	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353084	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353113	Intersections	Push button height is not compliant.	Provide a compliant push button.	41.00 - 48.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352787	Intersections	Push button is not located at least 10 feet from other accessible pedestrian signals.	Push button must be located at least 10 feet from other accessible pedestrian signals.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352862	Intersections	Push button is not located at least 10 feet from other accessible pedestrian signals.	Push button must be located at least 10 feet from other accessible pedestrian signals.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352798	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352812	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352825	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352837	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352848	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352860	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352873	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352886	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352998	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353012	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353026	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353040	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353053	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353066	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353079	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353093	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353123	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353136	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353149	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353162	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353174	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353186	Intersections	Speech walk message is not provided at the signal.	Provide compliant speech walk message for the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352803	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352816	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352877	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353127	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353140	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353153	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353165	Intersections	The clear ground space is not level.	Provide compliant level clear ground space at the control.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352793	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352807	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352820	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352832	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352843	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352855	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352868	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352881	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352993	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353007	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353021	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353035	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353048	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353061	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353074	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353088	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353118	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353131	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353144	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353157	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353169	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353181	Intersections	There are no color coded bands provided at the signal.	Provide 2" wide yellow band and 1" wide dark border bands above and below the yellow band.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352779	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352782	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352785	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353109	Intersections	There are no detectable warnings provided for the crosswalk.	Provide compliant detectable warnings for the crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352794	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352808	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352821	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352833	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352844	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352856	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352869	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352882	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352994	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353008	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353022	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353036	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353049	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353062	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353075	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353089	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353119	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353132	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353145	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353158	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353170	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353182	Intersections	There is no crosswalk map provided at the signal.	Provide a crosswalk map.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352792	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352806	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352819	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352831	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352842	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352854	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352867	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352880	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352992	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353006	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353020	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353034	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353047	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353060	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353073	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353087	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353117	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353130	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353143	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353156	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353168	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353180	Intersections	There is no street name information related signage at the signal.	Provide compliant signage that includes street name.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352797	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352811	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352824	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352836	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352847	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352859	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352872	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352885	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352997	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353011	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353025	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353039	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353052	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353065	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353078	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353092	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353122	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353135	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353148	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353161	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353173	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353185	Intersections	There is no vibro-tactile indication at the signal.	Provide compliant vibro-tactile indicator at the signal.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353114	Intersections	There is not enough clear ground space at the push button.	Provide compliant clear ground space at the push button.	At least 32.00 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352778	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352781	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352783	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352784	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352981	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352982	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352983	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352984	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	353110	Intersections	Traffic stop bars are not at a minimum of 4 feet from crosswalk.	Traffic stop bars shall be at a minimum of 4 feet from crosswalk.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482093	Path of Travel	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482225	Path of Travel	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352746	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352748	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352750	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352758	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352759	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352762	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352766	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352768	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352772	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482119	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482123	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482136	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482145	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482147	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482194	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482201	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482203	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482214	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482218	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482183	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352713	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352720	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352709	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352717	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352718	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352719	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482101	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482158	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482159	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482160	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352710	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482106	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482162	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482165	Sidewalks	Sidewalk running slope is not compliant.	Repave the sidewalk surface with the recommended running slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482100	Sidewalks	Sidewalk surface is not slip resistant.	Make sure that the sidewalk surface is firm, stable and slip resistant.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482105	Sidewalks	Sidewalk surface is not slip resistant.	Make sure that the sidewalk surface is firm, stable and slip resistant.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482122	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482125	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482190	Sidewalks	Slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant slope.	Up to 5.00 percent	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352747	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352749	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352757	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352760	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352761	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352765	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352767	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352771	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482118	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482124	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482135	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482141	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482144	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482146	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482192	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482193	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482200	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482202	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482213	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482217	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	351893	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352721	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352722	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352724	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352726	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Florence Avenue To Firestone Boulevard - Florence Avenue To Firestone Boulevard Downey, CA 90241	352728	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482109	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482110	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482172	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031

16. Paramount Boulevard - Phlox Street to 5th Street

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482173	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482177	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482180	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482182	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482184	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482185	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2031
Paramount Boulevard - Stewart & Gray Road to Firestone Boulevard - Stewart & Gray Road to Firestone Boulevard Downey, CA 90242	482264	Sidewalks	There is no 60X60 turn area at every 200 feet.	Provide a 60X60 turn every 200 feet on the sidewalk.	See Recommendation	6/30/2031

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479392	Curb Ramps	Curb ramp run surface has a grade break.	Provide a compliant curb ramp.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479672	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479679	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479684	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479687	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479836	Curb Ramps	The bottom landing of the curb ramp is on the street, and the slope of the bottom landing is not compliant.	Ensure the bottom landing slope is compliant and provides a smooth transition.	Up to 5.00 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479395	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479669	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479676	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479678	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479683	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479834	Curb Ramps	The cross slope is greater than allowed.	Provide a compliant curb ramp.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479394	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479667	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479671	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479675	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479677	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479682	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479686	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479826	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479828	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479830	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479832	Curb Ramps	The curb ramp does not provide a detectable warning surface which includes truncated domes.	Provide compliant detectable warnings to surface.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479668	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479833	Curb Ramps	The running slope is greater than allowed.	Provide a compliant curb ramp.	Up to 8.33 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479393	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479397	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479670	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479674	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479681	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479685	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479689	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479829	Curb Ramps	The slope at the top landing is greater than allowed.	Provide a top landing surface that does not exceed the maximum slope and cross slope. Provide a sufficient maneuvering clearance that does not accumulate water.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479835	Curb Ramps	The slope of the curb ramp side flare is greater than allowed.	Provide curb ramp side flares with a compliant slope.	Up to 10.00 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479396	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479673	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479680	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479688	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479831	Curb Ramps	The transition from the bottom of the curb ramp to the walk, gutter, or street is abrupt.	Patch the transition area at the bottom of the curb ramp so that the transition is flush and free of abrupt changes.	Up to 0.50 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479827	Curb Ramps	There is not enough top landing clear length.	Provide a level top landing with enough clear length.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332578	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332580	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332582	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332584	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332586	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332588	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332591	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332593	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332595	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332597	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332599	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479269	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479273	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479275	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479277	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479279	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479281	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479283	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479285	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479287	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479291	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479294	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479318	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479321	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479323	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479327	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479331	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479333	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479335	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479337	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479339	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479341	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479343	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479347	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479349	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479351	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479354	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479357	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479361	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479382	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479727	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479729	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479731	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479733	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479735	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479738	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479740	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479742	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479744	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479746	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479748	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479750	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479752	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479754	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479756	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479758	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479760	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479762	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479764	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479768	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479770	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479772	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479774	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479776	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479778	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479780	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479782	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479785	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479787	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479789	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479810	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479814	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479817	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479819	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479821	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479824	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479865	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479867	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479871	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479873	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479875	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479877	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479879	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479881	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479883	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479885	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479887	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479889	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479891	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479893	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479896	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479899	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479901	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479903	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479907	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479909	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479911	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479913	Sidewalks	Cross slope at vehicular traffic is not compliant.	Repave the surface to provide a compliant cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332566	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332568	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479259	Sidewalks	Ground surface has an opening that is not compliant.	Make sure that the surface opening does not allow passage of a sphere more than ½ inch in diameter.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332572	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332573	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479260	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479266	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479301	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479302	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479305	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479307	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479313	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479365	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479366	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479367	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479369	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479371	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479373	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479374	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479375	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479376	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479646	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479648	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479649	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479650	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479651	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479652	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479656	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479657	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479658	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479701	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479702	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479706	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479708	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479709	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479710	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479713	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479715	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479716	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479721	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479722	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479802	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479803	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479842	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479846	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479847	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479851	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479852	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479854	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479855	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479860	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479862	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479863	Sidewalks	Overhead obstruction height is not compliant.	Provide a compliant vertical clearance height.	At least 80.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479694	Sidewalks	Section of sidewalk is missing and consists of dirt, grass or gravel.	Provide a compliant sidewalk for the missing section.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332564	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332565	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479258	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479362	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479690	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479696	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479840	Sidewalks	Sidewalk cross slope is not compliant.	Repave the sidewalk surface with the recommended cross slope.	Up to 2.08 percent	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332567	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479257	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479298	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479642	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479643	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479644	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479645	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479691	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479692	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479693	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479695	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479697	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479698	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479790	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479791	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479792	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479793	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479794	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479795	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479837	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479838	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479839	Sidewalks	Sidewalk does not have enough width.	Widen the sidewalk to the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332563	Sidewalks	Sidewalk surface is not slip resistant.	Make sure that the sidewalk surface is firm, stable and slip resistant.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332571	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332574	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332575	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332576	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479262	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479306	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479309	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479314	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479315	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479316	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479654	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479704	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479705	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479717	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479718	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479841	Sidewalks	Sidewalk width at the obstruction is not compliant.	Sidewalk width at the obstruction shall have the recommended value.	At least 48.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479377	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479647	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479714	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479801	Sidewalks	The leading edge of the protruding object is more than 4 inches from the edge of sidewalk.	Install side extensions, modify, relocate, or lower the protruding object so that the leading edge protrudes less than 4 inches from the edge of sidewalk.	Up to 4.00 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332577	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332579	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332581	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332583	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332585	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332587	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332589	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332590	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332592	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332594	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332596	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332598	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479268	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479270	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479271	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479272	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479274	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479276	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479278	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479280	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479282	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479284	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479286	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479288	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479289	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479290	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479292	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479293	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479295	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479296	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479297	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479317	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479319	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479320	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479322	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479324	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479325	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479326	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479328	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479329	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479330	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479332	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479334	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479336	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479338	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479340	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479342	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479344	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479345	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479346	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479348	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479350	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479352	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479353	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479355	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479356	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479358	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479359	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479360	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479378	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479379	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479380	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479381	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479383	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479384	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479385	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479386	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479387	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479388	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479389	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479390	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479391	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479659	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479660	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479661	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479662	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479663	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479664	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479665	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479666	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479724	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479725	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479726	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479728	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479730	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479732	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479734	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479736	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479737	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479739	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479741	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479743	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479745	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479747	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479749	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479751	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479753	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479755	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479757	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479759	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479761	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479763	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479765	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479766	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479767	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479769	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479771	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479773	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479775	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479777	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479779	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479781	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479783	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479784	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479786	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479788	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479809	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479811	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479812	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479813	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479815	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479816	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479818	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479820	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479822	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479823	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479825	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479864	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479866	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479868	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479869	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479870	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479872	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479874	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479876	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479878	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479880	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479882	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479884	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479886	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479888	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479890	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479892	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479894	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479895	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479897	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479898	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479900	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479902	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479904	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479905	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479906	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479908	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479910	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479912	Sidewalks	There are no detectable warnings where the pedestrian route crosses vehicular traffic.	Provide detectable warnings.	See Recommendation	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332569	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue To City Limit - Woodruff Avenue To City Limit Downey, CA 90241	332570	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479261	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479263	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479264	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479265	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479267	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479299	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479300	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479303	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479304	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479308	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479310	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479311	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Woodruff Avenue to Brookshire Avenue - Woodruff Avenue to Brookshire Avenue Downey, CA 90240	479312	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479363	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479364	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479368	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479370	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479372	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479653	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Brookshire Avenue to Paramount Boulevard - Brookshire Avenue to Paramount Boulevard Downey, CA 92040	479655	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479699	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479700	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479703	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479707	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479711	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479712	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479719	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479720	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479723	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479796	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479797	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479798	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479799	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479800	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479804	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479805	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479806	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479807	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479808	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479843	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479844	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479845	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479848	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479849	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479850	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479853	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479856	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479857	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

3b. Firestone Boulevard - West City Limit to Stewart and Gray Road

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479858	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479859	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034
Firestone Boulevard - Paramount Boulevard to City Limits - Paramount Boulevard to City Limits Downey, CA 92040	479861	Sidewalks	There is a change in elevation greater than recommended value.	Ensure that the change in elevation is within the recommended value.	Up to 0.25 inches	6/30/2034

7. Florence Avenue - Perry Road to Tolar Avenue (City of Bell Gardens)

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date

NOTE: THIS LOCATION DOES NOT FALL WITHIN THE CITY OF DOWNEY JURISDICTION

8. Florence Avenue - Ira Avenue to West City Limit (City of Bell Gardens)

Facility	Record Number	Category	Finding	Recommendation	Recommended Value	City of Downey Projected Completion Date

NOTE: THIS LOCATION DOES NOT FALL WITHIN THE CITY OF DOWNEY JURISDICTION