

## Accessibility Survey

---



### City of Downey Eglise Avenue - Gotham Street to Woodruff Avenue

Gotham Street to Woodruff Avenue  
Downey, CA 90242

Date of Inspection  
6/13/2017

Prepared By

**Disability Access Consultants**

(800) 743-7067

## Eglise Avenue - Gotham Street to Woodruff Avenue

### Sidewalks - Exterior : Sidewalks , Change in Level

---

#### East Side

#### Change in Level South of Gotham Street @ 33.938416668612, -118.113349825144

Sidewalks , Change in Level : Change in Level Non Beveled

#### Finding

There is a change in elevation greater than recommended value.

**On-Site Finding** 0.50 inches

#### Recommendation

Ensure that the change in elevation is within the recommended value.

Recommendation Up to 0.25 inches

#### Costing Info (Estimated)

Remove tripping hazards \$198



**Code Reference** ADA 206, 302

#### Progress

---

<b>Record Number</b>	446723	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Two
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2021
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

## Eglise Avenue - Gotham Street to Woodruff Avenue

### Sidewalks - Exterior : Sidewalks , Vehicular Traffic

---

#### East Side

#### Driveway South of Gotham Street @ 33.938692600762, -118.113158047199

Sidewalks , Vehicular Traffic : Cross Walks and Detectable Warnings

#### Finding

There are no detectable warnings where the pedestrian route crosses vehicular traffic.

**On-Site Finding** Not Found

#### Recommendation

Provide detectable warnings.

Recommendation See Recommendation

#### Costing Info (Estimated)

Install compliant detectable warnings \$190



**Code Reference** ADA 705,CA 11B-705.1.2.5,CA 11B-247.1.2.5

#### Progress

---

<b>Record Number</b>	446724	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2032
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

## Eglise Avenue - Gotham Street to Woodruff Avenue

### Sidewalks - Exterior : Sidewalks

---

#### East Side

#### Driveway South of Gotham Street @ 33.938692600762, -118.113158047199

Sidewalks : Vehicular Traffic Cross Slope

#### Finding

Cross slope at vehicular traffic is not compliant.

**On-Site Finding** 4.80 percent

#### Recommendation

Repave the surface to provide a compliant cross slope.

Recommendation Up to 2.08 percent

#### Costing Info (Estimated)

Repave surface \$1,092



**Code Reference** ADA 206, 302, CA 11B-403.3

### Progress

---

<b>Record Number</b>	446725	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2032
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments	<b>New Value</b>	0
<b>Assignment</b>	None		
<b>Designated Staff</b>			

**Eglise Avenue - Gotham Street to Woodruff Avenue**

**Sidewalks - Exterior : Sidewalks**

**East Side @ 33.939175479872, -118.112803995609**

Sidewalks : Turn Area

**Finding**

Turn area is not level.

**On-Site Finding** Not Level

**Recommendation**

Make sure that the turn area is level.

Recommendation See Recommendation

**Costing Info (Estimated)**

\$1,260



**Code Reference** ADA 206, 302

**Progress**

<b>Record Number</b>	446722	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2032
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Eglise Avenue - Gotham Street to Woodruff Avenue**

**Sidewalks - Exterior : Sidewalks**

**West Side @ 33.938464511751, -118.113533556461**

Sidewalks : No Sidewalk

**Finding**

No sidewalk exists at the location.

**On-Site Finding** Not Found

**Recommendation**

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

**Costing Info (Estimated)**

Unassigned



**Code Reference** ADA 206

**Progress**

<b>Record Number</b>	446726	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2037
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Eglise Avenue - Gotham Street to Woodruff Avenue**



**Eglise Avenue - Gotham Street to Woodruff Avenue**

**Gotham Street to Woodruff Avenue  
Downey, CA 90242**

Date of Inspection  
6/13/2017

**\*Estimated Facility Total: \$2,740**

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

**Disability Access Consultants**

(800) 743-7067

Prepared Using



## Accessibility Survey

---



### City of Downey Eglise Avenue - Via Amorita to Florence Avenue

Via Amorita to Florence Avenue  
Downey, CA 90242

Date of Inspection  
8/6/2017

Prepared By  
**Disability Access Consultants**  
(800) 743-7067



## Eglise Avenue - Via Amorita to Florence Avenue

### Sidewalks - Exterior : Sidewalks

---

**East Side @ 33.941536435, -118.111082017422**

Sidewalks : No Sidewalk

#### Finding

No sidewalk exists at the location.

**On-Site Finding** Not Found

#### Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

#### Costing Info (Estimated)

Unassigned



**Code Reference** ADA 206

### Progress

---

<b>Record Number</b>	476952	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2037
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

## Eglise Avenue - Via Amorita to Florence Avenue

### Sidewalks - Exterior : Sidewalks

---

**West Side @ 33.941599847649, -118.111221492291**

Sidewalks : No Sidewalk

#### Finding

No sidewalk exists at the location.

**On-Site Finding** Not Found

#### Recommendation

No action necessary until a sidewalk is provided.

Recommendation See Recommendation

#### Costing Info (Estimated)

Unassigned



**Code Reference** ADA 206

### Progress

---

<b>Record Number</b>	476951	<b>Resolution</b>	None
<b>Progress</b>	Not_Started	<b>Priority</b>	Seven
<b>Actual Date</b>		<b>Projected Date</b>	06/30/2037
<b>Actual Cost</b>	\$0.00	<b>Contractor</b>	
<b>Comments</b>	No Comments		
<b>Assignment</b>	None	<b>New Value</b>	0
<b>Designated Staff</b>			

**Eglise Avenue - Via Amorita to Florence Avenue**



**Eglise Avenue - Via Amorita to Florence Avenue**

Via Amorita to Florence Avenue  
Downey, CA 90242

Date of Inspection  
8/6/2017

**\*Estimated Facility Total: \$0**

\*Estimated facility total is for estimating purposes only and does not represent total construction, repair totals or design fees.

Prepared By

**Disability Access Consultants**

(800) 743-7067

Prepared Using

